



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Page 1

Customer : AXA INSURANCE S'PORE PTE LTD

Document No. : SQT19001062

Date : 6. Mar 2019
Customer No. : WZA006
Svc Advisor : ANIKKA LAI SWEE KAM
Engine No : K24W72460389
Date | Time : 6. Mar 2019 7:48:53 PM

8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SMG6313S
Chassis No : JHMRG1890KC200480
Model : ODYSSEY 2.4 EXV-S 19YM (EURO 6)
Owner's Name : HO CHIN NING
Ins Policy No. :
Date of Accident : 5/3/2019

Surveyor Name :
Survey Date :
Authorisation Date :

Item Description Qty Unit Price Disc % Amount 0% GST Amount incld GST

)

TP DIRECT SETTLEMENT (J/NO:

OWNER: HO CHIN NING

OWNER INSURER: AVIVA

ACC DATE: 05/03/2019

SURVEYED BY:

DATE:

REF NO:

TP INSURER: AXA

TP VEH: SLO7060Z

68100-T6A-Q10ZZ

TAILGATE COMP

1 1070.80

84431-T6A-J01ZA

LINING ASSYTAILGATE LOWER

1 206.30

84433-T6A-J01ZA

GARNISH ASSYTAILGATE UPPER

1 42.60

68210-T6A-003ZZ

HINGE COMPTAILGATE

2 35.80

74440-T6A-003

WEATHERSTRIPTAILGATE

1 117.40

74800-TF0-J02

LOCKTAILGATE

1 185.40

74820-T6A-013

STAY ASSYR.TAILGATE OPEN

1 164.50

74870-T6A-013

STAY ASSYL.TAILGATE OPEN

1 164.50

84441-T6A-J01ZA

POCKETTAILGATE LINING PULL

1 10.70

74890-T6A-N11ZE

GARNISH ASSY,RR,LICEION LID

1 164.20

74891-T6A-003

MOLDING ASSYRR,LICENSE GARN

1 175.50

75701-T6A-000

EMBLEMH

1 26.30

91512-SR3-004

CLIP TUBULAR

2 2.30

75722-T6A-901

EMBLEM,RR.

1 31.00

73214-T6A-003

MOLDINGRR,WINDSHIELD SIDE

2 18.00

73215-T6A-003

MOLDINGR,RR,WINDSHIELD CORNER

1 16.90

73216-T6A-003

MOLDINGL,RR,WINDSHIELD CORNER

1 16.90

73221-SR4-000

SPACERRR,W/SHIELD

4 3.90

73225-TM8-000

RUBBER AWINDSHIELD DAM

1 3.70

25 803.10 56.22 859.32

25 154.72 10.83 165.55

25 31.95 2.24 34.19

25 53.70 3.76 57.46

25 88.05 6.16 94.21

25 139.05 9.73 148.78

25 123.37 8.64 132.01

25 123.37 8.64 132.01

25 123.37 8.64 132.01

25 11.70 0.82 12.52

Printed on 7/3/2019 1:33:18 PM

This is a computer generated invoice. No signature is required

Part prices are subjected to change without notice

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00. However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
 8 SHENTON WAY
 #27-01 AXA TOWER
 SINGAPORE 068811

Registration No : SMG6313S

Chassis No : JHMRC1890KC200480

Model : ODYSSEY 2.4 EXV-S 19YM (EURO 6)

Owner's Name : HO CHIN NING

Ins Policy No. :

Date of Accident : 5/3/2019

Document No. : SQT19001062

Date : 6. Mar 2019

Customer No. : WZA006

Svc Advisor : ANIKKA LAI SWEE KAM

Engine No : K24W72460389

Date | Time : 6. Mar 2019 7:48:53 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
73226-SZW-000	DAMPERSTD 5X5	2 <i>na</i>	8.50	25	12.75	0.89	13.64
76711-T6A-003	CAPPIVOT	1 <i>na</i>	4.80	25	3.60	0.25	3.85
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2 <i>na</i>	60.00		120.00	8.40	128.40
33500-T6A-J51	LIGHT ASSY,R.TAIL	1 <i>?</i>	838.10	25	628.57	44.00	672.57
33550-T6A-J51	LIGHT ASSY,L.TAIL	1 <i>?</i>	838.10	25	628.57	44.00	672.57
34150-T6A-J51	LIGHT ASSY,R.LID	1 <i>cu</i>	386.20	25	289.65	20.28	309.93
34155-T6A-J51	LIGHT ASSY,L.LID	1 <i>cu</i>	378.60	25	283.95	19.88	303.83
04715-T6A-N10ZZ	FACE ASSY,RR.BUMPER	1 <i>de</i>	557.20	25	417.90	29.25	447.15
71593-T6A-003	SPACERR.RR.BUMPER SIDE	1 <i>na</i>	19.10	25	14.32	1.00	15.32
71598-T6A-003	SPACERL.RR.BUMPER SIDE	1 <i>na</i>	19.10	25	14.32	1.00	15.32
91505-TM8-003	CLIP,BUMPER	8 <i>na</i>	2.30	25	13.80	0.97	14.77
84640-T6A-003ZA	LINING ASSYRR.PANEL	1 <i>?</i>	103.60	25	77.70	5.44	83.14
33505-SLJ-013	REFLECTOR ASSYR.RR.	1 <i>?</i>	45.40	25	34.05	2.38	36.43
33555-SLJ-013	REFLECTOR ASSYL.RR.	1 <i>?</i>	45.40	25	34.05	2.38	36.43
66100-T6A-Q00ZZ	PANEL COMP,REAR	1 <i>?</i>	460.80	25	345.60	24.19	369.79
04656-T6A-310ZZ	PAN SET,3RD SEAT	1 <i>?</i>	337.90	25	253.42	17.74	271.16
74940-TR0-003	BUZZER ASSYSMART	1 <i>?</i>	60.10	25	45.07	3.15	48.22
72841-SH3-315	OILSHEET	3 <i>?</i>	40.70	25	91.57	6.41	97.98
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR	1 <i>na</i>	320.00		320.00	22.40	342.40
BO-NUM-COMP-S	NUMBER PLATE WITH CASING-S(N)	1 <i>?</i>	45.00		45.00	3.15	48.15
Sum Item					5567.22	389.70	5,956.92
BOSUN	SUNDRIES	1 <i>50</i>	100.00		100.00	7.00	107.00
BOMISC1	RESET & CALLIBRATE SMART ENTRY SYSTEM (N)	1 <i>✓</i>	200.00		200.00	14.00	214.00
BOMISC1	REMOVE & INSTALL REAR VIEW CAMERA (N)	1 <i>✓</i>	280.00		280.00	19.60	299.60
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1 <i>✓</i>	100.00		100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT TAILGATE	1 <i>80</i>	100.00		100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT END PANEL	1 <i>80</i>	100.00		100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT FLOOR PANEL	1 <i>80</i>	100.00		100.00	7.00	107.00

Printed on 7/3/2019 1:33:18 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SMG6313S
Chassis No : JHMRC1890KC200480
Model : ODYSSEY 2.4 EXV-S 19YM (EURO 6)
Owner's Name : HO CHIN NING
Ins Policy No. :
Date of Accident : 5/3/2019

Document No. : SQT19001062
Date : 6. Mar 2019
Customer No. : WZA006
Svc Advisor : ANIKKA LAI SWEE KAM
Engine No : K24W72460389
Date | Time : 6. Mar 2019 7:48:53 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 3

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	800.00		800.00	56.00	856.00
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	800.00		800.00	56.00	856.00
BG02R	REPLACE RR. WINDSCREEN.(N)	1	560.00		560.00	39.20	599.20
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	120.00		120.00	8.40	128.40
BKRP22B	CUT OFF & RENEW RR FLOOR PANEL & DAMAGE PARTS.	1	4000.00		4000.00	280.00	4280.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	3000.00		3000.00	210.00	3210.00
Sum Labor					10260.00	718.20	10,978.20

Survey By

Date & Time

Excess

Status

Signature

Total Amount 15,827.22 1,107.90 16,935.12

Total (Inclusive of GST) 16,935.12

Repair - 1350
Replac - 2250
Repair before paint.
sure khando.com
taphu @ khando.com
7-8 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts, during resurvey
- Parts prices are subject to change without notice
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications allowed
- Supplementary items for repair is subject to final approval from LKK Auto Consultants

Acknowledged by Repairer
Signature:
Date:

Printed on 7/3/2019 1:33:18 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.