



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving 1 2006 TOYOTA HARRIER 2.4 (SFF636M)

Date of Loss 2 March 2019

Time of Loss

Loss Description SFF636M (INSD) C/W SHB2284D (TP)

Comment

Workshop Details

Total Rebate Amount 41351

Nett Loss Amount \$13,649.00

Assigned Workshop LKK AUTO CONSULTANTS PTE LTD (OD)

Days of work completion
*

20



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Vehicle & Driver Details

Vehicle Registration#	SFF636M	Purchase Date	dd/mm/yyyy
Registration State	SINGAPORE	Registration Date *	13/02/2007
Mileage	293077	Age of Vehicle	12

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Manufacturing Year	2006	2006
Make	TOYOTA	TOYOTA
Model	HARRIER 2.4	HARRIER 2.4 A

Driver Details

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Driver Name		
Date of Birth		dd/mm/yyyy
Age		

Type	POLICY	ASSESSMENT INFORMATION
CATEGORY	INFORMATION	
Type of Paint		
Chassis No	ACU300060514	ACU300060514
Engine No	2AZB235206	2AZB235206
Engine Capacity		2362
Sum Insured	0	0
Market Value	0	55000

CATEGORY	FNOL
Information	INFORMATION
Education Qualification	
Driving Experience	
Driver License #	
License Type	
License Issue Date	dd/mm/yyyy
License Expiration Date	dd/mm/yyyy
Address	
Address type	

Gender
CATEGORYFNOL
INFORMATION

POST SURVEY INFORMATION

Marital status

Identification #

 Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Detailed Assessment

Inspection Date *	08/03/2019
Total Loss	Yes No
Towing Charges	0
Voluntary Excess	0
Compulsory Excess	0
Young/Inexperienced/Un named Driver Excess	0
Other Excess	

Condition of Vehicle at time of survey

General condition	Good ▾
Steering (Serviceable)	Yes No
Footbrake (Serviceable)	Yes No
Handbrake (Serviceable)	Yes No
Engine Modification	Yes No
Pre-accident condition	Good ▾

Tyre Condition

Age of Tyres		Spare wheel	
--------------	-------------	-------------	-------------

Front Tyre Size

225/65R17

Rear Tyre Size

225/65R17

Front left side

YOKOHAMA2mm

Rear left side

YOKOHAMA4mm

Front right side

YOKOHAMA2mm

Rear right side

YOKOHAMA4mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes

No

Part Supplied by AXA

Yes

No

Save



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Parts

Add Approve Deny Submit All

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPL/ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)	REMOVE
		0	1		FRONT BUMPER (WCP) (10%)	Buckled	0	308	No					308	Reviewing	
		0	1		L/INN BUMPER BRACKET	Repair	0	0	No					0	Deny	
		0	1		LEFT HEADLAMP ASSY (WCP) (10%)	Cracked	0	495	No					495	Reviewing	
		0	1		L/F FOG LAMP CPL	Serviceable	0	0	No					0	Deny	
		0	1		L/F WING	Repair	0	0	No					0	Deny	
		0	1		L/F WHEELHOUSE COVER	Serviceable	0	0	No					0	Deny	
		0	1		FRN BUMP CLIPS (15)	Serviceable	0	0	No					0	Deny	
		0	1		FEND COWL CLIPS (8)	Serviceable	0	0	No					0	Deny	

Labour

Add Approve Deny Submit All											
	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMOVE
		0		WHEEL ALIGNMENT	0	60	0	0	Reviewing		
		0		CHECK WIRING	0	20	0	0	Reviewing		
		0		50.0 WU X 45.00 SGD/H	0	139.5	0	0	Reviewing		
		0		LABOUR COST 53.0 WU X 45.00 SGD/H	0	306	0	0	Reviewing		
		0		MATERIAL COST	0	148.14	0	0	Reviewing		

 Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

	EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
		0	DAYS OF REPAIR : 4 DAYS	Reviewing		0		
		0	TYRE LHF	Reviewing		0	SERVICEABLE	
		0	SPORTS RIM LHF (LOCAL REPAIR)	Reviewing		120	DENTED	



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Estimated Claim Amount \$0.00 Adjusted Claim Amount \$1,596.64

CATEGORY	ESTIMATE	ADJUSTED
Spare Parts	\$0.00	\$803.00
Labour	\$0.00	\$673.64
Miscellaneous	\$0.00	\$120.00

Submit for Review