



AUTOMOTIVE GROUP

A Sin Ming Autocity,
160 Sin Ming Drive #03-03
Singapore 575722
T 6453 2121 (4 lines) / 6458 1111 (24 hrs)
F 6459 9795 / 6459 0433
E admin@vinsautogroup.com.sg
W www.vinsautogroup.com.sg

Our Ref : TP/032019/3801

Accident date: 06/03/2019

Your Ref : SKC3175M

Invoice No:

Date: 07/03/2019

Motor Claim Department

Lonpac Insurance Bhd.

100 Beach Road

#19-00 Shaw Tower

Singapore 189702

ESTIMATE COST OF REPAIRS TO

Vehicle No. : SLP2715G

Make/Model : Honda Vezel

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1	pc	Rear glass moulding	\$	120.70	nei ✓
1	pc	Rear boot lid	\$	972.50	bt ✓
1	pc	Rear boot lid "Vezel" name plate	\$	43.00	nei ✓
1	pc	Rear boot lid rubber	\$	96.80	x
1	pc	Rear boot lid lock	\$	157.00	x
1	pc	Rear bumper	\$	762.70	de ✓
			\$	2,152.70	
Less 20%			\$	(430.54)	
			\$	1,722.16	

1	pc	Rear glass gum	\$	60.00	nei ✓
1	pc	Rear bumper sensor	\$	280.00	200
To remove and refix rear glass			\$	150.00	120
To repair rear damage			\$	580.00	400
To spray painting			\$	680.00	480
			\$	3,472.16	

VIN'S MOTOR PTE LTD

Tanjin 97495749
WP 2/3/19 e1145.
Resurvey before paint.
tanjin e1145@com
sure1145@com
4 days