

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

07 MAR 2019

ESTIMATE

Estimate No. : b1 50411
Date Estimated : 06/03/2019
Prepared By : Gary Poh Chai Hoon

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Chua Kean Huat
83 Yishun Street 81
#10-04

Singapore 768446

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SCU923R	V725495	28/02/2017	116d	0

DESCRIPTION

To replace rear bumper and attachment include knocking
cause by the accident.

850 ~~1,700.00~~

Painting rear bumper, tail panel

934 ~~1,781.00~~

To check electrical wiring systems and lightings at the
rear section for proper function.

156 ~~177.00~~

To check reverse camera not working after the accident
- rear camera mounted inside bumper (drop off)

? 405 ~~461.00~~

Sundries.

? 80.00

Total Labour 1: 4,189.00

DESCRIPTION

REAR BUMPER CARRIER ?
HOLDER CAMERA SYSTEM ?
HOLDER AERIAL ?
REAR BUMPER CENTRE GUIDE (M) ?
REAR BUMPER LH MOUNT ?
REAR BUMPER RH MOUNT ?
REAR BUMPER PRIMED (RFC) ~~DE~~
REAR PDC HOLDER SET ?
DECOUPLING RING PDC TORQUE CONVERTE ?
RR PDC SENSOR BLACK SAPPHIRE (475) ?
CONTROL UNIT REVERSING CAMERA ?
Bracket ?
REVERSING CAMERA ?
(DG/SL) ADHESIVE SET K6 ~~nu~~

QTY	PRIC	VALUE
1	416.45	416.45
1	34.90	34.90
1	32.30	32.30
1	67.05	67.05
1	142.55	142.55
1	142.55	142.55
1	1,009.30	1,009.30
1	24.60	24.60
4	5.05	20.20
4	236.85	947.40
1	920.60	920.60
1	23.10	23.10
1	681.10	681.10
1	53.05	53.05

Total Parts : 4,515.15

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : **b1 50411**
Date Estimated : **06/03/2019**
Prepared By : **Gary Poh Chai Hoon**

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SCU923R	V725495	28/02/2017	116d	0

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 2nd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date&Time 28/03/19 Excess S\$ _____

Surveyor's Name Rafael Sign _____

Surveyor's Tel 97000068 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____

Surveyor's E-mail _____

No. of Working Days Recommend 3-4 days

Labour 1	:	4,189.00
Parts	:	4,515.15
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	609.29
Grand Total	:	9,313.44

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **