

CASE OWNER:

CC 4, Asm 1900

4249,

Ghe 3/4

LEK:
IDAC:

102455

Surveyor:

DOI:

ASSIGNMENT

8/3/19

Date / Time:

7/3/2019

Registered in Mermon:

Pre-assign / CCU / FTE



Insured Vehicle No.:

YP 7965P

"NATURE"

Claim No.:

S9M01684

Name of Insured:

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :SS

D.O.A.:

5/3/19

Place of Accident:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

F88 6540



INSRS:

WSP:

Tel:

Liability:

RMKS:

My car
Confused

INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

STAGE

DATE / PIC

19/3

F88 6540

YP 7965P

19/3/2019

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

21/03/2020

TYPE REPORT TO SUBMIT WP REPORT

REPORT DONE

FORWARDED REPORT TO OI LAWYER

TO CLOSE. SUBMIT WP REPORT

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

L9

S\$

900.00

(

2

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

-

Loss of Rental (LOR):

S\$

-

(

days)

Loss of Use (LOU):

S\$

-

(\$

x

days)

Loss of Income (LOI):

S\$

-

(\$

x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$

-

Medical:

S\$

-

Disbursement:

S\$

-

(e.g. Tow/ Independent)

Legal Cost

S\$

-

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

WP REPORT

3) Survey fee:

250.00

Total:

S\$

-

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

-

Name 1:

-

Payee 2: (Strike if N.A.)

S\$

-

Name 2:

-

Payee 3: (Strike if N.A.)

S\$

-

Name 3:

-

COPY SENT

REF:

ASM

1646.E

ASSIGNMENT

(C-2026)

24 Nov 2006

From:

Date:

Veh No:

FBB 654D

Vt Regn:

Estimated Cost:

Type: M/Car / M/Truck / Bus / Van / Lorry / Taxi / Prime Mover /

OD (TP / WS / TP RES / OD RES / EVA / INV / MV)

Truck / Trailer or

To inspect Vehicle No:

FBB 654D

Make:

Yamaha T135

c.c.

135

at Workshop n/m:

My Car

Colour:

Black

A/C:

Insured / Std / NI / NA

of

53 Raja Ubi Ind Pk #01-33

Sp. Reading:

22311

T/Radio:

Insured / Std / NI / NA

Insured:

Eng/No:

Policy No:

ChNo:

5YP205177

Claims No:

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: Insured / Jammed / Leaked / Burnt or

(Client's Record)


Brake: Insured / Jammed / Leaked / Burnt or

Make of Veh:

Modi: M / S/Rim / STD A/Rim or

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Tyre Size:

F:

70/90-17

R:

90/80-17

BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Bal. or Market Value:

\$8800

Front

Rear

IDAC Accident Report:

Consistent? : Yes or No

R/Bal.

mm

R/Bal.

mm

GIA / PR Geon:

Consistent? : Yes or No

L/Bal.

mm

L/Bal.

mm

Est. Repairs:

2 days

Res.: Yes or No

D.O.A.

D.O.I.

08-03-19

Lump Sum:

20 %

3 Val.: Yes or No

Survey held at

w/s

2:30pm

CA / REV / REP. / 24 HRS

Des. of Damages: Frt / Rear / O/S / R/S / UIC / Rooftop or

Date:

Person Contacted:

Vehicle: IN / OUT

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Cob : 4815

\$900

Date/Time, File Pass to?

☐

: Prel. Report

Days Of Repair:

1)

☐

: Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2)

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Workshop (\$

Report Format :

Lump Sum / LB.1 (\$

(Survey Fee:

Dissemination

1. S + RS 2

1. Photos

1. Others

1. Other

1. Other

WG APPRAISAL SERVICES

Blk 224B, Compassvale Walk, #07-647, Singapore 542224
Email: winsongkk@hotmail.com Contact: 9747 0063
Company Register No. 53326249J

ACCIDENT DAMAGED VEHICLE INSPECTION REPORT

M/S LEE KWONG JIN
C/O MY CAR CONSULTANT PTE LTD
53 Ubi Ave 1, #01-33, Paya Ubi Industrial Park
Singapore 408934

Date : 01 April 2019
Our Ref : WG/TP/2019-112

REFERENCE PARTICULARS

Date of Accident : 05 March 2019
Date of Inspection : 11 March 2019

Type of Inspection : Third Party Claim
Date of Re-Inspr : 12 March 2019

VEHICLE PARTICULARS

Registration No : FBB654D
Make : YAMAHA
Model : 1135
Year : 2006

Engine No : 5YP205177
Chassis No : 5YP205177
Odometer : 22311km
Colour : Black

CONDITION OF VEHICLE (STATIC CHECKS AT TIME OF INSPECTION ONLY)

Engine condition : Good
Foot Brake : Serviceable
Hand Brake : Serviceable

General Body Work : Good
Steering : Serviceable
Lightings : Serviceable

TYRE CONDITION (Remaining estimated life of tyre in mm)

	Make	Size
Front Side	Yokohama	100/80-15
Rear side	Yokohama	100/80-15

Thread Balance
5mm
5mm

GENERAL DESCRIPTION OF DAMAGES

The vehicle sustained damage at the right side portion.
For details, refer to assessment for repairs and photographs attached.

ASSESSMENT SUMMARY

Our assessment of the repair costs to pre-accident condition was **S\$4,300.00** nett at lump sum basis. (Subject to GST if applicable)
Under normal circumstances, estimated period required for repairs : Seven (07) working days.

Enclosed One hundred and Fifty-six (56) photographs depicting damage to the vehicle.

Inspection conducted at : MY CAR CONSULTANT PTE LTD
53 Ubi Ave 1, #01-33, Paya Ubi Industrial Park . Singapore 408934

In accordance to your instruction, we have not authorise repairs and inspection
was conducted strictly on a "**WITHOUT PREJUDICE BASIS**".

VEHICLE NO : FBB654D
MODEL : T135

Our Ref : WG/TP/2019-112

ASSESSMENT OF REPAIRS AND SPARE PARTS COSTS

DESCRIPTION OF PARTS AND NATURE OF REPAIRS

SPARE PARTS	QTY PC/SET	ASSESSED CONDITION	ORIGINAL QUOTATION	REVISED QUOTATION
1 FRONT FENDER	1	GRAZED	\$ 120.00	\$ 120.00
2 FRONT LH FORK ASSY	1	BENT	\$ 350.00	\$ X 350.00
3 FRONT RH FORK ASSY	1	BENT	\$ 350.00	\$ X 350.00
4 STEERING HEADCROWM	1	BENT	\$ 150.00	\$ X 150.00
5 STEERING STEM UNDERBRACKET	1	NECESSARY	\$ 125.00	\$ X 125.00
6 STEERING STEM BEARING	2	NECESSARY	\$ 90.00	\$ X 90.00
7 FRONT RH SINGLE LAMP	1	NOT NECESSARY	\$ 150.00	\$
8 SIDE MIRROR	1 SET	GRAZED	\$ 120.00	\$ 120.00
9 HANDLE GRIP	1 SET	GRAZED	\$ 35.00	\$ X 35.00
10 BALANCER	1 SET	GRAZED	\$ 40.00	\$ 40.00
11 BRAKE LEVER	1	BENT	\$ 39.00	\$ 39.00
12 HEAD FAIRING ASSEMBLY	1	CRACKED	\$ 145.00	\$ 145.00
13 HEADLAMP ASSY	1	CRACKED	\$ 350.00	\$ X 350.00
14 HEADLAMP BRACKET	1	NECESSARY	\$ 175.00	\$ X 175.00
15 FRONT RH FAIRING INNER GARNISH	1	CRACKED	\$ 150.00	\$ 150.00
16 RIGHT FRONT FOOTREST	1	TORN	\$ 75.00	\$ 75.00
17 RIGHT FRONT FOOTREST HOLDER	1	BENT	\$ 135.00	\$ X 135.00
18 REAR RH SIDE FAIRING	1	CRACKED	\$ 310.00	\$ X 310.00
19 RADIATOR	1	BENT	\$ 550.00	\$ X 550.00
20 RH SIDE FAIRING	1	CRACKED	\$ 350.00	\$ X 350.00
21 MUFFLER CHROME PROTECTOR	1	GRAZED	\$ 110.00	\$ 110.00
22 MUFFLER COMP	1	GRAZED	\$ 550.00	\$ 550.00
			\$ 4,469.00	\$ 4,319.00
			Less 10%	\$ 446.90
				\$ 4,319.00
				\$ 4,022.10
				\$ 3,887.10

B) S/NETT ITEM

23 REAR BOX	1	GRAZED	\$ 390.00	\$ 390.00
24 FRONT NUMBER PLATE	1	NECESSARY	\$ 40.00	\$ X 40.00
			\$ 430.00	\$ 280.00

Parts Total :

\$ 4,452.10 \$ 4,167.10

C) LABOUR CHARGES & MISC

25 REPLACE, REALIGN AND ADJUST ABOVE DAMGE PARTS AND CHECK WIRING AND LIGHTNING SYSTEM			\$ 600.00	\$ 400.00
26 TO KNOCK, STRAIGHTEN CHASSIS AND BODY BALANCING			\$ 380.00	\$ 300.00
27 TO REMOVE/REFT, REPLACE FRONT FORK TUBES			\$ 180.00	\$ 130.00
28 SPRAY PAINTING			\$ 380.00	\$ 300.00
29 TOWING SERVICE			\$ 150.00	\$ 120.00
			\$ 1,690.00	\$ 1,250.00

Labour Total :

\$ 1,690.00 \$ 1,250.00

Total Parts and Laboure :

\$ 6,142.10 \$ 5,417.10

FINAL LUMP SUM ADJUSTMENT

\$ 4,300.00

L&K Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Automobile Consultants, Insurance Loss Assessors/Adjusters, Inspection and Evaluation

1138.4
20% : 900
2 Days

POINT OF IMPACT

The impact was confined to the right portion of the vehicle.
The damages appeared to be consistent as per the accident report statement.
Please refer the attached schedule and photographs for details.

ADJUSTMENT/RECOMMENDATIONS

We have thoroughly inspected each and every item on the repairer's estimates against the actual damaged found on the vehicle. We have listed the breakdown of our findings and recommendations as per assessment above.

CONCLUSION

The repairer has agreed to undertake repair the vehicle at a lump sum basis of **\$4,300.00 nett** corresponding to replacement of parts, spray painting and labour charges. We now revert for your decision on the above claim.

Yours faithfully
WG APPRAISAL SERVICES



Winsdn Goh
Automotive Appraiser

We do not accept service of Court documents by fax **60146661**

Our ref: AP/2019/001027

SEBASTIAN ROY S/O MANOHAR
Blk 428 Woodland Street 41
#03-240
Singapore 730428

AXA Insurance Pte Ltd
Insurer of YP7965P
8 Shenton Way
#24-01 AXA Tower
Singapore 068811
Attn: Motor Claim Department
(your ref: to be advised)

WITHOUT PREJUDICE

By Certificate of Posting

3 0 1 9 6 4 0 8 9 9 - - -

By Hand



Dear Sirs,

PROPERTY DAMAGE CLAIM ARISING FROM A ROAD TRAFFIC ACCIDENT ON 5 MARCH 2019 AT ABOUT 18:45HRS INVOLVING MOTOR VEHICLES NO(S). YP7965P & FBB654D ALONG JUNCTION OF LOR 23 GEYLANG

We refer to the above matter.

We act for LEE KWONG JIN, the owner of FBB654D.

We are instructed by our clients to claim damages against you in connection to the above-mentioned road traffic accident involving our clients' vehicle and your vehicle bearing registration number YP7965P.

We are instructed that the above-mentioned road traffic accident was caused by the negligence of your authorised driver in the driving, management and/or control of your vehicle.

As a result of the abovementioned road traffic accident, our clients' vehicle was damaged and our clients has been put to loss and expense, particular of which are as follows:

Costs of repair		\$ 4,300.00
Towing fee		\$ 60.00
Loss of use		\$ 850.00
- Pre-repair	\$ 400.00	
(8 days including intervening weekend x50.00 per day)		
- During repair works	\$ 450.00	
(9 days including intervening weekend x \$50.00 per day)		
Our Legal Costs		\$ 1,500.00
Disbursements (incurred to-date)		\$ 593.00
- Survey report fees	\$ 406.00	
- GIA/LTA search/document fee	\$ 37.00	
- Other Incidentals	\$ 150.00	
Total		\$ 7,303.00

23 April 2019

AP/2019/001027

A copy each of the following supporting documents is enclosed:

- (a) Singapore Accident Statement of FBB654D;
- (b) Motor surveyor's report by WG Appraisal Services;
- (c) Survey report invoice;
- (d) Towing fee invoice


In compliance with the pre-action protocol under the State Courts' Practice Direction 37, we had on 23 April 2019 notified your insurer AXA Insurance Pte Ltd, of the above-mentioned road traffic accident and to the best of our knowledge, your insurer had arranged for the pre-repair inspection of our client's vehicle

Please note that if you are insured and you wish to claim under your insurance policy, you should immediately pass this letter and all the enclosed documents to your insurer.

Please note that you or your insurer should send to us an acknowledgement of receipt to us within fourteen (14) days of your receipt of this letter, failing which, our client will have no alternative but to commence proceedings against you without further notice to you or your insurer.

Please also note that if you a counterclaim against our client arising out of the above-mentioned accident, you are required to send to us a letter giving full particulars of the counterclaim together with all relevant supporting documents within eight (8) weeks of your receipt of this letter.

Yours faithfully,



Charles Hoon
enc.

c.c. clients

My Car Consultant Pte Ltd

53, Ubi Avenue 1, Paya Ubi Industrial Park
#01-33, Singapore 40934

HP:9888 8885 (Jeremy)

INVOICE

LEE KWONG JIN

Invoice No.	MYCAR/19/112
Our Ref.	FBB654D
Your Ref.	-
Date	01 April 2019

No.	Description	Qty	Unit Price	Total
1	To supply labour and materials to repair below mentioned vehicle to its pre-accident condition. Vehicle: <u>FBB654D</u> Make/Model: <u>Yamaha/T135</u> Accident Date: <u>15 March 2019</u>			
			Amount Due	\$4,300.00



Authorised Signatory

WG APPRAISAL SERVICES

Blk 224B, Compassvale Walk, #07-647, Singapore 542224


Email: Winsongkk@hotmail.com Contact: 9747 0063

Company Register No. 53326249J

Our Ref: WG/TP/2019-112
Invoice No: TP/TWG/2019-112 Date 01 April 2019
Vehicle No: FBB654D
Attn: LEE KWONG JIN
Company: MY CAR CONSULTANT PTE LTD
Address: 53 Ubi Ave 1, #01-33, Paya Ubi Industrial Park, Singapore 408934

Invoice

Surveyor Fee: S\$250
Re-inspection Fee: S\$50
Transport: S\$50
Photographs: S\$56/- (@ \$1 per photo, total 56 photos)
Total: S\$406

Surveyor: 
Signature:
Date: 1 April 2019

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Parameters	
Owner ID Type:	Singapore NRIC
Owner ID:	1646E
Vehicle Details	
Vehicle No.:	FBB654D
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Mar 2019
Vehicle Make:	YAMAHA
Vehicle Model:	T135
Primary Colour:	Black
Manufacturing Year:	2006
Engine No.:	5YP205177
Chassis No.:	5YP205177
Maximum Power Output:	-
Open Market Value:	\$1,840.00
Original Registration Date:	24 Nov 2006
First Registration Date:	24 Nov 2006
Transfer Count:	1
Actual ARF Paid:	\$276.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Oct 2026
COE Category:	D - Motorcycle
COE Period(Years):	10
PQP Paid:	\$6,305.00
COE Rebate Amount:	\$4,815.00
Total Rebate Amount:	\$4,815.00

The information contained herein is correct as at 11 Mar 2019

OK

Bike model

Type

Any

Price From

Any

Price To

Any

Class

Any

MORE SEARCH OPTIONS ▾

Q SEARCH

VIEW ALL (/LISTING/USEDBIKES/LISTING/)

Q SEARCH ▾



REPORT ERROR > (/LISTING/LISTING/ERROR/USEDBIKE/9091/)

+ ADD TO SHORTLIST

Like 0

Share

© SHARE (WHATSAPP://SEND?TEXT=HTTPS://WWW.SGBIKEMART.COM.SG/LISTING/USEDBIKE/YAMAHA-YAMAHA-T135-SPARK/9091/)

<https://www.sgbikemart.com.sg/listing/usedbike/yamaha-yamaha-t135-spark/9091/>

Yamaha T135 Spark

Listing Type	Paid Ad
Brand	Yamaha (/listing/usedbike/brand/yamaha/)
Model	Yamaha T135 Spark (/listing/usedbike/model/yamaha-t135-spark/)
Engine Capacity	135cc
Classification	Class 2B
Registration Date	24/01/2006
COE Expiry Date	23/01/2026 (6 years 10 months left)
Mileage	-
No. of owners	-
Type of Vehicle	Cubs (/listing/usedbikes/listing/?bike_type=3)

Price: SGD\$7800

DETAILS

Tip top condition Clutchless spark 135. All original parts. COE till 2026. Visit us at Aljunied Motor Works. Well maintained condition. Seldom use, Trade in welcome

Accessories

New coversets.

SIMILAR BIKES

[VIEW ALL \(/listing/usedbikes/listing/\)](/listing/usedbikes/listing/)

Yamaha T135 Spark



Yamaha T135 Spark

Vic (LKKAUTO)

From: Vic (LKKAUTO)
Sent: Tuesday, 24 March, 2020 4:50 PM
To: Chee Kiong; 'Xin Yi'
Cc: samson@seahong.com.sg; amanda@seahong.com.sg; Admin-D (LKKAUTO); Admin A; Vic (LKKAUTO)
Subject: RE: V URGENT - SOP file ref: 19.27225 V.S.CK.xy | FBB 654D *** LKK REF: CC4/ASM19004249/Gha3
Attachments: LKK INSPECTION REPORT.pdf; LKK ADJUSTMENT REPORT.pdf; LKK INSPECTION PHOTOS.pdf

Without Prejudice

Dear Sir,

We refer to the below email.

Please find attached our Inspection Report as requested.

Our Surveyor had also recommended that the Economical Repair Limit is at \$3,980.00 (est).

Thank you.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vic@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

From: Chee Kiong [mailto:cheekiong@seahong.com.sg]
Sent: Friday, 20 March, 2020 6:58 PM
To: Mei Kwan (LKKAUTO); 'Xin Yi'; Vivian Lau (LKKAUTO)
Cc: samson@seahong.com.sg; amanda@seahong.com.sg; Admin-D (LKKAUTO); Admin A; CS A Team
Subject: RE: V URGENT - SOP file ref: 19.27225 V.S.CK.xy | FBB 654D *** LKK REF: CC4/ASM19004249/Gwa3

Dear Mei Kwan / Vivian

May we hear from you urgently ? The matter has been delayed. Please ensure that you provide your opinion on the economic repair limit for this case as the vehicle is old.

Thanks !

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM19004249/Gha3q2		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:VALE OH		Date : 27-03-2020		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YP 7965P	Veh. Inspected	FBB 654D	
Policy No.	VCA/P2061686	Coverage (\$)	0.00	
Claim No.	S9M01G8Y	Excess (\$)	0.00	
Assign From		Assign Date	07/03/2019	
2. Vehicle Particulars & Condition				
Make & Model	YAMAHA T135	c.c	135	
Engine No.	HIDDEN	Year of Reg.	2006	
Chassis No.	5YP205177	Colour	BLACK	
Odometer	22311	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	70/90-17	DUNLOP	4 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	90/80-17	DUNLOP	4 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND O/S & N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	05/03/2019	Inspection Date	08/03/2019	
Survey held at	MY CAR CONSULTANT PTE LTD 53 UBI AVENUE 1 #01-33 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBB 654D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT FENDER (CONSISTENT)	GRAZED	120.00	60.00
1	FRONT LH FORK ASSY (CONSISTENT)	SERVICEABLE	350.00	-
1	FRONT RH FORK ASSY (CONSISTENT)	SERVICEABLE	350.00	-
1	STEERING HEADCROWM (CONSISTENT)	SERVICEABLE	150.00	-
1	STEERING STEM UNDERBRACKET (CONSISTENT)	NECESSARY	125.00	-
2	STEERING STEM BEARING (CONSISTENT)	SERVICEABLE	90.00	-
1	FRONT RH SIGNAL LAMP (CONSISTENT)	NOT NECESSARY	150.00	-
1	SET SIDE MIRROR (CONSISTENT)	GRAZED	120.00	35.00
1	SET HANDLE GRIP (CONSISTENT)	SERVICEABLE	35.00	-
1	SET BALANCER (CONSISTENT)	GRAZED	40.00	20.00
1	BRAKE LEVER (CONSISTENT)	BENT	39.00	15.00
1	HEAD FAIRING ASSEMBLY (CONSISTENT)	CRACKED	145.00	105.00
1	HEADLAMP ASSY (CONSISTENT)	SERVICEABLE	350.00	-
1	HEADLAMP BRACKET (CONSISTENT)	SERVICEABLE	175.00	-
1	FRONT RH FAIRING INNER GARNISH (CONSISTENT)	CRACKED	150.00	45.00
1	RIGHT FRONT FOOTREST (CONSISTENT)	TORN	75.00	54.00
1	RIGHT FRONT FOOTREST HOLDER (CONSISTENT)	SERVICEABLE	135.00	-
1	REAR RH SIDE FAIRING (CONSISTENT)	SERVICEABLE	310.00	-
1	RADIATOR (CONSISTENT)	SERVICEABLE	550.00	-
1	RH SIDE FAIRING (CONSISTENT)	CRACKED	350.00	220.00
1	MUFFLER CHROME PROTECTOR (CONSISTENT)	GRAZED	110.00	42.00
1	MUFFLER COMP (CONSISTENT)	GRAZED	550.00	280.00
	LESS 10% DISCOUNT		-446.90	-87.60
			4,022.10	788.40
<u>SPECIAL NETT ITEMS</u>				
1	REAR BOX (SN) (CONSISTENT)	GRAZED	390.00	150.00
1	FRONT NUMBER PLATE (SN) (CONSISTENT)	SERVICEABLE	40.00	-
			430.00	150.00

Report Ref No. CC4/ASM19004249/Gha3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	REPLACE ,REALIGN AND ADJUST ABOVE DAMAGE PARTS AND CHECK WIRING AND LIGHTING SYSTEM.		600.00	200.00
	TO KNOCK ,STRAIGHTEN CHASSIS AND BODY BALANCING .	NOT NECESSARY	380.00	-
	TO REMOVE/REFIT ,REPLACE FRONT FORK TUDES.	NOT NECESSARY	180.00	-
	SPRAY PAINTING .	NOT NECESSARY	380.00	-
	TOWING SERVICE.	NOT NECESSARY	150.00	-
			1,690.00	200.00
	GRAND TOTAL		6,142.10	1,138.40
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			900.00

Report Ref No. CC4/ASM19004249/Gha3q2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Service Request Details

Claim: 59M01GBY

Reference: CCA/ASM19004249/Gha3q2

Loss Date: 5 March 2019

Report Date: 7 Mar 2019 1:02:08 PM

Request Date: 2 May 2019

Due Date:

Vendor Name: LKK AUTO CONSULTANTS PTE LTD (ITI)

Type of Loss: Third Party Vehicle Damage

Services: Pending verification - Direct Settlement

Vehicle Information

Incident Vehicle Registration #: FBB654D

Make: TPVD YAMAHA

Model: T135

Service Address:

...

Primary Contact/Insured

SRM SERVICES
BLK S2 SIMS PLACE, #04-14A, 380052, Singapore
63380083

Claim Handler

TAN Jun Hong
junhong.tan@axa.com.sg

Actions

Next Step: Wait for Approve Invoice

Add Invoice

Additional Instructions

VIRTUAL CASE NON REPORTING

1




MessagesInvoicesHistoryDocumentsAssessmentMetricsNotes

Document Type

Document SubType

+ Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
Accident Statement	Reports & Statement		Murimen	

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 LKXInvoice1 (3).pdf	Invoice	Surveyor/ Assessor expense	LKX AUTO CONSULTANTS PTE LTD (TP)	31 March 2020
 LKXInspection.pdf	Forms / Claim Documents	Others	LKX AUTO CONSULTANTS PTE LTD (TP)	31 March 2020
 LKXAdjustment1a.pdf	Forms / Claim Documents	Others	LKX AUTO CONSULTANTS PTE LTD (TP)	31 March 2020
 LKX PHOTO.pdf	Forms / Claim Documents	Others	LKX AUTO CONSULTANTS PTE LTD (TP)	31 March 2020
 EMAIL FR VIA ON LOA-RE OUR REF 59401G8VVO SIM SERVICES P2061686 -YP7965P .msg	Forms / Claim Documents	POA / Authority Letter	OH Vale	15 April 2019
 P2061686_RN_00002_3.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of Insurance	OH Vale	7 March 2019
 P2061686_CI_00002_1.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of Insurance	OH Vale	7 March 2019
 TP PRI EMAIL FROM WORKSHOP WITH TP GIA REPORT .msg	Letters and Correspondence	Workshop	DHIWAR Namrata	7 March 2019