

Car City Auto Centre Pte Ltd (Co.Reg.No:200719980C)

Blk 9006 #01-198, Tampines Street 93

Singapore 528840

Tel: 6781 0300 Fax: 6782 0300 Email: ccacpl@singnet.com.sg;carcity@singnet.com.sg

INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	DMCVSN3035801800	Date of Loss:	03/03/2019
Vehicle Reg. No.:	GBE8D	Driveable?	
Driver Age/Info:	53 / FEMALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	MS. STINGRAY FOREVER BBQ SEAFOOD PTE LTD		
Driver:	PHUA PUAY KHIM		

Fax: 62564315

Make/Model:	FORD RANGER DOUBLE CAB XLT, 3.2 TDCI 4X4 (A)	Vehicle Reg. Date:	23/06/2017
Vehicle Colour:	WHITE	Chassis No:	MNBUMFF50GW605035
Engine No:	P5AT2238369		
Odometer:	46616 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	6

p/p &

not Authorised
LKK
The 3rd party
Hony.
Excess \$ 450

Description of Accident/Loss	AS PER ATTACHED SKETCH PLAN
------------------------------	-----------------------------

Remarks:	UNDERSTAND THIS MODEL IS A VERY RARE VEHICLE IN SINGAPORE. ALL PARTS NEED TO BE INDENTED BY AIR
----------	---

Present Location:	CAR CITY AUTO CENTRE PTE LTD (HQ)
-------------------	-----------------------------------

COST OF CLAIMS

	Amount
Parts	8,673.00
Miscellaneous Items	295.00
Labour	2,070.00
Paintwork Labour	0.00
Towing	0.00
Calculated Gross Total (\$)	11,038.00
- Excess (\$)	450.00
(\$)	10,588.00
+ GST 7.00% (\$)	741.16
Nett Amount (\$)	11,329.16

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

This claim is handled by: HO TOO BOON

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** (Last Synchronised: 07 Mar 2019)**Parts:** N/A FORD RANGER DOUBLE CAB XLT 3.2 TDCI 4X4 (A) (Model not available in database)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Car City Auto Centre Pte Ltd/GBE8D/07/03/2019 16:43**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BONNET <i>D/Buc</i>	0.00	0.00	*1,150.00 F ✓
2	1		*FRONT BONNET LOCK <i>Top/An</i>	0.00	0.00	*220.00 F ✓
3	1		*FRONT LOWER BUMPER <i>11</i>	0.00	0.00	*250.00 F X
4	1		*FRONT LH FOG LAMP ASSY <i>11</i>	0.00	0.00	*180.00 F X
5	1		*FRONT BUMPER <i>Dis</i>	0.00	0.00	*630.00 F ✓
6	1		*FRONT BUMPER LOWER GRILE <i>Dis</i>	0.00	0.00	*200.00 F ✓
7	1		*FRONT REINFORCEMENT <i>11</i>	0.00	0.00	*420.00 F X
8	1		*FRONT BUMPER BUMPER BRACKET LH <i>11</i>	0.00	0.00	*52.00 F X
9	1		*FRONT RADIATOR GRILLE ASSY <i>11</i>	0.00	0.00	*1,300.00 F ✓
10	1		*FRONT SUPPORT PANEL <i>11</i>	0.00	0.00	*1,060.00 F X
11	1		*FRONT LH SUPPORT PANEL FILLER <i>11</i>	0.00	0.00	*65.00 F X
12	2		*FRONT SUPPORT PANEL DEFLECTOR LH & RH <i>Torn</i>	0.00	0.00	*156.00 F ✓
13	1		*FRONT INTERCOOLER <i>put</i>	0.00	0.00	*1,680.00 F ✓
14	1		*FRONT LH HEADLIGHT <i>11</i>	0.00	0.00	*1,050.00 F ✓
15	1		*FRONT TOP RADIATOR COVER <i>11/11</i>	0.00	0.00	*260.00 F ✓
Total Parts (S\$)						8,673.00

F=Franchise part.

Car City Auto Centre Pte Ltd/GBE8D/07/03/2019 16:43. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	FRONT HEADLIGHT LH LED BULB	245.00
2	1	FRONT NUMBER PLATE AND HOLDER	50.00
Sub Total (S\$)			295.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO REMOVE & REFIT AFFECTED PARTS; PANEL BEATING ON DAMAGED AREAS, CUT, WELD, KNOCK STRAIGHTEN, REALIGN & RESHAPE FRONT BONNET, FRONT BUMPER, FRONT FENDER LH & RH, FRONT SUPPORT PANEL	New	600 1,000.00
2	TO CHECK & REPAIR WIRING SYSTEM	New	20 60.00
3	TO PUTTY CLEANING SANDING POLISHING WAXING & SPRAY PAINT ON ALL NECESSARY PARTS AND AREAS, FRONT BONNET, FRONT BUMPER, FRONT SUPPORT PANEL AND ETC	New	600 800.00
4	TO CHECK LIGHT SYSTEM & FOCUS HEADLAMP	New	20 50.00
5	TO USE DIAGNOSTIC TOOL TO READ AND CLEAR FAULT CODE	New	50 100.00
6	TO REMOVE & REFIX INTERCOOLER	New	60.00
Gross Labour Cost (S\$)			2,070.00

Car City Auto Centre Pte Ltd/GBE8D/07/03/2019 16:43. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >