## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd. From: LKK Auto Consultants Pte Ltd

3 Anson Road #16-00 Springleaf Tower Singapore 079909

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Elaine Cheong Date: 11 Mar 2019

# **Preliminary Advice**

Vehicle No : GBE8D **Accident Date** : 03/03/2019

Make : FORD RANGER DOUBLE CAB XLT Policy No. : DMCVSN3035801800

: 08/03/2019 Assignment Date **Excess** : S\$450.00 Date of Inspection : 08/03/2019 Est. Duration of Repair : 4.00

Inspection At : CAR CITY AUTO CENTRE PTE LTD (HQ)

BLK 9006 #01-198, TAMPINES STREET 93

SINGAPORE 528840

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,038.00
Revised Amount	:S\$	8,231.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	8,231.00

Lump Sum Repair :S\$

Brake System : In Order Steering System : In Order Tyre Condition (Front): 7/7 mm Tyre Conditiion (Rear): 7/7 mm

### **Total Loss Consideration**

New for Old Value :S\$

Pre-Accident Value 110,000.00 :S\$ COE / PARF Rebate :S\$ 30,537.00

Salvage Value :S\$

Margin for Repair :S\$ 79,463.00

#### Remarks

( X )	The vehicle is repairable at our adjuste	ed amount. We have al	Iso confirmed excess a	nd policy coverage. Kindly le
	us have your authorisation.			

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments: Vehicle repair on part by part.