

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883
 Email: SM_AUTOMOTIVE@HOTMAIL.COM
 Tel: (65) 6747 9241 Fax: (65) 6741 7276
 RCB No.: 53231488C

07/03/2019

Blk 1 Kaki Bukit Ave 6
 # 01-43
 Singapore 417883

TPAXA.
 Vic

Accident date: 07/03/2019

Estimated repair cost for vehicle no: SLR5097B HONDA VEZEL 1.5X CVT '17

S/n	Qty	Items	U/price	Amount
1	1	Rear Boot Lid <i>Distorted</i>		\$1,100.90 ✓
2	2	Rear Boot Lid Hinges <i>Free New</i>	\$68.10	\$136.20 +
3	2	Rear Boot Lid Shock Absorbers <i>Best</i>	\$180.90	\$361.80 ✓
4	1	Rear Boot Lid Emblem Logo <i>me</i>		\$45.10 ✓
5	1	Rear Boot Lid Vezel Logo <i>me</i>		\$56.30 ✓
6	1	Rear Boot Lid Camera (Special Nett) <i>Dmgd</i>		\$550.00 <i>380(s)</i>
7	1	Rear Boot Lid Number Plate <i>Best</i>		\$50.00 ✓
8	1	Rear Boot Lid Emblem Top Garnish <i>Delnd</i>		\$335.80 ✓
9	2	Rear Boot Lid Side Reflector <i>LH Included RH Included</i>	\$284.60	\$569.20 ✓
10	1	Rear Boot Lid Inner Lock <i>Dmgd</i>		\$185.60 ✓
11	1	Rear Boot Lid Inner Rubber <i>lt</i>		\$135.25 ✓
12	1	Rear Boot Lid Inner Trim Board <i>Cracked</i>		\$355.75 ✓
13	1	Rear Boot Lid Inner Trim Board Side Handle Cover <i>me</i>		\$55.80 +
14	1	Rear Boot Lid Windscreen Seal <i>Free</i>		\$151.70 ✓
15	2	Rear Boot Lid Windscreen Side Moulding	\$75.00	\$150.00 ✓
16	2	Rear Tail Lamp <i>lt</i>	\$474.60	\$949.20 ✓
17	2	Rear Tail Lamp Panel <i>Repair</i>	\$135.70	\$271.40 +
18	4	Rear Tail Lamp Clips <i>me</i>	\$8.00	\$32.00 ✓
19	2	Rear Tail Lamp Lower Bracket <i>me</i>	\$18.10	\$36.20 +
20	1	Rear Bumper <i>Delnd</i>		\$801.70 ✓
21	2	Rear Bumper Side Cover <i>Repair</i>	\$198.70	\$397.40 x
22	2	Rear Bumper Side Retainer <i>me</i>	\$29.20	\$58.40 ✓
23	2	Rear Bumper Side Reflector <i>Cracked</i>	\$148.40	\$296.80 ✓
24	1	Rear Bumper Reverse Sensor (Special Nett) <i>Dmgd</i>		\$350.00 <i>2nd/5th</i>
25	1	Rear End Panel <i>Delnd</i>		\$595.60 ✓
26	1	Rear End Panel Top Garnish <i>Delnd</i>		\$122.30 ✓
27	1	Rear End Panel Lock Sensor <i>me</i>		\$98.10 +
28	1	Rear End Panel Buzzer <i>Dmgd</i>		\$85.50 ✓

29	2	Rear Fender Inner Trim Board	Cracked	\$325.25	\$650.50	✓
30	16	Rear Fender Inner Trim Board Clip	✓	\$6.50	\$104.00	✓
31	1	Rear Spare Tyre Panel	Repair		\$662.20	✓
32	1	Rear Spare Tyre Panel Top Cover	Cracked		\$306.65	✓
33	1	Rear Spare Tyre Panel Lower Cover	Torn		\$190.90	✓
34	1	Rear Spare Tyre Panel Foam Tool Box	Torn		\$226.70	✓
35	1	Rear Exhaust	2		\$868.00	✓
36	1	Rear Center Exhaust	✓		\$986.00	✓
37	4	Rear Exhaust Mounting	✓	\$25.60	\$102.40	✓
38	1	Rear LH Fender Protector	Cracked	160.30		
				Subtotal :-	\$12,431.35	

8077-95 SN: 580
6462-36

Labour charges

To remove & refit cushion	\$280.00	80
To remove & refit reverse sensor	\$100.00	50
To remove & refit rear & center exhaust	\$380.00	✓
To remove & refit rear camera	\$180.00	50
To remove & refit rear windscreen	\$120.00	✓
Gum	\$50.00	✓
To check wiring	\$100.00	30
Tuff kote	\$150.00	80
Panel beating	\$1,600.00	1000
Spray painting	\$1,600.00	1000

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Subtotal :- \$4,560.00

Total:- \$16,991.35

Adrian G. Tol. 950236
1/3 08/03/19 H/S: 7.6K.
06 days:
7.6K