

**MOVA Automotive Pte Ltd**  
**Blk 1008, Bukit Merah Lane**  
**3, #01-04/06/08. Singapore**  
**159722**

**Claim Reference:**

**Assessment number: ck134276**

**Version: 1810**

**Date calculated: 03/08/2019 10:06 AM**

**Full Report**

**Registration: SMJ2599U**

**Printed: 08/03/2019 10:07 AM**

---

## Summary Information

### Claim

Location: Singapore (SG)  
Printed by: GOH CHAI HOCK  
Claim Reference:  
Estimated Repair Time:  
Actual Repair Days:

Work Provider: AXA Insurance Pte Ltd  
Currency: SGD  
Date of Incident: 2019-03-05  
Hire Car Start:  
Hire Car End:

---

## Vehicle Details

### Vehicle

Manufacturer: HYUNDAI  
Model: AVANTE (HD)  
Sub Model: BASIS  
Model Sheet Number: 30 22 50  
Registration: SMJ2599U  
VIN number:  
Odometer:

---


## Vehicle Condition

### Vehicle Status

Pre-Accident Damage:  
Date of Inspection:

### Damage Areas

**All** ☐  
**Underbody** ☐



**MOVA Automotive Pte Ltd**  
**Blk 1008, Bukit Merah Lane**  
**3, #01-04/06/08. Singapore**  
**159722**

Claim Reference:

Assessment number: ck134276

Version: 1810

Date calculated: 03/08/2019 10:06 AM

Full Report

Registration: SMJ2599U

Printed: 08/03/2019 10:07 AM

## Labour

		Time Base 10 WU/h	Price = 45.00 SGD/h	
Code	Description		WU	Price SGD
86512R00	RENEW FRONT BUMPER INCLUDES: BUMPER AND REQUIRED ATTACHED PARTS R + R NOT INCLUDED: REINFORCEMENT BUMPER REMOVE AND REFIT		8.0	36.00
0561	LEFT HEADLAMP ASSY CHECK			
<b>Labour Cost</b>		<b>Hrs</b>	<b>WU</b>	
<b>Panel / Mechanical Labour</b>		<b>0.80</b>	<b>8.0</b>	<b>36.00</b>
<b>Total of Labour</b>				<b>36.00</b>

## Paint

Paint Work		SYSTEM AZT	Time Basis 10WU/h	
Code	Description		WU	Price SGD
	FRONT BUMPER NEW PART PAINT K1R		9.0	

### Paint Material Per Part

Code	Description	Price SGD
0283	FRONT BUMPER NEW PART PAINT K1R	33.50

<b>Labour Cost - Paint</b>		Hrs	WU	Price SGD
Factor	45.00 SGD/h			
Time Paint			9.0	
Preparation Comp. Work Plastic		0.70	7.0	31.50
<b>Total</b>	<b>10 WU/h</b>	<b>1.60</b>	<b>16.0</b>	<b>72.00</b>

<b>Material Cost - Paint</b>		Price SGD
New Part Painting - Plastic K1R		33.50
Material-constant Plastic		16.20
<b>Total</b>		<b>49.70</b>

## Spare Parts

**MOVA Automotive Pte Ltd**  
**Blk 1008, Bukit Merah Lane**  
**3, #01-04/06/08. Singapore**  
**159722**

**Claim Reference:**

**Assessment number: ck134276**

**Version: 1810**

**Date calculated: 03/08/2019 10:06 AM**

**Full Report**

**Registration: SMJ2599U**

**Printed: 08/03/2019 10:07 AM**

Code	Description	Part Number	Supplier	prices as at 2015-06-01	
					Price SGD
0283	FRONT BUMPER	865112H000			<b>470.00</b>
0315	FRT BUMPER ABSORBER	865202H010			<b>110.00</b>
0410	GRILLE	863502H000			<b>460.00</b>
f: OEM Parts					<b>0.00</b>
n: Non-OEM Parts					<b>1,040.00</b>
u: Used parts					<b>156.00</b>
<b>Savings</b>					
<b>Subtotal</b>					<b>1,040.00</b>
<b>Addition(+15.00%)</b>					<b>156.00</b>
<b>Total</b>					<b>1,196.00</b>

**Final Calculation**

	SGD	SGD
<b>Parts</b>	1,040.00	
Addition(+15.00%)	156.00	
<b>Total Parts</b>		<b>1,196.00</b>
<b>Labour Time Base 10 WU/h</b>		
Total 8.0 WU X 45.00 SGD/h	36.00	
<b>Total of Labour</b>		<b>36.00</b>
<b>Paint Work Time Base 10 WU/h</b>		
Labour Cost 16.0 WU X 45.00 SGD/h	72.00	
Material Cost	49.70	
<b>Total Paint Including Material</b>		<b>121.70</b>
<b>Repair Cost Excludes GST</b>		<b>1,353.70</b>
GST (+7.00%)		<b>94.76</b>
<b>Repair Cost Included GST</b>		<b>1,448.46</b>

**Comments**

\* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS