

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD 7140S

DATE 6/3/2019 16:51

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper <i>Rebrand</i>			\$ 553.00
	Rear Bumper Clip 10 pcs <i>mc</i>			\$ 22.00
	SUB TOTAL			\$ 575.00
	LESS 20%			\$ 115.00
	DISCOUNTED TOTAL			\$ 460.00
	Rear Bumper Rubber Mat <i>mc</i>			\$ 50.00 Nett
				\$ 50.00
	Labour Charge			200
	Panel Beating			\$ 400.00
	Spray Painting Charge			\$ 300.00 200
	Wiring Charge			\$ 30.00 X 2
	Remove/Refix Reverse Sensor			\$ 80.00 20
	TOTAL LABOUR			\$ 810.00
	ESTIMATE TOTAL			\$ 1,320.00
<p><i>Ka hua 11/11/19</i></p> <p><i>7/3/19 1100h</i></p> <p><i>200</i></p> <p><i>P/P</i></p> <p><i>Rebrand Panel p 66</i></p>				
<div> <p>LKK Auto Consultants hereby notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after survey painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer</p> <p>Signature:</p> <p>Date:</p> </div>				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

COMFORTDELGRO ENGINEERING

Our Job Ref No 305274879

Date : 08/03/19

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : KALVIN

: SHD7140S

Date of Accident : 06/03/19

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: CHINA --- GBG3784R
###

2. The finalized amount shall be:

(a) Spare Parts after List discount \$510.00

(b) Labour Charges ### \$430.00

Total for Part-By-Part Repair Cost \$940.00

(c.) Lumpsum Repair (if applicable) NI

Total for Lumpsum repair cost after Less: 20%

Final Lumpsum Repair cost

3. Estimated normal period for repairs: 2 working days

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : [Signature]

Name : JUMANI

Tel : 6214 8315

Fax : 65468156

Signature : [Signature]

Name : Karm

Date : 11/3/19

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305274879
REGN NO : SHD7140S
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 10.11.2016
DATE/TIME IN : 06.03.2019 14:15
ACCIDENT DATE : 06.03.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0103-0579-G	I40VC COVER ASSY-RR BUMPE	1	553.00	20.00	442.40
0002	04-01-0103-1150-A	I40VC PROTECTOR MAT	1	50.00	2.00-	50.00
0003	04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10 L	22.00	20.00	17.60

SUB-TOTAL : 510.00

JOB NATURE

0000	PB	PANEL BEATING	200.00
0001	SP	SPRAYPAINT CHARGE	200.00
0002	L	REMOVE/REFIX REVERSE SENSOR	30.00

SUB-TOTAL : 430.00

TOTAL : 940.00

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :