

China - JH
PLP

DATE 6/3/2019 16:51

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper			\$ 553.00
	Rear Bumper Clip 10 pcs			\$ 22.00
	SUB TOTAL			\$ 575.00
	LESS 20%			\$ 115.00
	DISCOUNTED TOTAL			\$ 460.00
	Rear Bumper Rubber Mat			\$ 50.00
				\$ 50.00
	Labour Charge			
	Panel Beating			\$ 400.00 200
	Spray Painting Charge			\$ 300.00 200
	Wiring Charge			\$ 30.00 X 1
	Remove/Refix Reverse Sensor			\$ 80.00 30
	TOTAL LABOUR			\$ 810.00
	ESTIMATE TOTAL			\$ 1,320.00
<div style="float: left; width: 45%;"> <p>Ka Lun Ukky 7/3/19 1106 200, P/P Refom Paul p U</p> </div> <div style="float: right; width: 50%; border: 1px solid black; padding: 5px;"> <p>LKK Auto Consultants hereby notify the Repairer of the following:</p> <ul style="list-style-type: none"> To resurvey before/after spray painting To display damaged part(s) during resurvey Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: Date:</p> </div> <div style="clear: both;"></div>				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				