

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE*

China Taiping-4S

TS

VEHICLE NO : SH 8372G

DATE 7/3/2019

MAKE :

MODEL : MERCEDES BENZ

E5

LKK - Kalvin.

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper			\$ 1,510.00
	Rear Bumper Retainer Mounting (LH)			\$ 115.00
	Rear Tyre Rim (LH)			\$ 1,250.00
	Rear Westlake Tyre LH			480.00
	SUB TOTAL			\$ 2,875.00
	LESS 20%			\$ 575.00
	DISCOUNTED TOTAL			\$ 2,300.00
	Labour Charge			
	Panel Beating-Repair Rear LH Fender			\$ 400.00
	Spray Painting Charge			\$ 600.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 50.00
	Remove/Refix Reverse Sensor			\$ 120.00
	Rear Wheel Alignment			\$ 120.00
	TOTAL LABOUR			\$ 1,440.00
	ESTIMATE TOTAL			\$ 3,740.00

Kalvin (LKK)

7/3/19

1245 hrs

2 Days

4s

After Repair photo

I hereby acknowledge and agree to the following:

- The repair work is subject to confirmation of the damaged part(s) during resurvey
- The prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.