



TRANS EUROKARS PTE LTD
ESTIMATE COST OF REPAIRS

EUROKARS GROUP

not allowed
near
Zhangke 24/11/18
3 days
11/3/18

INDIA INTERNATIONAL INSURANCE PTE LTD
64 CECIL STREET
#04-00 & #05-00 IOB BUILDING
SINGAPORE 049711
ATTN : MOTOR CLAIMS
FAX :

NAME : Mr Tan Xiang Wei, Ricky
ADDRESS : 279C Sengkang East Avenue
#09-535
Singapore 543279
TEL : 96395336

WIP : 44930
EXCESS :
DATE : 4-Mar-19

VEH NO : SMG6750M
CHASSIS NO : JM6BN24A8K0259506
MODEL : MAZDA3

DATE IN :
MILEAGE : 3747
DATE REG.: 28-Dec-18

CONTACT PERSON : Jess 63957874
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO. :

11/3/18

NATURE OF WORKS

Parts Description			REVISED	PRICES
NO	QTY			
1	1	REAR BUMPER MB63C-50-221ABB	de/cu?	\$ 950.00
2	1	BRACKET CENTER MKD53-50-251	11	\$ 5.10
3	1	PROTECTOR CENTER, REAR BUMPER MBHN9-50-369	11	\$ 56.00
4	1	TOWING COVER LHS MB63B-50-EL1 8B	11	\$ 15.00
5	1	REAR REINFORCEMENT MB45C-50-260	11	\$ 537.30
6	2	RETAINER CENTER, SENSOR MKD47-67-UC5A2Y	11	\$ 29.40
7	2	SENSOR, ULTRASONIC MGMK6-67-UC1 2Y	11	\$ 344.40
8	2	TAPE PROTECTOR, SENSOR MGS1D-50-EM1A	11	\$ 16.20
9	10	RIVET, REAR BUMPER MBBM4-50-355	11	\$ 42.00
10	2	RIVET, REAR BUMPER MEA01-50-037	11	\$ 15.20
11	2	CLIP, REAR BUMPER MBGV4-56-145	11	\$ 5.40
12	4	GROMMET, REAR BUMPER MBHN1-50-021A	11	\$ 10.00
13	2	GROMMET, REAR BUMPER M9991-00-501	11	\$ 5.60
14	1	GASKET LHS, TAILLAMP MBHP1-51-163	11	\$ 20.90
15	1	GASKET RHS, TAILLAMP MBHP1-51-153	11	\$ 20.90
TOTAL PARTS				\$ 2,073.40
LESS 10%				\$ 207.34
TOTAL PARTS COST				\$ 1,866.06

Labour Description

1	MZ-BR-REAR02	TO REPLACE REAR BUMPER AND REAR REINFORCEMENT. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	660	\$ 990.00
2	MZ-SP-SREAR2	TO RESPRAY REAR BUMPER AND REAR REINFORCEMENT.	630	\$ 945.00
3	MZ-BR-REVSEN	TO TRANSFER REVERSE SENSORS.	200	NETT \$ 315.00
4	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	11	\$ 250.00

5	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	120	\$	250.00
6	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	150	\$	350.00
7		TO SUPPLY BRILA PREMIUM COATING.	100	NETT	\$ 200.00
8	MZ-BR-SUNDRI	SUNDRIES.	per 10	NETT	\$ 100.00
			TOTAL LABOUR	\$ -	\$ 3,400.00
			TOTAL PARTS	\$ -	\$ 1,866.06
			TOTAL	\$ -	\$ 5,266.06
			LESS EXCESS	\$ -	\$ -
			TOTAL AFTER EXCESS	\$ -	
			GST 7%	\$ -	\$ -
			GRAND TOTAL	\$ -	\$ -

TRANS EUROKARS PTE LTD

REMARKS:
THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

Authorised Signature

LICK Auto Consultants hence notify the Repairs of the following:

- To resurvey before/after spray painting.
- To display damaged parts during resurvey.
- Parts prices are subject to confirmation.
- Third party survey is on a "Without Prejudice" basis.
- No illegal modification(s) is allowed.
- Supplemental work(s) must be resurveyed and is subject to final approval from Insurance Company.

Acknowledged by Repairer
Signature:
Date:



TRANS EUROKARS PTE LTD



FINALISED COST OF REPAIRS

ATTN : MOTOR CLAIMS		NAME : Mr Tan Xiang Wei, Ricky		WIP : 44930	
FAX :		ADDRESS : 279C Sengkang East Avenue		EXCESS :	
		#09-535		DATE: 4-Mar-19	
		Singapore 543279			
		TEL : 96395336			
VEH NO :	SMG6750M	DATE IN :		CONTACT PERSON :	Jess 63957874
CHASSIS NO :	JM6BN24A8K0259506	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA3	DATE REG.:	28-Dec-18	POLICY NO. :	
NATURE OF WORKS					
Parts Description					
NO	QTY			REVISED	PRICES
1	REAR BUMPER	1	MB63C-50-221ABB	\$ 950.00	\$ 950.00
2	BRACKET CENTER	1	MKD53-50-251		\$ 5.10
3	PROTECTOR CENTER, REAR BUMPER	1	MBHN9-50-369		\$ 56.00
4	TOWING COVER LHS	1	MB63B-50-EL1 BB		\$ 15.00
5	REAR REINFORCEMENT	1	MB45C-50-260		\$ 537.30
6	RETAINER CENTER, SENSOR	2	MKD47-67-UC5A2Y		\$ 29.40
7	SENSOR, ULTRASONIC	2	MGMK6-67-UC1 2Y		\$ 344.40
8	TAPE PROTECTOR, SENSOR	2	MG51D-50-EM1A	\$ 16.20	\$ 16.20
9	RIVET, REAR BUMPER	10	MBBM4-50-355	\$ 42.00	\$ 42.00
10	RIVET, REAR BUMPER	2	MEA01-50-037	\$ 15.20	\$ 15.20
11	CLIP, REAR BUMPER	2	MBGV4-56-145	\$ 5.40	\$ 5.40
12	GROMMET, REAR BUMPER	4	MBHN1-50-0Z1A	\$ 10.00	\$ 10.00
13	GROMMET, REAR BUMPER	2	M9991-00-501	\$ 5.60	\$ 5.60
14	GASKET LHS, TAILLAMP	1	MBHP1-51-163	\$ 20.90	\$ 20.90
15	GASKET RHS, TAILLAMP	1	MBHP1-51-153	\$ 20.90	\$ 20.90
TOTAL PARTS				\$ 1,086.20	\$ 2,073.40
LESS 10%				\$ 108.62	\$ 207.34
TOTAL PARTS COST				\$ 977.58	\$ 1,866.06
Labour Description					
1	MZ-BR-REAR02	TO REPLACE REAR BUMPER. REPAIR AREAS AFFECTED BY THE ACCIDENT.			\$ 660.00 \$ 990.00
2	MZ-SP-SREAR2	TO RESPRAY REAR BUMPER			\$ 630.00 \$ 945.00
3	MZ-BR-REVSEN	TO TRANSFER REVERSE SENSORS.			\$ 200.00 \$ 315.00
4	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.			\$ 250.00

5	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$ 120.00	\$ 250.00
6	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 150.00	\$ 350.00
7		TO SUPPLY BRILA PREMIUM COATING.	\$ 100.00	\$ 200.00
8	MZ-BR-SUNDRI	SUNDRIES.	\$ 10.00	\$ 100.00
TOTAL LABOUR			\$ 1,870.00	\$ 3,400.00
TOTAL PARTS			\$ 977.58	\$ 1,866.06
TOTAL			\$ 2,847.58	\$ 5,266.06
LESS EXCESS			\$ -	\$ -
TOTAL AFTER EXCESS			\$ 2,847.58	
GST 7%			\$ 199.33	\$ -
GRAND TOTAL			\$ 3,046.91	\$ -

REMARKS:

3 REPAIR DAYS (exclude preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)