

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG19004285/ADA3Q2

**Date:** 24/09/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100415009

**Claimant**  
**Vehicle No :** SFA868L **Insured Vehicle No :** SKT2784Y

Date of Loss: 07/03/2019 Nature of Claim: TP Claim No: 1108717670SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                      |             |                   |
|-----------------------------|--------------------------------------|-------------|-------------------|
| Reg No:                     | <b>SFA868L</b>                       |             |                   |
| Make & Model:               | MERCEDES-BENZ S400L, 3.0 R19 LED (A) | Engine No:  | 27682430371711    |
| Reg. Date:                  | 24/08/2016 (Man. Year: 2016)         | Chassis No: | WDD2221652A258734 |
| Colour:                     | White                                | Odometer:   | 21464 km          |
| Engine Capacity:            | 2996 cc                              |             |                   |
| Market Value/New Car Price: | N/A                                  |             |                   |
| Sum Insured (\$):           | <b>Market Value/New Car Price</b>    |             |                   |

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

### CONDITION OF TYRES

|                   |               |                  |               |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size:  | 245/45R19     | Rear Tyre Size:  | 245/45R19     |
| Front Left Side:  | Goodyear 6 mm | Rear Left Side:  | Goodyear 6 mm |
| Front Right Side: | Goodyear 6 mm | Rear Right Side: | Goodyear 6 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                         | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|-----------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                         | 33,198.30         | 5,589.00          | 27,609.30         | 83.16         |
| Miscellaneous Items                           | 0.00              | 0.00              | 0.00              |               |
| Labour                                        | 5,930.00          | 1,660.00          | 4,270.00          | 72.01         |
| Paintwork Labour                              | 0.00              | 0.00              | 0.00              |               |
| Towing                                        | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (\$)</b>            | <b>39,128.30</b>  | <b>7,249.00</b>   | <b>31,879.30</b>  | <b>81.47</b>  |
| <b>Approved Total (Overridden) (\$)</b>       |                   | <b>5,800.00</b>   |                   |               |
| <b>(\$)</b>                                   | 39,128.30         | 5,800.00          | 33,328.30         | 85.18         |
| <b>+ GST 7.00/7.00% (\$)</b>                  | 2,738.98          | 406.00            | 2,332.98          | 85.18         |
| <b>Nett Amount (\$)</b>                       | <b>41,867.28</b>  | <b>6,206.00</b>   | <b>35,661.28</b>  | <b>85.18</b>  |
| <b>+ Car Rental (7.0 x \$180.00/day) (\$)</b> |                   | 1,260.00          |                   |               |
| <b>+ Doc/Search Fee (\$)</b>                  |                   | 36.45             |                   |               |
| <b>Nett Liability (\$)</b>                    |                   | <b>7,502.45</b>   |                   |               |
| <b>Global Sum Settlement (\$)</b>             |                   | <b>7,500.00</b>   |                   |               |

### INSPECTION

Date of Assignment: 08/03/2019

Date Inspected: 08/03/2019 Inspected At:

96 Motorsports Pte Ltd (HQ)  
62 Kaki Bukit Avenue 6, The Ark@KB  
Singapore 417893

Estimated Period of Repair: 5.0 days

---

**Adjuster:** ADRIAN LING**Manager:** CHAN JIA LE

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. Particulars                     | Condition     | Repairer's  | Amount       |
|-----|-----|------------------------------------------|---------------|-------------|--------------|
| 1   | 1   | *FRONT FENDER RH                         | Repair        | 1,140.00 FL | *- FL        |
| 2   | 1   | *FRONT FENDER BOTTOM CHROME MOULDING RH  | Not Necessary | 84.00 FL    | *- FL        |
| 3   | 1   | *FRONT DOOR RH                           | Dented        | 2,588.00 FL | *2,588.00 FL |
| 4   | 1   | *FRONT DOOR SIDE MIRROR COVER RH         | Repair        | 195.00 FL   | *- FL        |
| 5   | 1   | *FRONT DOOR OUTER CHROME MOULDING RH     | Not Necessary | 322.00 FL   | *- FL        |
| 6   | 1   | *FRONT DOOR TOP FRAME CHROME MOULDING RH | Not Necessary | 225.00 FL   | *- FL        |
| 7   | 1   | *FRONT DOOR OUTER HANDLE RH              | Not Necessary | 421.00 FL   | *- FL        |
| 8   | 1   | *FRONT DOOR OUTER HANDLE JOINT RH        | Not Necessary | 100.00 FL   | *- FL        |
| 9   | 1   | *FRONT DOOR OUTER HANDLE AUTO SWICTH RH  | Not Necessary | 274.00 FL   | *- FL        |
| 10  | 2   | *FRONT DOOR HINGE RH                     | Not Necessary | 290.00 FL   | *- FL        |
| 11  | 1   | *FRONT DOOR CHECKER RH                   | Not Necessary | 215.00 FL   | *- FL        |
| 12  | 1   | *FRONT DOOR INNER LOCK RH                | Not Necessary | 860.00 FL   | *- FL        |
| 13  | 1   | *FRONT DOOR LOCK CATCH RH                | Not Necessary | 38.00 FL    | *- FL        |
| 14  | 1   | *FRONT DOOR INNER WEATHERSTRIP RH        | Necessary     | 328.00 FL   | *328.00 FL   |
| 15  | 1   | *FRONT DOOR TOP WEATHERSTRIP RH          | Not Necessary | 310.00 FL   | *- FL        |
| 16  | 1   | *FRONT DOOR BOTTOM WEATHERSTRIP RH       | Not Necessary | 310.00 FL   | *- FL        |
| 17  | 1   | *FRONT DOOR INNER TRIM RH                | Not Necessary | 3,665.00 FL | *- FL        |
| 18  | 10  | *FRONT DOOR INNER TRIM CLIP              | Not Necessary | 40.00 FL    | *- FL        |
| 19  | 1   | *FRONT DOOR CHANNEL RH                   | Not Necessary | 120.00 FL   | *- FL        |
| 20  | 1   | *FRONT DOOR CHANNEL SEAL RH              | Not Necessary | 274.00 FL   | *- FL        |
| 21  | 1   | *FRONT DOOR REGULATOR MOTOR RH           | Not Necessary | 495.00 FL   | *- FL        |
| 22  | 1   | *FRONT DOOR REGULATOR GEAR RH            | Not Necessary | 840.00 FL   | *- FL        |
| 23  | 1   | *FRONT DOOR BOTTOM CHROME MOULDING RH    | Cut           | 150.00 FL   | *150.00 FL   |
| 24  | 1   | *REAR DOOR RH                            | Dented        | 2,968.00 FL | *2,968.00 FL |
| 25  | 1   | *REAR DOOR OUTER CHROME MOULDING RH      | Not Necessary | 435.00 FL   | *- FL        |
| 26  | 1   | *REAR DOOR TOP FRAME CHROME MOULDING RH  | Not Necessary | 225.00 FL   | *- FL        |
| 27  | 1   | *REAR DOOR INNER LOCK RH                 | Not Necessary | 860.00 FL   | *- FL        |
| 28  | 1   | *REAR DOOR LOCK CATCH RH                 | Not Necessary | 38.00 FL    | *- FL        |
| 29  | 1   | *REAR DOOR INNER WEATHERSTRIP RH         | Not Necessary | 328.00 FL   | *- FL        |
| 30  | 1   | *REAR DOOR TOP WEATHERSTRIP RH           | Not Necessary | 310.00 FL   | *- FL        |
| 31  | 1   | *REAR DOOR BOTTOM WEATHERSTRIP RH        | Not Necessary | 310.00 FL   | *- FL        |
| 32  | 2   | *REAR DOOR HINGE RH                      | Not Necessary | 300.00 FL   | *- FL        |
| 33  | 1   | *REAR DOOR CHECKER RH                    | Not Necessary | 215.00 FL   | *- FL        |
| 34  | 1   | *REAR DOOR REGULATOR MOTOR RH            | Not Necessary | 555.00 FL   | *- FL        |
| 35  | 1   | *REAR DOOR REGULATOR GEAR RH             | Not Necessary | 835.00 FL   | *- FL        |
| 36  | 1   | *REAR DOOR CHANNEL RH                    | Not Necessary | 120.00 FL   | *- FL        |
| 37  | 1   | *REAR DOOR CHANNEL SEAL RH               | Not Necessary | 274.00 FL   | *- FL        |
| 38  | 1   | *REAR DOOR INNER TRIM RH                 | Not Necessary | 3,590.00 FL | *- FL        |
| 39  | 10  | *REAR DOOR INNER TRIM CLIP               | Not Necessary | 40.00 FL    | *- FL        |
| 40  | 1   | *REAR DOOR BOTTOM CHROME MOULDING        | Cut           | 176.00 FL   | *176.00 FL   |
| 41  | 1   | *SIDE SKIRT RH                           | Repair        | 920.00 FL   | *- FL        |
| 42  | 10  | *SIDE SKIRT CLIP                         | Not Necessary | 30.00 FL    | *- FL        |
| 43  | 1   | *FRONT ABSORBER RH                       | Not Necessary | 4,615.00 FL | *- FL        |
| 44  | 1   | *FRONT UPPER ARM RH                      | Not Necessary | 146.00 FL   | *- FL        |
| 45  | 1   | *FRONT LOWER ARM RH                      | Not Necessary | 1,098.00 FL | *- FL        |
| 46  | 1   | *FRONT KNUCKLE ARM RH                    | Not Necessary | 1,670.00 FL | *- FL        |
| 47  | 1   | *FRONT WHEEL BEARING RH                  | Not Necessary | 1,045.00 FL | *- FL        |
| 48  | 1   | *FRONT SPORT RIM RH                      | Not Necessary | 1,800.00 FS | *- FS        |
| 49  | 1   | *FRONT SPORT TYRE RH                     | Not Necessary | 450.00 FS   | *- FS        |

F=Franchise part. S=SpcNett. L=ListItemDisc.

**Sub Total (\$\$) 36,637.00 6,210.00**  
**- List Item Discount on L Items 10.00/10.00% (\$\$) 3,438.70 621.00**

Report was unsubmitted during this print-out.

| No.                      | Qty | Part No. | Particulars | Condition | Repairer's       | Amount          |
|--------------------------|-----|----------|-------------|-----------|------------------|-----------------|
| <b>Total Parts (S\$)</b> |     |          |             |           | <b>33,198.30</b> | <b>5,589.00</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                             | Particulars                                             | Lab.Type | Repairer's      | Amount          |
|--------------------------------|---------------------------------------------------------|----------|-----------------|-----------------|
| <b><u>Labour Items</u></b>     |                                                         |          |                 |                 |
| 1                              | TO KNOCK ,STRAIGHTEN AND REALIGN ACCIDENT AFFECTED AREA | New      | 1,600.00        | 600.00          |
| 2                              | TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA (PEARL)     | New      | 1,800.00        | 700.00          |
| 3                              | TO RUST PROOF ACCIDENT AFFECTED AREA                    | New      | 120.00          | 50.00           |
| 4                              | TO R&R CARPET AND SEAT                                  | New      | 250.00          | 0.00            |
| 5                              | TO R&R FRONT AND REAR DOOR PARTS                        | New      | 260.00          | 160.00          |
| 6                              | TO R & R FRONT UNDER CARRIAGE                           | New      | 550.00          | 0.00            |
| 7                              | TO CHECK AND REDIANOS PROGRAM                           | New      | 1,200.00        | 150.00          |
| 8                              | TO CHECK FOUR WHEEL ALIGNMENT                           | New      | 150.00          | 0.00            |
| <b>Gross Labour Cost (S\$)</b> |                                                         |          | <b>5,930.00</b> | <b>1,660.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >