

15/5/2010

INS. CASE OWNER:

CC6 / CTI1900

4286

Aphana

LKK:
IDAC:

Surveyor:

Adrian

DOI:

ASSIGNMENT

9/7/14

Date / Time:

8/7/14

Registered in Merimen:

Pre-assign / CCU / FIE



Insured Vehicle No.:

SJT 2261B

Name of Insured:

LO LU LUEN ANTHONY

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

6/7/14

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

KIS WONG VAI UNG

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

DMPGN709-11802

Honda

Kowloon Airport

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

SKK 4433B

INSRS:
WSP:
Tel:
Liability:
RMKS:111
chengINSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time

SKK 4433B - X

SJT 2261B - X

STAGE

DATE / PIC

16/4

can oi, mobile off, send LOI via email.

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

Email 16.0.14

After call ltr to OI:

11-11-19

File pass to typist to prepare report.

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: WSP

Repair Cost:

SS 2,700

(3 days) Reduction:

76 %

Email ☒ Call ☐

FINAL SETTLEMENT

Date/Time: 17-03-20

Confirm with MS LEE

Email ☒ Call ☐

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

12

If NO or B 28, Ass. Lia:

Repair Cost:

SS 2,889.00

Reay ended TP

Loss of Rental (LOR):

SS -

(days)

Loss of Use (LOU):

SS 400.00

(\$ 80 x 5 days)

Loss of Income (LOI):

SS -

(\$ x days)

LOR only ☐LOU only ☒LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

SS 2.00

Medical:

SS -

Disbursement:

SS -

(e.g. Tow/Independent)

Legal Cost

SS -

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

+ 400

Total:

SS 3,291.00

Global Sum SS:

FINAL PAYMENT

Date/Time: 17-03-20

Confirm with MS LEE

Email ☒ Call ☐

Payee 1:

SS 3,291.00

Name 1:

LEE SHING ANIO PTE LTD

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

ASS. REC. BY:

REF:

ASSIGNMENT

Adrian

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKX4433B Yr Regn: 2015 / June

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW 520i c.c 1997

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading 109852 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBASA 320800790266

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size: F: 245/45R18

R: 245/45R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Falken

Front

R/Bal. 96 mm R/Bal. 96 mm

L/Bal. 96 mm L/Bal. 96 mm

D.O.A. _____ D.O.I. 01/03/19

Survey held at Lee Sheng

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP Chiu
	46,2700 (RED: 8,759.67 76%)
	MV:
	PV:
	Nett:

Date/Time, File Pass to?	Date/Time, File Return to?	Part Prices Check:		Survey Fee:	Date:
1)	2)	IN	OUT	Basic & Add.	
3)	4)			S + RS, SI	
5)	6)			Photos	
Preli. Report:				Others	
Final Report:				TOTAL	

LEE SHENG AUTO PTE LTD

Page 1 / 2

1, Kaki Bukit Ave 6, Autobay@KakiBukit
#01-60/58, Singapore 417883
Tel No. : 67477333 Fax No. : 67457138
E-Mail : leesheng@singnet.com.sg
Tax Reg. No. : 201000701R Buss. Reg. No. : 201000701R

Messrs. LIU SI JIA
BLK 672D EDGEFIELD PLANS #09-585
S 824672

Attention : Motor Claim Department
Contact : 91993900

TP China
Asher.

Estimate : ES000865

Date : 07/03/2019
Vehicle Num. : SKX 4433B
Make/Model : BMW 525I-2014
Chassis/Eng# : WBA5A32080D790266/B5090821N20B;
Accident Date : 06/03/2019
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS:				
1.	1	REAR BUMPER <i>deformed</i>		1563
2.	1	REAR BUMPER REINFORCEMENT <i>gent</i>		2022.50
3.	1	REAR BUMPER MOULDING <i>gent</i>		180.50
4.	1	REAR BUMPER SENSOR <i>gent</i>		100.45
5.	1	REAR BUMPER LAMP LH <i>gent</i>		250.00
6.	1	REAR BUMPER LAMP RH <i>gent</i>		850.00
7.	1	REAR EXHAUST ASSY		850.00
8.	1	REAR BUMPER cover Reinforcement Cover <i>needed</i>		1,120.00
9.	4	REAR BUMPER SENSOR WIRE <i>gent</i>		150.00
10.	1	REAR BUMPER RETAINER LH <i>gent</i>	80.00	320.00
11.	1	REAR BUMPER RETAINER RH <i>gent</i>		95.00
12.	1	REAR LAMP CHROME COVER LH <i>gent</i>		95.00
13.	1	REAR LAMP CHROME COVER RH <i>gent</i>		75.00
14.	1	REAR TOWING COVER <i>gent</i>		75.00
15.	1	REAR END PANEL <i>gent</i>		85.65
16.	1	REAR END PANEL TOP GARNISH <i>gent</i>		950.65
17.	5	REAR END PANEL TOP GARNISH CLIPS <i>gent</i>		145.50
18.	1	STIFFENER LWR BUMPER <i>gent</i>	6.50	32.50
19.	1	REAR TRUNKLID <i>gent</i>		84.55
20.	5	TRUNKLID CLIPS <i>gent</i>	6.50	950.85
21.	1	TRUNKLID WEATHERSTRIP <i>gent</i>		32.50
22.	1	TRUNKLID LOCK <i>gent</i>		205.80
23.	1 PC	520i EMBLEM <i>gent</i>		188.50
24.	1 PC	BMW LOGO <i>gent</i>		56.50
List Total S\$:				84.50
10.00% Discount S\$:				9,010.75
				901.08
				8,109.67

CONTINUE / ...

LEE SHENG AUTO PTE LTD

Page 2 / 2

1, Kaki Bukit Ave 6, Autobay@KakiBukit
#01-60/58, Singapore 417883
Tel No. : 67477333 Fax No. : 67457138
E-Mail : leesheng@singnet.com.sg
Tax Reg. No. : 201000701R Buss. Reg. No. : 201000701R

Messrs. LIU SI JIA
BLK 672D EDGEFIELD PLANS #09-585
S 824672

Attention : Motor Claim Department
Contact : 91993900

Estimate : ES000865

Date : 07/03/2019
Vehicle Num. : SKX 4433B
Make/Model : BMW 525i-2014
Chassis/Eng# : WBA5A32080D790266/B5090821N20B;
Accident Date : 06/03/2019
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LABOUR :
KNOCKING /REMOVE & REFIX ETC
SPRAY PAINTING ON RR BUMPER /RR BOOTLID/RR PANEL
RR FENDER RH/LH ETC
WIRING

Labour Total S\$:

~~1,500.00~~ 300
~~1,800.00~~ 400
~~50.00~~ 30
3,350.00

730

Total S\$: 11,459.67
=====

LEE SHENG AUTO PTE LTD

total 3461.63

h/s 27K
0300p

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

Shu Pei (LKKAUTO)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Friday, 8 March 2019 4:39 PM
To: Shu Pei (LKKAUTO)
Cc: Hsiao Tong (LKKAUTO); Admin A
Subject: RE: Direct Settlement - Accident Involving SJT2261B (OI : CTI - TBA) AND SKX4433B (TP : LKK REF - CC6/CTI19004286/Ab3) on 06.03.2019
Attachments: INSURED REPORT.PDF

Dear Shupe, i,

Pls find Insured report.

Regards,

Chong Boon Sen

Claims Executive

Claims

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 63896171

Fax: 62247175

Email: boonsen.chong@sg.cntaiping.com

Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Shu Pei (LKKAUTO) [mailto:shupe@lkkauto.com]
Sent: Friday, 8 March, 2019 3:41 PM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Cc: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: Direct Settlement - Accident Involving SJT2261B (OI : CTI - TBA) AND SKX4433B (TP : LKK REF - CC6/CTI19004286/Ab3) on 06.03.2019

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

We have inspected TP vehicle SKX 4433B at M/s Lee Sheng Auto Pte Ltd on a WP basis and TP repairer proposed for a direct settlement.

Enclosed for your perusal is:

- TP GIA report

Please be informed that estimated cost of repair and preliminary advice is not ready yet.

Meanwhile, kindly let us have a copy of your insured's GLA report for our necessary action.

Kindly take note that the case handler in-charge is Hsiao Tong and she can be contacted at DID: 6742 3197.

Thank you

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC6/CTI19004286/Aea3n2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 31-03-2020



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJT 2261B	Veh. Inspected	SKX 4433B
Policy No.	DMPCSN3092111802	Coverage (\$)	0.00
Claim No.	SNM19D200988C02/1	Excess (\$)	0.00
Assign From		Assign Date	07/03/2019

2. Vehicle Particulars & Condition

Make & Model	B.M.W 520i	c.c	1997
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	WBA5A32080D790266	Colour	SILVER
Odometer	109852	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	245/45 R18	FALKEN	6 mm
L/H Front Tyre	245/45 R18	FALKEN	6 mm
R/H Rear Tyre	245/45 R18	FALKEN	6 mm
L/H Rear Tyre	245/45 R18	FALKEN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	06/03/2019	Inspection Date	07/03/2019
Survey held at	LEE SHENG AUTO PTE LTD 1 KAKI BUKIT AVE 6 #01-60 SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKX 4433B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DEFORMED	2,022.50	1,563.00
1	REAR BUMPER REINFORCEMENT	BENT	180.50	180.50
1	REAR BUMPER MOULDING	CRACKED	100.45	100.45
1	REAR BUMPER SENSOR	DAMAGED	250.00	250.00
1	REAR BUMPER LAMP LH	NOT NECESSARY	850.00	-
1	REAR BUMPER LAMP RH	NOT NECESSARY	850.00	-
1	REAR EXHAUST ASSY	NOT NECESSARY	1,120.00	-
1	REAR BUMPER REINFORCEMENT COVER	CRACKED	150.00	150.00
4	REAR BUMPER SENSOR WIRE @\$80.00	DAMAGED	320.00	320.00
1	REAR BUMPER RETAINER LH	NOT NECESSARY	95.00	-
1	REAR BUMPER RETAINER RH	NOT NECESSARY	95.00	-
1	REAR LAMP CHROME COVER LH	CUT	75.00	75.00
1	REAR LAMP CHROME COVER RH	CUT	75.00	75.00
1	REAR TOWING COVER	DEFORMED	85.65	85.65
1	REAR END PANEL	TO REPAIR SEE LABOUR	950.65	-
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	145.50	-
5	REAR END PANEL TOP GARNISH CLIPS @\$6.50	NOT NECESSARY	32.50	-
1	STIFFENER LWR BUMPER	DEFORMED	94.55	94.55
1	REAR TRUNKLID	TO REPAIR SEE LABOUR	950.85	-
5	TRUNKLID CLIPS @\$6.50	NOT NECESSARY	32.50	-
1	TRUNKLID WEATHERSTRIP	NOT NECESSARY	205.60	-
1	TRUNKLID LOCK	NOT NECESSARY	188.50	-
1	520I EMBLEM	NECESSARY	56.50	56.50
1	BMW LOGO	NECESSARY	84.50	84.50
	LESS 10% DISCOUNT		-901.08	-303.52
			8,109.67	2,731.63
LABOUR				
	KNOCKING/REMOVE & REFIX ETC.INCLUSIVE OF THE REPAIR OF REAR END PANEL AND REAR TRUNKLID.		1,500.00	300.00

Report Ref No. CC6/CT119004286/Aea3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPRAY PAINTING ON RR BUMPER/RR BOOTLID/RR PANEL,RR FENDER RH/LH ETC. WIRING.		1,800.00	400.00
			50.00	30.00
			3,350.00	730.00
GRAND TOTAL			11,459.67	3,461.63
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,700.00

Report Ref No. CC6/CTI19004286/Aea3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.