

LEE SHENG AUTO PTE LTD

1, Kaki Bukit Ave 6, Autobay@KakiBukit

#01-60/58, Singapore 417883

Tel No. : 67477333 Fax No. : 67457138

E-Mail : leesheng@singnet.com.sg

Tax Reg. No. : 201000701R Buss. Reg. No. : 201000701R

Messrs. LIU SI JIA

BLK 672D EDGEFIELD PLANS #09-585

S 824672

Attention : Motor Claim Department

Contact : 91993900

Estimate : ES000865

Date : 07/03/2019

Vehicle Num. : SKX 4433B

Make/Model : BMW 525I-2014

Chassis/Eng# : WBA5A32080D790266/B5090821N20B;

Accident Date : 06/03/2019

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	REAR BUMPER <i>reformed</i>		1563
2.	1	REAR BUMPER REINFORCEMENT <i>gent</i>		2022.50
3.	1	REAR BUMPER MOULDING <i>car</i>		180.50
4.	1	REAR BUMPER SENSOR <i>gaged</i>		100.45
5.	1	REAR BUMPER LAMP LH		250.00
6.	1	REAR BUMPER LAMP RH <i>frame</i>		850.00
7.	1	REAR EXHAUST ASSY		850.00
8.	1	REAR BUMPER REINFORCEMENT COVER <i>checked</i>		1,120.00
9.	4	REAR BUMPER SENSOR WIRE <i>dayd</i>		150.00
10.	1	REAR BUMPER RETAINER LH <i>frame</i>	80.00	320.00
11.	1	REAR BUMPER RETAINER RH		95.00
12.	1	REAR LAMP CHROME COVER LH <i>gent</i>		95.00
13.	1	REAR LAMP CHROME COVER RH <i>gent</i>		75.00
14.	1	REAR TOWING COVER <i>del</i>		75.00
15.	1	REAR END PANEL <i>Reps</i>		85.65
16.	1	REAR END PANEL TOP GARNISH <i>frame</i>		950.65
17.	5	REAR END PANEL TOP GARNISH CLIPS		145.50
18.	1	STIFFENER LWR BUMPER <i>del</i>	6.50	32.50
19.	1	REAR TRUNKLID <i>Reps</i>		94.55
20.	5	TRUNKLID CLIPS		950.85
21.	1	TRUNKLID WEATHERSTRIP <i>del</i>	6.50	32.50
22.	1	TRUNKLID LOCK <i>del</i>		205.60
23.	1 PC	520i EMBLEM <i>del</i>		188.50
24.	1 PC	BMW LOGO <i>del</i>		56.50
List TotalS\$:				9,010.75
10.00% Discount S\$:				901.08
				8,109.67

CONTINUE / ...

LEE SHENG AUTO PTE LTD

Page 2 / 2

1, Kaki Bukit Ave 6, Autobay@KakiBukit
#01-60/58, Singapore 417883
Tel No. : 67477333 Fax No. : 67457138
E-Mail : leesheng@singnet.com.sg
Tax Reg. No. : 201000701R Buss. Reg. No. : 201000701R

Messrs. LIU SI JIA
BLK 672D EDGEFIELD PLANS #09-585
S 824672

Attention : Motor Claim Department
Contact : 91993900

Estimate : ES000865

Date : 07/03/2019
Vehicle Num. : SKX 4433B
Make/Model : BMW 525I-2014
Chassis/Eng# : WBA5A32080D790266/B5090821N20B;
Accident Date : 06/03/2019
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LABOUR :
KNOCKING /REMOVE & REFIX ETC
SPRAY PAINTING ON RR BUMPER /RR BOOTLID/RR PANEL
RR FENDER RH/LH ETC
WIRING

Labour Total S\$:

~~1,500.00~~ 300

~~1,800.00~~ 400
~~50.00~~ 30

3,350.00

Total S\$: 11,459.67
=====

LEE SHENG AUTO PTE LTD

total: 3461.63

h/s: 2.7K

03 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and**
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: