



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS3/SMO17020609/Evd3e2-1

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERSINGAPORE 048623

Date : 15-03-2019



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	PC 6250A	Veh. Inspected	YM 8287Y
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1703793/AGC	Excess (\$)	0.00
Assign From	AGNES CHAN	Assign Date	08/03/2019

2. Vehicle Particulars & Condition

Make & Model	MITSUBISHI FM65FM1RDEA	c.c	7545
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	FM65FMB00010	Colour	RED
Odometer	358011	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	11 R22.5	LEAD	5 mm
L/H Front Tyre	11 R22.5	LEAD	5 mm
R/H Rear Tyre	11 R22.5	BRIDGESTONE	4 mm
L/H Rear Tyre	11 R22.5	BRIDGESTONE	4 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	26/10/2017	Inspection Date	06/11/2017
Survey held at	TWINCAR AUTOMOTIVE PTE LTD 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

- A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	15 Working Days
--	------------------------