



ROC No.: 201500047H
48 Toh Guan Road East #01-121
Enterprise Hub Singapore 608586
Tel: 6266 0555 Fax: 6266 3155

Date : 08 March 2019
Your Ref : SHD 9597U

To: AXA Insurance

By Fax & Email

Attn: Motor Claims Department.

Re: Accident involving motor vehicle nos. S6X 1006T and SHD9597U
Along Raffles Blvd Toward Raffles Ave. Before Junction on 03/03/2019
of Temasek Ave.

We refer to the above matter.

Under the new practice directions, we the repairers of motor vehicle no. S6X 1006T
Hereby give you the insurer of motor vehicle no. SHD9597U 2 working days.
Whether you are appointing your own surveyors to conduct a pre-repair inspection on our
customer's vehicle.

Location : 48 Toh Guan Road East #01-121
Enterprise Hub Singapore 608586

Contact/Tel : 6266 0555 / 9789 0992 Winson

If we do not hear from you after 2 working days, we shall carry out to appoint our own surveyors on
behalf of our said customer to conduct the said pre-repair inspection and proceed to repair the said
vehicle thereafter.

Thank You.

Regards


E-mail: pioneer@skauto.com.sg

FOR SURVEYOR
Please initial here after completion of pre-repair
inspection. Thank you.

Appointed Surveyor:

(Name & Signature)

Date of Inspection: _____

Time of Inspection: _____

Main office: 23 Kaki Bukit Ave 4, #03-01 (South Wing) Singapore 415933
Tel: +65 6789-5155 Fax: +65 6783-5155