

SK Automobile Pte. Ltd.
(Co Reg. No. 201500047H)
23 Kaki Bukit Ave 4, #03-01
Vicom Inspection Centre (S415933)
Tel: 6789 5155 Fax : 6783 5155

TO : AXA Insurance ATTENTION : MOTOR CLAIMS DEPARTMENT ESTIMATE REPORT : OWNER PARTICULAR NAME : ADDRESS : TEL. NO. : OWNER INSURANCE : EQ POLICY NO. : DMPPHQ18-005257 PERSON INCHARGE :	DATE : 9-Mar-19 JOB TYPE : T/P CLAIMS VEHICLE DETAILS VEHICLE NO. : SGX1006T MODEL / MAKE : MERCEDES BENZ A170 CHASSIS NO. : WDD1690322J481990 ACCIDENT DETAIL DATE : 03/03/2019 TIME : 21:45hrs
--	---

QUOTATION SUMMARY PAGE 01

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR FENDER LH <i>repair</i>	1	\$ 2,890.60	\$ 2,890.60
2	REAR FENDER INNER SHIELD LH <i>X</i>	1	\$ 125.30	\$ 125.30
3	REAR FENDER GLASS WITH MOULDING LH <i>X</i>	1	\$ 898.30	\$ 898.30
3	REAR BUMPER <i>✓</i>	1	\$ 1,075.90	\$ 1,075.90
4	REAR BUMPER CHROME MOULDING LH/RH <i>✓</i>	2	\$ 95.70	\$ 191.40
5	REAR BUMPER SIDE RETAINER LH/RH <i>LH ✓</i>	<i>1 pc</i>	\$ 28.90	\$ 57.80
6	REAR SPORT RIM LH <i>✓</i> <i>S/N</i>	1	\$ 590.40	<i>\$ 350</i> \$ 590.40
7	REAR SUSPENSION SHOCK ABSORBER LH <i>X</i>	1	\$ 232.50	\$ 232.50
8	REAR SUSPENSION STABILISER BAR LINK LH <i>X</i>	1	\$ 60.30	\$ 60.30
9	REAR SUSPENSION TRAILING ARM LH <i>X</i>	1	\$ 120.90	\$ 120.90
10	REAR SUSPENSION WHEEL HUB BEARING LH <i>?</i>	1	\$ 260.80	\$ 260.80

TOTAL PRICE	\$ 6,504.20
LESS -10%	\$ (650.42)
SUB TOTAL PRICE	\$ 5,853.78

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR FENDER SEALANT LH <i>X</i>	1	\$ 100.00	\$ 100.00
2	REAR FENDER INNER SHIELD CLIPS SET LH <i>✓</i>	1	\$ 50.00	<i>\$ 30</i> \$ 50.00
3	REAR FENDER GLASS SEALANT WITH PRIMER LH <i>X</i>	1	\$ 80.00	\$ 80.00
3	REAR FENDER INNER TRIM BOARD CLIPS SET LH <i>X</i>	1	\$ 60.00	\$ 60.00
4	REAR BUMPER CLIPS SET <i>✓</i>	1	\$ 60.00	<i>\$ 40</i> \$ 60.00
5	REAR BUMPER RIVET SET <i>✓</i>	1	\$ 50.00	<i>\$ 30</i> \$ 50.00

TOTAL	\$ 400.00
--------------	------------------

CLAIMS DETAIL : LABOUR CHARGES AND SPRAY PAINTING

TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	\$ 1,200.00	300	
TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	\$ 800.00	400	
TO APPLY ANTI-RUST & TUFF KOTE	\$ 80.00	20	
TO PERFORM LIGHTING & WIRING CHECK	\$ 80.00	X	
TO DISMANTLE & REINSTALL REAR FENDER GLASS PERFORM WITH WATER LEAK TEST	\$ 120.00	X	
TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR WITH DISTANCE SETTING	\$ 80.00	60	
TO PERFORM DIAGNOSTIC CHECK & RESET MEMORY FAULT CODE TO IDENTIFICATION STANDARD	\$ 280.00	80	
TO DISMANTLE & REPLACED REAR UNDER CARRIAGE COMPONENT LH/RH TO PERFORM FACILITATE REPAIRS	\$ 380.00	80	
TO SEND VEHICLE FOR 3D COMPUTERISED TO PERFORM CHECK & ADJUSTED ALL WHEEL ALIGNMENT	\$ 120.00	60	
TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR	\$ 280.00	280 60	
TO PERFORM CONDUCT WATER LEAKAGE TEST OF ACCIDENT PORTION	\$ 80.00	X	

TOTAL

\$ 3,500.00

LKK Auto Consultant, hence notify the Repairer of the following:

- To resurvey before and spray painting
- To display damaged, and(s) during resurvey
- Parts prices are subject to resurvey
- Third party survey is on "without Prejudice" basis
- No illegal modification is allowed
- Supplementary items must be surveyed and is subject to initial approval from insurance Company

Acknowledged by Repairer
Signature:
Date:

Farah

Hp 50010068

4 days

4S

12/03/19 @ 1610

Rey after repair

ESTIMATE REPORT

TOTAL PARTS COST	:	\$	6,253.78
TOTAL LABOUR COST	:	\$	3,500.00
TOTAL REPAIR COST	:	\$	9,753.78

APPROVED DETAILS

EXCESS :
 NO. OF REPAIR DAYS :
 RE-SURVEY :
 P / P OR L / S :

DATE / TIME OF SURVEY :
 SURVEYED BY / FROM :
 CONTACT NUMBER :
 FAX NUMBER :
 EMAIL ADDRESS :