

Company

655 REC-10

AMVest

REP

CI/TPDI9004308/A

Special Instruction

665

ASSIGNMENT (Office)

From Person: Kamalah Kanis

of SPF

Date/Time: 20/2/2019

Estimated Cost

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: FBJ1912K

Insured:

at Workshop m/s:

Tel:

of

Policy No: MHASPF06000014051

Claim No: TP/IP/05309/2019

Sum Insured:

Excess:

Make of Vch:

D.O.A 28/1/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Conducted

Vehicle IN / OUT

Date/Time Action/Inaction () Estimate

FBJ1912K-X

320K
450K

9

FBJ 1912K

G 101

On 10 November 2018 at 1.00 am, the accused was driving a motor car, SLL 3915 K along AYE (Tuas) 12.4 km when he claimed there are mechanical faults to the brakes and gear of the said motor car which resulted in him to lose control of his car on a straight road.

Vehicles to be inspected: SLL3915K (Accused)

IO In-Charge: SIO Jackson Mu

- f) Case IAFP-IB-20190201 - Mechanical Inspection of Tipper Truck, XD3396H (TP/IP/03829/2019)
- g) Case IAFP-IB-20190201 - Mechanical Inspection of Motorcycle, FBB8585S (TP/IP/03829/2019)

On 22 January 2019, sometime before 5.23 p.m., the Involved Party (XD3396H) was travelling along Old Choa Chu Kang Road towards the direction of Jalan Sungei Poyan on a single lane, 2-way direction (divided by a continuous white), when the Deceased (FBB8585S) riding on the opposite direction lost control of the motor cycle and fell on the opposite direction, in front of the tipper truck. The involved Party was unable to brake in time and run over the Deceased. As a result, the motorcyclist (Deceased) sustained fatal injuries and passed away at the accident scene.

Vehicles to be inspected: FBB8585S (Deceased)
XD3396H (Involved Party)

IO In-Charge: SIO Farhan

- h) Case IAFP-IB-20190201 - Mechanical Inspection of Motor Bus, PC3917E (TP/IP/05309/2019)

On 28 January 2019 (Monday) at about 5.32 p.m., the Involved Party was driving his motor bus, PC3917E, along the single lane, two-way traffic along Gul Road towards Pioneer Road when he suddenly felt an impact at the left rear wheel of his motor bus and ran over an object. He immediately stopped his motor bus and realised that he was involved in an accident with the Deceased. As a result of the accident, the Deceased sustained head injuries and was pronounced dead at scene by paramedic SSgt Hong Bin at 5.54 p.m.

Vehicle to be inspected: PC3917E (Involved party)

IO In-Charge: DOC Saleha

- i) Case IAFP-IB-20190201 - Mechanical Inspection of Motorcycle, FBJ1912K (TP/IP/05309/2019)

On 28 January 2019 (Monday) at about 5.32 p.m., the Involved Party was driving his motor bus, PC3917E, along the single lane, two-way traffic along Gul Road towards Pioneer Road when he suddenly felt an impact at the left rear wheel of his motor bus and ran over an object. He immediately stopped his motor bus and realised that he was involved in an accident with the Deceased (Motor cycle FBJ1912K). As a result of the accident, the Deceased sustained head injuries and was pronounced dead at scene by paramedic SSgt Hong Bin at 5.54 p.m.

Vehicle to be inspected: FBJ1912K (Deceased)

IO In-Charge: DOC Saleha

- j) Case IAFP-IB-20190201 - Mechanical Inspection of Motorcycle, SFR65Y (TP/IP/03061/2019)