

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/0097/2019
DATE : 08-MAR-2019

FWD SINGAPORE PTE LTD
6 TEMASEK BOULEVARD, #18-01 SUNTEC TOWER 4

S(038986)
TEL : 68208888
FAX :

OWNER'S NAME : DESMOND LEE THENG SIONG (LI TENGXIONG)
ADDRESS : 6 WHAMPOA EAST
#13-12
S(338519)
TELEPHONE NO : 91825896

TYPE OF CLAIM : COMPREHENSIVE CLAIM
POLICY NO : PNFV2018-00003519
VEHICLE NO : SLX749E
MODEL CODE : SJ5EK7C
MODEL/YEAR : FORESTER 2.0I-L AWD CVT
ENGINE NO : FB20YC84242
CHASSIS NO : JF1SJ5KC5JG105531
MILEAGE : 1 KM
DATE IN : 08/03/2019
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : DANIEL A JUDE**
ACCIDENT DATE : 06/03/2019

Print Date : 08/03/2019
Print Time : 15:14:54

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLX749E

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	OD/CLAIM	CONDUCT BODYWORK REPAIR (OWN DAMAGE CLAIM)		
2	ZZ/001	CONDUCT OD CLAIM FWD DATE:06/03/2019 TIME:0900HRS LOCATION: ALONG NORTH BOUNA VISTA ROAD		
3	ZZ/002	REPAIR/REPLACE FRT BUMPER, FRT BONNET, FRT LH FENDER , FRT RH FENDER AND PANEL	3360.00	11201
4	ZZ/003	RESPRAY FRT BUMPER, FRT BONNET, FRT LHS FENDER, FRT RH FENDER AND PANEL	2520.00	12601
5	ZZ/004	FAULT DIAGNOSTIC AND RESET SYSTEMS	280.00	?
6	ZZ/005	TO CONDUCT FRONT LIGHTING TEST	50.00	301
7	ZZ/006	TO CONDUCT PROTECTANT COATING	500.00	2301
8	ZZ/007	TO CONDUCT ANTI-RUST COATING	580.00	?
9	ZZ/008	SUNDRIES	100.00	301
10	ZZ/009	REMOVE & REFIT FRT HEADLAMP WASHER AND PIPING	150.00	?
TOTAL LABOUR CHARGES			7540.00	

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO 9LX749E

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
		NETT	LIST	S/NETT	
1 RAD PNL COMPL RFR	53029SG0019P	360.00	7		
2 FRT FENDER RH	(W/O SIGNAL LP) 571208G0209P	270.00	X		
3 FRT FENDER LH	(W/O SIGNAL LP) 571208G0309P	270.00	X		
4 HOOD F CPL	572298G0009P	882.00	X		
5 HINGE COMPL F HD RH	572608G0009P	43.20	X		
6 HINGE COMPL F HD LH	572608G0109P	43.20	X		
7 LOCK ASSY F HOOD ISR	573108G020	72.00	X		
8 STRIKER	57311AG010	36.00	X		
9 BRKT CORNER F RH	577078G000	36.00	X		
10 BRKT CORNER F LH	577078G010	36.00	7		
11 BRKT SD F RH	577078G020	12.60	X		
12 BRKT SD F LH	577078G030	12.60	7		
13 MOULDING RMFR F	FDI PARTS 577088G000A	43.20	7		
14 MOULDING RMFR F	FDI PARTS 577088G010A	43.20	7		
15 FRT BUMPER	577098G030A	594.00	✓		
16 BACK BEAM CPL F	577118G0009P	288.00	7		
17 ENERGY ABSOR F	577228G020	126.00	✓		
18 COVER HOOK F STD	577318G0220	4.40	X		
19 PACKING RAD	577808G010	9.00	7		
20 PACKING RAD	577808G020	9.00	7		
21 MUD GUARD ASSY F RH	USE SG020 591108G021	86.40	X		
22 MUD GUARD ASSY F LH	USE SG030 591108G031	86.40	X		
23 LAMP ASSY HEAD EOF	840028G022	2380.00	X		
24 LAMP ASSY HEAD EOF LH	840028G0230	2380.00	✓		
25 FOG LAMP ASSY F	84501AJ060	1088.00	X		

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLX749E

S/NO PARTS DESCRIPTION		PARTS NUMBER	DAMAGED PARTS & PRICES			
			NETT	LIST	S/NETT	S/LIST REMARKS
26 BRKT F POG ASSY RH	PDI PARTS	84927SG020A	fu 19.80	X		
27 BRKT F POG ASSY LH	PDI PARTS	84927SG030A	fu 19.80	X		
28 TANK HLS		866318G030	fu 93.60	X		
29 NOZZLE H L WASHERRH		866368G361	fu 79.20	X		
30 NOZZLE H L WASHERRH		866368G371	79.20	?		
31 NOZZLE COVER ASSY RH	PDI PARTS	866368G380A	fu 54.00	X		
32 NOZZLE COVER ASSY LH	PDI PARTS	866368G390A	mk 54.00	✓		
33 INSULATOR HOOD NA		908158G051	fu 79.20	X		
34 GRILLE ASSY F UPRRG	PDI STOCK	911218G210A	140.40	?		
35 GRILLE ASSY F CTRRG	PDI STOCK	911218G240A	180.00	?		
36 GRILLE ASSY F LMRG	PDI STOCK	911218G280A	316.80	?		
37 BRKT GRILLE LMR NA		911658G000	21.60	?		
38 FRONT NUMBER PLATE	WMD01				45.00	✓
SUB TOTAL			10348.80	0.00	45.00	0.00
LESS DISCOUNT (NETT-20 %)			2069.76	0.00	0.00	0.00
GRAND TOTAL			8279.04	0.00	45.00	0.00
OVERALL TOTAL			8324.04			

REMARKS: REMARK (X) = APPROVED, REMARK (?) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.

19 LEPONG C. TIA BAYOH

SINGAPORE 319255

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLX749E

TOTAL LABOUR CHARGES	7540.00
TOTAL SPARE PARTS CHARGES	8324.04
GRAND TOTAL	15864.04 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:
SURVEYED DATE	:
AUTHORIZED DATE	:
EXCESS CLAUSE	: 0.00
LIABILITY	: 0.00
REMARKS	:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Authorized

Resurvey B4 paint

Excess TBA

4 days

Ref: 62564315

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.