

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Clara Li Zi Rong

Date: 11 Mar 2019

Preliminary Advice

Vehicle No	: SLX749E	Accident Date	: 06/03/2019
Make	: SUBARU FORESTER	Policy No.	: PNPV2018-00003519
Assignment Date	: 11/03/2019	Excess	: S\$1,000.00
Date of Inspection	: 11/3/2019	Est. Duration of Repair	: 4
Inspection At	: MOTOR IMAGE ENTERPRISES PTE LTD		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	15,864.04
Revised Amount	:S\$	5,258.20
Check Items (Estimated)	:S\$	2,241.20
Total	:S\$	7,499.40

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	104,000.00
COE / PARF Rebate	:S\$	45,154.00
Salvage Value	:S\$	
Margin for Repair	:S\$	58,846.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :