

ASS. REC. BY:

REF:

CS/FWD19004323/Kvd367

Instruction:

Clerk
merimen

Kenneth

ASSIGNMENT (Office)

From (Person):

clara li

of

FWD

Date/Time:

8/3/2019 @ 3:55pm

Estimated Cost:

Bill to:

☒ OF / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV / ☐ CS

To Inspect Vehicle No:

SLX 749E

Insured:

at Workshop m/s:

Motor Image

Tel:

86113195

of

19 lorong 8 toa payoh

Policy No:

PNPV2018-00003519

Claim No:

120190005976

Sum Insured:

Excess:

7BA 1000

Make of Veh:

D.O.A.

06/03/2019

(Client's Brand)

CA / ☒ REV / REP. / REV 24 HRS

\$104K

H.O.D. Endorsement:

Date/Time:

1047am 11/3/19

Person Contacted:

Daniel

Vehicle:

☒ IN ☐ OUT

Date/Time:

Action/Instruction (✓) Estimate

SLX 749E - CC4 / FWD19004276 / R/c 3

D.O.A: 6/3/19

11/3/19

Revert via merimen

11/3/19

Rece approved \$6000 from clara by merimen

11/3/19

Informed Daniel Jude c/a ex \$1000 by email

9/4/19

Final fig \$ 6072.60 (Real 9591.44, 60% confirmed by email)

ASS. REC. BY:

REF: FWD/

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04 days

Res.: Yes or No

Lum Sum:

1.3.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLD 74PC

Yr Regn: 03, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Subaru Forester cc 1995

Colour:

M-Black

A/C: Insured / Std / NI / NA

Sp. Reading

19271

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

TF1ST5K65TG 105531

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / RIM or

Tyre Size:

F:

225/60R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

R/Bal.

L/Bal.

L/Bal.

D.O.A.

6/3/19

Q.O.I.

11/3/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FR N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 File pass to

RECEIVED 5 APR 2019

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

4

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

S - RS - SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

250

50

50+50

10

410

Report Format:

merimen

Lump Sum / I.B.I: (\$

6272.60

7 9/4- typist

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Mar 2019 Edit Reg		11 Mar 2019 00:00 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	Desmond Lee Theng Siong, ID: S8006414D			Date of Loss:	06/03/2019 09:00 - :59
Vehicle Reg. No.:	SLX749E			Policy/Cover Note No.:	PNPV2018-00003519 (Comprehensive)
Claim Type:	OD / 1201900005976			Excess:	S\$1,000.00
Repairer:	Motorimage Enterprises Pte Ltd (HQ) 19 LORONG 8, TOA PAYOH, 319255 Toa Payoh - Tel: 64730333 / 62222311 / 65063848				
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Clara Li Zi Rong]				
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 20/03/2019]				

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View Received Message

This mail is associated with :

***SLX749E (1201900005976)**

OD

Mar 6 2019 9:00AM

[Desmond Lee Theng Siong]
Motorimage Enterprises Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From FWD Singapore Pte. Ltd. (HQ) (FWD_SG), sent on 09/04/2019 12:01 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$6272.60) - SLX749E - Claim Handler: Clara Li Zi Rong

Approved:6272.60.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No.199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:	FWD Singapore Pte. Ltd. 6 Temasek Boulevard #18-01 Suntec Tower 4 Singapore 038986	From:	LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
-----	---	-------	---

Attn:	Clara Li Zi Rong	Date:	09 Apr 2019
-------	------------------	-------	-------------

Preliminary Advice

Vehicle No	: SLX749E	Accident Date	: 06/03/2019
Make	: SUBARU FORESTER	Policy No.	: PNPV2018-00003519
Assignment Date	: 11/03/2019	Excess	: S\$1,000.00
Date of Inspection	: 11/3/2019	Est. Duration of Repair	: 4
Inspection At	: MOTOR IMAGE ENTERPRISE PTE LTD		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	15,864.04
Revised Amount	:S\$	6,272.60
Check Items (Estimated)	:S\$	
Total	:S\$	6,272.60

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	104,000.00
COE / PARF Rebate	:S\$	45,154.00
Salvage Value	:S\$	
Margin for Repair	:S\$	58,846.00

Remarks

☒ The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

☐ The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

☐ Other comments :

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Monday, 11 March 2019 3:35 PM
To: Daniel Jude (danieljude@motorimage.net); SUR
Subject: SLX 749E-DOA: 6/3/2019 (FWD OD)

Dear Daniel,

As instructed by our client , please proceed to repair the **insured vehicle SLX 749E (Excess S1000/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

***SLX749E (1201900005976)**

OD

Mar 6 2019 9:00AM

[Desmond Lee Theng Siong]

Motorimage Enterprises Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From FWD Singapore Pte. Ltd. (HQ) (FWD_SG), sent on 11/03/2019 13:58 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$6000.00) - SLX749E - Claim Handler: Clara Li Zi Rong

Approved:6000,00:Hi Please re-seek mandate upon check items being verified. Thanks.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Clara Li Zi Rong

Date: 11 Mar 2019

Preliminary Advice

Vehicle No	: SLX749E	Accident Date	: 06/03/2019
Make	: SUBARU FORESTER	Policy No.	: PNPV2018-00003519
Assignment Date	: 11/03/2019	Excess	: S\$1,000.00
Date of Inspection	: 11/3/2019	Est. Duration of Repair	: 4
Inspection At	: MOTOR IMAGE ENTERPRISES PTE LTD		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	15,864.04
Revised Amount	:S\$	5,258.20
Check Items (Estimated)	:S\$	2,241.20
Total	:S\$	7,499.40

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	104,000.00
COE / PARF Rebate	:S\$	45,154.00
Salvage Value	:S\$	
Margin for Repair	:S\$	58,846.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Nivitha (LKK Auto)

From: clara.li@fwd.com
Sent: Friday, 8 March 2019 3:55 PM
To: assignments@lkkauto.com; sur@lkkauto.com; admin-a@lkkauto.com; admin-d@lkkauto.com
Cc: motorclaims.sg@fwd.com
Subject: FW: SLX749E - OD CLAIM - FWD INSURED - ARRANGE SURVEY 11/03/2019 - 1100HRS

Importance: High

Hi LKK team,

Please refer to the email below and liaise with the repairer for OD survey arrangement.

Please create the case in Merimen.

Thank you.

Kind Regards

Clara Li

Senior Executive, Claims

FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 6727 5722

E clara.li@fwd.com

W fwd.com.sg



From: Daniel Jude [mailto:danieljude@motorimage.net]
Sent: Friday, 8 March, 2019 3:26 PM
To: Motor Claims SG - SG Common
Cc: TPY Insurance Team; Mohamed Isman
Subject: SLX749E - OD CLAIM - FWD INSURED - ARRANGE SURVEY 11/03/2019 - 1100HRS
Importance: High

Hi Claims Team,

Kindly assist to arrange survey for the above mentioned FWD insured.

11/03/2019 - 1100hrs

Thank You.

Best Regards

Daniel A Jude

Service Executive


Motor Image Enterprises Pte Ltd

19 Lorong 8 Toa Payoh Singapore 319255

HP: 8611 3195

Email: danieljude@motorimage.net

Website: www.tanchong.com : www.motorimage.net



Disclaimer: This e-mail is confidential. It may also be legally privileged. If you are not the addressee you may not copy, forward, disclose or use any part of this message. If you have received this message in error, please delete it and all copies from your system and notify the sender immediately by return e-mail. Internet communications cannot be guaranteed to be timely, secure, error-free or virus-free. The sender does not accept liability for any errors or omissions.

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6414D
Vehicle Details	
Vehicle No.:	SLX749E
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Mar 2019
Vehicle Make:	SUBARU
Vehicle Model:	FORESTER 2.0i-L CVT AWD SR
Primary Colour:	Black
Manufacturing Year:	2018
Engine No.:	FB20YC84242
Chassis No.:	JF1SJ5KC5JG105531
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$13,365.00
Original Registration Date:	15 Mar 2018
First Registration Date:	15 Mar 2018
Transfer Count:	0
Actual ARF Paid:	\$13,365.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Mar 2028
PARF Rebate Amount:	\$10,023.00
Intended COE Rebate Details	
COE Expiry Date:	14 Mar 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$39,000.00
COE Rebate Amount:	\$35,131.00
Total Rebate Amount:	\$45,154.00

The information contained herein is correct as at 11 Mar 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/03/2019 13:06
Date Of Accident	06/03/2019 09:00
Exact Location Of Accident	ALONG NORTH BOUNA VISTA ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLX749E
-----------------------------	---------

Insured/Policyholder

Name Of Registered Owner	DESMOND LEE THENG SIONG
NRIC No	S8006414D
Email Address	DESMONDLEETS@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-91825896
Alternative Phone No	OTHERS-91825896

Vehicle Particulars

Manufacturer	SUBARU
Model	FORESTER 2.0I-L CVT AWD SR
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNPV2018-00003519
Cover Note Number	N.A

Driver

Name of Driver	DESMOND LEE THENG SIONG
NRIC No	S8006414D
Date Of Birth	15/03/1980
Occupation	INDOOR
Date Of Driving Pass	13/08/1999
Driving Experience	19 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91825896
Fax Number	
Contact Number	OTHERS-91825896
Email Address	DESMONDLEETS@YAHOO.COM.SG

Address	NIL
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I was driving my car along North Buona Vista Road filter Towards North Buona Vista Drive. I was following the suit to moving out, suddenly in front of my vehicle SGV956T jam brake and I cannot stop on time and collided his car. Damages of my car front left side position and number plate. No injuries were involved.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGV956T
Vehicle Make/Model/Colour	TOYOTA YARIS G AUTO
Details Of Properties	NIL
Vehicle Category	PRIVATE CAR
Name of Driver	CHENG CALINE
NRIC/Passport Number	S8322826A
Contact Number	93651739
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/are be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

VERIFIED BY AJAX MARS
REPORTING OFFICER
JOHNNY VOO

[Signature]

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre
Personnel

Sketch Plan

Along North Buona Vista Road Viller Towards North
Buona Vista Drive.

A: SLV74PE
B: SQUA66T

ACCIDENT STATEMENT (2000 characters)

I was driving my car along North Buona Vista Road filter Towards North Buona Vista drive. I was following the suit to moving out, suddenly in front of my vehicle SGV956T jam brake and I cannot stop on time and collided his car. Damages of my car front left side position and number plate. No injuries were involved.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
JOHNNY VOO CHEON YEE



MARS Officer

Registered Owner or Driver's Signature

Job Complete Date/Time

6 March 2019 at 12:39 PM

Date/Time:

6 March 2019 at 12:39 PM

STORIMAGE ENTERPRISES PTE. LTD.
9 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/0097/2019
DATE : 08-MAR-2019

WD SINGAPORE PTE LTD
TEMASEK BOULEVARD, #18-01 SUNTEC TOWER 4

(038986)
TEL : 68208888
FAX :

OWNER'S NAME : DESMOND LEE THENG SIONG (LI TENGXIONG)
ADDRESS : 6 WHAMPOA EAST
#13-12
S(338519)
TELEPHONE NO : 91825896

TYPE OF CLAIM : COMPREHENSIVE CLAIM
POLICY NO : PNPV2018-00003519
VEHICLE NO : SLX749E
MODEL CODE : SJ5EK7C
MODEL/YEAR : FORESTER 2.0I-L AND CVT
ENGINE NO : FB20YC84242
CHASSIS NO : JF1SJ5HC5JG105531
REGISTRATION : 1 FM
DATE IN : 08/03/2019
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : DANIEL A JUDE**
ACCIDENT DATE : 06/03/2019

Print Date : 08/03/2019
Print Time : 15:14:54

STORIMAGE ENTERPRISES PTE. LTD.
9 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLK749E

NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ODCLAIM	CONDUCT BODYWORK REPAIR (OWN DAMAGE CLAIM)		
2	ZZ/001	CONDUCT OD CLAIM FWD DATE:06/03/2019 TIME:0900HRS LOCATION: ALONG NORTH BOUNA VISTA ROAD		
3	ZZ/002	REPAIR/REPLACE FRT BUMPER, FRT BONNET, FRT LH FENDER , FRT RH FENDER AND PANEL	3360.00	11201 ✓
4	ZZ/003	RESPRAY FRT BUMPER, FRT BONNET , FRT LHS FENDER, FRT RHS FENDER AND PANEL	2520.00	12601 ✓
5	ZZ/004	FAULT DIAGNOSTIC AND RESET SYSTEMS	280.00	2 ✓
6	ZZ/005	TO CONDUCT FRONT LIGHTING TEST	50.00	301 ✓
7	ZZ/006	TO CONDUCT PROTECTANT COATING	500.00	2501 ✓
8	ZZ/007	TO CONDUCT ANTI-RUST COATING	na 580.00	2 ✗
9	ZZ/008	SUNDRIES	100.00	301 ✓
10	ZZ/009	REMOVE & REFIT FRT HEADLAMP WASHER AND PIPING	na 150.00	2 ✗
TOTAL LABOUR CHARGES			7540.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLX749E

		DAMAGED PARTS & PRICES			
/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	S/LIST REMARKS
1 RAD PNL COMPL RPR	53029SG0019P	360.00	X		
2 FRT FENDER RH	(W/O SIGNAL LP) 57120SG0209P	270.00	X		
3 FRT FENDER LH	(W/O SIGNAL LP) 57120SG0309P	270.00	X		
4 HOOD F CPL	57229SG0009P	882.00	X		
5 HINGE COMPL F HD RH	57260SG0009P	43.20	X		
6 HINGE COMPL F HD LH	57260SG0109P	43.20	X		
7 LOCK ASSY F HOOD ISR	57310SG020	72.00	X		
8 STRIKER	57311AG010	36.00	X		
9 BRKT CORNER F RH	57707SG000	36.00	X		
10 BRKT CORNER F LH	57707SG010	36.00	X		
11 BRKT SD F RH	57707SG020	12.60	X		
12 BRKT SD F LH	57707SG030	12.60	X		
13 MOLDING RMFR F	PDI PARTS 57708SG000A	43.20	X		
14 MOLDING RMFR F	PDI PARTS 57708SG010A	43.20	X		
15 FRT BUMPER	57709SG030A	594.00			
16 BACK BEAM CPL F	57711SG0009P	288.00	X		
17 ENERGY ABSOR F	57722SG020	126.00			
18 COVER HOOK F STD	57731SG220	4.40	X		
19 PACKING PAD	57780SG010	9.00	X		
20 PACKING PAD	57780SG020	9.00	X		
21 MUD GUARD ASSY F RH	USE SG020 59110SG021	86.40	X		
22 MUD GUARD ASSY F LH	SEE SG030 59110SG031	86.40	X		
23 LAMP ASSY HEAD EOF	84002SG222	2380.00	X		
24 LAMP ASSY HEAD EOF LH	84002SG230	2380.00			
25 FOG LAMP ASSY F	84501AJ060	1088.00	X		

OTORIMAGE ENTERPRISES PTE. LTD.
9 LUBONG 8, TOA PAYOH
SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLX749E

			DAMAGED PARTS & PRICES			
/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	S/LIST REMARKS
26	BRKT F FOG ASSY RH	PDI PARTS 84927SG020A	Sn 19.80	X		
27	BRKT F FOG ASSY LH	PDI PARTS 84927SG030A	Sn 19.80	X		
28	TANK HLS	86631SG030	Sn 93.60	X		
29	NOZZLE H L WASHERRH	86636SG361	Sn 79.20	X		
30	NOZZLE H L WASHERLH	86636SG371	Sn 79.20	? X		
31	NOZZLE COVER ASSY RH	PDI PARTS 86636SG380A	Sn 54.00	X		
32	NOZZLE COVER ASSY LH	PDI PARTS 86636SG390A	mis 54.00	✓	✓	
33	INSULATOR HOOD NA	90815SG051	Sn 79.20	X		
34	GRILLE ASSY F UPREG	PDI STOCK 91121SG210A	Sn 140.40	X		
35	GRILLE ASSY F CTREG	PDI STOCK 91121SG240A	Sn 180.00	X		
36	GRILLE ASSY F LWRG	PDI STOCK 91121SG280A	Sn 316.80	X		
37	BRKT GRILLE LWR NA	91165SG000	Sn 21.60	X		
38	FRONT NUMBER PLATE	WM001		45.00	✓	
SUB TOTAL			10348.80	0.00	45.00	0.00
LESS DISCOUNT (NETT-20 %)			2069.76	0.00	0.00	0.00
GRAND TOTAL			8279.04	0.00	45.00	0.00
OVERALL TOTAL			8324.04			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLX749E

TOTAL LABOUR CHARGES	7540.00
TOTAL SPARE PARTS CHARGES	8324.04

RAND TOTAL	15864.04 *

All charges do2 not include GST.

SURVEYOR'S PARTICULARS

AME	:	
SURVEYED DATE	:	
UTHORIZED DATE	:	
XCESS CLAUSE	:	0.00
LIABILITY	:	0.00
EMARKS	:	

Not Authorized
Resurvey B4 paint
Excess TBA
4 days
Ref: 62564315

S NOTE : This estimate is based on visual inspection of the
 affected vehicle. Should we require further labour
 charges & spare parts in the process of repairs, we
 shall inform you accordingly.

LIXX Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To clarify damaged parts; during resurvey
 • Parts costs are subject to confirmation
 • This survey service is on a "Without Prejudice" basis
 • No legal responsibility is allowed
 • Excess/claim payable must be resurveyed and
 is subject to final approval from Insurance Company

 Acknowledged by Repairer
 Signature: _____
 Date: _____

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

FINALIZED : ACCIDENT/BOOY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : IMS/IC/CHI/0097/2019
DATE : 08-MAR-2019

PWD SINGAPORE PTE LTD
6 TEMASEK BOULEVARD, #18-01 SUNTEC TOWER 4

S(038986)
TEL : 68208888
FAX :

OWNER'S NAME : DESMOND LEE THENG SIONG (LI TENGKIONG)
ADDRESS : 6 WHAMPOA EAST
#13-12
S(338519)
TELEPHONE NO : 91825896

TYPE OF CLAIM : COMPREHENSIVE CLAIM
POLICY NO : PNPV2018-00003519
VEHICLE NO : SLX749E
MODEL CODE : SJ5EK7C
MODEL/YEAR : FORESTER 2.0I-L AWD CVT
ENGINE NO : FB20YC84242
CHASSIS NO : JF1SJSK5JG105531
MILEAGE : 19273 KM
DATE IN : 08/03/2019
LIABILITY : 0.00
EXCESS CLAUSE : 1000.00
ESTIMATE BY : SAYEDINAH ALI**
ACCIDENT DATE : 06/03/2019

Print Date : 08/04/2019
Print Time : 12:48:00

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLX749E

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	OD/CLAIM	CONDUCT BODYWORK REPAIR (OWN DAMAGE CLAIM)		
2	ZZ/001	CONDUCT OD CLAIM FWD DATE:06/03/2019 TIME:0900HRS LOCATION: ALONG NORTH BOUNA VISTA ROAD		
3	ZZ/002	REPAIR/REPLACE FRT BUMPER, FRT BONNET, FRT LH FENDER , FRT RH FENDER AND PANEL	3360.00	1120.00
4	ZZ/003	RESPRAY FRT BUMPER, FRT BONNET, FRT LHS FENDER, FRT RHS FENDER AND PANEL	2520.00	1260.00
5	ZZ/004	FAULT DIAGNOSTIC AND RESET SYSTEMS	280.00	280.00
6	ZZ/005	TO CONDUCT FRONT LIGHTING TEST	50.00	30.00
7	ZZ/006	TO CONDUCT PROTECTANT COATING	500.00	250.00
8	ZZ/007	TO CONDUCT ANTI-RUST COATING	580.00	.00
9	ZZ/008	SUNDRIES	100.00	30.00
10	ZZ/009	REMOVE & REFIT FRT HEADLAMP WASHER AND PIPING	150.00	.00
TOTAL LABOUR CHARGES			7540.00	2970.00

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLX749E

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES				REMARKS
			NETT	LIST	S/NETT	S/LIST	
1	RAD FNL CMPL RFR	53029SG0019P	360.00				X
2	FRT FENDER RH	(W/O SIGNAL LP) 57120SG0209P	270.00				X
3	FRT FENDER LH	(W/O SIGNAL LP) 57120SG0309P	270.00				X
4	HOOD F CPL	57229SG0009P	882.00				OK
5	HINGE CMPL F HD RH	57260SG0009P	43.20				X
6	HINGE CMPL F HD LH	57260SG0109P	43.20				X
7	LOCK ASSY F HOOD ISR	57310SG020	72.00				X
8	STRIKER	57311AG010	36.00				X
9	BRKT CORNER F RH	57707SG000	36.00				X
10	BRKT CORNER F LH	57707SG010	36.00				OK
11	BRKT SD F RH	57707SG020	12.60				X
12	BRKT SD F LH	57707SG030	12.60				X
13	MOLDING EMFR F	PDI PARTS 57708SG000A	43.20				X
14	MOULDING EMFR F	PDI PARTS 57708SG010A	43.20				X
15	FRT BUMPER	57709SG030A	594.00				OK
16	BACK BEAM CPL F	57711SG0009P	288.00				X
17	ENERGY ASSOR F	57722SG020	126.00				OK
18	COVER HOOK F STD	57731SG220	4.40				X
19	PACKING RAD	57780SG010	9.00				X
20	PACKING RAD	57780SG020	9.00				X
21	MUD GUARD ASSY F RH	USE SG020 59110SG021	86.40				X
22	MUD GUARD ASSY F LH	SEE SG030 59110SG031	86.40				X
23	LAMP ASSY HEAD EOF	84002SG222	2380.00				X
24	LAMP ASSY HEAD EOF LH	84002SG230	2380.00				OK
25	FOG LAMP ASSY F	84501AJ060	1088.00				X

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLX749E

			DAMAGED PARTS & PRICES			
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	S/LIST REMARKS
26	BRKT F FOG ASSY RH	PDI PARTS 84927SG020A	19.80			X
27	BRKT F FOG ASSY LH	PDI PARTS 84927SG030A	19.80			X
28	TANK HLS	86631SG030	93.60			X
29	NOZZLE H L WASHERRH	86636SG361	79.20			X
30	NOZZLE H L WASHERLH	86636SG371	79.20			X
31	NOZZLE COVER ASSY RH	PDI PARTS 86636SG380A	54.00			X
32	NOZZLE COVER ASSY LH	PDI PARTS 86636SG390A	54.00			OK
33	INSULATOR HOOD NA	90815SG051	79.20			X
34	GRILLE ASSY F UPRHC	PDI STOCK 91121SG210A	140.40			X
35	GRILLE ASSY F CTRHC	PDI STOCK 91121SG240A	180.00			X
36	GRILLE ASSY F LMRHC	PDI STOCK 91121SG280A	316.80			X
37	BRKT GRILLE LWR NA	91165SG000	21.60			X
38	FRONT NUMBER PLATE	WM001			45.00	OK
SUB TOTAL			4072.00	0.00	45.00	0.00
LESS DISCOUNT (NETT-20 %)			814.40	0.00	0.00	0.00
GRAND TOTAL			3257.60	0.00	45.00	0.00
OVERALL TOTAL			3302.60			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SLX749E

NETT ITEM 4072.00
LESS 20 % -814.40
NETT AMOUNT 3257.60

LIST ITEM 0.00
LESS 50 % 0.00
LIST AMOUNT 0.00

SPECIAL NETT AMOUNT 45.00

S/LIST ITEM 0.00
LESS 30 % 0.00
S/LIST AMOUNT 0.00

TOTAL LABOUR CHARGES 2970.00
TOTAL SPARE PARTS CHARGES 3302.60

TOTAL CHARGES 6272.60
LESS EXCESS 1000.00

TOTAL 5272.60
ADD 7 % GST 369.08

GRAND TOTAL 5641.68

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 9 April 2019 10:17 AM
To: Sayedinah
Cc: TPY Insurance Team; Mohamed Isman; SUR
Subject: RE: SLX749E-OD-FWD INS-FINALIZED

Dear Sayed,

Confirmed finalize amount \$6272.60 before excess \$1000 @ 4 working days.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sayedinah <sayedinah@motorimage.net>
Sent: Monday, 8 April 2019 12:54 PM
To: Kenneth Kong (LKKAUTO) <KennethKong@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Cc: TPY Insurance Team <tpyinstead@tanchong.org>; Mohamed Isman <isman@motorimage.net>
Subject: SLX749E-OD-FWD INS-FINALIZED
Importance: High

Hi Kenneth,

attached for your reference and closure. Thank you.

Regards
Sayedinah Ali
Service Executive
Motor Image Enterprises Pte Ltd
19 Lorong 8 Toa Payoh Singapore 319255
HP:92992693 DID:67038109 FAX:+65-62535535
Email:sayedinah@motorimage.net
Website:www.tanchong.com :: www.motorimage.net

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	08 Mar 2019 Edit Reg		08 Mar 2019 00:00 Edit Adj Rpt	\$46,272.60 Edit Estimates	\$46,272.60 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: Desmond Lee Theng Siong , ID: S8006414D									
Vehicle Reg. No.: SLX749E		Date of Loss: 06/03/2019 09:00 - :59 [11 Months and 19 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / 1201900005976		Policy/Cover Note No.: PNPV2018-00003519 (Comprehensive)							
		Excess: \$51,000.00							
Repairer: Motorimage Enterprises Pte Ltd (HQ) 19 LORONG 8, TOA PAYOH, 319255 Toa Payoh - Tel: 64730333 / 62222311 / 65063848									
Handling Insurer: FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Clara Li Zi Rong]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 20/03/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- FWD_SG (09/04/2019): Alert - Adj Mandate Approved (\$46272.60) - SLX749E - Claim Handler: Clara Li Zi ... - FWD_SG (11/03/2019): Alert - Adj Mandate Approved (\$56000.00) - SLX749E - Claim Handler: Clara Li Zi ...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLX749E (1201900005976)
OD
Mar 6 2019 9:00AM
[Desmond Lee Theng Siong]
Motorimage Enterprises Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View View in Browser

Assessment Reports				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	11/03/19 13:44	Adjuster Immediate Advice		Load HTM	
2	09/04/19 10:30	Adjuster Immediate Advice		Load HTM	

Photos/ Images				3 per page	☒
No	Relabel/ Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	09/04/19 10:19	General View		Load JPG	☒
2	09/04/19 10:19	General View		Load JPG	☒
3	09/04/19 10:19	General View		Load JPG	☒
4	09/04/19 10:19	General View		Load JPG	☒
5	09/04/19 10:19	General View		Load JPG	☒
6	09/04/19 10:19	General View		Load JPG	☒
7	09/04/19 10:19	General View		Load JPG	☒
8	09/04/19 10:19	General View		Load JPG	☒
9	09/04/19 10:19	General View		Load JPG	☒
10	09/04/19 10:19	General View		Load JPG	☒
11	09/04/19 10:19	General View		Load JPG	☒
12	09/04/19 10:19	General View		Load JPG	☒
13	09/04/19 10:19	General View		Load JPG	☒
14	09/04/19 10:19	General View		Load JPG	☒
15	09/04/19 10:19	General View		Load JPG	☒
16	09/04/19 10:19	General View		Load JPG	☒
17	09/04/19 10:19	General View		Load JPG	☒
18	09/04/19 10:22	Reinspection Photo		Load JPG	☒
19	09/04/19 10:22	Reinspection Photo		Load JPG	☒
20	09/04/19 10:22	Reinspection Photo		Load JPG	☒
21	09/04/19 10:22	Reinspection Photo		Load JPG	☒
22	09/04/19 10:22	Reinspection Photo		Load JPG	☒
23	09/04/19 10:22	Reinspection Photo		Load JPG	☒
24	09/04/19 10:23	Reinspection Photo		Load JPG	☒

Documentation				1 per page	☒
No	Relabel/ Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	11/03/19 13:45	MARK ESTIMATE		Load PDF	

No	Finalized On	FWD Singapore Pte. Ltd. (HQ)		Thumbnail	Print
1	11/03/19 13:05	OI GIA Report		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower 4
Singapore 038986

Our File No: CS/FWD19004323/KVD3E2

Date: 09/04/2019

REFERENCE

Insured/Claimant: Desmond Lee Theng Siong Policy No: PNPV2018-00003519
Date of Loss: 06/03/2019 Nature of Claim: OD Claim No: 1201900005976

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLX749E
Make & Model: SUBARU FORESTER, 2.0 I-L CVT AWD SR (A) Engine No: FB20YC84242
Reg. Date: 15/03/2018 (Man. Year: 2018) Chassis No: JF1SJ5KC5JG105531
Colour: Metallic Black Odometer: 19271 km
Engine Capacity: 1995 cc
Market Value/New Car Price: S\$104,000.00
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/60 R17 Rear Tyre Size: 225/60 R17
Front Left Side: Yokohama 8 mm Rear Left Side: Yokohama 8 mm
Front Right Side: Yokohama 8 mm Rear Right Side: Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,424.04	3,332.60	5,091.44	60.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,440.00	2,940.00	4,500.00	60.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,864.04	6,272.60	9,591.44	60.46
- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
Nett Amount (S\$)	14,864.04	5,272.60	9,591.44	64.53

INSPECTION

Date of Assignment: 08/03/2019
Date Inspected: 11/03/2019 Inspected At: Motorimage Enterprises Pte Ltd (HQ)
19 LORONG 8, TOA PAYOH
Singapore 319255

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 Apr 2019)
Parts:	M1-SUV	SUBARU FORESTER 2.0 I-L CVT AWD SR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLX749E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	100.00 FS	*30.00 FS
2	1		*RAD PNL COMPL RPR	Repair	360.00 FN	*- FN
3	1		*FRT FENDER RH	Repair	270.00 FN	*- FN
4	1		*FRT FENDER LH	Repair	270.00 FN	*- FN
5	1		*HOOD F CPL	Buckled	882.00 FN	*882.00 FN
6	1		*HINGE COMPL F HD RH	Repair	43.20 FN	*- FN
7	1		*HINGE COMPL F HD LH	Repair	43.20 FN	*- FN
8	1		*LOCK ASSY F HOOD ISR	Repair	72.00 FN	*- FN
9	1		*STRIKER	Repair	36.00 FN	*- FN
10	1		*BRKT CORNER F RH	Serviceable	36.00 FN	*- FN
11	1		*BRKT CORNER F LH	Cracked	36.00 FN	*36.00 FN
12	1		*BRKT SD F RH	Repair	12.60 FN	*- FN
13	1		*BRKT SD F LH	Repair	12.60 FN	*- FN
14	1		*MOLDING BMPR F	Serviceable	43.20 FN	*- FN
15	1		*MOULDING BMPR F	Serviceable	43.20 FN	*- FN
16	1		*FRT BUMPER	Buckled	594.00 FN	*594.00 FN
17	1		*BACK BEAM CPL F	Repair	288.00 FN	*- FN
18	1		*ENERGY ABSOR F	Buckled	126.00 FN	*126.00 FN
19	1		*COVER HOOK F STD	Serviceable	4.40 FN	*- FN
20	1		*PACKING RAD	Not Necessary	9.00 FN	*- FN
21	1		*PACKING RAD	Not Necessary	9.00 FN	*- FN
22	1		*MUD GUARD ASSY F RH	Serviceable	86.40 FN	*- FN
23	1		*MUD GUARD ASSY F LH	Serviceable	86.40 FN	*- FN
24	1		*LAMP ASSY HEAD E0F	Serviceable	2,380.00 FN	*- FN
25	1		*LAMP ASSY HEAD E0F LH	Mtg Cracked	2,380.00 FN	*2,380.00 FN
26	1		*FOG LAMP ASSY F	Serviceable	1,088.00 FN	*- FN
27	1		*BRKT F FOG ASSY LH	Serviceable	19.80 FN	*- FN
28	1		*TANK HLS	Serviceable	93.60 FN	*- FN
29	1		*NOZZLE H L WASHERRH	Serviceable	79.20 FN	*- FN
30	1		*NOZZLE H L WASHERLH	Serviceable	79.20 FN	*- FN
31	1		*NOZZLE COVER ASSY RH	Serviceable	54.00 FN	*- FN
32	1		*NOZZLE COVER ASSY LH	Missing	54.00 FN	*54.00 FN
33	1		*INSULATOR HOOD NA	Serviceable	79.20 FN	*- FN
34	1		*GRILLE ASSY F UPRHG	Serviceable	140.40 FN	*- FN
35	1		*GRILLE ASSY F CTRHG	Serviceable	180.00 FN	*- FN
36	1		*GRILLE ASSY F LWRHG	Serviceable	316.80 FN	*- FN
37	1		*BRKT GRILLE LWR NA	Serviceable	21.60 FN	*- FN
38	1		*FRONT NUMBER PLATE	Bent	45.00 FS	*45.00 FS
39	1		*BRKT F FOG ASSY RH	Serviceable	19.80 FN	*- FN

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
F=Franchise part. S=SpcNett. N=NettItemDisc.						
				Sub Total (S\$)	10,493.80	4,147.00
			- Nett Item Discount on N Items 20.00/20.00% (S\$)		2,069.76	814.40
				Total Parts (S\$)	8,424.04	3,332.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REPAIR / REPLACE FRT BUMPER, FRT BONNET, FRT LH FENDER, FRT RH FENDER AND PANEL	New	3,360.00	1,120.00
2	RESPRAY FRT BUMPER, FRT LH FENDER AND PANEL	New	2,520.00	1,260.00
3	FAULT DIAGNOSTIC AND RESET SYSTEMS	New	280.00	280.00
4	TO CONDUCT FRONT LIGHTING TEST	New	50.00	30.00
5	TO CONDUCT PROTECTANT COATING	New	500.00	250.00
6	TO CONDUCT ANTI-RUST COATING	New	580.00	0.00
7	REMOVE & REFIT FRT HEADLAMP WASHER AND PIPING	New	150.00	0.00
Gross Labour Cost (S\$)			7,440.00	2,940.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >