

**96 MOTORSPORTS PTE LTD**

64 Kaki Bukit Ave 6 Singapore (417893)

Email: claims@96motorsports.com

Tel: 86840506

VEHICLE NUM:

SLF 5877 E

MAKE & MODEL:

HONDA CIVIC

MILEAGE:

TYRE: FRONT

TYRE: REAR

CHASSIS NUM:

TPA16

Vic

JHMF0462085200850

ATTN:

NO.	DESCRIPTION - PARTS	QTY	PRICE	ADJUSTED PRICE
1	BOOT LID <i>Dented</i>	1	\$ 780.40	683
2	BOOT LID BADGE <i>Ne</i>	1	\$ 65.30	-
3	BOOT LID EMBLEM (CIVIC) <i>Ne</i>	1	\$ 74.00	-
4	BOOT LID NUMBER PLATE LAMP L+R <i>Ne</i>	2	\$ 110.00	+
5	BOOT LID NUMBER PLATE LAMP GARNISH <i>Ne</i>	1	\$ 125.40	+
6	BOOT LID LAMP L+R <i>LH cracked, RH cracked.</i>	2	\$ 648.40	405.80
7	BOOT LID LAMP INNER SEAL L+R <i>Ne LH, RH</i>	2	\$ 80.00	50
8	BOOT LID LAMP CLIP <i>Ne</i>	10	\$ 20.00	-
9	BOOT LID INNER LOCK <i>Damaged</i>	1	\$ 248.40	115.30
10	BOOT LID LOCK CATCH <i>Ne</i>	1	\$ 46.00	+
11	BOOT LID INSULATOR <i>Ne</i>	1	\$ 167.80	+
12	BOOT LID INSULATOR CLIP <i>Ne</i>	10	\$ 30.00	+
13	BOOT LID WEATHERSTRIP <i>Cr</i>	1	\$ 189.70	-
14	BOOT LID HINGE L+R <i>Ne</i>	2	\$ 210.00	+
15	REAR BUMPER <i>Distorted</i>	1	\$ 728.00	638
16	REAR BUMPER SIDE RETAINER L+R <i>Ne</i>	2	\$ 120.00	45
17	REAR BUMPER CLIP <i>Ne</i>	10	\$ 50.00	30
18	REAR BUMPER LOWER ARCH BRACKET <i>Cr</i>	1	\$ 127.00	24.50
19	TAIL LAMP L+R <i>LH cracked, RH ut</i>	2	\$ 784.80	616
20	TAIL LAMP INNER SEAL L+R <i>Ne</i>	2	\$ 80.00	40
21	TAIL LAMP CLIP <i>Ne</i>	10	\$ 20.00	-
22	END PANEL <i>Dented</i>	1	\$ 498.00	325
23	END PANEL TOP TRIM <i>Cr</i>	1	\$ 156.00	-
24	END PANEL TOP TRIM CLIP <i>Ne</i>	10	\$ 30.00	10
25	SPARE TYRE PANEL <i>Repair</i>	1	\$ 987.30	+
26	SPARE TYRE PANEL TOP BOARD <i>Cr</i>	1	\$ 379.40	258.80
27	REAR FENDER L+R <i>Repair</i>	2	\$ 1,770.80	+
28	REAR FENDER INNER TRIM L+R <i>LH cracked, RH</i>	2	\$ 684.00	342.242.80
29	REAR FENDER INNER TRIM CLIP <i>Ne</i>	10	\$ 30.00	+
30	REAR FENDER INNER SHIELD L+R <i>Ne</i>	2	\$ 210.00	+
31	REAR FENDER INNER SHIELD CLIP	10	\$ 30.00	+
32	REAR WINDSCREEN MOULDING <i>Ne</i>	1	\$ 166.00	+

33	REAR WINDSCREEN INNER SEAL	1	\$	50.00	+
34	REAR EXHAUST SILENSER	1	\$	825.40	+
35	REAR EXHAUST MOUNTING	2	\$	80.00	+
36	REAR EXHAUST GASKET	1	\$	40.00	+
37	REAR EXHAUST HEAT PLATE	1	\$	154.20	+
			4059.60		
			3247.68		
SUBTOTAL			\$	10,796.30	\$ -
20%			\$	2,159.26	\$ -
PARTS TOTAL			\$	8,637.04	\$ -
SPECIAL NETT			QTY	PRICE	PRICE
1	REAR WINDSCREEN SEALANT	1	\$	120.00	+
2	REAR NUMBER PLATE WITH COVER	1	\$	150.00	+ 70.
3	BODY PANEL JOINT SEALANT	1	\$	150.00	60.
4	REAR EXHAUST CHROME PIPE	2	\$	300.00	+
5	REVERSE SENSOR	1	\$	350.00	200.
SPECIAL NETT 1			\$	1,070.00	\$ -
LABOUR			QTY	PRICE	PRICE
1	TO KNOCK, STRAIGHTEN AND REALIGN ACCIDENT AFFECTED AREA	1	\$	2,000.00	1200.
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	1	\$	1,800.00	1000.
3	TO RUST PROOF ACCIDENT AFFECTED AREA	1	\$	120.00	80.
4	TO R & R REAR WINDSCREEN	1	\$	150.00	+
5	TO R & R CARPET AND SEAT	1	\$	250.00	80
6	TO R & R REVERSE SENSOR	1	\$	150.00	50
7	TO R & R REAR EXHAUST	1	\$	200.00	+
LABOUR TOTAL			\$	4,670.00	\$ -
GRAND TOTAL COST			\$	14,377.04	\$ -

PAGE 2 OF 2

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian L
4/5/11/03/19.

07 days

total 5597.68
1/5: 4.8K

4.8K