

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29
Kaki Bukit Autohub, Singapore 417921
Tel No. : 67461515 / 67471787 Fax No. : 67485015
Website : www.successunited.com.sg
Buss. Reg. No. : GST No. 200402570G

AIG Asia Pacific Insurance Pte Ltd
AIG Building
78 Shenton Way, #07-16
Singapore 079120
Attention : Motor Claim Department
Contact : 64191053 Fax No. : 68357416

Estimate : TP19-030

Date : 07/03/2019
Vehicle Num. : SLS5882X
Make/Model : Toyota CHR-2017
Chassis/Eng# : ZYX10204734/2ZR8128536
Accident Date : 06/03/2019
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1 pc	Bonnet		1,417.52 +
2.	1 pc	Bonnet Weatherstrip		277.10 +
3.	1 pc	Bonnet Mechanism Lock		281.90 +
4.	1 pc	Bonnet Hinge LH		227.04 +
5.	1 pc	Frt Bumper		980.40
6.	8 pcs	Frt Bumper Clips	18.90	151.20 - 30.82
7.	1 pc	Frt Bumper Side Holder LH		171.28 - 82
8.	1 pc	Frt Bumper Tow Hook Cover		155.28 +
9.	1 pc	Headlamp Assy LH		2,721.52
10.	1 pc	Headlamp Bracket LH		274.14 +
11.	1 pc	Frt Fender LH		685.10
12.	1 pc	Frt Fender Guard LH		274.40
13.	1 pc	Frt Fender Hybrid Emblem		181.82 - 59.70
14.	1 pc	Frt Fender Inner Panel LH		374.45 +
15.	1 pc	Frt Fender Inner Liner RH		289.90 +
16.	1 pc	Frt Shock Absorber LH		651.60 - 456
17.	1 pc	Frt Wheel Bearing LH		752.10 - 374
18.	1 pc	Frt Wheel Bearing Hub LH		581.10 - 299.70
19.	1 pc	Frt Lower Arm LH		475.30
20.	1 pc	Anti Roll Bar		561.60 +
21.	1 pc	Anti Roll Bar Linkage LH		231.35 +
22.	1 pc	ABS Wire Sensor		378.10 +

List Total S\$:
25.00% Discount S\$:

12,094.20
3,023.55
9,070.65

SPECIAL NETT ITEMS :

1.	1 pc	Frt Sport Rim LH		760.00 - 480
2.	1 pc	Frt Road Tire LH		320.00 +

Special Nett Total S\$:

1,080.00

CONTINUE / ...

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29
 Kaki Bukit Autohub, Singapore 417921
 Tel No. : 67461515 / 67471787 Fax No. : 67485015
 Website : www.successunited.com.sg
 Buss. Reg. No. : GST No. 200402570G

AIG Asia Pacific Insurance Pte Ltd
 AIG Building
 78 Shenton Way, #07-16
 Singapore 079120
 Attention : Motor Claim Department
 Contact : 64191053 Fax No. : 68357416

Estimate : TP19-030

Date : 07/03/2019
 Vehicle Num. : SLS5882X
 Make/Model : Toyota CHR-2017
 Chassis/Eng# : ZYX10204734/2ZR8128536
 Accident Date : 06/03/2019
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		LABOUR :		
		To remove, rearrange electrical wirings, check lighting	120.00	30
		To remove, replace frt undercarriage parts.	480.00	220
		To remove, repair and replaced damaged bodyparts, realign bodyworks & where consistent to the accident	1,200.00	500
		To putty and respray painting on affected areas.	1,500.00	500
		To road test driving & reset wheel alignment.	150.00	80
		Labour Total S\$:		3,450.00

1330

Total: 6638.59.
 4/5 : 53K.
 05 Days.

53K

E. & O.E.

Total S\$: 13,600.65



for SUCCESS UNITED PTE LTD

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: