

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: AIG	DATE	: 8-Mar-19
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SLU4708M		
MODEL	: HONDA CIVIC 1.6L	JHMF B1630CS201244	
CHASSIS NO		Asher	
<u>ACCIDENT DETAILS</u>		DATE	: 7-Mar-19
		TIME	: 08:45HRS
THIRD PARTY REQUESTOR / CONTACT : JACK LI			

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	BOOTLID <i>Dented</i>	1	\$ 876.50	\$ 876.50
2	BOOTLID LOGO <i>2</i>	1	\$ 78.00	\$ 78.00
3	BOOTLID 'CIVIC' EMBLEM <i>see</i>	1	\$ 65.00	\$ 65.00
4	BOOTLID 'I-VTEC' EMBLEM	1	\$ 58.00	\$ 58.00
5	BOOTLID '1.6' EMBLEM	1	\$ 42.00	\$ 42.00
6	BOOTLID INSULATOR <i>new</i>	1	\$ 162.00	\$ 162.00
7	BOOTLID HINGE <i>new</i>	2	\$ 83.60	\$ 167.20
8	BOOTLID REFLECTOR <i>cracked</i>	2	\$ 355.20	\$ 710.40
9	BOOTLID LOCK <i>Dented</i>	1	\$ 324.90	\$ 324.90
10	BOOTLID LOCK CATCH <i>new</i>	1	\$ 125.60	\$ 125.60
11	BOOTLID WEATHERSTRIP <i>cut</i>	1	\$ 178.60	\$ 178.60
12	REAR NUMBER PLATE LAMP <i>new</i>	2	\$ 64.90	\$ 129.80
13	REAR NUMBER PLATE LAMP GARNISH <i>new</i>	1	\$ 168.50	\$ 168.50
14	REAR BUMPER <i>Dislatched</i>	1	\$ 856.00	\$ 856.00
15	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 62.50	\$ 125.00
16	REAR TAIL LAMP <i>cracked</i>	2	\$ 528.70	\$ 1,057.40
17	REAR TAIL LAMP PANEL <i>Repair Rtl Dented</i>	2	\$ 211.00	\$ 422.00
18	REAR TAIL LAMP LOWER BRACKET <i>new</i>	2	\$ 56.80	\$ 113.60

669.40

760.

211

+

19	REAR FENDER <i>Repairs</i>	2	\$ 225.00	\$ 450.00	+
20	REAR END PANEL <i>Dented</i>	1	\$ 540.50	\$ 540.50	✓ 316.
21	REAR END PANEL TOP GARNISH <i>Del'd</i>	1	\$ 138.60	\$ 138.60	✓
22	REAR FLOOR PANEL <i>Repairs</i>	1	\$ 1,165.40	\$ 1,165.40	+
23	REAR FLOOR PANEL TOP BOARD <i>Del'd</i>	1	\$ 238.70	\$ 238.70	✓
24	SPARE TYRE TOOL SPONGE <i>New</i>	1	\$ 163.00	\$ 163.00	+
25	REAR EXHAUST CHROME PIPE <i>?</i>	1	\$ 865.00	\$ 865.00	+
26	REAR EXHAUST INSULATOR <i>New</i>	1	\$ 220.00	\$ 220.00	+
27	REAR EXHAUST MOUNTING	4	\$ 45.20	\$ 180.80	+

4792.10

TOTAL PRICE \$ 9,622.50

3833.68

LESS 20% \$ 1,924.50

SUB TOTAL PRICE \$ 7,698.00

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>Best</i>	1	\$ 50.00	\$ 50.00	✓
2	BOOTLID SEALANT <i>New</i>	1	\$ 100.00	\$ 100.00	+
3	REAR BUMPER CLIP (SET) <i>New</i>	1	\$ 20.00	\$ 20.00	✓
4	TAILLAMP PANEL SEALANT <i>New</i>	2	\$ 60.00	\$ 120.00	+
5	REAR WINDSCREEN SEALANT <i>New</i>	1	\$ 100.00	\$ 100.00	+
6	REAR END PANEL TOP GARNISH CLIPS (SET) <i>New</i>	1	\$ 20.00	\$ 20.00	10
7	REAR END PANEL INSULATION SEAL <i>New</i>	1	\$ 180.00	\$ 180.00	60
8	REAR FLOOR PANEL INSULATION SEAL <i>New</i>	1	\$ 180.00	\$ 180.00	+
9	TRIANGLE BREAKDOWN SIGN <i>New</i>	1	\$ 150.00	\$ 150.00	+
10	REVERSE SENSOR <i>Damaged</i>	1	\$ 220.00	\$ 220.00	20

340

TOTAL \$ 1,140.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,600.00	800	
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,400.00	800 1000	
3	TUFF COAT	\$ 250.00	60	
4	WIRING CHECK	\$ 180.00	30	
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY AND ROOF LINING TO FACILITATE REPAIR	\$ 180.00	60	
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50	

7	TRANSFER BOOTLID MECHANISM	\$	80.00 60	
8	CONDUCT WATER LEAKAGE TEST	\$	80.00	X
9	REMOVE AND REFIX REAR EXHAUST PIPE	\$	180.00	X
10	REMOVE AND REFIX REAR WINDSCREEN	\$	150.00	X
11	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$	180.00	X

TOTAL

\$4,360.00

2060

ESTIMATE REPORT

TOTAL PARTS COST : \$ 8,838.00
TOTAL LABOUR COST : \$ 4,360.00
TOTAL REPAIR COST : \$ 13,198.00

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

FAX :

PART BY PART / LUMP SUM :

NO OF DAYS :

Adrian hiny
2/s 08/03/19.

Supplementary: 464 06 days.
total 6697.68
4/s 5.3K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: AIG	DATE	: 8-Mar-19
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SLU4708M		
MODEL	: HONDA CIVIC 1.6L		
CHASSIS NO			
<u>ACCIDENT DETAILS</u>	DATE : 7-Mar-19		
	TIME : 08:45HRS		
THIRD PARTY REQUESTOR / CONTACT	: JACK LI		

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR REVERSE SENSOR <i>2x20 3pins</i>	4	\$ 255.80	\$ 1,023.20
2	REAR REVERSE SENSOR COVER <i>Nu</i>	4	\$ 88.50	\$ 354.00

TOTAL PRICE \$ 1,377.20

LESS 20% \$ 275.44

SUB TOTAL PRICE \$ 1,101.76

580

464

540
40