

INSUR

INS. CASE OWNER:

JNS

CC 4 ASM / AXA1900

4744, 5/2/19

LKK: IDAC:

Surveyor:

STOVE

DOI:

ASSIGNMENT

12/7/19

Date/Time:

11/7/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SGP 1546T

Claim No.:

SM11G84 / 107077

Name of Insured:

EMKRO CORPORATION VIL

Policy No.:

CA3195701

Insured Tel No.:

HP:

Make / Model:

CATER

Excess Sec II :SS

D.O.A.:

4/7/19

Place of Accident:

RD 1 SOUTH BUNKER

Is driver the owner? ( YES / NO )

Nature of Accident:

If NO, Driver Name / Age:

PAE KHEWA 51004

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO )

Insured Liability:

Final ? Yes / No

FB 6113L



INSRS: WSP: Tel: Liability: RMKS:

SG98



INSRS: WSP: Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:

Date/Time	STAGE	DATE / PIC
2/19 -	Recd Adv CAR from both parties. Send LOI.	
2/19 -	* amendment - virtual	
2/19 -	All date no PIR given from p. Call AXA	
2/19 -	submit wp inform weds to submit claim	
	divulge to AXA if no PIR.	

**PRELIMINARY ADVICE** Date/Time: \_\_\_\_\_ Sent By: \_\_\_\_\_

**FINALIZATION** Date/Time: \_\_\_\_\_ Confirm with: \_\_\_\_\_ Confirm by: \_\_\_\_\_

Repair Cost: 46 \$S 2400.00 | 4 days | Reduction:  Email  Call

**FINAL SETTLEMENT** Date/Time: \_\_\_\_\_ Confirm with: \_\_\_\_\_ Email  Call

Final Liability: % (Agreed / Assessed) BOLA S/N No. : \_\_\_\_\_ If NO or B 28, Ass. Lia: \_\_\_\_\_

Repair Cost: \$S \_\_\_\_\_

Loss of Rental (LOR): \$S \_\_\_\_\_ ( \_\_\_\_\_ days)

Loss of Use (LOU): \$S \_\_\_\_\_ (\$ \_\_\_\_\_ x \_\_\_\_\_ days)

Loss of Income (LOI): \$S \_\_\_\_\_ (\$ \_\_\_\_\_ x \_\_\_\_\_ days)

LOR only  LOU only  LOR + LOU  LOR + LOI  [Tick only one]

GIALTA Search: \$S \_\_\_\_\_

Medical: \$S \_\_\_\_\_

Disbursement: \$S \_\_\_\_\_ (e.g. Tow/ Independent)

Legal Cost: \$S \_\_\_\_\_

**Total:** \$S \_\_\_\_\_ **Global Sum \$S:** \_\_\_\_\_

**FINAL PAYMENT** Date/Time: \_\_\_\_\_ Confirm with: \_\_\_\_\_ Email  Call

Payee 1: \$S \_\_\_\_\_ Name 1: \_\_\_\_\_

Payee 2: (Strike if N.A.) \$S \_\_\_\_\_ Name 2: \_\_\_\_\_

Payee 3: (Strike if N.A.) \$S \_\_\_\_\_ Name 3: \_\_\_\_\_

Handwritten signature/initials

Handwritten initials



Steve (LKK)

with Privilege 12/3/19, 11.00 am  
4 days L/S, Reng AL spray

# SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 69622  
Tel: 6452 4888 Fax: 6452 4868 Linda  
Email: sg\_motor\_enterprise@yahoo.com.sg

Date: 12 March 2019

To : LKK

Attn: Steve

By Fax: 6256-4315

Tel: 83228913

VEHICLE NO : FB 6113L  
ACCIDENT DATE: 4 March 2019

Vespa PX 200

Description	Qty	Quotation \$
1 Head Lamp / OR	1	300.00 ✓
2 Meter Top Cover X NAI	1	160.00 X
3 Front Mudguard X R	1	250.00 X
4 Handle Bar / BT	1	190.00 ✓
5 Side Mirror X NN	2	150.00 X
6 Brake Lever - BR (PR)	1	160.00 26 ✓
7 Clutch Lever X NAI	1	95.00 X
8 Fork X NAI	1	320.00 X
9 Front Rim X NN	1	350.00 X
10 Front Shock Absorber X NAI	1	450.00 X
11 Steering Cone / Bearing - AIEC	1	150.00 75 ✓
12 Wheel Shaft X NAI	1	135.00 X
13 Body Beading / BD	1 set	550.00 ✓
14 Front Signal RH/LH / OR	2	190.00 110 ✓
15 Rear Tail Lamp - OR	1	195.00 ✓
16 Exhaust Pipe X NAI	1	650.00 X
17 Rear Suspension X NAI	1	450.00 ✓
18 Rear Rim RH X NAI	1	255.00 X
Sub-Total		5,000.00 1446
Less 10%		500.00 -102
Sub-Total		4,500.00 1301.40

forward to Steve  
22/3/19

labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion. Thank you

SG 98 MOTOR PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis



**Steve Chen (LKK Auto)**

---

**From:** Sg Motor <sgmotor2000@yahoo.com.sg>  
**Sent:** Friday, July 05, 2019 12:18 PM  
**To:** Steve Chen (LKK Auto)  
**Subject:** Re: Finalize FB6113L

Ok we accept.

Thank You

Regards  
Leena

**SG 98 Motor Pte Ltd**  
Blk 4001 #01-21  
Ang Mo Kio Industrial Park 1  
Singapore 569622  
Tel: 64524898 Fax: 64526898

On Monday, 24 June 2019, 07:36:08 pm GMT+8, Steve Chen (LKK Auto) <[SteveChen@lkkauto.com](mailto:SteveChen@lkkauto.com)> wrote:

Dear Leena,

The finalize is \$2400 (L/S, before GST), 4 repair days.

Kindly confirm.

Thanks

Best Regards,

**Steve Chen** | Assistant Automotive Assessor

*Sg 9x  
- VERIFIED  
- BIKE AT MAKE WORK*

## Service Request Details

Claim

S9M01G84

Reference

None 

Loss Date

4 March 2019

Report Date

7 Mar 2019 11:12:35 AM

Request Date

8 March 2019

Due Date

11 March 2020

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

### Actions

Next Step

Finish the work

Complete Work	Assign 
---------------	--

### Vehicle Information

Incident Vehicle Registration #

FB6113L

Make

TPVD

Model

UNKNOWN

Primary Contact/Insured

---

ENGRO CORPORATION LIMITED  
29 INTERNATIONAL BUSINESS PARK, #08-05/06 ACER BLDG TOWER B, 609923, Singapore  
63380083  
JEUNESSE@VIRTUALINVEST.BIZ

Claim Handler

---

TAN Jas  
6568804844  
jas.tan@axa.com.sg

Additional Instructions  
Virtual Account please do not finalise repair. thanks.

[Messages](#)   [Invoices](#)   [History](#)   [Documents](#)   [Assessment](#)   [Metrics](#)   [Notes](#)

---

[New Message](#)

# SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569822

Tel: 6452 4898 Fax: 6452 4868

Email: sg\_motor\_enterprise@yahoo.com.sg

Date: 12 March 2019

To : LKK

FB 6113L

By Fax: 6256-4315

Attn :

Tel:

VEHICLE NO : FB 6113L

Vespa PX 200

ACCIDENT DATE: 4 March 2019

<u>Description</u>	<u>Qty</u>	<u>Quotation \$</u>
1 Head Lamp	1	
2 Meter Top Cover	1	
3 Front Mudguard	1	
4 Handle Bar	1	
5 Side Mirror	2	
6 Brake Lever	1	
7 Clutch Lever	1	
8 Fork	1	
9 Front Rim	1	
10 Front Shock Absorber	1	
11 Steering Cone / Bearing	1	
12 Wheel Shaft	1	
13 Body Beading	1 set	
14 Front Signal RH/LH	2	
15 Rear Tail Lamp	1	
16 Exhaust Pipe	1	
17 Rear Suspension	1	
18 Rear Rim RH	1	
	Sub-Total	0.00
	Less 10%	0.00
	Sub-Total	0.00

1/2

Survey at:

Leang Shop

No 25 Kadal Kulait Rd 4

#1 01-71

Tel 98921618

VEHICLE NO : FB 6113L

Vespa PX 200

Nett Items

1	Number plate - Sticker	
2	Front Box	
3	Box Lid	
4	Rear RH side box	
5	Rear LH side box	
6	Towing fee	120.00
7	Remove & replace necessary parts, welding where necessary, re-shape body dents & etc	480.00
8	Remove & replace fork, shock absorber, steering shaft, rim & etc	250.00
9	Putty & respray paint work	650.00
	Sub-Total	1,500.00
	Nett Total	1,500.00

NB. This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly

Kindly revert upon completion. Thank you

**SG 98 MOTOR PTE LTD**

2/2



## Re:RE: PIR

Type

📍 Question

Message

please close your case and advse workshop to submit claim to us directly if no PIR given. thanks.

Reply

## Cecilia Chong (LKK Auto)

---

**From:** Cecilia Chong (LKK Auto)  
**Sent:** Thursday, 26 March 2020 10:43 AM  
**To:** Sg Motor; Sg Motor  
**Subject:** RE: Our Ref: FB 6113L

WITHOUT PREJUDICE

Dear Leena,

We have our principal's instruction to close the matter at our end.

As till date we have yet to hear from you in regards to the PIR.

Kindly submit claim directly to our principal AXA Insurance Pte Ltd if there is NO PIR.

Thanks

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

*Best Regards,*

*Cecilia Chong | Case Handler*

*LKK Auto Consultants Pte Ltd*

*Phone: 6749-4274 | email: CeciliaChong@lkkauto.com | fax: 6741-4108*

*Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)*



Auto  
Consultants  
Pte Ltd

*Save the Earth. Print only when necessary.*

---

**From:** Cecilia Chong (LKK Auto)  
**Sent:** Friday, 17 January 2020 12:01 PM  
**To:** Sg Motor <sgmotor2000@yahoo.com.sg>; Sg Motor <sg\_motor\_enterprise@yahoo.com.sg>  
**Subject:** RE: Our Ref: FB 6113L

WITHOUT PREJUDICE

Dear Leena,

We are still pending for evidence from your end.

However, till date, nothing was given.

Kindly provide us a copy of PIR to review the matter.

Thanks



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19004344/Ega3q2

8 SHENTON WAY #24-01  
AXA TOWERSINGAPORE 068811

Date : 03-04-2020



ATTN:JAS

Code : ASM

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGP 1546T	Veh. Inspected	FB 6113L
Policy No.	GA319570/1	Coverage (\$)	0.00
Claim No.	S9M01G84	Excess (\$)	0.00
Assign From		Assign Date	11/03/2019

## 2. Vehicle Particulars & Condition

Make & Model	PIAGGIO	c.c	200
Engine No.	HIDDEN	Year of Reg.	1983
Chassis No.	VSX1T177452	Colour	SILVER
Odometer	3601	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	3.5-10	MITAS	6 mm
L/H Front Tyre			mm
R/H Rear Tyre	3.5-10	MITAS	6 mm
L/H Rear Tyre			mm

## 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR & FRONT PORTION.  
DAMAGES SEE DETAILS.

## 5. General Information

Accident Date	04/03/2019	Inspection Date	12/03/2019
Survey held at	25 KAKI BUKIT RD 4 # 01-71		
Repairer	SG 98 MOTOR PTE LTD		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

## 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FB 6113L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	HEAD LAMP (CONSISTENT)	BROKEN	300.00	300.00
1	METER TOP COVER (CONSISTENT)	NOT NECESSARY	160.00	-
1	FRONT MUDGUARD (CONSISTENT)	TO REPAIR SEE LABOUR	250.00	-
1	HANDLE BAR (CONSISTENT)	BENT	190.00	190.00
2	SIDE MIRROR (CONSISTENT)	NOT NECESSARY	150.00	-
1	BRAKE LEVER (CONSISTENT)	BROKEN	160.00	26.00
1	CLUTCH LEVER (CONSISTENT)	NOT NECESSARY	95.00	-
1	FORK (CONSISTENT)	NOT NECESSARY	320.00	-
1	FRONT RIM (CONSISTENT)	NOT NECESSARY	350.00	-
1	FRONT SHOCK ABSORBER (CONSISTENT)	NOT NECESSARY	450.00	-
1	STEERING CONE/BEARING (CONSISTENT)	NECESSARY	150.00	75.00
1	WHEEL SHAFT (CONSISTENT)	NOT NECESSARY	135.00	-
1	SET BODY BEADING (CONSISTENT)	DENTED	550.00	550.00
2	FRONT SIGNAL RH/LH (CONSISTENT)	BROKEN	190.00	110.00
1	REAR TAIL LAMP (CONSISTENT)	BROKEN	195.00	195.00
1	EXHAUST PIPE (CONSISTENT)	NOT NECESSARY	650.00	-
1	REAR SUSPENSION (CONSISTENT)	NOT NECESSARY	450.00	-
1	REAR RIM RH (CONSISTENT)	NOT NECESSARY	255.00	-
	LESS 10% DISCOUNT		-500.00	-144.60
			4,500.00	1,301.40
<b>SPECIAL NETT ITEMS</b>				
1	NUMBER PLATE -STICKER (SN) (CONSISTENT)	NECESSARY	95.00	20.00
1	FRONT BOX (SN) (CONSISTENT)	DENTED	135.00	135.00
1	BOX LID (SN) (CONSISTENT)	DENTED	150.00	150.00
1	REAR RH SIDE BOX (SN) (CONSISTENT)	DENTED	180.00	180.00
1	REAR LH SIDE BOX (SN) (CONSISTENT)	DENTED	180.00	180.00
			740.00	665.00
<b>LABOUR</b>				
	TOWING FEE.		120.00	30.00

Report Ref No. CC4/ASM19004344/Ega3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE & REPLACE NECESSARY PARTS, WELDING WHERE NECESSARY, RESHAPE BODY DENTS & ETC. INCLUSIVE OF THE REPAIR OF FRONT MUDGUARD.		480.00	450.00
	REMOVE & REPLACE FORK, SHOCK ABSORBER, STEERING SHAFT, RIM & ETC.		250.00	150.00
	PUTTY & RESPRAY PAINT WORK.		650.00	400.00
			1,500.00	1,030.00
	<b>GRAND TOTAL</b>		<b>6,740.00</b>	<b>2,996.40</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>2,400.00</b>

Report Ref No. CC4/ASM19004344/Ega3q2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

### Service Request Details

Claim	SPM01G84	Vehicle Information	Incident Vehicle Registration #	FB6113L
Reference	CCA/ASM1900344-Eg302	Make	Model	TPWD UNKNOWN
Loss Date	4 March 2019	Service Address	...	
Report Date	7 Mar 2019 11:12:35 AM	Primary Contact/Insured	ENRO CORPORATION LIMITED 29 INTERNATIONAL BUSINESS PARK, #08-05/06 ACER BLDG TOWER B, 609923, Singapore 63380083 JELUNESSE@VIRTUALINVEST.BIZ	
Request Date	8 March 2019	Claim Handler	TAN Jas 656804844 jas.tan@axa.com.sg	
Due Date				
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)			
Type of Loss	Third Party Vehicle Damage			
Services	Pending verification - Direct Settlement			

**Actions**

Next Step: Wait for Approve Invoice

Add Invoice

Additional Instructions: Virtual Account please do not finalize repair, thanks.

Messages Invoices History Documents Assessment Metrics Notes

Document Type:

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
LKKInvoice1.pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	6 April 2020

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 LKKInspection (1).pdf	Forms / Claim Documents	Others	LKK-AUTO CONSULTANTS PTE LTD (TP)	6 April 2020
 LKKAdjustment11.pdf	Forms / Claim Documents	Others	LKK-AUTO CONSULTANTS PTE LTD (TP)	6 April 2020
 LKK SURVEY PHOTO.pdf	Reports & Statement	Others	LKK-AUTO CONSULTANTS PTE LTD (TP)	26 March 2020
 LKK RESURVEY PHOTO.pdf	Reports & Statement	Others	LKK-AUTO CONSULTANTS PTE LTD (TP)	26 March 2020
 EMAIL TP DD 26022020.pdf	Reports & Statement	Others	LKK-AUTO CONSULTANTS PTE LTD (TP)	26 March 2020
 Insured GIA Report (SGP 15467).pdf	Reports & Statement	GIA Report	DHIWAR Namrata	7 March 2019
 TP SGP8-EMAIL FROM WORKSHOP FOR TP REQ.mpeg	Letters and Correspondence	Others	NIKAM Sanjosh Pavalarang	7 March 2019