Denise Tay (LKKAuto)

From:

Denise Tay (LKKAuto)

Sent:

Tuesday, 12 March 2019 2:29 PM

To:

'Claims Dept'; SUR

Subject:

RE: OD CLAIM FOR SKL 8550 H

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle SKL 8550H (Excess \$1000/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | 5(408933)

From: Claims Dept <claims@premiumauto.com.sg>

Sent: Tuesday, 12 March 2019 12:30 PM

To: SUR <sur@lkkauto.com>

Cc: 'Claims Dept' <claims@premiumauto.com.sg>

Subject: RE: OD CLAIM FOR 8550 H

Dear All,

Attached is the GIA Addendum report and repair estimates for your kind reference. Survey has been carry out by Adrian at 8/3/2019.

Kindly assist to follow up repair approval.

Thank you.

Best regards, Kelvin Khoo

Premium Automobiles Pte Ltd (Neg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

View Received Message

This mail is associated with:

*SKL8550H (4063494776SG)

OD Feb 26 2019 12:35PM [LIU JUN] Premium Automobiles Pte Ltd

From	AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 12/03/2019 12:45 PM.
To	LKK_HQ
Subject	Alert - Adj Mandate Approved (\$\$9792.00) - SKL8550H - Claim Handler: Md Ishak, Mohd Imran
DOCUM	ENTS SUMMARY

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:

AIG Asia Pacific Insurance Pte. Ltd.

AIG Building

78 Shenton Way #08-16 Singapore 079120

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park

Singapore 408933

Attn:

Date:

11 Mar 2019

Preliminary Advice

Vehicle No

: SKL8550H

Accident Date

: 26/02/2019

Make

Policy No.

: 2100364322-04

: AUDI Q5

Assignment Date

: 11/03/2019

Excess

: \$\$0.00

Date of Inspection

: 08/03/2019

Est. Duration of Repair

: 5.00

Inspection At

: PREMIUM AUTOMOBILES PTE LTD (UBI)

55 UBI ROAD 1

SINGAPORE 408699

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	15,722.00
Revised Amount	:S\$	9,792.00
Check Items (Estimated)	:S\$	729,00
Total	-88	10.521.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
-------------------	------

90.000.00 Pre-Accident Value :8\$ COE / PARF Rebate :S\$ 75,021.00

:S\$ Salvage Value

:S\$ 14,979.00 Margin for Repair

Remarks

(X)	The vehicle is repairable at our a	idjusted amount.	We have	also	confirmed	excess	and	policy	coverage.	Kindly
	let us have your authorisation.									

ä ä)	The vehicle	is uneconomical	to	be repaired.	you are	advised	to	invite	tender	for	the	wrec	k
-----	---	-------------	-----------------	----	--------------	---------	---------	----	--------	--------	-----	-----	------	---

Other comments:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

ehicle Owner Particulars	Singapore NRIC
Owner ID Type: Owner ID:	8315Z
Vehicle Details	03132
Vehicle No.:	SKL8550H
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Mar 2019
Vehicle Make:	AUDI
Vehicle Model:	Q5 2.0 TFSI QUATTRO (EU6)
Primary Colour:	Black
Manufacturing Year:	2013
Engine No.:	CNC027633
Chassis No.:	WAUZZZ8R6EA040814
Maximum Power Output:	165.0 kW (221 bhp)
Open Market Value:	\$45,202.00
Original Registration Date:	30 Dec 2013
First Registration Date:	30 Dec 2013
Transfer Count:	1
Actual ARF Paid:	\$55,283.00
Intended PARF Rebate Details	\$33,200.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Dec 2023
PARF Rebate Amount:	\$38,698.00
Intended COE Rebate Details	The second of th
COE Expiry Date:	29 Dec 2023
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$77,501.00
COE Rebate Amount:	\$36,323.00
Total Rebate Amount:	\$75,021.00

The information contained herein is correct as at 11 Mar 2019

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- Any false reporting may be referred to the Police for investigation.
 This report will be forwarded by the insurers of the GiA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

By the lodgement of this report to the insurers, you hereby consideresaid.	sent to the archiving of this report at the centre and to copies of the report being made available
	ACCIDENT STATEMENT
Date Of Report	26/02/2019 16:38
Date Of Accident	26/02/2019 12:35
Exact Location Of Accident	51 SOON LEE ROAD
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SKL8550H
Insured/Policyholder	
Name Of Registered Owner	LIU JUN
NRIC No	S7168315Z
Email Address	YUECHENG@LIVE.COM.SG
Mobile Phone No	(LOCAL) +65-96988666
Alternative Phone No	OTHERS-96988666
Vehicle Particulars	
Manufacturer	AUDI
Model	Q5 2.0 TFSI QU
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE

Are you claiming under your own insurance policy

for repair to your vehicle?

THIRD PART If No, Please state action to be taken

Vehicle Category

for clavins.

PRIVATE CAR

Insurance Company

Name of Insurance Company AIG ASIA PACIFIC INSURANCE PTE. LTD.

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number 2100364322-04

Cover Note Number

Driver

Name of Driver LIU JUN NRIC No S7168315Z Date Of Birth 06/09/1971 Occupation INDOOR Date Of Driving Pass 17/05/2007

Driving Experience 11 YEARS AND 9 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-96988666

Fax Number

Contact Number OTHERS-96988666

EMail Address YUECHENG@LIVE.COM.SG

BLK 867 TAMPINES STREET 83 Address

#10-247

Postcode 520867

Was driver an employee of the Insured's Company NO

If No. Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident COLLISION - MAJOR/MINOR RD

Weather Conditions CLEAR Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle)

involved in the accident

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

ambulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

YES

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

WHEN I WAS STOP AND WAITING TO TURN RIGHT TO EXIT THE CARPARK, AS A CAR STOP IN FRONT OF ME. SUDDENLY A LORRY REVERSED AND HIT INTO MY CAR FRONT LHS.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

GBC1258C

Vehicle Make/Model/Colour

MIAH KAWCHER

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

G2317707U

Contact Number

84697410 / 87863782 / 65055508

Address

Postcode

Insurance Company Name

SOMPO INSURANCE SINGAPORE PTE. LTD.

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudlate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- E. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me,
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- [d] my Personal information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed
 - to all mourers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Pulleyfloider's Signation Date & Time:

Oriver's Signature (If striver is not the policyholder) Date & Time: Name: Which Extends Stands Facory NAME: Which Extends Stands Facory NAME/FORNIO: G.1987-954


Sketch Plan #2

SKETCH PLAN	Ext Co	arpark
		A-Sk:85
		71 34283
		B-
	A6 A	
	I A	
DESCRIBE CIRCUMSTANI	to turn right to Exit the Sunddenly on librar reprised	compare as a our stop
Car fant US-	sunching a long released	and left into mix my my
(D) 191 513		
DECLARATION		(399.6)
I/We declare the foregoing pa	disculars are true in every respect.	
Policypoliter's Signature Class & Time:	Other's Signature (if driver is not the policyholder) Date & Time:	Reporting Centre Persistent's Signature Ratter butch schools Signature NRIC/FIN No.: Co. 1937-1954





COUNTY of birth







CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder

: LIU JUN

Period of Insurance

: 30 Jun 2018 To 29 Jun 2019

Engine No.

: CNC027633

Chassis No.

: WAUZZZ8R6EA040814

Vehicle No.

: SKL8550H

Policy No.

: 2100364322-04

Endorsement No.

Issued Date

: 01 Jun 2018

ABOUT THE COVER

Make/Model

- NA

: AUDI Q5 2.0 TFSI QU (FACELIFT)(DYNAMIC STEERING) Engine Capacity/Tonnage: 1,984.00 CC

Sum Insured : Market Value

First Year of Registration : 2013

Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive":

a) The Policyholder

Driver Restriction

b) Any other person who is driving on the Policyholder's order or with his/her permission.

This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Inesperienced Driver Excess" ("IDR") if You are or Your Authorised Driver (named or unnamed) has less than 2 years' driving experience.

Off Peak Car : No

Age Condition

: 40 years old and above

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for him or reward, driving fullow, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$1000 Theft - \$0 Flood Cover - \$0

Section 2

Property Demage - \$0

Windscreen: \$100

Named Driver and Excess (where applicable)

LIU JUN - \$1000 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS).

1 Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other: Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotine at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sp or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

I/We hemby certify that the policy to which the Certificate of Insurance relates is inused in accordance with the provisions of the Motor Vehicles (Third Party Rinks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Rinks) Rules, 1959 (Mullaysia)

0504125233

PREMIUM LEASING -DC

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE

SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd. **AUTHORISED REPRESENTATIVE**

AIG Asia Pacific Insurance 11st 145.

24-HOUR AIG AUTO HOTLINE: +65 6338 6200

IMPORTANT: KEEP THIS DOCUMENT IN YOUR CAR AT ALL TIMES.

What can the 24-hour AIG Auto Emergency Hotline provide for you?

- Immediate assistance after an accident
- Emergency breekdown service
- Towing service (accident or non-accident related)
- Advice on Motor Claims procedures
 - Medical Referral Assistance

What should I do in the event of an accident?

- Keep palm and move your car to a safe place.
- Do not admit or discuss fault or blame with the other party(les)
- Report the accident to us with your accident vehicle (whether damaged or not)
 via our approved reporting centres or authorised repairers within 24 hours or the
 next working day of the accident.
- Submit Writ/Summons/Correspondences from third party(ies) to AIG immediately.

If no one is injured in the accident:

- · You are not required to make any police report.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s).
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

If the accident involves injuries or damage to government property & vehicles, foreign registered vehicles or non-injury hit & run case:

- Report the accident to the police, providing full details of the circumstances of the accident.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s), if applicable.
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

LOSS OF USE CAR REPLACEMENT BENEFIT

Applicable only if this benefit is included in your motor insurance. Please refer to your Policy Schedule for details. Policy terms and conditions apply. Please call our customer service hotline number (65) 6419-3000 for assistance.

The Certificate of Insurance (CI) should be produced without demand when collecting the Rental Car and the Rental Car Company reserves the right to verify the identity of the holder. The CI is the property of AIG and its use is subject to the terms and conditions contained in the Loss of Use Endorsement under the policy issued to the policyholder.

Steps to activate Loss of Use Car Replacement Benefit and Important Information

- To activate your loss of use car replacement, please contact the Rental Car Company (listed below) after filing/reporting your accident claim.
- 2. Your rental car will be made available within 5 working hours of activation with the Rental Car Company.
- At the time of collection of the Rental Car, the original insurance policy and schedule issued by AIG, a copy of the Accident Report from Audi Customer Service Centre must be produced.
- The number of days is based on the period your vehicle is in the repair workshop unless the number of days of loss of use entitlement is stated in the Policy.
- 5. Rental cars are strictly for use in Singapore only.
- Extension of rental beyond repair period approved by AIG surveyor will be chargeable by the Rental Car Company on per day basis.
- Upgrade of Rental Car is available upon request subject to additional charges by the Rental Car Company.

Rental Car Company: Popular Rent A Car Pte. Ltd.

Activation Hotline: 67428888

501 Guillemard Road Singapore 399840

Operation Hours: Monday to Friday: 9am to 6pm Saturday (Half Day): 9am to 4pm

"The Rental Car Company's Terms & Conditions apply (i.e., refundable security deposit, excess sability for the Rental Car, Collision Damage Waiver, etc.)

IMPORTANT NOTICE

If you sell your motor vehicle, this Notice is IMPORTANT and MUST be complied with. Policyholders are hereby warned that under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.99), it shall be unlawful for any person to use or cause or permit any other person to use a motor vehicle without a valid policy of insurance under the Act.

The Policyholder is further warned that on the sale of a motor vehicle, they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.88).

This Policy will cease to be valid once the motor vehicle has been sold to another person unless the transfer of interest has been duly notified to and agreed to by the insurance company concerned. If the insurance company agrees to cover the new owner, they will issue a new Certificate of Insurance in the new owner's name. The premium chargeable may vary according to the new owner's profile.

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Accident Repairs Estimate Workshop Ubi Road 1 Contact No 6366 2323 : 6841 1183 Fax No

Reference PA/0D/0258/2019/GW

Date : 27-Feb-19

Vehicle IN workshop.

AXA Insurance Singapore Pte Ltd

8 Shenton Way #27-01 AXA Tower Singapore 068811

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax 6880 4838

Owner's Name Mr Jun Liu

Address Blk 867 Tampines St 83

#10-247

Singapore 520867

Telephone 96988666

Third Party Claims 0 D claim . Type of Claim

Policy No. 2100364322-04 : Vehicle No SKL 8550 H Model Code Audi Q5 2.0 TFSI Model / Year 30/12/2013 : Engine No CNC 027633

Chassis No WAUZZZ8R6EA040814

Mileage

Date In

Liability Excess Cost

Estimated By : Johnny Boo / Allan Wu

Accident Date : 26-Feb-19 Place of Accident : 51 Soon Lee Road

Premium Automobiles 55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKL 8550 H

S/n	Nature of Jobs		_	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assy and front parking aid	S/N	\$	480.00	//
2	To dismantle and renew front bumper, LHS front fender and headlight. Re-organize front crash management components. Reinstall all parts removed		s	2,450.00	1252/
3	To respray front bumper, bennet and RHS front fender and hinges.		\$	2,300.00	1650
4	To renew LHS front rim and carry out wheel alignment	S/N	S	280.00	+
5	To carry out diagnostic check.	S/N	s	192.00	//
	TOTAL LABOUR CHARGES	:	\$	5,702.00	

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKL 8550 H

C/N	David Barrella II	Damaged Parts			
S/N	Parts Description		S/Nett	Remark	
1	FRONT BUMPER COVER DEL	\$	2,353.00	1882.40	
2	FRONT BUMPER SPOILER	\$	569.00 ±		
3	FRONT BUMPER FIXING PARTS	s	249.00 €		
4	FRONT BUMPER SECURING STRIP - LH 🔑 🥌	5	34.00 £		
5	FRONT BUMPER GUIDE SECTION - LH Q d	\$	34.00	27-12	
6	FRONT FENDER - LH Devled	\$	913.00	730	
7	ATTACHMENT PARTS FOR FRONT FENDER-LH	5	61.00	×	
8	FRONT FENDER BRACKET - LH Bent	\$	49.00	37.56	
9	FRONT FENDER CENTER BRACKET - LH / RH 21H And	5	45:00 22	50 35.60	
10	FRONT FENDER REAR RRACKET - LH / RH	\$	45.00 223	35.60	
11	FRONT FENDER BRACE - LH BUT	5	79.00	67.64	
12	LINING FOR FRONT FENDER - LH RIVE NEW	5	174.00 7	10	
13	FRONT WHEEL HOUSING LINER - LH DULL	\$	246.00	19640	
14	ATTACHMENT PARTS FOR WHEEL HOUSING LINER	Ws	94.00	X	
15	HEADLIGHT-LH COULD	5	2,501.00	2000 700	
16	MOUNTING FOR MAIN BEAM HEADLIGHT - LH	\$	104.00	20-60 \$	
17	HEADLIGHT RETAINING PLATE - LH	\$	71.00 20	5032	
18	LED WITH HEAT SINK-LH	s	944.00 1		
19	FRONT ALUMINIUM RIM-LH	s	1,055.00 1		
20	SUDNRIES WE.	\$	400.00	57.52	
	TOTAL SPARE PARTS :	\$	10,020.00		
	TOTAL LABOUR CHARGES	\$	5,702.00		
	GRAND TOTAL	\$	15,722.00		

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

Ne Atlansed, 05 Days

Please Note

: This estimate is based on visual inspection of the affected vehicle.

Should we require further labour charges and spare parts in the

progress of repair, we shall inform you accordingly.

For inspection of vehicle, please refer to Ms Norah Khai at

Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo

Body Repair Manager

Allan Wu

Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel: (65) 6366 2323 Fax: (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept Regn No

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

Date Service Advisor

Pages

Model No

PA/00/0258/2019/GW

29-Mar-19 Glory Tan

1 of 1

SKL 8550 H

Audi Q5 2.0 TFSI

Quantity Description

Unit Price Amount

Parts

To respray bonnet and front bumper spoiler

1,550.00

TOTAL

\$ 1,650.00

1100.00

For Premium Automobiles Pte Ltd

Authorised Signature

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs

Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183

Reference : PA/TP/0258/2019/KN

Date : 27-Feb-19

Vehicle IN workshop.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 / Fax: 6256 4315

Owner's Name : Mr Jun Liu

Address : Blk 867 Tampines St 83

#10-247

Singapore 520867

Telephone : 96988666

Type of Claim : Third Party Claims
Policy No. : 2100364322-04
Vehicle No : SKL 8550 H

 Model Code
 ; Audi Q5 2.0 TFSI

 Model / Year
 ; 30/12/2013

 Engine No
 ; CNC 027633

Chassis No : WAUZZZ8R6EA040814

Mileage :

Date In :

Liability :

Excess Cost : -

Estimated By : Johnny Boo / Allan Wu

Accident Date : 26-Feb-19

Place of Accident : 51 Soon Lee Road

Hi Adrian 5 days - ck - jb - 15 Apr 19

Premium Automobiles 55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKL 8550 H

S/n	Nature of Jobs			Estimated Charges		urveyor's mmendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assy and front parking aid	S/N	\$	480.00	s	480.00
2	To dismantle and renew front bumper, LHS front fender and headlight. Re-organize front crash management components. Reinstall all parts removed		\$	2,450.00	\$	1,250.00
3	To respray front bumper, bonnet and RHS front fender and hinges.		\$	2,300.00	\$	1,650.00
4	To renew LHS front rim and carry out wheel alignment	S/N	\$	280.00		
5	Added labour - see attached		s	1,650.00	\$	1,100.00
6	To carry out diagnostic check.	S/N	\$	192.00	\$	192.00
	TOTAL LABOUR CHARGES	:	\$	7,352.00	\$	4,672.00

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKL 8550 H

			Damaged Parts & Prices					
S/N	Parts Description		S/Nett		Remark			
1	FRONT BUMPER COVER	s	2,353.00	\$	1,882.40			
2	FRONT SPOILER	\$	569.00					
3	FRONT BUMPER FIXING PARTS	\$	249.00					
4	FRONT BUMPER SECURING STRIP - LH	\$	34.00					
5	FRONT BUMPER GUIDE SECTION - LH	\$	34.00	\$	27.12			
6	FRONT BUMPER WING - LH	\$	913.00	\$	730.00			
7	ATTACHMENT PARTS FOR FENDER	\$	61.00					
8	FRONT BRACKET - LH	\$	49.00	\$	38.56			
9	FRONT CENTER BRACKET - LH / RH	\$	45.00	\$	35.60			
10	REAR RRACKET - LH / RH	\$	45.00	\$	35.60			
11	FRONT BRACE - LH	\$	79.00	\$	62.64			
12	LINING FOR FRONT FENDER - LH	\$	174.00					
13	FRONT WHEEL HOUSING LINER - LH	\$	246.00	\$	196.40			
14	ATTACHMENT PARTS FOR WHEEL HOUSING LINER	\$	94.00					
15	HEADLIGHT FOR GAS DISCHARGE BULB - LH	\$	2,501.00	\$	2,000.80			
16	MOUNTING FOR MAIN BEAM HEADLIGHT - LH	\$	104.00	\$	85.60			
17	RETAINING PLATE - LH	\$	71.00	\$	56.32			
18	LED WITH HEAT SINK	\$	944.00					
19	ALUMINIUM RIM	\$	1,055.00					
21	SUDNRIES	\$	400.00	\$	57.52			
	TOTAL SPARE PARTS	\$	10,020.00	\$	5,208.56			
	TOTAL LABOUR CHARGES	\$	7,352.00	\$	4,672.00			
	GRAND TOTAL	\$	17,372.00	\$	9,880.5			

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability :

Remarks :

Please Note

: This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the

progress of repair, we shall inform you accordingly.

For inspection of vehicle, please refer to Ms Norah Khai at

Tel:6768 9828 for appointment.

Yours faithfully, Premium Automobiles Pte Ltd

Johnny Boo

Body Repair Manager

Allan Wu

Claims Consultant

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Motor Claims Dept Yr Ref: SKL 8550 H Norah Khai 6768 9911 6841 1183 Nora.khai@premiumauto.com.sg

> Body & Paint Dept PA/OD/0258/2019/KS

> > 17 June 2019

from

Telephone +65-Telefax +65-

EMail

Our department

Our Ref Your Ref Date

total pages

Dear Sir.

RE: INSURANCE CLAIM FOR SKL 8550 H, Audi Q5 2.0 TFSI QU.

With reference to the above-mentioned vehicle, no. SKL 8550 H, claimant, Mr. Jun Liu, please find the related document per attached.

- A copy of the Original invoice no. 85013919 S\$9,502.20.
- 2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai Claims Dept

Encl AIG – SKL 8550 H total payes

Premium Automobiles Pte Ltd Showroom 9 Leng Kee Road Singapore 159090 Telephone (65) 6566 1111 Telefax (65) 6471 3733

Service & Parts Centres 55 Ubi Rd 1 Singapore 408699 Telephone (65) 6336 2323 Telefax (65) 684 11183

Premium Automobiles Pte Ltd



Customer

Audi Centre Singapore 281 Alexandra Road Singapore 159938 Main Telephone 6836 2223 Main Telefax 6471 3733

. .

Alexandra Service Centre 281 Alexandra Road Singapore 159938 Main Telephone 6386 2223 Main Talefax 6475 1023

Ubi Service Centre 55 Ubi Road Singapore 408699 Main Telephone 6388 2323 Main Telefax 6841 1183

Customer Service Service Appointment 24-hour Breskdown Service 9828 1233 customer care@premiumauto.com.sg

INS TAX INVOICE

Page

1

16:17

Company Reg. No. 199902271W GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD

MOTOR CLAIM DEPT AIG BUILDING

78 SHENTON WAY

#07-16

SINGAPORE 079120 079120

Invoice: 85013919

Account: A0006

17

AIG ASIA PACIFIC INSURANCE PTE LTD

0.3

Date: 14/06/2019

Order : SELB550H

MOTOR CLAIM DEPT AIG BUILDING

78 SHENTON WAY

#07-16

SINGAPORE 079120

Regn No: SKL8550H

177 22011) Regn Date: 30/12/2013

Mileage: 151259

WIP No.: 44209

Model: Q5 2.0 TFSI QU BRBOAA (MY 14) Chassis: WAUXZZBREEA040814

Term : 30

Engine: CNC 027633

Dept: U

9,502.20

Grand Total

You have been assisted by :- UB-Tony Foong

(33)

	Details	Qty	Unit Price	Amount
EXC	M: 8888	-1000.00	1.00	-1,000.00
REDWYDOR	Insurance Excess/Liability M: TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE	480.00	1.00	480.00
BODYWORK	SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING A M: TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND HEADLIGHT. RE-ORGANIZE FRONT CRASH	1250.00	1.00	1,250.00
BODYWORK	MANAGEMENT COMPONENTS, REINSTALL ALL PARTS REMOVED N: TO RESPRAY FRONT BUMPER, DOOR AND RHS FRONT FENDER	1650.00	1.00	1,650.00
BODYWORK	TO CARRY OUT DIAGNOSTIC CHECK.	192.00	1.00	192.00
BODYWORK	M: TO RESPRAY BONNET AND FRONT BUMPER SPOILER.	1100.00	1.00	1,100.00
A8R0821105A A8R0941043D A8R0821171K A8R0807065C GRU A8R0805607B A8R0821467A A8R0807283C A8R0821135 A8R0821469 A8R0821471 A8R0941453A A8K0010520A A8T0010515B AN 0161857 AN 90765701	FENDEB HEADLAMP Less 020% WHEEL HOUS COVER MOUNTING Less 020% (SK) BRACKET SUPPORT GUIDE SUPPORT Less 020%	1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00	912.50 2501.00 245.50 2353.00 107.00 48.20 26.50 33.90 78.30 44.50 70.40 12.20 6.40 3.00 1.40	730.00 2,000.80 196.40 1,882.40 85.60 38.56 21.20 27.12 62.64 35.60 35.60 56.32 9.76 5.12 19.20 2.24
Farts 5,208.56 Labour 0.00 Sublet 4,672.00 Menus 0.00	NO MORIES		Sub-Total 7% GST	8,880.56 621.64

Received by

For & on behalf of Premium Automobiles Pte Ltd

Telefax

to AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Motor Claims Dept Yr Ref: SKL 8550 H

Norah Khai 6768 9828

6841 1183

Body Repair

Mobile +65-Our department

Telephone +65-

+65-

Your Claim Ref

PA/OD/0258/2019/KK 3 April 2019

Our Ref Date

Telefax

from

1 total pages

CLAIM - OWNER'S SATISFACTION/DISCHARGE VOUCHER RE:

Make & Model Audi Q5 2.0 TFSI :

Vehicle Chassis No. WAUZZZ8R6EA040814

Vehicle Regn No. SKL 8550 H :

Vehicle Mileage 146206 KM :

Mr Jun LlU Vehicle Owner :

Certificate No 2100364322-04 :

\$1070.00 (Inclusive 7%GST) Own Damage Excess :

Accident Date 26/2/2019

Place 51 Soon Lee Road

\$ 9,500.20 Repair Cost :

WIP No. 44209 :

Premium Automobiles Pte Ltd Repairer's Name :

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature

Time

Date :

Premium Automobiles Pte Ltd

Showroom 9 Leng Kee Road Singapore 159090

Telephone (65) 6566 1111 Telefax (65) 6471 3733

Service & Parts Centres 55 Ubi Road 1 Singapore 408699

Telephone (65) 6366 2323 Telefax (65) 6841 1183

Merimen e-Claims Page 1 of 1

...CLAIM SUBFOLDER...(Pending for Survey Report)

LAIM SUBF	OLDER TRA	CKING								
Case	Notified	Est Submitted	Adj Assigned	Adj Rot	Ad	Submitted	Ins Auth'ed	Sta	tus	
Main	04 Mar 2019		11 Mar 2019 17:23 Edit Adj Rpt	5\$9,88 Edit E		9,880.56 lew Rpt		Rep	Pending for Survey Report Cancel Case	
,	fain:	R	eference		laim Details		Document	ts	52	IIA woo
CLAIM SUI	SFOLDER DE	TAILS				[Created	by insurer]			
Insured:	LIU JUN,	ID: 57168315Z,	Tel: +659698866	6, Email:	YUECHENGOL	IVE.COM.SG				
Vehicle Reg. No.:	SKL855	SKL8550H Date of Loss: 26/02/2019 12:00 - :59 [61 Months and 27 Days From LTA Reg Date (Man Yr)]						an Yr)]		
Claim Type:	pe: OD / 4063494776SG Policy/Cover Note No.: 2100364322-04 (Comprehensive)									
					Excess:	5\$1,000.00)			
Repairer:	Premium	Automobiles Pt	Ltd (UBI) 55 Ubi	Road 1, 40	8699 Ubi - Tel	67689828/9	827/9911			
Handling Insurer:	AIG Asia	Pacific Insuranc	e Pte. Ltd. (SG) -	Tel: 65-641	ı9-3000 [Hi	indled by Md	Ishak, Mohd Ir	mran] Im	ran.Ishak@	aig.com
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel: 62	56-3561	. [Handled by	ADRIAN LIN	G) [Final R	pt due :	20/03/201	9]
Driver/Custo dian:	LIU JUN (4	7 / Male) , NR3	C: 57168315Z, Te	1: +659696	38666 Email: Y	UECHENGOL	IVE.COM.SG			
ASSOCIAT	ED MAIL RE	CEIVED					VI	ew All	Compose (ase Mail
MASSOCIA!				A RESIDENCE OF STREET	A STATE OF THE PARTY OF THE PAR	CONTRACTOR OF STREET	The second secon			
AIG_SG AIG_SG	12/03/2019)	Alert - Adj Mar	date Approved (S date Approved (S D / 26/02/2019 /	\$9792.00	- SKL8550H	- Claim Han				
AIG_SG AIG_SG	12/03/2019)	: Alert - Adj Mar : SKL8550H / O	date Approved (S	\$9792.00	- SKL8550H	- Claim Han date	dler: Md Ishak		w Task	Complete

Claim Documents

*SKL8550H (4063494776SG) OD Feb 26 2019 12:35PM [LIU JUN] Premium Automobiles Pte Ltd

Ass	essment Reports		1 per	page 🔻	50
No.	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	11/03/19 17:33	Adjuster Immediate Advice	0	Load HTM	
Pho	tos/Images		3 per	page 💟	V
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	11/03/19 17:33	General View	0	Load JPG	V
2	11/03/19 17:33	Chassis Number	0	Load JPG	8
3	11/03/19 17:33	General View	0	Load JPG	50
4	11/03/19 17:33	General View	0	Load JPG	V
5	11/03/19 17:33	General View	0	Load JPG	V
6	11/03/19 17:33	General View	0	Load JPG	V
7	11/03/19 17:33	General View	0	Load JPG	V
B	11/03/19 17:33	General View	0	Load JPG	V
9	11/03/19 17:33	General View	0	Load JPG	2
10	11/03/19 17:33	General View	0	Load JPG	W
11	11/03/19 17:33	General View	0	Load JPG	V
12	11/03/19 17:33	General View	0	Load JPG	V
13	11/03/19 17:33	General View	0	Load JPG	52
14	11/03/19 17:33	General View	0	Load JPG	Ø
15	11/03/19 17:33	General View	0	Load JPG	Z
16	11/03/19 17:33	General View	0	Load JPG	[2]
	I Marie and Control of the Control o	0366/0300/03030	1.5		
Doc	umentation		I per	page V	V
No.	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	11/03/19 17:36	Singapore Accident Statement	0	Load PDF	
2	11/03/19 17:36	Certificate of Insurance	0	Load PDF	
3	11/03/19 17:36	Driver's Driving License	0	Load PDF	
4	11/03/19 17:36	ESTIMATE	0	Load PDF	
5	17/04/19 11:19	SUPPLEMENTARY ESTIMATE	0	Load PDF	
6	07/05/19 12:16	ESTIMATE MARKING	Ö	Load PDF	
7	19/06/19 15:34	Workshop Invoice	0	Load PDF	
В	19/06/19 15:34	Discharge Voucher	0	Load PDF	

Linked Accident Report Documents

Ass	ssessment Reports		1 per p	V	
No.	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnall	Print
1	26/02/19 17:01	Accident Statement	0	Load HTM	
2	08/03/19 13:33	Accident Statement Addm. #1	0	Load HTM	
3	08/03/19 14:01	Addendum Sheet	0	Load JPG	1

Merimen e-Claims Page 2 of 2

Ass	essment Reports		1 per p	page v	V
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
Pho	tos/Images		3 per ;	page 🔍	V
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnall	-
1	26/02/19 16:57	Accident Photo	0	Load JPG	Ø
2	26/02/19 16:57	Accident Photo	0	Load JPG	M
3	26/02/19 16:57	Accident Photo	0	Load JPG	V
4	26/02/19 16:57	Accident Photo	0	Load JPG	V
5	26/02/19 16:57	Accident Photo	0	Load JPG	N
6	26/02/19 16:57	Accident Photo	0	Load 3PG	N.
7.	26/02/19 16:57	Accident Photo	0	Load JPG	V
8	26/02/19 16:57	Accident Photo	0	Load JPG	V
9	26/02/19 16:57	Accident Photo	0	Load JPG	V
10	26/02/19 16:57	Accident Photo	0	Load JPG	V
11	26/02/19 16:57	Accident Photo	0	Load 3PG	V
12	26/02/19 16:57	Accident Photo	0	Load JPG	V
13	26/02/19 16:57	Accident Photo	0	Load 3PG	S
14	26/02/19 16:57	Accident Photo	0	Load JPG	V
15	26/02/19 16:57	Accident Photo	0	Load JPG	V
16	26/02/19 16:57	Accident Photo	0	Load JPG	V
17	26/02/19 16:57	Accident Photo	0	Load JPG	V
Dog	cumentation	•	1 per	page 🔻	52
No	Finanzed On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	26/02/19 16:48	Sketch Plan	0	Load JPG	V
2	26/02/19 16:48	Sketch Plan #2	0	Load JPG	V

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
	^
	~
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.	

LKK Auto Consultants Pte Ltd (Co Reg No. 199607198R)

51 Ubi Ave 1 #01-25, Pava Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.

AIG Building, 78 Shenton Way #08-16

Singapore 079120

Our File No:

CC3/AIG19004346/ATD3E2

Date:

19/06/2019

REFERENCE

Insured/Claimant: Date of Loss:

LIU JUN 26/02/2019 Policy No:

2100364322-04

Nature of Claim: OD Claim No:

4063494776SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SKL8550H

Make & Model:

AUDI Q5, 2.0 TFSI Quattro (A)

Engine No: Chassis No: CNC027633

Reg. Date:

Black

30/12/2013 (Man. Year: 2013)

Odometer:

WAUZZZ8R6EA040814 144964 km

Colour Engine Capacity:

1984 cc

Market Value/New Car Price: S\$90,000.00

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Engine Modification:

Yes Footbrake (Serviceable): Pre-accident Condition:

Yes

Handbrake (Serviceable): CONDITION OF TYRES

Front Tyre Size:

225/55 R19

Rear Tyre Size:

225/55 R19

Front Left Side: Front Right Side:

Michelin 6 mm Michelin 6 mm Rear Left Side: Rear Right Side: Michelin 6 mm Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		10,020.00	5,208.56	4,811.44	48.02
Miscellaneous Items		0.00	0.00	0.00	
Labour		7,352.00	4,672.00	2,680.00	36.45
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	17,372.00	9,880.56	7,491.44	43.12
	- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
	(S\$)	16,372.00	8,880.56	7,491.44	45.76
	+ GST 7.00/7.00% (S\$)	1,146.04	621.64	524.40	45.76
	Nett Amount (S\$)	17,518.04	9,502.20	8,015.84	45.76

INSPECTION

Date of Assignment:

11/03/2019

Date Inspected:

08/03/2019 Inspected At:

Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1

Singapore 408699

Estimated Period of Repair:

5.0 days

Adjuster: ADRIAN LING

Manager:

DENISE TAY KWEE CHENG

Adjuster Report Page 2 of 4

NOTE. This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER COVER	Deformed	2,353.00 FS	*1,882.40 FS
2	1		*FRONT BUMPER SPOILER	Not Necessary	569.00 FS	*-FS
3	1		*FRONT BUMPER FIXING PARTS	Not Necessary	249.00 FS	*-FS
4	1		*FRONT BUMPER SECURING STRIP - LH	Not Necessary	34.00 FS	*-FS
5	1		*FRONT BUMPER GUIDE SECTION - LH	Damaged	34.00 FS	*27.12 FS
6	1		*FRONT FENDER - LH	Dented	913.00 FS	*730.00 FS
7	1		*ATTACHMENT PARTS FOR FRONT FENDER - LH	Not Necessary	61.00 FS	*-FS
8	1		*FRONT FENDER BRACKET - LH	Bent	49.00 FS	*38.56 FS
9	1		*FRONT FENDER CENTER BRACKET - LH/RH	N/S Damaged	45.00 FS	*35.60 FS
10	1		*FRONT FENDER REAR BRACKET - LH/RH	N/S Damaged	45.00 FS	*35.60 FS
11	1		*FRONT FENDER BRACE - LH	Bent	79.00 FS	*62.64 FS
12	1		*LINING FOR FRONT FENDER - LH	Not Necessary	174.00 FS	*-FS
13	1		*FRONT WHEEL HOUSING LINER - LH	Deformed	246.00 FS	*196.40 FS
14	1		*ATTACHMENT PARTS FOR WHEEL HOUSING LINER	Not Necessary	94.00 FS	*-FS
15	1		*HEADLIGHT - LH	Cracked	2,501.00 FS	*2,000.80 FS
16	1		*MOUNTING FOR MAIN BEAM HEADLIGHT - LH	Damaged	104.00 FS	*85.60 FS
17	1		*HEADLIGHT RETAINING PLATE - LH	Damaged	71.00 FS	*56.32 FS
18	1		*LED WITH HEAT SINK - LH	Not Necessary	944.00 FS	*-FS
19	1		*FRONT ALUMINIUM RIM - LH	Not Necessary	1,055.00 FS	*-FS
20	1		*SUNDRIES	Necessary	400.00FS	*57.52 FS
F=Fra	nchise	part. S=Spc	Nett		10/00/00 - 20/00/00 TO	(Firefiel (Netherla)
				Total Parts (S\$)	10,020.00	5,208.56

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND HEADLIGHT. RE-ORGANIZE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,450.00	1,250.00
3	TO RESPRAY FRONT BUMPER, DOOR AND RHS FRONT FENDER AND HINGES	New	2,300.00	1,650.00
4	TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	0.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
6	TO RESPRAY BONNET AND FRONT BUMPER SPOILER	New	1,650.00	1,100.00
	Gross Labor	ur Cost (S\$)	7,352.00	4,672.00
	Report was unsubmitted during	this print-out.		

< END OF ESTIMATES >