

INS2010

INS. CASE OWNER:

Jas

CC 4/AXA1900

4750, R2665<sup>2</sup>

LKK:  
IDAC:

Surveyor:

Kasul

DOI:

ASSIGNMENT

11/2/19

Date / Time:

11/2/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

XE 7754B

Name of Insured:

PSIA MORTAR BLO

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

7/2/19

Is driver the owner?

( YES / NO )

Nature of Accident:

If NO, Driver Name / Age:

prmt kim phw

Driver Tel No.:

(VL: YES / NO)

Claim No.:

SA010106

Policy No.:

NA/180929

Make / Model:

IVECO

Place of Accident:

UE

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

5/7/2020



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:

world auto



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:

Date/ Time

5/7/2020 - X

XE 7754B - X

STAGE

DATE / PIC

Non-Reporting ltr (1st):  
Non-Reporting ltr (2nd):  
Non-Reporting ltr (Final):  
Notification ltr (if non-pickup):  
Call OI:  
After call ltr to OI:

Documentation Check List: Handler, Typist

Notification ltr (if non-pickup) ☒ ☐  
After call ltr to OI: ☒ ☐  
Authorisation To Act: ☒ ☐  
Release Voucher: ☒ ☐  
Final Repair Bill: ☒ ☐  
Car Rental Invoice: ☒ ☐  
Towing Invoice: ☒ ☐  
LTA / GIA: ☒ ☐  
Medical Bill: ☒ ☐  
PIR: ☒ ☐  
Mandate/Reject Instruction: ☒ ☐  
LOD: ☒ ☐  
Payment Breakdown Form: ☒ ☐  
Post-Repair Photos: ☐ ☐  
Others: ☐ ☐

30/7/19

seek mandate via #SNAP7

16/10

to pass file to Paul to adjust COR amt. as per TP instruction.

29/4

Binding mandate approval (approved)

2/12

offer \$16,628.57 as per TP LOD. File PACS su send dr.

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Kasul

Repair Cost:

PIP

SS

4,492.12

(12 days)

Reduction:

4,486.35

%

22

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

10/2/19

Email

Call

Final Liability:

%

100

(Agreed / Assessed)

BOLA S/N No.:

Hil

If NO or B 28, Ass. Lia:

Repair Cost:

WIA

SS

15,506.57

Loss of Rental (LOR):

SS

1

( days)

Loss of Use (LOU):

SS

1120.00

( \$ 80 x 14 days)

Loss of Income (LOI):

SS

( \$ x days)

LOR only

☐

LOU only

☐

LOR + LOU

☐

LOR + LO

☐

[Tick only one]

GIA/LTA Search

SS

2.00

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost

SS

Total:

SS

16,628.57

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

16,628.57

Name 1:

World Auto Pte Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

✓ GIA



# WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

AXA INSURANCE SINGAPORE PTE LTD

8 SHENTON WAY #24-01 AXA TOWER

068811

Attention : Motor Claim Department

Contact : 68804888 Fax No. : 880 4838

Estimate : ES190015

Date : 07/03/2019

Vehicle Num. : SLT 2573C(LCR)

Make/Model : TOYOTA PRIUS HYBRID 1.8S

Chassis/Eng# : JTDKB3FMX03962520/2017

Accident Date : 07/03/2019

Claim No. :

Reference :

Policy No. :

| S/N | Quantity | Particular | Unit Price | Amount S\$ |
|-----|----------|------------|------------|------------|
|-----|----------|------------|------------|------------|

## LIST ITEMS :

|     |   |                                                      |              |          |
|-----|---|------------------------------------------------------|--------------|----------|
| 1.  | 1 | REAR TAILGATE <i>PA</i>                              |              | 922.50   |
| 2.  | 1 | REAR TAILGATE LOCK <i>PA</i>                         |              | 477.40   |
| 3.  | 1 | REAR TAILGATE OUTER GARNISH <i>de</i>                |              | 891.00   |
| 4.  | 1 | REAR TAILGATE PRIUS EMBLEM <i>de</i>                 |              | 60.50    |
| 5.  | 1 | REAR TAILGATE HYBRID EMBLEM <i>de</i>                |              | 52.30    |
| 6.  | 1 | REAR TAILGATE INNER TRIM BOARD UPPER <i>Xsrc</i>     |              | 320.00X  |
| 7.  | 1 | REAR TAILGATE INNER TRIM BOARD LOWER <i>DE</i>       |              | 350.00   |
| 8.  | 1 | REAR TAILGATE SPOILER <i>CR</i>                      |              | 1,345.00 |
| 9.  | 2 | REAR TAILGATE STOPPER <i>de</i>                      | 30.50        | 61.00    |
| 10. | 1 | REAR TAILGATE WINDSCREEN GLASS <i>BA</i>             |              | 1,554.90 |
| 11. | 1 | REAR TAILGATE LOWER GLASS <i>BA</i>                  |              | 720.90   |
| 12. | 2 | REAR TAILGATE DAMPER <i>de</i>                       | 232.40       | 464.80   |
| 13. | 2 | REAR TAILGATE HINGE <i>PA</i>                        | 78.50        | 157.00   |
| 14. | 1 | REAR BUMPER <i>DE</i>                                |              | 423.90   |
| 15. | 1 | REAR LOWER BUMPER <i>DE</i>                          |              | 552.30   |
| 16. | 1 | REAR BUMPER LOWER SIDE SPOILER LH <i>Xsrc</i>        |              | 148.40X  |
| 17. | 1 | REAR BUMPER TOW COVER <i>Xsrc</i>                    |              | 28.90X   |
| 18. | 1 | REAR BUMPER REINFORCEMENT <i>Xsrc</i>                |              | 318.80X  |
| 19. | 1 | REAR BUMPER SIDE RETAINER RH <i>de</i>               |              | 111.50   |
| 20. | 2 | REAR BUMPER TAIL LAMP <i>RH - 620 / LH - 7. Xsrc</i> | lpc (481.90) | 963.80X  |
| 21. | 1 | REAR BUMPER WIRING HARNESS <i>Xsrc</i>               |              | 165.80X  |
| 22. | 2 | REAR TAIL LAMP <i>RH - 620 / LH - 7. Xsrc</i>        | lpc (433.70) | 867.40X  |
| 23. | 1 | REAR END PANEL <i>PA</i>                             |              | 623.90   |
| 24. | 1 | REAR END PANEL TOP GARNISH <i>DE</i>                 |              | 135.60   |
| 25. | 1 | REAR BOOT WEATHER STRIP <i>de</i>                    |              | 356.80   |
| 26. | 1 | REAR BOOT FLOOR BOARD <i>DE</i>                      |              | 890.00   |
| 27. | 1 | REAR FENDER RH <i>BU</i>                             |              | 817.50   |
| 28. | 1 | ROOF PANEL GARNISH REAR <i>CR</i>                    |              | 631.50   |
| 29. | 1 | ROOF PANEL SIDE GARNISH REAR <i>CR</i>               |              | 95.00    |

12610.90

CONTINUE / ...

**WORLD AUTO PTE LTD**

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

**AXA INSURANCE SINGAPORE PTE LTD**

8 SHENTON WAY #24-01 AXA TOWER

068811

Attention : Motor Claim Department

Contact : 68804888 Fax No. : 880 4838

**Estimate : ES190015**

Date : 07/03/2019

Vehicle Num. : SLT 2573C(LCR)

Make/Model : TOYOTA PRIUS HYBRID 1.8S

Chassis/Eng# :

Accident Date : 07/03/2019

Claim No. :

Reference :

Policy No. :

| S/N                                             | Quantity | Particular                                       | Unit Price | Amount S\$      |
|-------------------------------------------------|----------|--------------------------------------------------|------------|-----------------|
|                                                 |          |                                                  |            | 1153.10         |
| 30.                                             | 1        | TAIL LAMP PANEL RH <i>BA</i>                     |            | 151.80          |
| 31.                                             | 1        | REAR FENDER AIR GRILLE - RH <i>DE</i>            |            | 68.90           |
| 32.                                             | 1        | REAR FENDER QUARTER GARNISH RH <i>X SUC</i>      |            | 199.10 <i>X</i> |
| 33.                                             | 1        | 3RD BRAKE LAMP <i>bro</i>                        |            | 194.90          |
| 34.                                             | 1        | REAR BOOT FOAM BOX LH <i>? X SUC</i>             |            | 355.90 <i>X</i> |
| 35.                                             | 1        | REAR BOOT FOAM BOX RH <i>CM</i>                  |            | 355.90          |
| 36.                                             | 1        | REAR BOOT TOOLKIT FOAM BOX CENTRE <i>? X SUC</i> |            | 322.80 <i>X</i> |
| 37.                                             | 1        | SPARE TYRE LOCKING BOLT <i>? X SUC</i>           |            | 32.00 <i>X</i>  |
| 38.                                             | 1        | REAR FENDER INNER TRIM COVER RH <i>DE</i>        |            | 381.60          |
| List Total S\$ :                                |          |                                                  |            | 16,571.30       |
| 25.00% Discount S\$ :                           |          |                                                  |            | 4,142.83        |
|                                                 |          |                                                  |            | 12,428.47       |
| SPECIAL NETT ITEMS :                            |          |                                                  |            |                 |
| 1.                                              | 1SET     | REAR TAILGATE OUTER GARNISH CLIPS <i>he</i>      |            | 30.00           |
| 2.                                              | 1SET     | REAR TAILGATE INNER TRIM BOARD CLIPS <i>he</i>   |            | 30.00           |
| 3.                                              | 1SET     | REAR BUMPER CLIP <i>he</i>                       |            | 30.00           |
| 4.                                              | 3SET     | REAR END PANEL TOP GARNISH CLIPS <i>he</i>       |            | 30.00           |
| 5.                                              | 1SET     | REAR FENDER INNER TRIM COVER CLIPS <i>he</i>     |            | 30.00           |
| Special Nett Total S\$ :                        |          |                                                  |            | 150.00          |
| LABOUR :                                        |          |                                                  |            |                 |
| REPLACE REAR WINDSCREEN GLASS<br>(X2-GLASS)     |          |                                                  |            | 200 360.00      |
| WIRINGS CHECK AND RECTIFY WHERE NECESSARY       |          |                                                  |            | 30 180.00       |
| TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES |          |                                                  |            | 80 180.00       |

CONTINUE / ...

**WORLD AUTO PTE LTD**

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

**AXA INSURANCE SINGAPORE PTE LTD**8 SHENTON WAY #24-01 AXA TOWER  
068811

Attention : Motor Claim Department

Contact : 68804888 Fax No. : 880 4838

Estimate : ES190015

Date : 07/03/2019

Vehicle Num. : SLT 2573C(LCR)

Make/Model : TOYOTA PRIUS HYBRID 1.8S

Chassis/Eng# :

Accident Date : 07/03/2019

Claim No. :

Reference :

Policy No. :

| S/N | Quantity | Particular                                                                                                                                              | Unit Price | Amount S\$ |
|-----|----------|---------------------------------------------------------------------------------------------------------------------------------------------------------|------------|------------|
|     |          | REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING PANEL BEAT, CUT/WELD, STRAIGHTEN CHASSIS WHERE NECESSARY AND REPLACE ABOVE PARTS | 1600       | 2,200.00   |
|     |          | REMOVE REAR UPHOLSTERY IN ORDER TO FACILITATE REPAIRS TO REAR CHASSIS AND REFIT BACK SAME                                                               | 100        | 280.00     |
|     |          | DEACTIVATE HV HYBRID SYSTEM IN ORDER TO FACILITATE REPAIRS AND REACTIVATE BACK SAME (HV HYBRID SYSTEM SAFETY PROCEDURES)                                | 250        | 450.00     |
|     |          | PERFORM WHOLE VEHICLE DIAGNOSTICS INCLUDING INITIALISE HV HYBRID SYSTEM (HV HYBRID SYSTEM SAFETY PROCEDURES)                                            | 200        | 450.00     |
|     |          | PUTTY AND SPRAY PAINT ALL AFFECTED AREAS (INNER/OUTER, PEARL WHITE)                                                                                     | 1200       | 2,000.00   |
|     |          | <b>Labour Total S\$ :</b>                                                                                                                               |            | 6,100.00   |

Resu  
Hr 900 10068

12 days

P/P

3660

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

E. &amp; O.E.

11/03/19

P 1415

Total S\$ :

18,678.47

19057.59

Resu 54 paint

for WORLD AUTO PTE LTD

# WORLD AUTO PTE LTD

7 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

AXA INSURANCE SINGAPORE PTE LTD

8 SHENTON WAY #24-01 AXA TOWER

068811

Attention : Motor Claim Department

Contact : 68804888 Fax No. : 880 4838

Supplementary Estimate : SE190015

Date : 07/03/2019

Vehicle Num. : SLT 2573C(LCR)

Make/Model : TOYOTA PRIUS HYBRID 1.8S

Chassis/Eng# :

Accident Date : 07/03/2019

Claim No. :

Reference :

Policy No. :

| S/N | Quantity | Particular | Unit Price | Amount S\$ |
|-----|----------|------------|------------|------------|
|-----|----------|------------|------------|------------|

|    |      |                                      |       |       |
|----|------|--------------------------------------|-------|-------|
| 1. | 1    | LIST ITEMS :                         |       |       |
| 2. | 1    | REAR QUARTER PANEL EXTENSION RH BA / |       | 75.20 |
| 3. | 1    | REAR TAILGATE DAMPER BRACKET RH BA / |       | 60.00 |
| 4. | 1    | REAR TAIL LAMP GARNISH RH DC /       |       | 55.00 |
| 5. | 1    | REAR TAILGATE LOCK COVER BE /        |       | 45.80 |
| 6. | 2    | REAR TAIL LAMP GUIDE BR /            | 15.00 | 30.00 |
| 7. | 2    | REAR TAIL LAMP CLIP W /              | 15.00 | 30.00 |
| 7. | 1SET | REAR WINDSCREEN GLASS MOULDING W /   |       | 49.50 |

List Total S\$ :

25.00% Discount S\$ :

P- 10,323

S/N - 150

L - 3660

Suppl - 259.12

Suppl S/N - 100.00

T - 14,492.12

12 days

|    |      |                                 |  |       |
|----|------|---------------------------------|--|-------|
| 1. | 1SET | SPECIAL NETT ITEMS :            |  |       |
| 2. | 1    | REAR NUMBER PLATE W/CASING CA / |  | 40.00 |
|    |      | REAR WINDSCREEN SEALANT W /     |  | 80.00 |

Special Nett Total S\$ :

120.00

100

E. & O.E.

Total S\$ :

379.12

for WORLD AUTO PTE LTD

**WORLD AUTO PTE LTD**

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

**AXA INSURANCE SINGAPORE PTE LTD**

8 SHENTON WAY #24-01 AXA TOWER

068811

Attention : Motor Claim Department

Contact : 68804888 Fax No. : 880 4838

**Estimate : ES190015**

Date : 07/03/2019

Vehicle Num. : SLT 2573C(LCR)

Make/Model : TOYOTA PRIUS HYBRID 1.8S

Chassis/Eng# :

Accident Date : 07/03/2019

Claim No. :

Reference :

Policy No. :

| S/N          | Quantity | Particular                                     | Unit Price | Amount S\$ |
|--------------|----------|------------------------------------------------|------------|------------|
| LIST ITEMS : |          |                                                |            |            |
| 1.           | 1        | REAR TAILGATE <i>PA</i>                        |            | 922.50     |
| 2.           | 1        | REAR TAILGATE LOCK <i>jam</i>                  |            | 477.40     |
| 3.           | 1        | REAR TAILGATE OUTER GARNISH                    |            | 891.00     |
| 4.           | 1        | REAR TAILGATE PRIUS EMBLEM <i>neu</i>          |            | 60.50      |
| 5.           | 1        | REAR TAILGATE HYBRID EMBLEM <i>neu</i>         |            | 52.30      |
| 6.           | 1        | REAR TAILGATE INNER TRIM BOARD UPPER <i>X</i>  |            | 320.00     |
| 7.           | 1        | REAR TAILGATE INNER TRIM BOARD LOWER <i>DE</i> |            | 350.00     |
| 8.           | 1        | REAR TAILGATE SPOILER <i>CA</i>                |            | 1,345.00   |
| 9.           | 2        | REAR TAILGATE STOPPER <i>neu</i>               | 30.50      | 61.00      |
| 10.          | 1        | REAR TAILGATE WINDSCREEN GLASS <i>Bko</i>      |            | 1,554.90   |
| 11.          | 1        | REAR TAILGATE LOWER GLASS <i>Bko</i>           |            | 720.90     |
| 12.          | 2        | REAR TAILGATE DAMPER <i>neu</i>                | 232.40     | 464.80     |
| 13.          | 2        | REAR TAILGATE HINGE <i>PA</i>                  | 78.50      | 157.00     |
| 14.          | 1        | REAR BUMPER <i>DE</i>                          |            | 423.90     |
| 15.          | 1        | REAR LOWER BUMPER <i>DE</i>                    |            | 552.30     |
| 16.          | 1        | REAR BUMPER LOWER SIDE SPOILER LH <i>X</i>     |            | 148.40     |
| 17.          | 1        | REAR BUMPER TOW COVER <i>X</i>                 |            | 28.90      |
| 18.          | 1        | REAR BUMPER REINFORCEMENT <i>?</i>             |            | 318.80     |
| 19.          | 1        | REAR BUMPER SIDE RETAINER RH <i>neu</i>        |            | 111.50     |
| 20.          | 2        | REAR BUMPER TAIL LAMP <i>RH - bko / LH - ?</i> | 481.90     | 963.80     |
| 21.          | 1        | REAR BUMPER WIRING HARNESS <i>?</i>            |            | 165.80     |
| 22.          | 2        | REAR TAIL LAMP <i>RH - bko / LH - ?</i>        | 433.70     | 867.40     |
| 23.          | 1        | REAR END PANEL <i>PA</i>                       |            | 623.90     |
| 24.          | 1        | REAR END PANEL TOP GARNISH <i>DE</i>           |            | 135.60     |
| 25.          | 1        | REAR BOOT WEATHER STRIP <i>neu</i>             |            | 356.80     |
| 26.          | 1        | REAR BOOT FLOOR BOARD <i>DE</i>                |            | 890.00     |
| 27.          | 1        | REAR FENDER RH <i>neu</i>                      |            | 817.50     |
| 28.          | 1        | ROOF PANEL GARNISH REAR <i>CA</i>              |            | 631.50     |
| 29.          | 1        | ROOF PANEL SIDE GARNISH REAR <i>CA</i>         |            | 95.00      |

CONTINUE / ...

**WORLD AUTO PTE LTD**

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

**AXA INSURANCE SINGAPORE PTE LTD**

8 SHENTON WAY #24-01 AXA TOWER

068811

Attention : Motor Claim Department

Contact : 68804888 Fax No. : 880 4838

**Estimate : ES190015**

Date : 07/03/2019

Vehicle Num. : SLT 2573C(LCR)

Make/Model : TOYOTA PRIUS HYBRID 1.8S

Chassis/Eng# :

Accident Date : 07/03/2019

Claim No. :

Reference :

Policy No. :

| S/N                                             | Quantity | Particular                                     | Unit Price | Amount S\$        |
|-------------------------------------------------|----------|------------------------------------------------|------------|-------------------|
| 30.                                             | 1        | TAIL LAMP PANEL RH <i>RM</i>                   |            | 151.80            |
| 31.                                             | 1        | REAR FENDER AIR GRILLE - RH <i>DE</i>          |            | 68.90             |
| 32.                                             | 1        | REAR FENDER QUARTER GARNISH RH <i>X</i>        |            | 199.10            |
| 33.                                             | 1        | 3RD BRAKE LAMP <i>bro</i>                      |            | 194.90            |
| 34.                                             | 1        | REAR BOOT FOAM BOX LH <i>?</i>                 |            | 355.90            |
| 35.                                             | 1        | REAR BOOT FOAM BOX RH <i>CR</i>                |            | 355.90            |
| 36.                                             | 1        | REAR BOOT TOOLKIT FOAM BOX CENTRE <i>?</i>     |            | 322.80            |
| 37.                                             | 1        | SPARE TYRE LOCKING BOLT <i>?</i>               |            | 32.00             |
| 38.                                             | 1        | REAR FENDER INNER TRIM COVER RH <i>DE</i>      |            | 381.60            |
| List TotalS\$ :                                 |          |                                                |            | 16,571.30         |
| 25.00% Discount S\$ :                           |          |                                                |            | 4,142.83          |
|                                                 |          |                                                |            | 12,428.47         |
| SPECIAL NETT ITEMS :                            |          |                                                |            |                   |
| 1.                                              | 1SET     | REAR TAILGATE OUTER GARNISH CLIPS <i>RM</i>    |            | 30.00             |
| 2.                                              | 1SET     | REAR TAILGATE INNER TRIM BOARD CLIPS <i>RM</i> |            | 30.00             |
| 3.                                              | 1SET     | REAR BUMPER CLIP <i>RM</i>                     |            | 30.00             |
| 4.                                              | 1SET     | REAR END PANEL TOP GARNISH CLIPS <i>RM</i>     |            | 30.00             |
| 5.                                              | 1SET     | REAR FENDER INNER TRIM COVER CLIPS <i>RM</i>   |            | 30.00             |
| Special Nett Total S\$ :                        |          |                                                |            | 150.00            |
| LABOUR :                                        |          |                                                |            |                   |
| REPLACE REAR WINDSCREEN GLASS<br>(X2 GLASS)     |          |                                                |            | <i>200</i> 360.00 |
| WIRINGS CHECK AND RECTIFY WHERE NECESSARY       |          |                                                |            | <i>30</i> 180.00  |
| TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES |          |                                                |            | <i>80</i> 180.00  |

CONTINUE / ...

**WORLD AUTO PTE LTD**

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

**AXA INSURANCE SINGAPORE PTE LTD**

8 SHENTON WAY #24-01 AXA TOWER

068811

Attention : Motor Claim Department

Contact : 68804888 Fax No. : 880 4838

Estimate : ES190015

Date : 07/03/2019

Vehicle Num. : SLT 2573C(LCR)

Make/Model : TOYOTA PRIUS HYBRID 1.8S

Chassis/Eng# :

Accident Date : 07/03/2019

Claim No. :

Reference :

Policy No. :

| S/N | Quantity | Particular                                                                                                                                              | Unit Price | Amount S\$          |
|-----|----------|---------------------------------------------------------------------------------------------------------------------------------------------------------|------------|---------------------|
|     |          | REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING PANEL BEAT, CUT/WELD, STRAIGHTEN CHASSIS WHERE NECESSARY AND REPLACE ABOVE PARTS | 1600       | <del>2,200.00</del> |
|     |          | REMOVE REAR UPHOLSTERY IN ORDER TO FACILITATE REPAIRS TO REAR CHASSIS AND REFIT BACK SAME                                                               | 100        | <del>280.00</del>   |
|     |          | DEACTIVATE HV HYBRID SYSTEM IN ORDER TO FACILITATE REPAIRS AND REACTIVATE BACK SAME (HV HYBRID SYSTEM SAFETY PROCEDURES)                                | 250        | <del>450.00</del>   |
|     |          | PERFORM WHOLE VEHICLE DIAGNOSTICS INCLUDING INITIALISE HV HYBRID SYSTEM (HV HYBRID SYSTEM SAFETY PROCEDURES)                                            | 200        | <del>450.00</del>   |
|     |          | PUTTY AND SPRAY PAINT ALL AFFECTED AREAS (INNER/OUTER, PEARL WHITE)                                                                                     | 1200       | <del>2,000.00</del> |
|     |          | Labour Total S\$ :                                                                                                                                      |            | 6,100.00            |

*Paul*  
*Hq 900 10068*

*12 days*  
*P/P*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary work(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

E. &amp; O.E.

11/03/19

Total S\$ :

18,678.47

P 1415

*Resay 54 paint*

for WORLD AUTO PTE LTD

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

| Vehicle Owner Particulars     |                                  |
|-------------------------------|----------------------------------|
| Owner ID Type:                | Company                          |
| Owner ID:                     | 4597K                            |
| Vehicle Details               |                                  |
| Vehicle No.:                  | SLT2573C                         |
| Vehicle to be Exported:       | No                               |
| Intended Deregistration Date: | 12 Mar 2019                      |
| Vehicle Make:                 | TOYOTA                           |
| Vehicle Model:                | PRIUS HYBRID 1.8 CVT             |
| Primary Colour:               | White                            |
| Manufacturing Year:           | 2017                             |
| Engine No.:                   | 2ZRS058855                       |
| Chassis No.:                  | JTDKB3FUX03562520                |
| Maximum Power Output:         | 90.0 kW (120 bhp)                |
| Open Market Value:            | \$29,007.00                      |
| Original Registration Date:   | 24 Oct 2017                      |
| First Registration Date:      | 24 Oct 2017                      |
| Transfer Count:               | 0                                |
| Actual ARF Paid:              | \$5,000.00                       |
| Intended PARF Rebate Details  |                                  |
| PARF Eligibility:             | Yes                              |
| PARF Eligibility Expiry Date: | 23 Oct 2027                      |
| PARF Rebate Amount:           | \$3,750.00                       |
| Intended COE Rebate Details   |                                  |
| COE Expiry Date:              | 23 Oct 2027                      |
| COE Category:                 | E - Open - all except motorcycle |
| COE Period(Years):            | 10                               |
| QP Paid:                      | \$50,101.00                      |
| COE Rebate Amount:            | \$43,065.00                      |
| <b>Total Rebate Amount:</b>   | <b>\$46,815.00</b>               |

The information contained herein is correct as at 12 Mar 2019

OK

79,000  
46,815  

---

32,185

AXIA

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

|                            |                                             |
|----------------------------|---------------------------------------------|
| Date Of Report             | 07/03/2019 16:17                            |
| Date Of Accident           | 07/03/2019 12:30                            |
| Exact Location Of Accident | SLIP RD INTO CTE TOWARDS SLE OF BRADDELL RD |
| Country/State of Loss      | SINGAPORE                                   |

### DETAILS OF OWN VEHICLE

|                             |                 |
|-----------------------------|-----------------|
| Vehicle Registration Number | SLT2573C        |
| <b>Insured/Policyholder</b> |                 |
| Name Of Registered Owner    | LCRF PTE LTD    |
| Co Reg No                   | 201624597K      |
| Email Address               | NOEMAIL         |
| Mobile Phone No             |                 |
| Alternative Phone No        | OFFICE-62414992 |

### Vehicle Particulars

|                                                                              |                          |
|------------------------------------------------------------------------------|--------------------------|
| Manufacturer                                                                 | TOYOTA                   |
| Model                                                                        | PRIUS-1.8 HYBRID CVT (A) |
| Exact Purpose for which vehicle was being used at time of accident           |                          |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO                       |
| If No, Please state action to be taken                                       | THIRD PARTY              |
| Vehicle Category                                                             | PRIVATE HIRE             |

### Insurance Company

|                           |                                      |
|---------------------------|--------------------------------------|
| Name of Insurance Company | TOKIO MARINE INSURANCE SINGAPORE LTD |
| Type Of Coverage          | THIRD PARTY                          |
| Fleet Policy              | YES                                  |
| Policy Number             | 19-MK000194-R00                      |
| Cover Note Number         |                                      |

### Driver

|                      |                       |
|----------------------|-----------------------|
| Name of Driver       | LOW HENG CHEONG       |
| NRIC No              | S7715658E             |
| Date Of Birth        | 16/06/1977            |
| Occupation           | OUTDOOR               |
| Date Of Driving Pass | 24/08/2006            |
| Driving Experience   | 12 YEARS AND 6 MONTHS |
| Gender               | MALE                  |
| Mobile Number        | (LOCAL) +65-81182868  |
| Fax Number           |                       |
| Contact Number       |                       |
| EMail Address        | NOEMAIL               |

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

#### DETAILS OF INJURED PERSON 1

Name

LOW HENG CHEONG

Approximate Age

Injuries Sustain

Injured person in which vehicle?

Were seat belts worn?


Was this injured conveyed to hospital by ambulance?

Address

Postcode

## Sketch Plan #2

### SKETCH PLAN



### DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 07/03/2019, around 1230hrs, I was driving along Braddell Road towards Bartley Road direction. I took the exit to CTE heading towards SLE direction. While at the slip road, suddenly I felt multiple impact from the rear. I was shocked by the multiple impact and only managed to stop my car after a distance. I alighted from my car and realised this truck XE 7754 B had collided into my car, causing serious damages to the rear portion.

### DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature  
Date & Time:

07/03/19

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No:

## Sketch Plan #4



**SINGAPORE  
POLICE FORCE**



T/20190307/2112

2 of 3

Police Station Of Origin:

Hougang N.P.C

60 Hougang Avenue 9 SINGAPORE 538775

Tel No. 1800-4890999

Report No. T/20190307/2112

**CONTINUATION OF REPORT**

|                                   |                             |                                        |                                   |
|-----------------------------------|-----------------------------|----------------------------------------|-----------------------------------|
| <b>Details of Person Involved</b> |                             |                                        |                                   |
| Any Pedestrian Involved: No       |                             |                                        |                                   |
| No. of Pedestrians Injured: NIL   |                             | Use of Pedestrian Crossing: NA         |                                   |
| <b>Driver</b>                     |                             |                                        |                                   |
| Name                              | LOW HENG CHEONG             | ID No.                                 | S7715658E                         |
| Related Vehicle                   | SLT2573C (Car)              | Contact No.                            | 81182868                          |
| Hospital/Clinic                   | POW FAMILY CLINIC & SURGERY | Class of Driving Licence & Expiry Date | Class: 3<br>Date of Expiry: NIL   |
| Date Treatment                    | 07/03/2019                  | Date Discharge                         | 07/03/2019                        |
| No. of Days granted Medical Leave | 03                          | Degree of Injury                       | Slight                            |
| <b>Other Person Involved</b>      |                             |                                        |                                   |
| Name                              | Unknown                     | ID No.                                 | NIL                               |
| Related Vehicle                   | XE7754B (Lorry)             | Contact No.                            | 94843088                          |
| Hospital/Clinic                   | NIL                         | Class of Driving Licence & Expiry Date | Class: NIL<br>Date of Expiry: NIL |
| Date Treatment                    | NIL                         | Date Discharge                         | NIL                               |
| No. of Days granted Medical Leave | NIL                         | Degree of Injury                       | NIL                               |

**Brief Details.**

On 07/03/2019 at about 1230hrs, I was driving along Braddell Road towards Bartley Road direction. I took the exit to CTE heading towards SLE direction. While at the slip road, suddenly, I felt multiple impacts from the rear. I was shocked by the multiple impacts and only managed to stop my vehicle after a distance away. I alighted from my vehicle and realized that a truck (XE7754B) had collided into my car causing serious damages to the rear portion.

When confronting the driver, he told me that he did not see me.

I have since seen the doctor and have been awarded three days medical leave.

I have also informed Grab regarding this matter as well as the insurance company of the private hire.



## Certificate of Insurance

**MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)**  
**MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960**  
**ROAD TRANSPORT ACT, 1987 (MALAYSIA)**  
**MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)**

Policy No.: 19-MK000196-R00 (Private Motor Car)

1. **Index Mark and Registration Number of Vehicle** SLT2573C **Chassis No.:** JTDKB3FUX03562520
2. **Name of Policyholder** LCRF PTE. LTD.
3. **Effective date of the Commencement of Insurance for the purposes of the Act** 25/02/2019
4. **Date of Expiry of Insurance** 24/02/2020
5. **Persons or Class of Persons entitled to drive\***  
 Any person who is driving on the Policyholder's order or with their permission.  
 The hirer.  
 Any other person who is driving on the hirer's order or with his/ their permission.

\* Provided that the Person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle. And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident loss or damage.

**6. Limitations as to use\***

- Use for the carriage of passengers or goods in connection with the Policyholder's business or the hirer's business.  
 Use for social domestic and pleasure purpose and business purposes of the Policyholder or of any person to whom the vehicle is hired.  
 The Policy does not cover:-  
 1) Use for racing, pace-making, reliability trial or speed-testing.  
 2) Use whilst drawing a trailer except the towing (other than for reward) of any one disabled mechanically propelled vehicle.

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

We hereby certify that the Policy to which this Certificate relates is issued in accordance with the provision of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Please refer to the Policy Schedule for full details, terms and conditions of the insurance.

**IMPORTANT NOTICE**

This Certificate is not transferable. During its currency, if the insurance is cancelled for whatsoever reason, you must return the Certificate to Tokio Marine Insurance Singapore Ltd. within 7 days thereof or, if the Certificate has been lost destroyed, you must make a statutory declaration to that effect. Failure to comply with this duty is an offence under Motor Vehicle (Third-Party Risks and Compensation) Act (Chapter 189).

**ADDITIONAL INFORMATION**

Account: 2960DDZ

**Insurance Plan:** Third Party Cover Only  
**Financial Interest:** UNITED OVERSEAS BANK LTD

Tokio Marine Insurance Singapore Ltd.

Authorised Signature



**List of Approved Workshops (With 24 Hours Towing Service)**  
**24-hour Hotline - 1800 225 8647 (In Singapore)**  
**- +65 6225 8647 (In Malaysia/Thailand)**

| Zone         | Area                             | Name of Workshop                                                              | Address                                                                                                                 | Contact No.                                         |
|--------------|----------------------------------|-------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------|
| Central      | Ang Mo Kio                       | Ah Lim Motor Company                                                          | No. 10 Ang Mo Kio Ind Park 2A, #01-09 AMK Autopoint, S(568047)                                                          | Tel: 6483 1244<br>Towing: 9620 5405                 |
|              |                                  | Cheng Hoe Motor Service                                                       | No. 10 Ang Mo Kio Ind Park 2A, #01-04 AMK Autopoint, S(568047)                                                          | Tel: 6481 2001<br>Towing: 6481 2001                 |
|              | Alexandra                        | Kah Motor Co. Sdn Bhd.<br>(Excluding Honda's Parallel Import Vehicles)        | 255 Alexandra Road, S(159937)                                                                                           | Tel: 6841 3838<br>Towing: 6841 3838                 |
|              | Bukit Merah                      | Mova Automotive Pte Ltd                                                       | Bk 1008 Bukit Merah Lane 3, #01-04, S(159722)                                                                           | Tel: 6272 3892<br>Towing: 9799 8888                 |
|              | Sin Ming                         | Alan's United Auto                                                            | Bk 7 Sin Ming Road, Sin Ming Industrial Estate, #01-76, S(575642)                                                       | Tel: 6453 8686<br>Towing: 6453 8686                 |
|              |                                  | BH Auto Services Pte Ltd                                                      | Bk 1 Sin Ming Industrial Estate Sector C, #01-111, S(575636)<br>Operating hours: Mon-Sat: 9am to 11pm, Sun: 10am to 4pm | Tel: 6559 8944<br>Towing: 9101 3232                 |
|              |                                  | City Auto Testing Centre Pte Ltd                                              | Bk 8 Sin Ming Road, Sin Ming Industrial Estate, #01-60/62, S(575643)                                                    | Tel: 6453 1235<br>Towing: 9823 9898                 |
|              |                                  | Falcon-Air Auto Services Pte Ltd                                              | 176 Sin Ming Drive, Sin Ming Autocare, #01-06/07/13, S(575721)                                                          | Tel: 6452 0880<br>Towing: 6459 2552                 |
|              |                                  | K Kim Hin Auto Pte Ltd                                                        | 160 Sin Ming Drive, #02-20 Sin Ming Autocity, S(575722)                                                                 | Tel: 6452 7018<br>Towing: 6452 7018                 |
|              |                                  | Lai Huat (Meng Kee) Motor Pte Ltd                                             | 160 Sin Ming Drive, #04-01, #04-02 and #07-03, Sin Ming Autocity, S(575722)                                             | Tel: 6453 8110<br>Towing: 6453 8110                 |
|              |                                  | MBM Wheelpower Pte Ltd                                                        | 160 Sin Ming Drive #06-02 Sin Ming Autocity, S(575722)                                                                  | Tel: 6262 8888<br>Towing: 8828 5188                 |
|              |                                  | S&H Motor Pte Ltd                                                             | 160 Sin Ming Drive, #07-02 Sin Ming Autocity, S(575722)                                                                 | Tel: 6453 4730<br>Towing: 9677 8873                 |
|              |                                  | Vin's Motor Pte Ltd                                                           | 160 Sin Ming Drive, #03-03 Sin Ming Autocity, S(575722)                                                                 | Tel: 6453 2121<br>Towing: 6453 2121                 |
|              | North                            | Kranji                                                                        | Toh Ah Swee Spray Painting Co.                                                                                          | Bk 2 Kranji Loop #01-02, Off Kranji Road, S(739538) |
| Mandai       |                                  | Kah Motor Co. Sdn Bhd.<br>(Excluding Honda's Parallel Import Vehicles)        | 6A Mandai Estate, S(729903)                                                                                             | Tel: 6841 3838<br>Towing: 6841 3838                 |
| Sungei Kadut |                                  | Lee Kuan Hwa Motor Service                                                    | 24 Sungei Kadut Street 4, S(729050)                                                                                     | Tel: 6269 9192<br>Towing: 6563 5620                 |
| Woodlands    |                                  | Cheng Hoe Motor Service                                                       | 38 Woodlands Industrial Park E1, #05-04/05, S(757700)                                                                   | Tel: 6765 6142<br>Towing: 6765 6142                 |
|              |                                  | Sin Yew Hup Auto Pte Ltd                                                      | Bk 4 Woodlands Road, 393M Yew Tee Industrial Estate, S(677981)                                                          | Tel: 6760 0819<br>Towing: 9815 2772                 |
| Yishun       |                                  | Cheng Hoe Motor Service                                                       | Bk 1019 Yishun Industrial Park A, #01-374, S(768761)                                                                    | Tel: 6755 6142<br>Towing: 6755 6142                 |
| East         | Bedok                            | Hock Wah Motor Workshop Pte Ltd                                               | Bk 3011 Bedok Industrial Park E, #01-2008/2010/2012, S(489977)                                                          | Tel: 6441 5655<br>Towing: 8339 6888                 |
|              | Defu                             | Ban Hock Hin Co. Pte Ltd<br>(For Motorcycles Only)                            | 6 Defu Lane 4, S(539410)                                                                                                | Tel: 6281 6520<br>Towing: 6282 7227                 |
|              |                                  | Kan Fook Sing Motor Workshop                                                  | Bk 61 Defu Lane 12, S(539147)                                                                                           | Tel: 6747 9560<br>Towing: 6747 9560                 |
|              | Kaki Bukit                       | Auto N Cars Services Pte Ltd                                                  | Bk A, Autobay @ Kaki Bukit, Avenue 6, #01-04, S(417883)                                                                 | Tel: 6555 2909<br>Towing: 6555 2909                 |
|              |                                  | Chin Meng Motors                                                              | 1 Kaki Bukit Ave 6, AutoBay @ Kaki Bukit, #01-40/63, S(417883)                                                          | Tel: 6747 4810<br>Towing: 6747 4810                 |
|              |                                  | SME Motor Pte Ltd                                                             | 1 Kaki Bukit Avenue 6, AutoBay @ Kaki Bukit, #02-15/16/17/18, S(417883)                                                 | Tel: 6747 6106<br>Towing: 6747 6106                 |
|              |                                  | WTS Automotive Services Pte Ltd                                               | 17, Kaki Bukit Road 4, #01-58/59/60/61/62, Bartley BizCentre, S(417809)                                                 | Tel: 6844 9449<br>Towing: 9618 0311                 |
|              | Ubi                              | Cycle & Carriage Fulco Motor Dealer Pte Ltd<br>(For Mitsubishi & KIA Repairs) | 330 Ubi Road 3, S(408650)                                                                                               | Tel: 6746 1000<br>Towing: 9834 1939                 |
|              |                                  | Kah Motor Co. Sdn Bhd.<br>(Excluding Honda's Parallel Import Vehicles)        | 15 Ubi Road 4, S(408610)                                                                                                | Tel: 6841 3838<br>Towing: 6841 3838                 |
|              |                                  | Progressive Automotive Pte Ltd                                                | Bk 3022A Ubi Road 1, #01-45/46 S(408716)                                                                                | Tel: 6741 5336<br>Towing: 6858 4067                 |
| Tampines     | Falcon-Air Auto Services Pte Ltd | Bk 9006 Tampines Street 93, #01-200, S(528840)                                | Tel: 6789 7997<br>Towing: 6459 2552                                                                                     |                                                     |
| West         | Bukit Batok                      | CarCrafters Singapore Pte Ltd (VAG)<br>(For Volkswagen & Audi Repairs)        | 48 Toh Guan Road East, #05-155, Enterprise Hub, S(608586)                                                               | Tel: 6267 9916<br>Towing: 6795 0005                 |
|              |                                  | Ban Choon Motor Works                                                         | Bk 3 Pioneer Road North, #01-14/15, S(628457)                                                                           | Tel: 6264 1191<br>Towing: 9637 9368                 |
|              | Jurong                           | Cheng Auto Bodyworks                                                          | 5 Soon Lee Street, Pioneer Point, #01-59/60, S(627607)                                                                  | Tel: 6631 0707<br>Towing: 8666 7775                 |
|              |                                  | Hitachi Capital (S) Pte Ltd                                                   | No. 8 Forth Lok Yang Road S(629705)                                                                                     | Tel: 6466 3022<br>Towing: 9118 5263                 |
|              |                                  | Section Automotive Services                                                   | 5 Benoi Place S(629926)                                                                                                 | Tel: 6861 0908<br>Towing: 6747 7400                 |
|              |                                  | Sng Ah Tee Motor & Panel Service Pte Ltd                                      | Bk 3 Pioneer Road North, #01-18, S(628457)                                                                              | Tel: 6268 6183<br>Towing: 9118 1186                 |
|              |                                  | Pandan                                                                        | Falcon-Air Auto Services Pte Ltd                                                                                        | No. 8 Pandan Loop, S(126226)                        |

**For Windscreen Repair or Replacement Only**

|         |             |                        |                                                               |                |
|---------|-------------|------------------------|---------------------------------------------------------------|----------------|
| Central | Sin Ming    | Tuffi Tech Pte Limited | 160 Sin Ming Drive, #04-07 Sin Ming Autocity, S(575722)       | Tel: 6453 3722 |
| East    | Kaki Bukit  | Auto Glass Venture     | 8 Kaki Bukit Avenue 4, #03-29 Premier @ Kaki Bukit, S(415875) | Tel: 6702 1095 |
| East    | Ubi         | Glass-Fix Pte Ltd      | 52 Ubi Ave 3 # 04-42, Frontier @ Ubi, S(408867)               | Tel: 6278 0887 |
| West    | Bukit Batok | Auto Glass Venture     | 1 Bukit Batok Crescent, WCEGA Plaza, #04-23, S(658064)        | Tel: 6569 2318 |
| West    | Jurong      | Cheng Auto Bodyworks   | 5 Soon Lee Street, Pioneer Point, #01-41, S(627607)           | Tel: 6631 0707 |

**Nivitha (LKK Auto)**

---

**From:** Shu Pei (LKKAuto) <shupeil@lkkauto.com>  
**Sent:** Monday, 11 March 2019 9:17 AM  
**To:** assignments  
**Cc:** Admin A  
**Subject:** FW: Request for Third Party Motor Claim Survey

\*\*\*\*SMARTCLAIM NEW CASE\*\*\*\*

SPOKEN WITH DANIEL -VEHICLE IN \*\*\*\*CAN SURVEY TODAY

\*\*\*\*VIRTUAL ACC\*\*\*\*

10:29 am @ 11/3/19  
vehicle in  
Jewel  
for @ Rahul.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: [shupeil@lkkauto.com](mailto:shupeil@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** daniel@worldauto.com.sg <daniel@worldauto.com.sg>  
**Sent:** Thursday, 7 March 2019 6:06 PM  
**To:** SG AXA Insurance SM AXA SGP - Motor Survey <motor.survey@axa.com.sg>  
**Cc:** 'Gan Ping' <ganping@worldauto.com.sg>; 'Adrian Tan' <adrian22@worldauto.com.sg>; kana@worldauto.com.sg; 'Geraldine' <geraldine@worldauto.com.sg>  
**Subject:** Request for Third Party Motor Claim Survey

Good evening,

We would like to request for a third party motor claim survey, details as follow;  
Our Vehicle: SLT2573C  
Your Insured: XE7754B  
DOA: 07-03-2019

Our vehicle is currently in the workshop, address as follow;  
**World Auto Pte Ltd**  
**No.1, Kranji Loop**  
**Singapore 739535**

Please response immediately upon receiving this request, send us your list of Loss Adjustor for our choice within 48 hours.  
Kindly note that should you fail to response to us within the above stipulated timeline, we may, at our discretion, appoint our own Loss Adjustor to perform this PRI.

Thks & Rgds,  
Daniel

## Service Request Details

### Claim

S9M01GAV

### Reference

None

### Loss Date

7 March 2019

### Report Date

8 Mar 2019 8:48:00 AM

### Request Date

8 March 2019

### Due Date

11 March 2020

### Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

### Type of Loss

Third Party Vehicle Damage

### Services

Pending verification - Direct Settlement

### Actions

#### Next Step

Finish the work

Complete Work

More

### Vehicle Information

#### Incident Vehicle Registration #

SLT2573C

#### Make

TPVD

#### Model

TOYOTA

would auto - veh in  
virtual

## Primary Contact/Insured

ASIA MORTAR PTE. LTD.  
19 SUNGEI KADUT STREET 6, 728864, Singapore  
63380083  
GRACE@VIRTUALINVEST.BIZ

## Claim Handler

TAN Jas  
6568804844  
jas.tan@axa.com.sg

## Additional Instructions

WORLD AUTO VIRTUAL ACC PLEASE DO NOT FINALISE REPAIR.

[Messenger](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

## Rasul (LKKAuto)

---

**From:** daniel@worldauto.com.sg  
**Sent:** Saturday, 23 November, 2019 1:45 PM  
**To:** Rasul (LKKAuto)  
**Cc:** adrian22@worldauto.com.sg; geraldine@worldauto.com.sg;  
ganping@worldauto.com.sg  
**Subject:** RE: SLT 2573C Our ref: TP/2505/19

Hi Rasul,

Reference to above matter, and to your email request below.

The price quoted in the repair estimate are based on recommended List Price for Toyota Prius Hybrid.

We are unable to provide any more discount.

Thks & Rgds,  
Daniel  
World Auto Pte Ltd  
Tel: 64513933

---

**From:** [tggtan@worldauto.com.sg](mailto:tggtan@worldauto.com.sg) <[tggtan@worldauto.com.sg](mailto:tggtan@worldauto.com.sg)>  
**Sent:** Friday, 15 November 2019 11:17 AM  
**To:** [daniel@worldauto.com.sg](mailto:daniel@worldauto.com.sg); [geraldine@worldauto.com.sg](mailto:geraldine@worldauto.com.sg)  
**Cc:** [adrian22@worldauto.com.sg](mailto:adrian22@worldauto.com.sg)  
**Subject:** FW: SLT 2573C Our ref: TP/2505/19

---

**From:** Rasul (LKKAuto) <[Rasul@lkkauto.com](mailto:Rasul@lkkauto.com)>  
**Sent:** Friday, 15 November 2019 10:29 AM  
**To:** [tggtan@worldauto.com.sg](mailto:tggtan@worldauto.com.sg)  
**Subject:** RE: SLT 2573C Our ref: TP/2505/19

Hi Sophia,

Kindly assist


Best Regards,

**Rasul** | Assessor

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Rasul@lkkauto.com](mailto:Rasul@lkkauto.com) | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto  
Consultants  
Pte Ltd

*Save the Earth. Print only when necessary.*

---

**From:** Rasul (LKKAuto)  
**Sent:** Tuesday, 12 November, 2019 3:47 PM  
**To:** [tggtan@worldauto.com.sg](mailto:tggtan@worldauto.com.sg)  
**Subject:** RE: SLT 2573C Our ref: TP/2505/19

## Report Remarks Entry - CC4/ASM19004350/R1wb3

Remarks

Remarks

Add

| Remarks 1                                                                                                                                                                                                                                                                                                          | By  | On                       |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----|--------------------------|
| <input type="checkbox"/> SLT 2573C ; XE 7754B                                                                                                                                                                                                                                                                      | LSP | 11/3/2019<br>4:09:04 PM  |
| <input type="checkbox"/> EST : \$ ---- SUR : --- WKSP : WORLD AUTO PTE LTD                                                                                                                                                                                                                                         | LSP | 11/3/2019<br>4:09:14 PM  |
| <input type="checkbox"/> S9M01GAV / 103106                                                                                                                                                                                                                                                                         | LSP | 11/3/2019<br>4:09:22 PM  |
| <input type="checkbox"/> Services Pending verification - Direct Settlement                                                                                                                                                                                                                                         | LSP | 11/3/2019<br>4:09:28 PM  |
| <input type="checkbox"/> Additional Instructions WORLD AUTO VIRTUAL ACC PLEASE DO NOT FINALISE REPAIR.                                                                                                                                                                                                             | LSP | 11/3/2019<br>4:09:31 PM  |
| <input type="checkbox"/> IA UPLOADED IN VIEWS                                                                                                                                                                                                                                                                      | LSP | 12/3/2019<br>3:40:32 PM  |
| <input type="checkbox"/> FILE PASS TO ASHER                                                                                                                                                                                                                                                                        | LSP | 14/3/2019<br>10:09:07 AM |
| <input type="checkbox"/> 8/4/19 1:51 PM TAN Jas ---- hi, please update IA. thanks.                                                                                                                                                                                                                                 | LSP | 8/4/2019<br>6:42:53 PM   |
| <input type="checkbox"/> FILE TRANSFER TO VIVIAN                                                                                                                                                                                                                                                                   | SRY | 29/5/2019<br>1:52:06 PM  |
| <input type="checkbox"/> REC'D TP ESTIMATE_F FROM RASUL**PASS TO VIVIAN                                                                                                                                                                                                                                            | STU | 18/6/2019<br>1:58:10 PM  |
| <input type="checkbox"/> 18.6.19 Receive Estimate                                                                                                                                                                                                                                                                  | LPF | 18/6/2019<br>2:32:51 PM  |
| <input type="checkbox"/> 24.7.19 receive LOD from TP via email                                                                                                                                                                                                                                                     | LPF | 24/7/2019<br>10:11:01 AM |
| <input type="checkbox"/> Dear Jas, we refer to the above matter Liability(TP) 100% Proposed repair cost \$15,506.57 Loss of use \$1,120.00 no. of days 14days x\$ 80.00 Loss of rental \$ no. of days Loss of income \$ no. of days LTA search fees \$2.00 Others \$ Proposed Total Thank you Vivian Lau( 30.7.19) | LPF | 30/7/2019<br>5:07:59 PM  |
| <input type="checkbox"/> 8/2/19 9:40 AM TAN Jas-----are they repairing on part by part or lump sum ? the repair cost is on the high side. please get your surveyor to review the cost. thanks.                                                                                                                     | LSP | 5/8/2019<br>8:51:39 AM   |

27/9/19  
 TP proposed.  
 \$ 15500 (all-in).  
 \$15,500 (all-in).



## Re:TP MANDATE IA-S9M01GAV

Type

🔗 Question

Message

are they repairing on part by part or lump sum ? the repair cost is on the high side. please get your surveyor to review the cost. thanks.

Reply



WORLD AUTO PTE LTD

47 JALAN PEMIMPIN #01-02/03

HALCYON 2

SINGAPORE 577200

Tel: 64513933 Fax: 64557576

Date: 17/6/2019

Your ref: XE 7754B (insured)

Our ref: TP/2505/19

AXA Insurance Singapore Pte Ltd  
8 Shenton Way  
#24-01 AXA Tower  
Singapore 068811

BY EMAIL

Dear Sirs

**ACCIDENT INVOLVING SLT 2573C & XE 7754B ON 7.3.2019 ALONG SLIP ROAD INTO CTE**

Reference is made to the aforesaid matter (on behalf of our client M/S LCRF PTE LTD)

Enclosed herewith are the following documents for your attention:-

- A. Tax Invoice;
- B. Search fee;
- C. Letter of Authority

We are claiming the following:-

|                                 |   |                    |
|---------------------------------|---|--------------------|
| 1. Final bill                   | : | \$14,492.12        |
| 2. Gst 7%                       | : | \$ 1,014.45        |
| 3. Search fee                   | : | \$ 2.00            |
| 4. PRI (\$80 x 2)               | : | \$ 160.00          |
| 5. Loss of use (\$80 x 12 days) | : | \$ 960.00          |
|                                 |   | <u>\$16,628.57</u> |

Kindly let us have your clients' mandate to settle.

Yours faithfully,

For: World Auto Pte Ltd

Encls:

WORLD AUTO PTE LTD  
 47 JALAN PEMIMPIN #01-02/03 HALCYON 2 BLDG  
 S'PORE 577200  
 Tel No. : 64513933 Fax No. : 64557576  
 E-Mail : worldaut@singnet.com.sg  
 Website : www.worldauto.com.sg  
 Tax Reg. No. : 200006765H Buss. Reg. No. : 200006765H

Page 1 / 2

AXA INSURANCE SINGAPORE PTE LTD  
 8 SHENTON WAY #24-01 AXA TOWER  
 S'PORE 068811

Attention : Motor Claim Department  
 Contact : 68804888 Fax No. : 68804838

## Tax Invoice : F189395

Date : 17/06/2019  
 Vehicle Num. : SLT 2573C  
 Make/Model : TOYOTA PRIUS, 1.8 HYBRID  
 Chassis/Eng# :  
 Accident Date : 07/03/2019  
 Claim No. : TP/2505/2019  
 Reference :  
 Policy No. :

| S/N                  | Quantity | Particular                      | Unit Price | Amount SS |
|----------------------|----------|---------------------------------|------------|-----------|
| LIST ITEMS :         |          |                                 |            |           |
| 1.                   | 1        | REAR TAILGATE                   |            | 922.50    |
| 2.                   | 1        | REAR TAILGATE LOCK              |            | 477.40    |
| 3.                   | 1        | TAILGATE OUTER GARNISH          |            | 891.00    |
| 4.                   | 1        | TAILGATE PRIUS EMBLEM           |            | 60.50     |
| 5.                   | 1        | TAILGATE HYBRID EMBLEM          |            | 52.30     |
| 6.                   | 1        | TAILGATE INNER TRIM LOWER       |            | 350.00    |
| 7.                   | 1        | TAILGATE STOPPER                |            | 1,345.00  |
| 8.                   | 2        | TAILGATE STOPPER                | 30.50      | 61.00     |
| 9.                   | 1        | REAR WINDSCREEN GLASS           |            | 1,554.90  |
| 10.                  | 1        | REAR TAILGATE LOWER GLASS       |            | 720.90    |
| 11.                  | 2        | TAILGATE DAMPER                 | 232.40     | 464.80    |
| 12.                  | 2        | TAILGATE HINGE                  | 78.50      | 157.00    |
| 13.                  | 1        | REAR BUMPER                     |            | 423.90    |
| 14.                  | 1        | REAR LOWER BUMPER               |            | 552.30    |
| 15.                  | 1        | REAR BUMPER SIDE RETAINER RH    |            | 111.50    |
| 16.                  | 1        | REAR BUMPER TAILLAMP RH         |            | 481.90    |
| 17.                  | 1        | TAILLAMP RH                     |            | 433.70    |
| 18.                  | 1        | REAR END PANEL                  |            | 623.90    |
| 19.                  | 1        | REAR END PANEL TOP GARNISH      |            | 135.60    |
| 20.                  | 1        | REAR BOOT WEATHER STRIP         |            | 356.80    |
| 21.                  | 1        | REAR BOOT FLOOR BOARD           |            | 890.00    |
| 22.                  | 1        | REAR FENDER RH                  |            | 817.50    |
| 23.                  | 1        | ROOF PANEL GARNISH REAR         |            | 631.50    |
| 24.                  | 1        | ROOF PANEL SIDE GARNISH REAR    |            | 95.00     |
| 25.                  | 1        | TAILLAMP PANEL RH               |            | 151.80    |
| 26.                  | 1        | REAR FENDER AIR GRILLE RH       |            | 68.90     |
| 27.                  | 1        | 3RD BRAKE LIGHT                 |            | 194.90    |
| 28.                  | 1        | REAR BOOT FOAM BOX RH           |            | 355.90    |
| 29.                  | 1        | REAR FENDER INNER TRIM COVER RH |            | 381.60    |
| 30.                  | 1        | REAR QUARTER PANEL EXTENSION RH |            | 75.20     |
| 31.                  | 1        | TAILGATE DAMPER BRACKET RH      |            | 60.00     |
| 32.                  | 1        | TAILLAMP GARNISH RH             |            | 55.00     |
| 33.                  | 1        | REAR TAILGATE LOCK COVER        |            | 45.80     |
| 34.                  | 2        | TAILLAMP GUIDE                  | 15.00      | 30.00     |
| 35.                  | 2        | TAILLAMP CLIP                   | 15.00      | 30.00     |
| 36.                  | 1        | REAR WINDSCREEN GLASS MOULDING  |            | 49.50     |
| List TotalSS :       |          |                                 |            | 14,109.50 |
| 25.00% Discount SS : |          |                                 |            | 3,527.38  |
|                      |          |                                 |            | 10,582.12 |

CONTINUE / ...

WORLD AUTO PTE LTD  
 47 JALAN PEMIMPIN #01-02/03 HALCYON 2 BLDG  
 S'PORE 577200  
 Tel No. : 64513933 Fax No. : 64557576  
 E-Mail : worldaut@singnet.com.sg  
 Website : www.worldauto.com.sg  
 Tax Reg. No. : 200006765H Buss. Reg. No. : 200006765H

Page 2 / 2

AXA INSURANCE SINGAPORE PTE LTD  
 8 SHENTON WAY #24-01 AXA TOWER  
 S'PORE 068811

Attention : Motor Claim Department  
 Contact : 68804888 Fax No. : 68804838

## Tax Invoice : F189395

Date : 17/06/2019  
 Vehicle Num. : SLT 2573C  
 Make/Model : TOYOTA PRIUS, 1.8 HYBRID  
 Chassis/Eng# :  
 Accident Date : 07/03/2019  
 Claim No. : TP/2505/2019  
 Reference :  
 Policy No. :

| S/N | Quantity | Particular                                                                                                 | Unit Price | Amount S\$ |
|-----|----------|------------------------------------------------------------------------------------------------------------|------------|------------|
| 1.  | 1SET     | SPECIAL NETT ITEMS :                                                                                       |            |            |
| 2.  | 1SET     | TAILGATE OUTER GARNISH CLIPS                                                                               |            | 30.00      |
| 3.  | 1SET     | TAILGATE INNER TRIM BOARD CLIPS                                                                            |            | 30.00      |
| 4.  | 1SET     | REAR BUMPER CLIPS                                                                                          |            | 30.00      |
| 5.  | 1SET     | REAR END PANEL TOP GARNISH CLIPS                                                                           |            | 30.00      |
| 6.  | 1        | REAR FENDER INNER TRIM COVER CLIPS                                                                         |            | 30.00      |
| 7.  | 1        | REAR NUMBER PLATE W/CASING                                                                                 |            | 40.00      |
|     |          | REAR WINDSCREEN SEALANT                                                                                    |            | 60.00      |
|     |          | Special Nett Total S\$ :                                                                                   |            | 250.00     |
|     |          | LABOUR :                                                                                                   |            |            |
|     |          | REPLACE REAR WINDSCREEN GLASS (x2 GLASS)                                                                   |            | 200.00     |
|     |          | CHECK RECTIFY WIRINGS WHERE NECESSARY                                                                      |            | 30.00      |
|     |          | TRANSFER REAR BOOTLID MECHANISM & ACCESSORIES                                                              |            | 80.00      |
|     |          | REMOVE & REPLACE DAMAGED PARTS TO FACILITATE REPAIRS<br>INCLUDING PANEL BEAT, CUT/WELD, STRAIGHTEN CHASSIS |            | 1,600.00   |
|     |          | REMOVE & REFIT REAR UPHOLSTERY TO FACILITATE REPAIRS TO<br>REAR CHASSIS                                    |            | 100.00     |
|     |          | DEACTIVATE & REACTIVATE HV HYBRID SYSTEM TO FACILITATE<br>REPAIRS                                          |            | 250.00     |
|     |          | PERFORM WHOLE VEHICLE DIAGNOSTICS INCLUDING INITIALISE<br>HV HYBRID SYSTEM                                 |            | 200.00     |
|     |          | PUTTY & SPRAY PAINT ON AFFECTED AREAS (PEARL WHITE)                                                        |            | 1,200.00   |
|     |          | Labour Total S\$ :                                                                                         |            | 3,660.00   |

Total S\$ : 14,492.12  
 GST 7% S\$ : 1,014.45  
 Amount Due S\$ : 15,506.57  
 =====

WORLD AUTO PTE LTD



## Re:RE: Re:RE: Re:TP MANDATE IA-S9M01GAV

Type

🔗 Question

Message

proceed.

Reply



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19004350/R1gb3s2

8 SHENTON WAY #24-01  
AXA TOWERSINGAPORE 068811  
ATTN: JAS TAN

Date : 13-12-2019



Code : ASM

### 1. Policy Particulars :- THIRD PARTY CLAIM

|              |              |                |            |
|--------------|--------------|----------------|------------|
| Insured Veh. | XE 7754B     | Veh. Inspected | SLT 2573C  |
| Policy No.   | VCA/P1869229 | Coverage (\$)  | 0.00       |
| Claim No.    | S9M01GAV     | Excess (\$)    | 0.00       |
| Assign From  | JAS TAN      | Assign Date    | 11/03/2019 |

### 2. Vehicle Particulars & Condition

|              |                               |              |            |
|--------------|-------------------------------|--------------|------------|
| Make & Model | TOYOTA PRIUS HYBRID<br>1.8CVT | c.c          | 1797       |
| Engine No.   | HIDDEN                        | Year of Reg. | 2017       |
| Chassis No.  | JTDKB3FUX03562520             | Colour       | WHITE      |
| Odometer     | 102176                        | Steering     | IN ORDER   |
| Brakes       | IN ORDER                      | Modification | SPORTS RIM |
| General      | FAIR                          |              |            |

### 3. Conditions of Tyres

|                | Size       | Make   | Balance |
|----------------|------------|--------|---------|
| R/H Front Tyre | 195/65 R15 | ROVELO | 6 mm    |
| L/H Front Tyre | 195/65 R15 | ROVELO | 6 mm    |
| R/H Rear Tyre  | 195/65 R15 | ROVELO | 6 mm    |
| L/H Rear Tyre  | 195/65 R15 | ROVELO | 6 mm    |

### 4. Description of Damages

|                                                                            |
|----------------------------------------------------------------------------|
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.<br>DAMAGES SEE DETAILS. |
|----------------------------------------------------------------------------|

### 5. General Information

|                |                    |                 |            |
|----------------|--------------------|-----------------|------------|
| Accident Date  | 07/03/2019         | Inspection Date | 11/03/2019 |
| Survey held at | NO.1 KRANJI LOOP   |                 |            |
| Repairer       | WORLD AUTO PTE LTD |                 |            |

### 5a. Remarks

|                                                                                                                                        |
|----------------------------------------------------------------------------------------------------------------------------------------|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|----------------------------------------------------------------------------------------------------------------------------------------|

### 5b. Estimate Days of Repair

|                                     |                 |
|-------------------------------------|-----------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | 12 Working Days |
|-------------------------------------|-----------------|



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLT 2573C

| Qty | Description of Parts                              | Condition                    | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|---------------------------------------------------|------------------------------|---------------------------|-------------------|
|     | <b>REPLACEMENT OF PARTS</b>                       |                              |                           |                   |
| 1   | REAR TAILGATE (CONSISTENT)                        | BENT                         | 922.50                    | 922.50            |
| 1   | REAR TAILGATE LOCK (CONSISTENT)                   | JAMMED                       | 477.40                    | 477.40            |
| 1   | REAR TAILGATE OUTER GARNISH (CONSISTENT)          | DEFORMED                     | 891.00                    | 891.00            |
| 1   | REAR TAILGATE PRIUS EMBLEM (CONSISTENT)           | NECESSARY                    | 60.50                     | 60.50             |
| 1   | REAR TAILGATE HYBRID EMBLEM (CONSISTENT)          | NECESSARY                    | 52.30                     | 52.30             |
| 1   | REAR TAILGATE INNER TRIM BOARD UPPER (CONSISTENT) | SERVICEABLE                  | 320.00                    | -                 |
| 1   | REAR TAILGATE INNER TRIM BOARD LOWER (CONSISTENT) | DEFORMED                     | 350.00                    | 350.00            |
| 1   | REAR TAILGATE SPOILER (CONSISTENT)                | CRACKED                      | 1,345.00                  | 1,345.00          |
| 2   | REAR TAILGATE STOPPER @ \$30.50 (CONSISTENT)      | NECESSARY                    | 61.00                     | 61.00             |
| 1   | REAR TAILGATE WINDSCREEN GLASS (CONSISTENT)       | BROKEN                       | 1,554.90                  | 1,554.90          |
| 1   | REAR TAILGATE LOWER GLASS (CONSISTENT)            | BROKEN                       | 720.90                    | 720.90            |
| 2   | REAR TAILGATE DAMPER @ \$232.40 (CONSISTENT)      | NECESSARY                    | 464.80                    | 464.80            |
| 2   | REAR TAILGATE HINGE @ \$78.50 (CONSISTENT)        | BENT                         | 157.00                    | 157.00            |
| 1   | REAR BUMPER (CONSISTENT)                          | DEFORMED                     | 423.90                    | 423.90            |
| 1   | REAR LOWER BUMPER (CONSISTENT)                    | DEFORMED                     | 552.30                    | 552.30            |
| 1   | REAR BUMPER LOWER SIDE SPOILER LH (CONSISTENT)    | SERVICEABLE                  | 148.40                    | -                 |
| 1   | REAR BUMPER TOW COVER (CONSISTENT)                | SERVICEABLE                  | 28.90                     | -                 |
| 1   | REAR BUMPER REINFORCEMENT (CONSISTENT)            | SERVICEABLE                  | 318.80                    | -                 |
| 1   | REAR BUMPER SIDE RETAINER RH (CONSISTENT)         | NECESSARY                    | 111.50                    | 111.50            |
| 2   | REAR BUMPER TAIL LAMP @ \$481.90 (CONSISTENT)     | O/S BROKEN / N/S SERVICEABLE | 963.80                    | 481.90            |
| 1   | REAR BUMPER WIRING HARNESS (CONSISTENT)           | SERVICEABLE                  | 165.80                    | -                 |
| 2   | REAR TAIL LAMP @ \$433.70 (CONSISTENT)            | O/S BROKEN / N/S SERVICEABLE | 867.40                    | 433.70            |
| 1   | REAR END PANEL (CONSISTENT)                       | BENT                         | 623.90                    | 623.90            |
| 1   | REAR END PANEL TOP GARNISH (CONSISTENT)           | DEFORMED                     | 135.60                    | 135.60            |
| 1   | REAR BOOT WEATHERSTRIP (CONSISTENT)               | NECESSARY                    | 356.80                    | 356.80            |
| 1   | REAR BOOT FLOOR BOARD (CONSISTENT)                | DEFORMED                     | 890.00                    | 890.00            |
| 1   | REAR FENDER RH (CONSISTENT)                       | BUCKLED                      | 817.50                    | 817.50            |
| 1   | ROOF PANEL GARNISH REAR (CONSISTENT)              | CRACKED                      | 631.50                    | 631.50            |

Report Ref No. CC4/ASM19004350/R1gb3s2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

| Qty | Description of Parts                                         | Condition   | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|--------------------------------------------------------------|-------------|---------------------------|-------------------|
| 1   | ROOF PANEL SIDE GARNISH REAR (CONSISTENT)                    | CRACKED     | 95.00                     | 95.00             |
| 1   | TAIL LAMP PANEL RH (CONSISTENT)                              | BENT        | 151.80                    | 151.80            |
| 1   | REAR FENDER AIR GRILLE - RH (CONSISTENT)                     | DEFORMED    | 68.90                     | 68.90             |
| 1   | REAR FENDER QUARTER GARNISH RH (CONSISTENT)                  | SERVICEABLE | 199.10                    | -                 |
| 1   | 3RD BRAKE LAMP (CONSISTENT)                                  | BROKEN      | 194.90                    | 194.90            |
| 1   | REAR BOOT FOAM BOX LH (CONSISTENT)                           | SERVICEABLE | 355.90                    | -                 |
| 1   | REAR BOOT FOAM BOX RH (CONSISTENT)                           | CRACKED     | 355.90                    | 355.90            |
| 1   | REAR BOOT TOOLKIT FOAM BOX CENTRE (CONSISTENT)               | SERVICEABLE | 322.80                    | -                 |
| 1   | SPARE TYRE LOCKING BOLT (CONSISTENT)                         | SERVICEABLE | 32.00                     | -                 |
| 1   | REAR FENDER INNER TRIM COVER RH (CONSISTENT)                 | DEFORMED    | 381.60                    | 381.60            |
| 1   | REAR QUARTER PANEL EXTENSION RH (CONSISTENT) (ADDITIONAL)    | BENT        | 75.20                     | 75.20             |
| 1   | REAR TAILGATE DAMPER BRACKET RH (CONSISTENT) (ADDITIONAL)    | BENT        | 60.00                     | 60.00             |
| 1   | REAR TAIL LAMP GARNISH RH (CONSISTENT) (ADDITIONAL)          | DEFORMED    | 55.00                     | 55.00             |
| 1   | REAR TAILGATE LOCK COVER (CONSISTENT) (ADDITIONAL)           | DEFORMED    | 45.80                     | 45.80             |
| 2   | REAR TAIL LAMP GUIDE @ \$15.00 (CONSISTENT) (ADDITIONAL)     | BROKEN      | 30.00                     | 30.00             |
| 2   | REAR TAIL LAMP CLIP @ \$15.00 (CONSISTENT) (ADDITIONAL)      | NECESSARY   | 30.00                     | 30.00             |
| 1   | SET REAR WINDSCREEN GLASS MOULDING (CONSISTENT) (ADDITIONAL) | NECESSARY   | 49.50                     | 49.50             |
|     | LESS 25% DISCOUNT                                            |             | -4,229.21                 | -3,527.38         |
|     |                                                              |             | 12,687.59                 | 10,582.12         |
|     | <b>SPECIAL NETT ITEMS</b>                                    |             |                           |                   |
| 1   | SET REAR TAILGATE OUTER GARNISH CLIPS (SN) (CONSISTENT)      | NECESSARY   | 30.00                     | 30.00             |
| 1   | SET REAR TAILGATE INNER TRIM BOARD CLIPS (SN) (CONSISTENT)   | NECESSARY   | 30.00                     | 30.00             |
| 1   | SET REAR BUMPER CLIP (SN) (CONSISTENT)                       | NECESSARY   | 30.00                     | 30.00             |
| 1   | SET REAR END PANEL TOP GARNISH CLIPS (SN) (CONSISTENT)       | NECESSARY   | 30.00                     | 30.00             |
| 1   | SET REAR FENDER INNER TRIM COVER CLIPS (SN) (CONSISTENT)     | NECESSARY   | 30.00                     | 30.00             |

Report Ref No. CC4/ASM19004350/R1gb3s2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

| Qty                                | Description of Parts                                                                                                                                       | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|---------------------------|-------------------|
| 1                                  | SET REAR NUMBER PLATE W/CASING (SN) (CONSISTENT) (ADDITIONAL)                                                                                              | CRACKED   | 40.00                     | 40.00             |
| 1                                  | REAR WINDSCREEN SEALANT (SN) (CONSISTENT) (ADDITIONAL)                                                                                                     | NECESSARY | 80.00                     | 60.00             |
|                                    |                                                                                                                                                            |           | 270.00                    | 250.00            |
|                                    | <b>LABOUR</b>                                                                                                                                              |           |                           |                   |
|                                    | REPLACE REAR WINDSCREEN GLASS.                                                                                                                             |           | 360.00                    | 200.00            |
|                                    | WIRING CHECK AND RECTIFY WHERE NECESSARY.                                                                                                                  |           | 180.00                    | 30.00             |
|                                    | TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES.                                                                                                           |           | 180.00                    | 80.00             |
|                                    | REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING PANEL BEAT, CUT / WELD, STRAIGHTEN CHASSIS WHERE NECESSARY AND REPLACE ABOVE PARTS. |           | 2,200.00                  | 1,600.00          |
|                                    | REMOVE REAR UPHOLSTERY IN ORDER TO FACILITATE REPAIRS TO REAR CHASSIS AND REFIT BACK SAME.                                                                 |           | 280.00                    | 100.00            |
|                                    | DEACTIVATE HV HYBRID SYSTEM IN ORDER TO FACILITATE REPAIRS AND REACTIVATE BACK SAME (HV HYBRID SYSTEM SAFETY PROCEDURES).                                  |           | 450.00                    | 250.00            |
|                                    | PERFORM WHOLE VEHICLE DIAGNOSTIC INCLUDING INITIALISE HV HYBRID SYSTEM (HV HYBRID SYSTEM SAFETY PROCEDURES).                                               |           | 450.00                    | 200.00            |
|                                    | PUTTY AND SPRAY PAINT ALL AFFECTED AREAS. (INNER / OUTER, PEARL WHITE)                                                                                     |           | 2,000.00                  | 1,200.00          |
|                                    |                                                                                                                                                            |           | 6,100.00                  | 3,660.00          |
| <b>GRAND TOTAL</b>                 |                                                                                                                                                            |           | <b>19,057.59</b>          | <b>14,492.12</b>  |
| <b>RECOMMENDED COST OF REPAIRS</b> |                                                                                                                                                            |           |                           | <b>14,492.12</b>  |

Report Ref No. CC4/ASM19004350/R1gb3s2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.