

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

AXA INSURANCE SINGAPORE PTE LTD

8 SHENTON WAY #24-01 AXA TOWER

068811

Attention : Motor Claim Department

Contact : 68804888 Fax No. : 880 4838

Estimate : ES190015

Date : 07/03/2019

Vehicle Num. : SLT 2573C(LCR)

Make/Model : TOYOTA PRIUS HYBRID 1.8S

Chassis/Eng# :

Accident Date : 07/03/2019

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	REAR TAILGATE <i>PA</i>		922.50
2.	1	REAR TAILGATE LOCK <i>jam</i>		477.40
3.	1	REAR TAILGATE OUTER GARNISH		891.00
4.	1	REAR TAILGATE PRIUS EMBLEM <i>neu</i>		60.50
5.	1	REAR TAILGATE HYBRID EMBLEM <i>neu</i>		52.30
6.	1	REAR TAILGATE INNER TRIM BOARD UPPER <i>X</i>		320.00
7.	1	REAR TAILGATE INNER TRIM BOARD LOWER <i>DE</i>		350.00
8.	1	REAR TAILGATE SPOILER <i>CR</i>		1,345.00
9.	2	REAR TAILGATE STOPPER <i>neu</i>	30.50	61.00
10.	1	REAR TAILGATE WINDSCREEN GLASS <i>bro</i>		1,554.90
11.	1	REAR TAILGATE LOWER GLASS <i>bro</i>		720.90
12.	2	REAR TAILGATE DAMPER <i>neu</i>	232.40	464.80
13.	2	REAR TAILGATE HINGE <i>PA</i>	78.50	157.00
14.	1	REAR BUMPER <i>DE</i>		423.90
15.	1	REAR LOWER BUMPER <i>DE</i>		552.30
16.	1	REAR BUMPER LOWER SIDE SPOILER LH <i>X</i>		148.40
17.	1	REAR BUMPER TOW COVER <i>X</i>		28.90
18.	1	REAR BUMPER REINFORCEMENT <i>?</i>		318.80
19.	1	REAR BUMPER SIDE RETAINER RH <i>neu</i>		111.50
20.	2	REAR BUMPER TAIL LAMP <i>RH - bro / LH - ?</i>	481.90	963.80
21.	1	REAR BUMPER WIRING HARNESS <i>?</i>		165.80
22.	2	REAR TAIL LAMP <i>RH - bro / LH - ?</i>	433.70	867.40
23.	1	REAR END PANEL <i>PA</i>		623.90
24.	1	REAR END PANEL TOP GARNISH <i>DE</i>		135.60
25.	1	REAR BOOT WEATHER STRIP <i>neu</i>		356.80
26.	1	REAR BOOT FLOOR BOARD <i>DE</i>		890.00
27.	1	REAR FENDER RH <i>neu</i>		817.50
28.	1	ROOF PANEL GARNISH REAR <i>CR</i>		631.50
29.	1	ROOF PANEL SIDE GARNISH REAR <i>CR</i>		95.00

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

AXA INSURANCE SINGAPORE PTE LTD
 8 SHENTON WAY #24-01 AXA TOWER
 068811

Attention : Motor Claim Department
 Contact : 68804888 Fax No. : 880 4838

Estimate : ES190015

Date : 07/03/2019
 Vehicle Num. : SLT 2573C(LCR)
 Make/Model : TOYOTA PRIUS HYBRID 1.8S
 Chassis/Eng# :
 Accident Date : 07/03/2019
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
30.	1	TAIL LAMP PANEL RH <i>RA</i>		151.80
31.	1	REAR FENDER AIR GRILLE - RH <i>DE</i>		68.90
32.	1	REAR FENDER QUARTER GARNISH RH <i>X</i>		199.10
33.	1	3RD BRAKE LAMP <i>bro</i>		194.90
34.	1	REAR BOOT FOAM BOX LH <i>?</i>		355.90
35.	1	REAR BOOT FOAM BOX RH <i>CR</i>		355.90
36.	1	REAR BOOT TOOLKIT FOAM BOX CENTRE <i>?</i>		322.80
37.	1	SPARE TYRE LOCKING BOLT <i>?</i>		32.00
38.	1	REAR FENDER INNER TRIM COVER RH <i>DE</i>		381.60
List TotalS\$:				16,571.30
25.00% Discount S\$:				4,142.83
				12,428.47
SPECIAL NETT ITEMS :				
1.	1SET	REAR TAILGATE OUTER GARNISH CLIPS <i>me</i>		30.00
2.	1SET	REAR TAILGATE INNER TRIM BOARD CLIPS <i>me</i>		30.00
3.	1SET	REAR BUMPER CLIP <i>me</i>		30.00
4.	1SET	REAR END PANEL TOP GARNISH CLIPS <i>me</i>		30.00
5.	1SET	REAR FENDER INNER TRIM COVER CLIPS <i>me</i>		30.00
Special Nett Total S\$:				150.00
LABOUR :				
REPLACE REAR WINDSCREEN GLASS (X2 GLASS)				<i>200</i> 360.00
WIRINGS CHECK AND RECTIFY WHERE NECESSARY				<i>30</i> 180.00
TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES				<i>80</i> 180.00

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

AXA INSURANCE SINGAPORE PTE LTD

8 SHENTON WAY #24-01 AXA TOWER

068811

Attention : Motor Claim Department

Contact : 68804888 Fax No. : 880 4838

Estimate : ES190015

Date : 07/03/2019

Vehicle Num. : SLT 2573C(LCR)

Make/Model : TOYOTA PRIUS HYBRID 1.8S

Chassis/Eng# :

Accident Date : 07/03/2019

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING PANEL BEAT, CUT/WELD, STRAIGHTEN CHASSIS WHERE NECESSARY AND REPLACE ABOVE PARTS	1600	2,200.00
		REMOVE REAR UPHOLSTERY IN ORDER TO FACILITATE REPAIRS TO REAR CHASSIS AND REFIT BACK SAME	100	280.00
		DEACTIVATE HV HYBRID SYSTEM IN ORDER TO FACILITATE REPAIRS AND REACTIVATE BACK SAME (HV HYBRID SYSTEM SAFETY PROCEDURES)	250	450.00
		PERFORM WHOLE VEHICLE DIAGNOSTICS INCLUDING INITIALISE HV HYBRID SYSTEM (HV HYBRID SYSTEM SAFETY PROCEDURES)	200	450.00
		PUTTY AND SPRAY PAINT ALL AFFECTED AREAS (INNER/OUTER, PEARL WHITE)	1200	2,000.00
		Labour Total S\$:		6,100.00

Resnu
Hr 90010068

12 days

P/P

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

E. & O.E.

11/03/19

191415

Total S\$:

18,678.47

=====

Resay by paint

for WORLD AUTO PTE LTD