

**Sng Ah Tee Motor Pte Ltd**  
**Blk 3 Pioneer Road North,**  
**#01-18,**  
**628457**

**Claim Reference:**  
**Assessment number: SJJ1455T-AXA-TP**  
**Version: 1810**  
**Date calculated: 03/08/2019 02:03 PM**

**Full Report**  
**Registration: SJJ1455T**  
**Printed: 08/03/2019 2:04 PM**

### Summary Information

#### Claim

Location:	Singapore (SG)	Work Provider:	AXA Insurance Pte Ltd
Printed by:	DARREN SNG	Currency:	SGD
Claim Reference:		Date of Incident:	2019-01-29
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

### Vehicle Details

#### Vehicle

Manufacturer:	TOYOTA
Model:	RUSH (F700)
Sub Model:	BASE MODEL
Model Sheet Number:	70 R1 01
Registration:	SJJ1455T
VIN number:	
Odometer:	


### Vehicle Condition

#### Vehicle Status

Pre-Accident Damage:  
Date of Inspection:

#### Damage Areas

All ☐  
Underbody ☐



**Sng Ah Tee Motor Pte Ltd**  
**Blk 3 Pioneer Road North,**  
**#01-18,**  
**628457**

Claim Reference:

Assessment number: SJJ1455T-AXA-TP

Version: 1810

Date calculated: 03/08/2019 02:03 PM

Full Report

Registration: SJJ1455T

Printed: 08/03/2019 2:04 PM

**Labour**

Code	Description	Time Base 10 WU/h	Price = 45.00 SGD/h	
			WU	Price SGD
520011)	RENEW FRONT BUMPER (REMOVED)		5.0	22.50
531011	R + R L/F WING		18.0	81.00
	INCLUDES: R + R FRONT BUMPER, HEADLAMP			
	AND WHEELHOUSE COVER			
NO NUMBER	R + R R/F BUMPER MOUNTING		1.0	4.50
<b>Labour Cost</b>		<b>Hrs</b>	<b>WU</b>	
<b>Panel / Mechanical Labour</b>		2.40	24.0	108.00
<b>Total of Labour</b>				108.00

**Paint**

Paint Work		SYSTEM AZT	Time Basis 10WU/h	
Code	Description		WU	Price SGD
	L/F WING NEW PART PAINTING		9.0	
	FRONT BUMPER NEW PART PAINT K1R		10.0	
	TOWING EYE COVER NEW PART PAINT K1R		3.0	

**Paint Material Per Part**

Code	Description	Price SGD
0741	L/F WING NEW PART PAINTING	14.11
0283	FRONT BUMPER NEW PART PAINT K1R	41.88
0285	TOWING EYE COVER NEW PART PAINT K1R	1.05

**Labour Cost - Paint**

	45.00 SGD/h	Hrs	WU	Price SGD
Factor			22.0	
Time Paint		0.70	7.0	31.50
Preparation Main Work Metal		0.30	3.0	13.50
Preparation Comp. Work Plastic		3.20	32.0	144.00
<b>Total</b>	<b>10 WU/h</b>			

**Sng Ah Tee Motor Pte Ltd**  
**Blk 3 Pioneer Road North,**  
**#01-18,**  
**628457**

Claim Reference:  
 Assessment number: **SJJ1455T-AXA-TP**  
 Version: **1810**  
 Date calculated: **03/08/2019 02:03 PM**

**LKK Auto Consultants** hence notify  
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

**Full Report**  
 Registration: **SJJ1455T**  
 Printed: **08/03/2019 2:04 PM**

Material Cost - Paint	Price SGD
New Part Painting	14.11
New Part Painting - Plastic K1R	42.93
Material-constant Metal	18.10
Material-constant Plastic	9.00
<b>Total</b>	<b>84.14</b>

**Spare Parts**

				prices as at 2015-06-01/01
Code	Description	Part Number	Supplier	Price SGD
0283	FRONT BUMPER	52119 BZ110	✓ DO	200.00
0285	TOWING EYE COVER	52128 BZ070	X NN	25.00
0317	L/F BUMPER BRACKET	52116 BZ050	✓ DR	35.00
0318	R/F BUMPER BRACKET	52115 BZ050	X NN	35.00
0350	FRT BUMPER CLAMP KIT	USE SINGLE PARTS	✓ NEC	15.00
0741	L/F WING	53812 BZ130	✓ DO	170.00
0789	L/F WING CLAMP KIT	91661 60616	X NN	12.00
0841	L/F WHEELHOUSE COVER	53876 BZ070	X NN	45.00
f: OEM Parts	<b>Savings</b>			<b>0.00</b>
n: Non-OEM Parts	<b>Subtotal</b>			<b>537.00</b>
u: Used parts	<b>Addition(+15.00%)</b>			<b>80.55</b>
	<b>Total</b>			<b>617.55</b>

**Extras**

Code	Description	Price SGD
1000	APPLY ANTI RUST COAT ANTI RUST COAT	X 80.00*
	<b>Total Extras</b>	<b>80.00</b>

Steve (LKK) *Wm* *28/3/19 11:30am*  
 8322 8813 *3 chys*  
*L/S*  
*Ry AF sply*

**Sng Ah Tee Motor Pte Ltd  
Blk 3 Pioneer Road North,  
#01-18,  
628457**

Claim Reference:

Assessment number: SJJ1455T-AXA-TP

Version: 1810

Date calculated: 03/08/2019 02:03 PM

**Full Report**

Registration: SJJ1455T

Printed: 08/03/2019 2:04 PM

**Final Calculation**

	SGD	SGD
<b>Parts</b>	537.00	
Addition(+15.00%)	80.55	
<b>Total Parts</b>		<b>617.55</b>
<b>Labour Time Base 10 WU/h</b>		
Total 24.0 WU X 45.00 SGD/h	108.00	
<b>Total of Labour</b>		<b>108.00</b>
<b>Total Of Extras</b>		<b>80.00</b>
<b>Paint Work Time Base 10 WU/h</b>		
Labour Cost 32.0 WU X 45.00 SGD/h	144.00	
Material Cost	84.14	
<b>Total Paint Including Material</b>		<b>228.14</b>
<b>Repair Cost Excludes GST</b>		<b>1,033.69</b>
GST (+7.0%)		<b>72.36</b>
<b>Repair Cost Included GST</b>		<b>1,106.05</b>

**Comments**

\* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS