

15/5/2010

INS. CASE OWNER:

CC3/CTI1900

4256, K2J657

LKK:

IDAC:

Surveyor:

Enlvin

DOI:

ASSIGNMENT

8/11/19

Date / Time:

8/11/19

Registered in Merimen:

Pre-assign / CCU / FTE

SUD 6155J

Claim No.:

SWMH021017



Insured Vehicle No.:

Name of Insured:

EAS40RINE CAR RENTAL

Policy No.:

DMTESN 1904101900

Insured Tel No.:

HP:

D.O.A.:

8/11/19

Make / Model:

Mazda

Place of Accident:

Cinco Rd

Excess Sec II :\$5

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Muhammad Hafiz Khan Bin Abdul

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability:

% Final ? Yes / No

SUD 6155J

SHB8437R

SHC8124M



INSRS:

WSP:

Tel:

Liability:

RMKS:

01



INSRS:

WSP:

Tel:

Liability:

RMKS:

premier
TP

INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time	STAGE	DATE / PIC
	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	27/10/19 - JIMMY - au
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	☒ ☐
	After call ltr to OI:	☒ ☐
	Authorisation To Act:	☒ ☐
	Release Voucher:	☒ ☐
	Final Repair Bill:	☒ ☐
	Car Rental Invoice:	☒ ☐
	Towing Invoice:	☒ ☐
	LTA / GIA:	☒ ☐
	Medical Bill:	☒ ☐
	PIR:	☒ ☐
	Mandate/Reject Instruction:	☒ ☐
	LOD:	☒ ☐
	Payment Breakdown Form:	☒ ☐
	Post-Repair Photos:	☒ ☐
	Others:	☒ ☐

PRELIMINARY ADVICE Date/Time:		Sent By:	
FINALIZATION Date/Time:		Confirm with:	
Repair Cost:	\$5	() days) Reduction:	%
FINAL SETTLEMENT Date/Time: 11/10/19		Confirm with: Shafarati	
Final Liability:	% 100	(Agreed / Assessed) BOLA S/N No.:	28
Repair Cost: (w/bx)	\$5 6045.50		
Loss of Rental (LOR):	\$5 1489.80	(15 days) x \$99.32	
Loss of Use (LOU):	\$5 -	(\$ x days)	
Loss of Income (LOI):	\$5 -	(\$ x days)	
LOR only ☒ LOU only ☐	LOR + LOU ☐ LOR + LO ☐	[Tick only one]	
GIA/LTA Search	\$5 2.00		
Medical:	\$5 -		
Disbursement:	\$5 -	(e.g. Tow/ Independent)	
Legal Cost	\$5 -		
Total:	\$5 7537.50	Global Sum \$5:	
FINAL PAYMENT Date/Time:		Confirm with:	
Payee 1:	\$5 7537.30	Name 1:	Premier Automotive Services Pte Ltd
Payee 2: (Strike if N.A.)	\$5	Name 2:	
Payee 3: (Strike if N.A.)	\$5	Name 3:	



Auto
Consultants
Pte Ltd

Company Registration No. 199607109R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your ref: To Be Advised
Our ref: CC3/CTI19004356/K1jb3

Date: 11.03.2019

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.


SHB8437R

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 08.03.2019 at the premises of M/s Premier Automotive Services Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	14,591.50
Revised Estimate Amount	: S\$	7,060.70
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:
The vehicle sustained damages at the
Front & Rear Portion



Comments/Present Status:
Damages Consistent
Estimated normal period for repairs: 5 days

Yours faithfully,

KALVIN ANG
Licensed Appraiser

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

8-Mar-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8437 R

1 pc	Bonnet grille <i>X repair</i>	\$	385.00
1 pc	Support panel <i>X</i>	\$	645.00
1 pc	Front bumper <i>/</i>	\$	531.00
1 pc	Front bumper emblem <i>/</i>	\$	44.00
1 pc	Front bumper centre grille <i>X</i>	\$	174.00
1 pc	Front bumper lower stiffer <i>X</i>	\$	134.00
1 pc	Front bumper tow hook cover <i>/</i>	\$	14.00
1 pc	Front bumper lip <i>X</i>	\$	52.00
1 pc	Front bumper inner sponge <i>X</i>	\$	110.00
1 pc	Front bumper reinforcement <i>X</i>	\$	328.00
2 pcs	Front bumper o/s & n/s side retainer @ \$16.00 <i>X</i>	\$	32.00
2 pcs	Front bumper o/s & n/s upper bracket @ \$16.00 <i>X</i>	\$	32.00
2 pcs	Front bumper o/s & n/s support bracket @ \$16.00 <i>X</i>	\$	32.00
2 pcs	n/s & o/s headlamp @ \$1028.00 <i>X</i>	\$	2,056.00
2 pcs	Front bumper o/s & n/s fog lamp cover @ \$66.00 <i>X</i>	\$	132.00
1 pc	Boot lid <i>/</i>	\$	1,119.00
1 pc	Boot lid lock <i>/</i>	\$	99.00
1 pc	Bootlid lock cable <i>X</i>	\$	35.00
1 pc	Bootlid striker <i>X</i>	\$	21.00
1 pc	Bootlid emblem <i>/</i>	\$	27.00
1 pc	Bootlid CRDi <i>/</i>	\$	29.00
1 pc	Boot lid rubber weatherstrip <i>X</i>	\$	96.00
1 pc	Boot lid lower garnish <i>/</i>	\$	290.00
2 pcs	Bootlid hinges @ \$66.00 <i>/</i>	\$	132.00
1 pc	Bootlid inner trim <i>X</i>	\$	190.00
1 pc	End panel <i>/</i>	\$	250.00
1 pc	End panel inner garnish <i>/</i>	\$	74.00
1 pc	Rear bumper <i>/</i>	\$	696.00
1 pc	Rear bumper lower cover <i>/</i>	\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00 <i>X</i>	\$	58.00
1 pc	Rear bumper inner sponge <i>/</i>	\$	114.00
1 pc	Rear bumper reinforcement <i>/</i>	\$	607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00 <i>/</i>	\$	108.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00 <i>/</i>	\$	36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00 <i>/</i>	\$	36.00

8-Mar-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8437 R

2 pcs	Rear bumper reflector n/s & o/s @ \$46.00	X	\$	92.00
2 pcs	n/s & o/s tail lamp @ \$421.00	n/s - o/s x	\$	842.00
2 pcs	n/s & o/s reflector @ \$350.00	X	\$	700.00
1 pc	Exhaust pipe	X	\$	1,009.00
1 pc	Exhaust pipe hanger	X	\$	28.00
			\$	11,595.00
		Less 10%	\$	1,159.50
			\$	10,435.50

S/NETT

1 set	Rear bumper clips	/	\$	48.00
1 set	End panel inner garnish clips	X	\$	30.00
1 set	Bootlid inner trim clips	X	\$	52.00
1 set	Bootlid lower garnish clips	X	\$	60.00
1 set	Bootlid stickers	/	\$	100.00
1 set	Reverse sensor	/	\$	280.00 20
1 pc	Front no. plate with casing	/	\$	50.00 35
1 pc	Front bumper clips	/	\$	48.00
2 pcs	Front n/s & o/s head lamp lower clip @ \$6.00	X	\$	12.00
2 pcs	Front n/s & o/s head lamp side clip @ \$3.00	X	\$	6.00
			\$	50.00 20
	Sundry		\$	50.00 /
	Towing Fee		\$	80.00 X
	To check for wiring and to focus head lamps		\$	120.00 X
	To remove / refit the rear exhaust pipe		\$	120.00 X
	To top up aircon gas		\$	120.00 X
	To dismantle / replace reverse sensor to new bumper and reset to the same		\$	120.00 20
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		\$	180.00 50
	To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the the end panel. Including knock-out, straighten, repair, reshape and adjust of the floorboard compartment, etc		\$	1,400.00 1000
	To putty and spray painting on bootlid, bootlid lower garnish, rear bumper, floorboard compartment, end panel, front bumper		\$	1,200.00 1080
	To apply rustproofing on the repaired and replaced panels.		\$	150.00 50
			\$	14,591.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Kalina LKK
11/8/3/19 1700h, S
5 Days
L/s
After Repair g/LH

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)
THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.

Enquire Transaction History**Transaction History Details**

Log Date/Time: 27 Sep 2013 / 09:17:03 Receipt No.: AACCK001-AX239-130927-000003

Asset Type: Vehicle Transaction Amount: \$70,976.00

Asset ID: SHB8437R Channel: AA Counterless - CYCLE & CARRIAGE KIA PTE LTD

Transaction Type: 01.02 Register New Vehicle (AA)

Business Transaction Reference No.: 20130927091703896693

Vehicle No.: SHB8437R

Vehicle Type: H10 - Public Transport Taxi (Motor Car)

Vehicle Attachment 1: Air-Con (Taxi)

Vehicle Attachment 2: -

Vehicle Attachment 3: -

Vehicle Scheme: Taxi (Company)

First Registration Date: 27 Sep 2013

Original Registration Date: 27 Sep 2013

Vehicle Make: KIA

Vehicle Model: OPTIMA 1.7(A) DIESEL

Chassis No.: KNAGM414ME5446551

Engine No.: D4FDDH308044

Motor No.: -

Trailer Chassis No.: -

Propellant: Diesel

Passenger Capacity: 4

Engine Capacity: 1685

Power Rating: -

Unladen Weight: 1584

Maximum Laden Weight: 2050

Primary Color: Silver

Secondary Color: -

Manufacturing Year: 2013

Open Market Value: \$20,137.00

Minimum PARF Benefit: \$7,615.00

PARF Eligibility: Y

No. of Transfer: 0

Effective Ownership Date/Time: 27 Sep 2013 09:17:03

COE No.: 2013092701000781H

COE Expiry Date: 26 Sep 2021

COE Bid Category: -

Actual QP/PQP Paid Amount: \$58,144.00

Lifespan Expiry Date: 26 Sep 2021

Owner ID Type: Company

CASH SALE/WORK ORDER

No: AE 8399



PEOPLE'S VEHICLE SERVICE PTE LTD

BLK 3023A, UBI ROAD 1 #01-60, SINGAPORE 408717

TEL : 6743 1987 (3 LINES) FAX : 6743 0013

Reg No: 200415052W

Date, ...

8/3/19

寶號

Messrs:

車號

Vehicle No:

SHB 843 7R

車型

Model No:

KIA

由

From:

TP Pongol

到

To:

Ang

其他

Remark:

Collect key and memo omega

時間

Time:

09:00-09:30 / 10:00

AMOUNT: \$

注意：本公司對所拖之車輛，在進行中如有任何損失或破壞，一概由車主自行負責。

NOTE: Vehicle is towed at owner's risk. The company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed.

經手人

Authorised by:

MSB

收貨人

Received by:

WJ

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

8-Mar-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8437 R

1 pc	Bonnet grille <i>X repair</i>	\$	385.00
1 pc	Support panel <i>X su</i>	\$	645.00
1 pc	Front bumper <i>- Rehd</i>	\$	531.00
1 pc	Front bumper emblem <i>- su</i>	\$	44.00
1 pc	Front bumper centre grille <i>X su</i>	\$	174.00
1 pc	Front bumper lower stiffer <i>X su</i>	\$	134.00
1 pc	Front bumper tow hook cover <i>- su</i>	\$	14.00
1 pc	Front bumper lip <i>X su</i>	\$	52.00
1 pc	Front bumper inner sponge <i>X su</i>	\$	110.00
1 pc	Front bumper reinforcement <i>X su</i>	\$	328.00
2 pcs	Front bumper o/s & n/s side retainer @ \$16.00 <i>X su</i>	\$	32.00
2 pcs	Front bumper o/s & n/s upper bracket @ \$16.00 <i>X su</i>	\$	32.00
2 pcs	Front bumper o/s & n/s support bracket @ \$16.00 <i>X su</i>	\$	32.00
2 pcs	n/s & o/s headlamp @ \$1028.00 <i>X su</i>	\$	2,056.00
2 pcs	Front bumper o/s & n/s fog lamp cover @ \$66.00 <i>X su</i>	\$	132.00
1 pc	Boot lid <i>- Rehd</i>	\$	1,119.00
1 pc	Boot lid lock <i>- Rehd</i>	\$	99.00
1 pc	Bootlid lock cable <i>X su</i>	\$	35.00
1 pc	Bootlid striker <i>X su</i>	\$	21.00
1 pc	Bootlid emblem <i>- su</i>	\$	27.00
1 pc	Bootlid CRDi <i>- su</i>	\$	29.00
1 pc	Boot lid rubber weatherstrip <i>X su</i>	\$	96.00
1 pc	Boot lid lower garnish <i>- su</i>	\$	290.00
2 pcs	Bootlid hinges @ \$66.00 <i>- Rehd</i>	\$	132.00
1 pc	Bootlid inner trim <i>X su</i>	\$	190.00
1 pc	End panel <i>- Bracket</i>	\$	250.00
1 pc	End panel inner garnish <i>- su</i>	\$	74.00
1 pc	Rear bumper <i>- Rehd</i>	\$	696.00
1 pc	Rear bumper lower cover <i>- Rehd</i>	\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00 <i>X su</i>	\$	58.00
1 pc	Rear bumper inner sponge <i>- su</i>	\$	114.00
1 pc	Rear bumper reinforcement <i>- su</i>	\$	607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00 <i>- Rehd</i>	\$	108.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00 <i>- su</i>	\$	36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00 <i>- su</i>	\$	36.00

8-Mar-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8437 R

2 pcs	Rear bumper reflector n/s & o/s @ \$46.00	X <i>see</i>	\$	92.00
2 pcs	n/s & o/s tail lamp @ \$421.00	<i>n/s on o/s x see</i>	\$	842.00
2 pcs	n/s & o/s reflector @ \$350.00	X <i>see</i>	\$	700.00
1 pc	Exhaust pipe	X <i>see</i>	\$	1,009.00
1 pc	Exhaust pipe hanger	X <i>see</i>	\$	28.00
			\$	11,595.00
		Less 10%	\$	1,159.50
			\$	10,435.50

S/NETT

1 set	Rear bumper clips	<i>see</i>	\$	48.00
1 set	End panel inner garnish clips	X <i>see</i>	\$	30.00
1 set	Bootlid inner trim clips	X <i>see</i>	\$	52.00
1 set	Bootlid lower garnish clips	X <i>see</i>	\$	60.00
1 set	Bootlid stickers	<i>see</i>	\$	100.00
1 set	Reverse sensor	<i>see</i>	\$	280.00 <i>2m</i>
1 pc	Front no. plate with casing	<i>see</i>	\$	50.00 <i>35</i>
1 pc	Front bumper clips	<i>see</i>	\$	48.00
2 pcs	Front n/s & o/s head lamp lower clip @ \$6.00	X	\$	12.00
2 pcs	Front n/s & o/s head lamp side clip @ \$3.00	X	\$	6.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Sundry		\$	50.00 <i>2m</i>
Towing Fee		\$	50.00
To check for wiring and to focus head lamps		\$	80.00 X <i>1m</i>
To remove / refit the rear exhaust pipe		\$	120.00 X <i>1m</i>
To top up aircon gas		\$	120.00 X <i>1m</i>
To dismantle / replace reverse sensor to new bumper and reset to the same		\$	120.00 <i>1m</i>
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		\$	180.00 <i>1m</i>
To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the the end panel. Including knock-out, straighten, repair, reshape and adjust of the floorboard compartment, etc		\$	1,400.00
To putty and spray painting on bootlid, bootlid lower garnish, rear bumper, floorboard compartment, end panel, front bumper		\$	1,200.00
To apply rustproofing on the repaired and replaced panels.		\$	150.00 <i>50</i>
		\$	14,591.50

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)
THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

25/3/19

add 435650/500
see

Shu Pei (LKKAUTO)

From: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Sent: Thursday, 20 June 2019 2:34 PM
To: Shu Pei (LKKAUTO)
Cc: Chee So Chow
Subject: RE: OUR REF: SNM19D201017/TANKL - Direct Settlement - Accident Involving SLD6155J (OI : CTI - TBA) AND SHB8437R (TP : LKK REF - CC3/CTI19004356/K1jb3) on 28.02.2019
Attachments: SLD6155J.PDF

Without Prejudice

Dear Shu Pei,

We refer to your email below.

Attached is our insured's accident report as requested.

Thank you.

Regards

Tan Kah Leong
Assistant Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6193 | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Lim Shu Min
Sent: Thursday, 20 June, 2019 1:18 PM
To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>; Shu Pei (LKKAUTO) <shupeil@lkkauto.com>
Subject: OUR REF: SNM19D201017/TANKL - Direct Settlement - Accident Involving SLD6155J (OI : CTI - TBA) AND SHB8437R (TP : LKK REF - CC3/CTI19004356/K1jb3) on 28.02.2019

Dear Kah Leong,

Please revert LKK.

Thank you

Lim Shu Min

Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 63896156 | F: (65) 62247175

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Shu Pei (LKKAUTO) [<mailto:shupeil@lkkauto.com>]
Sent: Thursday, 20 June, 2019 9:24 AM
To: Lim Shu Min <shumin.lim@sg.cntaiping.com>
Subject: RE: Direct Settlement - Accident Involving SLD6155J (OI : CTI - TBA) AND SHB8437R (TP : LKK REF - CC3/CTI19004356/K1jb3) on 28.02.2019

Dear Shu Min,

Please be informed that OI vehicle number is should be SLD 6155J.

Amended subject email.

Thank you

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shu Pei (LKKAUTO)
Sent: Wednesday, 19 June 2019 4:08 PM
To: claimsdept@sg.cntaiping.com; Alfred Toh <alfred.toh@sg.cntaiping.com>
Subject: RE: Direct Settlement - Accident Involving SLR6155J (OI : CTI - TBA) AND SHB8437R (TP : LKK REF - CC3/CTI19004356/K1jb3) on 28.02.2019

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

Kindly advice whether insured has reported. If so, kindly let us have a copy of insured's accident report for our necessary action.

Thank you

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shu Pei (LKKAuto)

Sent: Monday, 27 May 2019 9:45 AM

To: claimsdept@sg.cntaiping.com; Alfred Toh <alfred.toh@sg.cntaiping.com>

Cc: Elaine Cheong <elaine.cheong@sg.cntaiping.com>

Subject: RE: Direct Settlement - Accident Involving SLR6155J (OI : CTI - TBA) AND SHB8437R (TP : LKK REF - CC3/CTI19004356/K1jb3) on 28.02.2019

WITHOUT PREJUDICE

URGENT

Dear Sir / Madam,

We refer to the above matter.

Kindly advice whether insured has reported. If so, kindly let us have a copy of insured's accident report for our necessary action.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shu Pei (LKKAuto)

Sent: Monday, 13 May 2019 12:17 PM

To: claimsdept@sg.cntaiping.com

Cc: Alfred Toh <alfred.toh@sg.cntaiping.com>; Elaine Cheong <elaine.cheong@sg.cntaiping.com>; Joy Irene (LKKAuto) <JoyIrene@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Subject: RE: Direct Settlement - Accident Involving SLR6155J (OI : CTI - TBA) AND SHB8437R (TP : LKK REF - CC3/CTI19004356/K1jb3) on 28.02.2019

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

Kindly advice whether insured has reported. If so, kindly let us have a copy of insured's accident report for our necessary action.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shu Pei (LKKAuto)

Sent: Monday, 11 March 2019 6:32 PM

To: claimsdept@sg.cntaiping.com

Cc: Alfred Toh <alfred.toh@sg.cntaiping.com>; Elaine Cheong <elaine.cheong@sg.cntaiping.com>; Joy Irene (LKKAuto) <JoyIrene@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Subject: Direct Settlement - Accident Involving SLR6155J (OI : CTI - TBA) AND SHB8437R (TP : LKK REF - CC3/CTI19004356/K1jb3) on 28.02.2019

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

We have inspected TP vehicle SHB 8437R at M/s Premier Automotive Services Pte Ltd on a WP basis and TP repairer proposed for a direct settlement.

Enclosed for your perusal is:

- TP GIA report
- Estimated cost of repair
- Preliminary advice

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action

Kindly take note that the case handler in-charge is Joy and she can be contacted at DID: 6841 2409.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

RENTAL AGREEMENT

EasyDrive Car Rental

200 Jalan Sultan Textile Centre #02-38 Singapore 199018

Tel: 63339441 Fax: 68832418 HP: 96735989

Registration No. 53375868L

Car Rental / Leasing Agreement

Date: 27/11/18

Hirer Particulars MUHAMMAD HAFIZHAN BIN ABDULAZIZ (can drive)
 Name (as per NRIC): QUAH JIA KHENG License Pass Date: 28/1/09
 NRIC: S86379132 Date of Birth: 15/12/1986 (DD/MM/YYYY)
 Address: BLK 253 SIMKI ST1 #08-547 S520253
 Contact Number: 93880105 2nd Contact Number: 97832920

Vehicle Description

Make/Model: Honda Vezel Vehicle Car Plate No.: SLD 6155 J
 Date of Collection: 27/11/18 Date of Return: _____
 Time of Collection: 5pm Time of Return: _____
 Contract Period: 3 months 26/2/19 Insurance Excess 1: 2,500
 Fuel: Petrol Insurance Excess 2: 3,000

Payment

Rental Amount: \$425 weekly Payment on every: Wed before 2359 hours
 Deposits: \$500 trf from SLC52156

Return of Deposit to Hirer: _____ (Hirer Signature & Date)

Payment for the subsequent week rental is to be made on every _____ before 2359 hours. Penalty of SGD 20 exclude car rental fee will be imposed of everyday of late payment. Exclude towing fee of SGD 100 to SGD 1,000

Payment can be made either by bank transfer to UOB Account 631-305-661-6 or cash payment at 200 Jalan Sultan Textile Centre #02-38 Singapore 199018


 Hirer Signature & Date

Terms and Conditions

EasyDrive Car Rental
 200 Jalan Sultan
 #02-38 Textile Centre
 Singapore 199018
 Tel: 6673 5989 Fax: 6883 2418
 Email: easydrivesg@gmail.com
 UEN: 53375868L


 Authorized staff Signature & Date

1 (SLC52156) 27/11 - \$200
5/12 - \$425
17/12 - \$425



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC3/CTI19004356/K1db3s2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 30-10-2019



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLD 6155J	Veh. Inspected	SHB 8437R
Policy No.	DMHCSN1904101900	Coverage (\$)	0.00
Claim No.	SNM19D201017	Excess (\$)	0.00
Assign From		Assign Date	08/03/2019

2. Vehicle Particulars & Condition

Make & Model	KIA OPTIMA	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	KNAGM414ME5446551	Colour	SILVER
Odometer	362978	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/65 R16	HANKOOK	6 mm
L/H Front Tyre	205/65 R16	HANKOOK	6 mm
R/H Rear Tyre	205/65 R16	HANKOOK	6 mm
L/H Rear Tyre	205/65 R16	HANKOOK	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	28/02/2019	Inspection Date	08/03/2019
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 8437R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BONNET GRILLE	TO REPAIR SEE LABOUR	385.00	-
1	SUPPORT PANEL	SERVICEABLE	645.00	-
1	FRONT BUMPER	DEFORMED	531.00	531.00
1	FRONT BUMPER EMBLEM	NECESSARY	44.00	44.00
1	FRONT BUMPER CENTRE GRILLE	SERVICEABLE	174.00	-
1	FRONT BUMPER LOWER STIFFER	SERVICEABLE	134.00	-
1	FRONT BUMPER TOW HOOK COVER	CRACKED	14.00	14.00
1	FRONT BUMPER LIP	SERVICEABLE	52.00	-
1	FRONT BUMPER INNER SPONGE	SERVICEABLE	110.00	-
1	FRONT BUMPER REINFORCEMENT	SERVICEABLE	328.00	-
2	FRONT BUMPER O/S & N/S RETAINER @ \$16.00	SERVICEABLE	32.00	-
2	FRONT BUMPER O/S & N/S UPPER BRACKET @ \$16.00	SERVICEABLE	32.00	-
2	FRONT BUMPER O/S & N/S SUPPORT BRACKET @ \$16.00	SERVICEABLE	32.00	-
2	N/S & O/S HEADLAMP @ \$1028.00	SERVICEABLE	2,056.00	-
2	FRONT BUMPER O/S & N/S FOG LAMP COVER @ \$66.00	SERVICEABLE	132.00	-
1	BOOT LID	DENTED	1,119.00	1,119.00
1	BOOT LID LOCK	JAMMED	99.00	99.00
1	BOOTLID LOCK CABLE	SERVICEABLE	35.00	-
1	BOOTLID STRIKER	SERVICEABLE	21.00	-
1	BOOTLID EMBLEM	NECESSARY	27.00	27.00
1	BOOTLID CRDI	NECESSARY	29.00	29.00
1	BOOT LID RUBBER WEATHERSTRIP	SERVICEABLE	96.00	-
1	BOOT LID LOWER GARNISH	CRACKED	290.00	290.00
2	BOOTLID HINGES @ \$66.00	BENT	132.00	132.00
1	BOOTLID INNER TRIM	SERVICEABLE	190.00	-
1	END PANEL	BUCKLED	250.00	250.00
1	END PANEL INNER GARNISH	CRACKED	74.00	74.00
1	REAR BUMPER	DEFORMED	696.00	696.00
1	REAR BUMPER LOWER COVER	DEFORMED	206.00	206.00
2	REAR BUMPER SIDE BRACKET O/S & N/S @ \$29.00	SERVICEABLE	58.00	-

Report Ref No. CC3/CT119004356/K1db3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BUMPER INNER SPONGE	TORN	114.00	114.00
1	REAR BUMPER REINFORCEMENT	CRACKED	607.00	607.00
2	REAR BUMPER STAY O/S & N/S @ \$53.00	BENT	108.00	108.00
2	REAR BUMPER REINFORCEMENT LOWER BRACKET @ \$18.00	CRACKED	36.00	36.00
2	REAR BUMPER REINFORCEMENT UPPER BRACKET @ \$18.00	CRACKED	36.00	36.00
2	REAR BUMPER REFLECTOR N/S & O/S @ \$46.00	SERVICEABLE	92.00	-
2	N/S & O/S TAIL LAMP @ \$421.00	N/S CRACKED / O/S SERVICEABLE	842.00	421.00
2	N/S & O/S REFLECTOR @ \$350.00	SERVICEABLE	700.00	-
1	EXHAUST PIPE	SERVICEABLE	1,009.00	-
1	EXHAUST PIPE HANGER	SERVICEABLE	28.00	-
	LESS 10% DISCOUNT		-1,159.50	-483.30
			10,435.50	4,349.70
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	48.00	48.00
1	SET END PANEL INNER GARNISH CLIPS (SN)	NOT NECESSARY	30.00	-
1	SET BOOTLID INNER TRIM CLIPS (SN)	NOT NECESSARY	52.00	-
1	SET BOOTLID LOWER GARNISH CLIPS (SN)	NOT NECESSARY	60.00	-
1	SET BOOTLID STICKERS (SN)	NECESSARY	100.00	100.00
1	SET REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	FRONT NO. PLATE WITH CASING (SN)	BENT	50.00	35.00
1	FRONT BUMPER CLIPS (SN)	NECESSARY	48.00	48.00
2	FRONT N/S & O/S HEAD LAMP LOWER CLIP @ \$6.00 (SN)	NOT NECESSARY	12.00	-
2	FRONT N/S & O/S HEAD LAMP SIDE CLIP @ \$3.00 (SN)	NOT NECESSARY	6.00	-
1	SUNDRY (SN)	NECESSARY	50.00	20.00
			736.00	451.00
	LABOUR			
	TOWING FEE.		50.00	50.00
	TO CHECK FOR WIRING AND TO FOCUS HEAD LAMPS.	NOT NECESSARY	80.00	-
	TO REMOVE / REFIT THE REAR EXHAUST PIPE.	NOT NECESSARY	120.00	-
	TO TOP UP AIRCON GAS.	NOT NECESSARY	120.00	-

Report Ref No. CC3/CT119004356/K1db3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO DISMANTLE / REPLACE REVERSE SENSOR TO NEW BUMPER AND RESET THE SAME.		120.00	30.00
	TO DISMANTLE / REFIT THE INNER GARNISHES, INNER LININGS, INNER TRIMS, CUSHION SEAT, CARPET, ETC TO FACILITATE REPAIRS.		180.00	50.00
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS. TO HEAT / WELD, CUT-OFF THE THE END PANEL. INCLUDING KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE AND ADJUST OF THE FLOORBOARD COMPARTMENT, ETC.		1,400.00	1,000.00
	TO PUTTY AND SPRAY PAINTING ON BOOTLID, BOOTLID LOWER GARNISH, REAR BUMPER, FLOORBOARD COMPARTMENT, END PANEL, FRONT BUMPER.		1,200.00	1,080.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.		150.00	50.00
			3,420.00	2,260.00
GRAND TOTAL			14,591.50	7,060.70
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,650.00

Report Ref No. CC3/CT119004356/K1db3s2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.