

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

8-Mar-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8437 R

1 pc	Bonnet grille <i>X repair</i>	\$	385.00
1 pc	Support panel <i>X</i>	\$	645.00
1 pc	Front bumper <i>-</i>	\$	531.00
1 pc	Front bumper emblem <i>-</i>	\$	44.00
1 pc	Front bumper centre grille <i>X</i>	\$	174.00
1 pc	Front bumper lower stiffer <i>X</i>	\$	134.00
1 pc	Front bumper tow hook cover <i>✓</i>	\$	14.00
1 pc	Front bumper lip <i>X</i>	\$	52.00
1 pc	Front bumper inner sponge <i>X</i>	\$	110.00
1 pc	Front bumper reinforcement <i>X</i>	\$	328.00
2 pcs	Front bumper o/s & n/s side retainer @ \$16.00 <i>X</i>	\$	32.00
2 pcs	Front bumper o/s & n/s upper bracket @ \$16.00 <i>X</i>	\$	32.00
2 pcs	Front bumper o/s & n/s support bracket @ \$16.00 <i>X</i>	\$	32.00
2 pcs	n/s & o/s headlamp @ \$1028.00 <i>X</i>	\$	2,056.00
2 pcs	Front bumper o/s & n/s fog lamp cover @ \$66.00 <i>X</i>	\$	132.00
1 pc	Boot lid <i>-</i>	\$	1,119.00
1 pc	Boot lid lock <i>-</i>	\$	99.00
1 pc	Bootlid lock cable <i>X</i>	\$	35.00
1 pc	Bootlid striker <i>X</i>	\$	21.00
1 pc	Bootlid emblem <i>-</i>	\$	27.00
1 pc	Bootlid CRDi <i>-</i>	\$	29.00
1 pc	Boot lid rubber weatherstrip <i>X</i>	\$	96.00
1 pc	Boot lid lower garnish <i>-</i>	\$	290.00
2 pcs	Bootlid hinges @ \$66.00 <i>-</i>	\$	132.00
1 pc	Bootlid inner trim <i>X</i>	\$	190.00
1 pc	End panel <i>-</i>	\$	250.00
1 pc	End panel inner garnish <i>-</i>	\$	74.00
1 pc	Rear bumper <i>-</i>	\$	696.00
1 pc	Rear bumper lower cover <i>-</i>	\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00 <i>X</i>	\$	58.00
1 pc	Rear bumper inner sponge <i>-</i>	\$	114.00
1 pc	Rear bumper reinforcement <i>-</i>	\$	607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00 <i>-</i>	\$	108.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00 <i>-</i>	\$	36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00 <i>-</i>	\$	36.00

8-Mar-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8437 R

2 pcs	Rear bumper reflector n/s & o/s @ \$46.00	X	\$	92.00
2 pcs	n/s & o/s tail lamp @ \$421.00	n/s - o/s	\$	842.00
2 pcs	n/s & o/s reflector @ \$350.00	X	\$	700.00
1 pc	Exhaust pipe	X	\$	1,009.00
1 pc	Exhaust pipe hanger	X	\$	28.00
			\$	11,595.00
		Less 10%	\$	1,159.50
			\$	10,435.50

S/NETT

1 set	Rear bumper clips	/	\$	48.00
1 set	End panel inner garnish clips	X	\$	30.00
1 set	Bootlid inner trim clips	X	\$	52.00
1 set	Bootlid lower garnish clips	X	\$	60.00
1 set	Bootlid stickers	/	\$	100.00
1 set	Reverse sensor	/	\$	280.00 200
1 pc	Front no. plate with casing	/	\$	50.00 35
1 pc	Front bumper clips	/	\$	48.00
2 pcs	Front n/s & o/s head lamp lower clip @ \$6.00		\$	12.00
2 pcs	Front n/s & o/s head lamp side clip @ \$3.00		\$	6.00
	Sundry		\$	50.00 20
	Towing Fee		\$	50.00 /
	To check for wiring and to focus head lamps		\$	80.00 X
	To remove / refit the rear exhaust pipe		\$	120.00 X
	To top up aircon gas		\$	120.00 X
	To dismantle / replace reverse sensor to new bumper and reset to the same		\$	120.00 30
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		\$	180.00 50
	To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the the end panel. Including knock-out, straighten, repair, reshape and adjust of the floorboard compartment, etc		\$	1,400.00 1000
	To putty and spray painting on bootlid, bootlid lower garnish, rear bumper, floorboard compartment, end panel, front bumper		\$	1,200.00 1080
	To apply rustproofing on the repaired and replaced panels.		\$	150.00 50
			\$	14,591.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- No illegal modification(s) is allowed
- Third party survey is on a "Without Prejudice" basis
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Kalvin LKK

8/3/19 17:00h

5 Reps

L/S

After Repair of L/S

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)
THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.