

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0273/2019/GW
Date : 2-Mar-19

Vehicle not in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Tan Bing
Address : 12 Upper Serangoon Cresent
: #16-30
Singapore 534030
Telephone : HP +65 83180199
Type of Claim : Own Damage Claims
Policy No. : 1800148995
Vehicle No : **SJL 6187 Z**
Model Code : Audi A3 SB 1.0 TF
Model / Year : 30/11/2018
Engine No : CHZ 822594
Chassis No : WAUZZZ8V8KA014062
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 1-Mar-19
Place of Accident : Along KPE

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SJL 6187 Z

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00	✓
2	To dismantle and renew front bumper. Re-organise crash management components. Reinstall all parts removed.	\$ 900.00	SSO
3	To respray front bumper.	\$ 800.00	SSO
4	To carry out diagnostic check.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 2,252.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJL 6187 Z

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER <i>Regis</i>	\$ 1,698.00	X
2	FRONT BUMPER FIXING PARTS	\$ 170.00	X
3	FRONT BUMPER GUIDE SECTION-LH/RH <i>2 ne</i>	2 \$ 70.00	X
4	FRONT BUMPER GRILLE-CENTER <i>ne</i>	\$ 146.00	X
5	FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE <i>2 ne</i>	\$ 270.00	X
6	FRONT BUMPER CLOSING ELEMENT-LH/RH	2 \$ 540.00	X
7	FRONT AIR GUIDE GRILLE-LH/RH <i>ne</i>	2 \$ 342.00	X
8	RADIATOR GRILLE <i>Checked</i>	\$ 1,301.00	✓
9	RADIATOR GRILLE CLOSING ELEMENT <i>?</i>	\$ 174.00	?
10	FOAM FILLER PIECE <i>2 ne</i>	\$ 172.00	X
11	FRONT BUMPER SIDE REINFORCEMENT	\$ 660.00	X
12	FRONT BUMPER COVER <i>ne</i>	\$ 111.00	X
13	AIR CONDITONER FOR STICKER <i>2 ne</i>	\$ 7.00	X
14	SIGN " CAUTION "	\$ 13.00	X
15	FRONT NO. PLATE <i>Bent</i>	S/N \$ 25.00	✓
16	SUNDRIES <i>!</i>	\$ 300.00	?
TOTAL SPARE PARTS CHARGES		: \$ 5,999.00	
TOTAL LABOUR CHARGES		: \$ 2,252.00	
GRAND TOTAL		: \$ 8,251.00	

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian King
Surveyed Date : 08/03/19
Authorised Date :
Excess Cost :
Liability :
Remarks : Authorised Repairs, 03 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant