

7/20/12/2009

ASS. REC. BY

REF

CO/MSG19004370/Ktd3/02

Special Instruction

Surveyor

ASSIGNMENT (Office)

From (Person)

Greene Tan

of

MSG

Date/Time

8/3/2019

Estimated Cost

Bill to

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.

SIG 3330Y

Insured

STV 6282D

at Workshop n/a

Cheng Hoe

Tel

or Bk 10 AMK #01-04

Policy No.

A80454444QMX

Claim No.

587052

Sum Insured

Excess

Make of Veh.

(Client's Record)

D.O.A.

7/3/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement

Date/Time

Person Contacted

Vehicle IN/OUT

Date/Time

Action/Instruction () Estimate

SIG 3330Y-X

STV 6282D-NA/MSG19001259/r3 DOA: 20/1/2019

V/S

revised via merimen preli advise

13/5 11 Lp 863501 Confirm Effect (Red: 2418.24; 2790)

ASS. REC. BY:

REF:

MSK/

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

10 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

File pass to

Veh No:

STG 33304

Yr Regn:

09, 08

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Vios

c.c.

1497

Colour:

A- Blue

A/C: Insured / Std / NI / NA

Sp. Reading

175853

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

NR05314Y 9305076253

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NII / S/Rlm / STD A/Rlm or

Tyre Size:

F:

185/60R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

P

mm

Rear

R/Bal.

7

mm

L/Bal.

P

mm

L/Bal.

7

mm

D.O.A.

7/3/19

D.O.I.

P/3/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear & 13

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 14 MAY 2019

13/5/2019

Date/Time, File Pass to?

11/4/5 Typist

Date/Time, File Return to?



: Prell. Report



: Final Report

Days Of Repair:

10

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

150

10

S + RS. \$

Fees:

Others

TOTAL

160

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

6350

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tan Gek Ing

Date: 12 Mar 2019

Preliminary Advice

Insured Vehicle No	: SJV6282D	Accident Date	: 07/03/2019
TP Vehicle No	: SJG3330Y	Assignment Date	: 08/03/2019
Make	: TOYOTA VIOS EA	Est. Duration of Repair	: 10.00
Date of Inspection	: 08/03/2019		
Inspection At	: CHENG HOE MOTOR PTE LTD (AMK) 10 ANG MO KIO IND PARK 2A, #01-04 ANG MO KIO AUTOPOINT SINGAPORE 568047		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front and rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,768.24
Revised Amount	:S\$	7,684.48
Check Items (Estimated)	:S\$	262.73
Total	:S\$	7,947.21
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (x) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Mar 2019		08 Mar 2019 16:45 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	NG BOON CHWEE, ID: S8338656H, Tel: +6597973898, Email: JOHNSON09115@GMAIL.COM		
Main Claimant:	TEO SHU FEN TIFFANIE, ID: S8529996D		
Vehicle Reg. No.:	SJG3330Y	Date of Loss:	07/03/2019 08:00 - :59 [126 Months and 6 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 587052	Policy/Cover Note No.:	A8045444QMX (Comprehensive) Coverage: 22/02/2019 - 21/02/2020
Vehicle Reg. No. (Insured):	SJV6282D	Policy No. (Claimant):	
		Excess:	S\$500.00
Repairer:	Cheng Hoe Motor Pte Ltd (AMK) 10 ANG MO KIO IND PARK 2A, #01-04 ANG MO KIO AUTOPOINT, 568047 Ang Mo Kio - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 09/03/2019]		
Driver/Custodian (Insured):	NG BOON CHWEE (35 / Male), NRIC: S8338656H, Tel: +6597973898 Email: JOHNSON09115@GMAIL.COM		
Adj Asg. Remarks:	SJE : AGREED / LIABILITY 100% (Urgent Request) VEHICLE IN THE WORKSHOP Please appoint MR KENNETH KONG from LKK AUTO to conduct the survey . Kindly contact MS DORLYN LI @ 6481 2001 to arrange for survey .		

ASSOCIATED MAIL RECEIVED
[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS
[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SGCARMART.COM

Login Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

- New Electricity Service providers
- Project Jewel at Changi Airport to cost \$1.47b
- Mazda CX-30

toyota vios

Price Range

Depreciation

> 10 year

Vehicle Type

Submit

Advanced Search

Home » Used Cars » Car Search » Toyota Vios 1.5A J (COE till 11/2028)

Resources

- Car Buying
- Car Selling
- Car Ownership
- Car Aftermarket
- On The Move
- Lifestyle

Featured Merchants



AASHNI + CO

RAJDEEP RANAWAT
CO. SHOP NOW

Toyota Vios 1.5A J (COE till 11/2028)

Overview Financial Insurance Accessories Similar Research Photos Map

CONSIGNMENT



Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

Car Details

Price	\$44,800
Depreciation	\$4,610 /yr
Reg Date	26-Nov-2008 (9yrs 8mths 17days COE left)
Manufactured	2008
Mileage	73,500 km (7.1k /yr)
Transmission	Auto
Engine Cap	1,497 cc
Road Tax	\$752 /yr
Power	80.0 kW (107 bhp) View specs of the Toyota Vios (2007-2013)
Curb Weight	1,095 kg
Features	Fuel Efficient And Powerful 1.6L 16 Valve DOHC VVTI Engine, Smooth Auto Transmission With ECT, Dual SRS Airbags, ABS, Digital Climate Control Aircon.
Accessories	Sports Rims, Factory Fitted Audio System, Electrical Retractable Side Mirrors With Indicators, Upholstery Leather Seats.
Description	Renewed 10 Years COE! One Of The Most Reliable And Fuel Efficient Ride! Well Maintained By Previous Owner! Good Condition Suitable For All Ages! Flexible Loan Scheme Provided, Consignment Unit, Call And Arrange Viewing Now.
COE	\$29,670
OMV	\$11,434
ARF	\$58
Dereg Value	\$28,857 as of today (change)
No. of Owners	2
Type of Veh	Mid-Sized Sedan
Category	COE Car, Consignment Car, Low Mileage Car
Availability	Available

?

?

?

?

?

?

?

?

?

?

?

?

Owner Consignment Car

This car is for sale by direct owner via a consignment agent. Consignment agents help to market, sell and handle all documentation on the car seller's behalf.

- » List of owner consignment cars
- » List of consignment agents



Location Map

Seller Information

Company	Car Search
	» dealer's pricelist
	» 40 vehs sold 183 vehs available
Address	18 Sin Ming Lane #04-02 Search cars nearby this location
Location	Midview City
Office No	62620728
Contact Person(s)	Kelvin 97593539 Justin 91827511

Add to Shortlist

Add to Compare

Add a Note

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 9996D

Vehicle Details

Vehicle No.: SJG3330Y

Vehicle to be Exported: No

Intended Deregistration Date: 08 Mar 2019

Vehicle Make: TOYOTA

Vehicle Model: VIOS E AUTO

Primary Colour: Blue

Manufacturing Year: 2008

Engine No.: 1NZX789002

Chassis No.: MR053HY9305076253

Maximum Power Output: 80.0 kW (107 bhp)

Open Market Value: \$11,834.00

Original Registration Date: 01 Sep 2008

First Registration Date: 01 Sep 2008

Transfer Count: 1

Actual ARF Paid: \$11,834.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 31 Aug 2028

COE Category: A - Car (1600cc & below)

COE Period(Years): 10

PQP Paid: \$34,197.00

COE Rebate Amount: \$32,413.00

Total Rebate Amount: \$32,413.00

The information contained herein is correct as at 08 Mar 2019

OK

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (VIS) Email: chmotor@singnet.com.sg
GST 201001158E RCB NO.201001158E

M/S: MSIG INSURANCE (S) PTE LTD (SGX)
16 RAFFLES QUAY
#24-01 HONG LEONG BUILDING
SINGAPORE 048581

TEL: 68277660

FAX: 62257402

ATTN: Motor Claim Department

WS Ref: TP/MSIG/AMK

Claim Type: Third Party

Accident Date: 07/03/2019

TP Veh Reg No: SJV6282D

Estimate No: ES1991244/AMK

Date: 08 Mar 2019

Policy No: GA137626/1

Veh Reg No: SJG3330Y

Make/Model: TOYOTA VIOS 1.5E A

Chassis No: MR053HY9305076253

Engine No: 1NZX789002

Reg. Date: 01/09/2008

Estimate Repair Cost to Vehicle No :SJG3330Y

Description	U/Price	Quantity	List Price	Amount
			SS	SS
List Price				
1 FRONT BUMPER	398.20	1 PC	398.20	✓
2 FRONT BUMPER REINFORCEMENT	350.30	1 PC	350.30	✓
3 FRT BUMPER LOGO	49.87	1 PC	49.87	✓
4 FRONT BUMPER CLIP	2.21	8 PC	17.68	✓
5 FRONT GRILLE	261.20	1 PC	261.20	✓
6 FRONT GRILLE OUTER CHROME	105.40	1 PC	105.40	✓
7 REAR BUMPER	451.90	1 PC	451.90	✓
8 REAR BUMPER REFLECTOR	81.78	2 PC	163.56	✓
9 REAR BUMPER SIDE RETAINER	91.90	2 PC	183.80	✓
10 REAR BUMPER CORNAL RETAINER	51.70	2 PC	103.40	✓
11 REAR BUMPER LOWER SKIRT	329.00	1 PC	329.00	✓
12 REAR BUMPER CLIP	3.89	6 PC	23.34	✓
13 REAR BOOT	692.20	1 PC	692.20	✓
14 REAR BOOT SPOILER	288.00	1 PC	288.00	X
15 REAR BOOT INNER RUBBER	186.50	1 PC	186.50	502.20 93.25N
16 REAR BOOT INNER LOCK	112.60	1 PC	112.60	✓
17 REAR BOOT EMBLEM 'VIOS'	47.80	1 PC	47.80	✓
18 REAR BOOT EMBLEM 'SPORTS'	61.21	1 PC	61.21	✓
19 REAR BOOT EMBLEM 'E'	39.20	1 PC	39.20	✓
20 REAR BOOT LOGO	56.80	1 PC	56.80	✓
21 REAR BOOT HINGE	65.60	2 PC	131.20	X
22 REAR BOOT OUTER MOULDING	145.72	1 PC	145.72	✓
23 TAILLAMP	328.90	2 PC	657.80	✓
24 TAILLAMP PANEL	128.91	2 PC	257.82	✓
25 TAILLAMP INNER GASKET	32.40	2 PC	64.80	✓
26 TAILLAMP LOWER RETAINER	26.20	2 PC	52.40	✓
27 TAILLAMP CLIP	4.22	2 PC	8.44	✓
28 REAR END PANEL	678.10	1 PC	678.10	✓
29 REAR END PANEL INNER TOP GARNISH	212.70	1 PC	212.70	✓
30 REAR END PANEL INNER TOP GARNISH CLIP	3.22	2 PC	6.44	✓
31 REAR SPARE TYRE SIDE SPONGE	217.50	2 PC	435.00	✓
32 REAR SPARE TYRE INNER TOP BOARD	198.60	1 PC	198.60	✓
			6,770.98	
		Less 25%	1,692.75	5,078.24
Special Net				
33 FRONT NUMBER PLATE	35.00	1 PC	35.00	✓
34 REAR NUMBER PLATE	35.00	1 PC	35.00	✓

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST: 201001158E RCB NO: 201001158E

M/S: MSIG INSURANCE (S) PTE LTD (SGX)
16 RAFFLES QUAY
#24-01 HONG LEONG BUILDING
SINGAPORE 048581
TEL: 68277660 FAX: 62257402
ATTN: Motor Claim Department
WS Ref: TP/MSIG/AMK
Claim Type: Third Party
Accident Date: 07/03/2019
TP Veh Reg No: SJV6282D

Estimate No: ES1991244/AMK
Date: 08 Mar 2019
Policy No: GA137626/1
Veh Reg No: SJG3330Y
Make/Model: TOYOTA VIOS 1.5E A
Chassis No: MR053HY9305076253
Engine No: 1NZX789002
Reg. Date: 01/09/2008

Estimate Repair Cost to Vehicle No :SJG3330Y

Description	U/Price	Quantity	List Price	Amount
35 REVERSE SENSOR	200.00	1 SET	<i>Per</i> <u>SS</u> 200.00	<i>✓</i> <u>SS</u> 270.00
Labour				
36 REMOVE & REFIX FRT BUMPER & LOWER SKIRT & ATTACHMENTS,GRILLE:KNOCKING & REPAIR FRT PANEL & REALIGN THE SAME	400.00	1 LA	400.00	<i>300</i>
37 PUTTY & RESPRAY FRT BUMPER & LOWER SKIRT,REINFORCEMENT,GRILLE,FRT PANEL & ALL AFFECTED AREAS	500.00	1 LA	500.00	<i>400</i>
38 REMOVE & REFIX REAR BUMPER & LOWER SKIRT,REAR BOOT,SPOILER & ATTACHMENTS,TAILLAMP,TO CUT,WELD & RENEW REAR END PANEL,BOTH TAILLAMP PANELS,KNOCKING & REPAIR REAR BOTH FENDERS,REAR SPARE TYRE PANEL & REALIGN THE SAME	1,200.00	1 LA	1,200.00	<i>1100</i>
39 PUTTY & RESPRAY REAR BUMPER & LOWER SKIRT,REAR BOOT & SPOILER,BOTH FENDERS,BOTH TAILLAMP PANELS,REAR END PANEL,REAR SPARE TYRE PANEL & ALL AFFECTED AREAS	1,200.00	1 LA	1,200.00	<i>1100</i>
40 RUSTPROOFING	120.00	1 LA	120.00	<i>60</i>
			3,420.00	3,420.00
Total				S\$ 8,768.24
Add GST @ 7%				613.78
Total Amount Payable				S\$ 9,382.02

* SURVEY VEHICLE AT ANG MO KIO WORKSHOP

For Cheng Hoe Motor Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Suspected part(s) must be resurveyed and is subject to final approval from Insurance Company

Authorised Repairer:

Signature:

DORLYN LI

AUTHORISED SIGNATURE

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19004370/KTD3N2

Date: 21/05/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A80454444QMX
Claimant Vehicle No :	SJG3330Y	Insured Vehicle No :	SJV6282D
Date of Loss:	07/03/2019	Nature of Claim:	TP
		Claim No:	587052

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJG3330Y	Engine No:	1NZX789002
Make & Model:	TOYOTA VIOS EA, 1.5 (A)	Chassis No:	MR053HY9305076253
Reg. Date:	01/09/2008 (Man. Year: 2008)	Odometer:	175853 km
Colour:	Metallic Blue		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60R15	Rear Tyre Size:	185/60R15
Front Left Side:	Michelin 8 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Michelin 8 mm	Rear Right Side:	Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,348.24	4,987.21	361.03	6.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,420.00	2,960.00	460.00	13.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,768.24	7,947.21	821.03	9.36
Approved Total (Overridden) (S\$)		6,350.00		
	(S\$)	8,768.24	6,350.00	2,418.24
	+ GST 7.00/7.00% (S\$)	613.78	444.50	169.28
	Nett Amount (S\$)	9,382.02	6,794.50	2,587.52
				27.58

INSPECTION

Date of Assignment:	08/03/2019	
Date Inspected:	08/03/2019 Inspected At:	10 ANG MO KIO IND PARK 2A #01-04 ANG MO KIO AUTOPOINT SINGAPORE 568047 REPAIRER: CHENG HOE MOTOR PL
Estimated Period of Repair:	10.0 days	

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 21 May 2019)
Parts: 143	TOYOTA VIOS EA 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJG3330Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled	398.20 FL	*398.20 FL
2	1		*FRONT BUMPER REINFORCEMENT	Bent	350.30 FL	*350.30 FL
3	1		*FRT BUMPER LOGO	Necessary	49.87 FL	*49.87 FL
4	8		*FRONT BUMPER CLIP	Necessary	17.68 FL	*17.68 FL
5	1		*FRONT GRILLE	Cracked	261.20 FL	*261.20 FL
6	1		*FRONT GRILLE OUTER CHROME	Necessary	105.40 FL	*105.40 FL
7	1		*REAR BUMPER	Bent	451.90 FL	*451.90 FL
8	2		*REAR BUMPER REFLECTOR	Cracked	163.56 FL	*163.56 FL
9	2		*REAR BUMPER SIDE RETAINER	Cracked	183.80 FL	*183.80 FL
10	2		*REAR BUMPER CORNAL RETAINER	Cracked	103.40 FL	*103.40 FL
11	1		*REAR BUMPER LOWER SKIRT	Cracked	329.00 FL	*329.00 FL
12	6		*REAR BUMPER CLIP	Necessary	23.34 FL	*23.34 FL
13	1		*REAR BOOT	Bent	692.20 FL	*692.20 FL
14	1		*REAR BOOT SPOILER	Repair	288.00 FL	*- FL
15	1		*REAR BOOT INNER LOCK	Dented	112.60 FL	*112.60 FL
16	1		*REAR BOOT EMBLEM VIOS	Necessary	47.80 FL	*47.80 FL
17	1		*REAR BOOT EMBLEM SPORTS	Necessary	61.21 FL	*61.21 FL
18	1		*REAR BOOT EMBLEM E	Necessary	39.20 FL	*39.20 FL
19	1		*REAR BOOT LOGO	Necessary	56.80 FL	*56.80 FL
20	2		*REAR BOOT HINGE	Repair	131.20 FL	*- FL
21	1		*REAR BOOT OUTER MOULDING	Warped	145.72 FL	*145.72 FL
22	2		*TAILLAMP	Cracked	657.80 FL	*657.80 FL
23	2		*TAILLAMP PANEL	Bent	257.82 FL	*257.82 FL
24	2		*TAILLAMP INNER GASKET	Necessary	64.80 FL	*64.80 FL
25	2		*TAILLAMP LOWER RETAINER	Cracked	52.40 FL	*52.40 FL
26	2		*TAILLAMP CLIP	Necessary	8.44 FL	*8.44 FL
27	1		*REAR END PANEL	Bent	678.10 FL	*678.10 FL
28	1		*REAR END PANEL INNER TOP GARNISH	Dented	212.70 FL	*212.70 FL
29	2		*REAR END PANEL INNER TOP GARNISH CLIP	Necessary	6.44 FL	*6.44 FL
30	2		*REAR SPARE TYRE SIDE SPONGE	Cracked	435.00 FL	*435.00 FL
31	1		*REAR SPARE TYRE INNER TOP BOARD	Warped	198.60 FL	*198.60 FL
32	1		*REAR BOOT INNER RUBBER (50%)	Dented/Cut	139.88 FS	*93.25 FS
33	1		*FRONT NUMBER PLATE	Bent	35.00 FS	*35.00 FS
34	1		*REAR NUMBER PLATE	Bent	35.00 FS	*35.00 FS
35	1		*SET REVERSE SENSOR	Dented	200.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	6,994.36	6,528.53
- List Item Discount on L Items 25.00/25.00% (S\$)	1,646.12	1,541.32
Total Parts (S\$)	5,348.24	4,987.21

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIX FRT BUMPER & LOWER SKIRT & ATTACHMENTS,GRILLE,KNOCKING & REPAIR FRT PANEL & REALIGN THE SAME	New	400.00	300.00
2	PUTTY & RESPRAY FRT BUMPER & LOWER SKIRT,REINFORCEMENT,GRILLE,FRT PANEL & ALL AFFECTED AREAS	New	500.00	400.00
3	REMOVE & REFIX REAR BUMPER & LOWER SKIRT,REAR BOOT,SPOILER & ATTACHMENTS,TAILLAMPS.TO CUT,WELD & RENEW REAR END PANEL,BOTH TAILLAMP PANELS,KNOCKING & REPAIR REAR BOTH FENDERS,REAR SPARE TYRE PANEL & REALIGN THE SAME	New	1,200.00	1,100.00
4	PUTTY & RESPRAY REAR BUMPER & LOWER SKIRT,REAR BOOT & SPOILER,BOTH FENDERS,BOTH TAILLAMP PANELS,REAR END PANEL,REAR SPARE TYRE PANEL & ALL AFFECTED AREAS	New	1,200.00	1,100.00
5	RUSTPROOFING	New	120.00	60.00
Gross Labour Cost (S\$)			3,420.00	2,960.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >