

REF: es/CTI1904373/R1230

Sally Yoon
Munin

Rasul

ASSIGNMENT (Office)

From (Person)

Chang Eun Sen

of

CTI

Date/Time

8/3/19 @ 6:11pm

Estimated Cost

Bill to

OD ☒ WS / TP / RES / OD / RES / EVA / INV / MV / CS

To Inspect Vehicle No.

SDZ 2438Z

Insured:

SBT3606D

at Workshop n/a

S.K. Automobile

Tel:

6266 0555

of

48 Joh Guan Rd East #01-121

Policy No.

Claim No.

Name Insured

Excess:

Make of Veh:

(If Not's Record)

D.O.A

6/3/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement

Date/Time

8/3/19 @

Person Contacted

Yvonne

Vehicle

☒ IN ☐ OUT

Date/Time

Action/Instruction (✓) Estimate

SDZ 2438Z-NA/NCM006753/s!

D.O.A: 29/3/2009

SBT3606D-X

3/5/19

LS \$ 8600 confirmed by email (Ref 15,446-72, 649)

WITNESS

Peru

REF:

33392

ASSIGNMENT

From: _____ Insured: _____
 Estimated Cost: _____
 OO / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: **SDZ 24382**
 at Workshop n/s: **SK AUTO**
 of: **48, Tott-hum 25 persi No 1-121**
 Insured: **CTI**
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Est. or Market Value: _____
 IDAC Accident Report: Consistent? Yes or No
 GIA / FR Score: Consistent? Yes or No
 Est. Repair: days Res: Yes or No
 Turn Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: **SDZ 24382** To Inspect: **2015 OCT**
 Type: **Cap / B/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /**
 Truck / Trailer or
 Make: **Honda Vezel 1.5X** CC: **1496**
 Colour: **Brown** AB: Insured / Std / HI / HA
 Sp Reading: **073996** (Check) Insured / Std / HI / HA
 Eng/Hr: _____
 C/Mr: **Ru11100991**
 Gen. Cond: Good / **Car** / Poor / Burnt
 Steering: **Order** / Jammed / Locked / Burnt or
 Brake: **Order** / Jammed / Locked / Burnt or
 Mode: **HI** / **CR** / STD / R/R or
 Tyre Size: F: **215/60R16**
 R: _____
 BS / **OUR** / EXNOVA / GY / FS / LEA / MIC / OHTSU / PIR / SUM /
 TOYO / YOKO or
 Front: _____ Rear: _____
 R/Rol: **6** mm F/Rol: **6** mm
 L/Rol: **6** mm L/Rol: **6** mm
 D.O.A: **06/03/19** D.O.L: **08/03/19**
 Survey held at: **SK AUTO**
 Des. of Damages: Fit / **Rear** / ORS / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time: _____ Action / Instruction: _____

RECEIVED 03 MAY 2019

Date/Time, File Path to: ☐ Prel. Report

or ☐ Final Report

Director, (to Return to)

35 - typst

Report Format: **mermen**

Lump Sum / U/C: **Stoop**

Days Of Repair: **8**

Resurvey No. of Trip: **1**

Add Fee: ☐ Sub Inp: 15

☐ Interview: 15

☐ Tech Inp: 15

☐ Photo Inp: 15

Survey Fee:

to inspection:

to report:

to file:

to print:

to total:

220

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	(Not Notified)		08 Mar 2019 18:11 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	KOH KOK WAH		
Vehicle Reg. No.:	SDZ2438Z	Date of Loss:	06/03/2019 00:00 - :59
Claim Type:	TP	Policy/Cover Note No.:	
Vehicle Reg. No. (Insured):	SBT3606D	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	SK Automobile Pte Ltd (Toh Guan) 48 Toh Guan Road East #01-121, Enterprise Hub, 608586 Jurong East - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 19/03/2019]		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)

[Compose Case Mail](#)

ALL ASSOCIATED TASKS

[View All](#)

[Search Tasks](#)

[Create New Task](#)

[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Veron Chen (LKKAuto)

From: Admin-D (LKKAuto)
Sent: Tuesday, 2 April 2019 10:48 AM
To: 'Chong Boon Sen'; SUR
Cc: assignments
Subject: RE: Arrange for Pre-repair Inspection for SDZ2438Z (YOUR Insured: SBT3606D) DOA 06/03/2019

Dear Boon Sen,

Thank you for the email.

Dear Veron,

Kindly assist

FYNA Our Ref : CS/CTI19004373/R1vd3

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Chong Boon Sen [mailto:boonsen.chong@sg.cntaiping.com]

Sent: Monday, 1 April 2019 5:35 PM

To: Pioneer Workshop <pioneer@skauto.com.sg>

Cc: assignments <assignments@lkkauto.com>

Subject: RE: Arrange for Pre-repair Inspection for SDZ2438Z (YOUR Insured: SBT3606D) DOA 06/03/2019

Without Prejudice

Dear Sirs

We refer to the above matter.

Liability is in favor of your client and we agree to go for Direct Settlement, subject to consistency of damages, based on our appointed surveyor's findings, with supporting documents.

Aside to M/s LKK, please upload your report and bill for services rendered in Merimen at your earliest convenience.

Thank you.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG 3 Anson Road
#16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Pioneer Workshop [<mailto:pioneer@skauto.com.sg>]

Sent: Monday, 1 April, 2019 4:30 PM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Subject: Re: Arrange for Pre-repair Inspection for SDZ2438Z (YOUR Insured: SBT3606D) DOA 06/03/2019

Dear Boon Sen,

Any update for liability ?

On Wed, Mar 20, 2019 at 5:05 PM Chong Boon Sen <boonsen.chong@sg.cntaiping.com> wrote:

Without Prejudice

Dear Sir,

Insured yet to report.

Will follow up with Insured.

Regards,

Chong Boon Sen

Claims Executive

Claims

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 63896171

Fax: 62247175

Email: boonsen.chong@sg.cntaiping.com

Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Pioneer Workshop [<mailto:pioneer@skauto.com.sg>]

Sent: Wednesday, 20 March, 2019 4:28 PM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Subject: Re: Arrange for Pre-repair Inspection for SDZ2438Z (YOUR Insured: SBT3606D) DOA 06/03/2019

Dear Boon Sen,

Any update for liability ?

On Fri, Mar 8, 2019 at 4:40 PM Chong Boon Sen <boonsen.chong@sg.cntaiping.com> wrote:

Without prejudice

Dear Sir,

Our insured not yet reported.

Unable to advise on liability.

Regards,

Chong Boon Sen

Claims Executive

Claims

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 63896171

Fax: 62247175

Email: boonsen.chong@sg.cntaiping.com

Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Pioneer Workshop [<mailto:pioneer@skauto.com.sg>]

Sent: Friday, 8 March, 2019 3:42 PM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Subject: Re: Arrange for Pre-repair Inspection for SDZ2438Z (YOUR Insured: SBT3606D) DOA 06/03/2019

Dear Boon Sen,

Kindly check attached GIA report & Estimate and let us know the liability

On Fri, Mar 8, 2019 at 8:54 AM Chong Boon Sen <boonsen.chong@sg.cntaiping.com> wrote:

Without Prejudice

Dear Sir,

We will appoint LKK.

Dear LKK,

Pls proceed to pri.

Regards,

Chong Boon Sen

Claims Executive

Claims

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 63896171

Fax: 62247175

Email: boonsen.chong@sg.cntaiping.com

Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Pioneer Workshop [mailto:pioneer@skauto.com.sg]

Sent: Thursday, 7 March, 2019 6:16 PM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Subject: Re: Arrange for Pre-repair Inspection for SDZ2438Z (YOUR Insured: SBT3606D) DOA 06/03/2019

Dear Boon Sen,

We choose ADRIAN LING survey our vehicle. Kindly arrange ASAP

On Thu, Mar 7, 2019 at 6:02 PM Chong Boon Sen <boonsen.chong@sg.cntaiping.com> wrote:

WITHOUT PREJUDICE

Dear Sir ,

We refer to your email of 06.03.19.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Regards,

Chong Boon Sen

Claims Executive

Claims

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 63896171

Fax: 62247175

Email: boonsen.chong@sg.cntaiping.com

Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Pioneer Workshop [mailto:pioneer@skauto.com.sg]

Sent: Thursday, 7 March, 2019 5:34 PM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>; Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Subject: Fwd: Arrange for Pre-repair Inspection for SDZ2438Z (YOUR Insured: SBT3606D) DOA 06/03/2019

Resend, Please arrange survey ASAP

----- Forwarded message -----

From: Pioneer Workshop <pioneer@skauto.com.sg>

Date: Wed, Mar 6, 2019 at 5:07 PM

Subject: Arrange for Pre-repair Inspection for SDZ2438Z (YOUR Insured: SBT3606D) DOA 06/03/2019
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>, <claimsdept@sg.cntaiping.com>
Cc: Winson Ng <winsonng@skauto.com.sg>

Dear Motor Claim Department,

Kindly Arrange survey for below vehicle:

TP Survey Before Repair:

Our vehicle No.: SDZ2438Z

Your Vehicle No.: SBT3606D

D.O.A : 06/03/2019

Location: 48 Toh Guan Road East #01-121 Enterpriser Hub Singapore 608586

--

Thanks & Regards,

Yvonne

SK Automobile Pte Ltd
48 Toh Guan Road East #01-121
Enterprise Hub Singapore 608586
Tel: +65-6266 0555
Fax: +65-6266 3155
Email: pioneer@skauto.com.sg

--
Thanks & Regards,

Yvonne

SK Automobile Pte Ltd
48 Toh Guan Road East #01-121
Enterprise Hub Singapore 608586
Tel: +65-6266 0555
Fax: +65-6266 3155
Email: pioneer@skauto.com.sg

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

--
Thanks & Regards,

Yvonne

SK Automobile Pte Ltd
48 Toh Guan Road East #01-121
Enterprise Hub Singapore 608586
Tel: +65-6266 0555
Fax: +65-6266 3155
Email: pioneer@skauto.com.sg

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

--
Thanks & Regards,

Yvonne

SK Automobile Pte Ltd
48 Toh Guan Road East #01-121
Enterprise Hub Singapore 608586
Tel: +65-6266 0555
Fax: +65-6266 3155
Email: pioneer@skauto.com.sg

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

--
Thanks & Regards,

Yvette Zhao

SK Automobile Pte Ltd
48 Toh Guan Road East # 01-121
Enterprise Hub, Singapore 608586
D: +65 6266 0555 | F: +65 6266 3155 | pioneer@skauto.com.sg

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

Thanks & Regards,

Yvette Zhao

SK Automobile Pte Ltd

48 Toh Guan Road East # 01-121

Enterprise Hub, Singapore 608586

D: +65 6266 0555 | F: +65 6266 3155 | pioneer@skauto.com.sg

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Friday, 8 March 2019 8:54 AM
To: Pioneer Workshop
Cc: assignments
Subject: RE: Arrange for Pre-repair Inspection for SDZ2438Z (YOUR Insured: SBT3606D) DOA 06/03/2019

Without Prejudice

Dear Sir,

We will appoint LKK.

Dear LKK,

Pls proceed to pri.

Regards,

Chong Boon Sen

Claims Executive

Claims

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 63896171

Fax: 62247175

Email: boonsen.chong@sg.cntaiping.com

Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Pioneer Workshop [mailto:pioneer@skauto.com.sg]

Sent: Thursday, 7 March, 2019 6:16 PM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Subject: Re: Arrange for Pre-repair Inspection for SDZ2438Z (YOUR Insured: SBT3606D) DOA 06/03/2019

Dear Boon Sen,

We choose ADRIAN LING survey our vehicle. Kindly arrange ASAP

On Thu, Mar 7, 2019 at 6:02 PM Chong Boon Sen <boonsen.chong@sg.cntaiping.com> wrote:

WITHOUT PREJUDICE

Dear Sir ,

We refer to your email of 06.03.19.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Regards,

Chong Boon Sen

Claims Executive

Claims

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 63896171

Fax: 62247175

Email: boonsen.chong@sg.cntaiping.com

Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Pioneer Workshop [mailto:pioneer@skauto.com.sg]

Sent: Thursday, 7 March, 2019 5:34 PM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>; Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Subject: Fwd: Arrange for Pre-repair Inspection for SDZ2438Z (YOUR Insured: SBT3606D) DOA 06/03/2019

Resend, Please arrange survey ASAP

----- Forwarded message -----

From: Pioneer Workshop <pioneer@skauto.com.sg>

Date: Wed, Mar 6, 2019 at 5:07 PM

Subject: Arrange for Pre-repair Inspection for SDZ2438Z (YOUR Insured: SBT3606D) DOA 06/03/2019

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>, <claimsdept@sg.cntaiping.com>

Cc: Winson Ng <winsonng@skauto.com.sg>

Dear Motor Claim Department,

Kindly Arrange survey for below vehicle:

TP Survey Before Repair:

Our vehicle No.: SDZ2438Z

Your Vehicle No.: SBT3606D

D.O.A : 06/03/2019

Location: 48 Toh Guan Road East #01-121 Enterpriser Hub Singapore 608586

--
Thanks & Regards,

Yvonne

SK Automobile Pte Ltd

48 Toh Guan Road East #01-121

Enterprise Hub Singapore608586
Tel: +65-6266 0555
Fax: +65-6266 3155
Email: pioneer@skauto.com.sg

--
Thanks & Regards,

Yvonne

SK Automobile Pte Ltd
48 Toh Guan Road East #01-121
Enterprise Hub Singapore608586
Tel: +65-6266 0555
Fax: +65-6266 3155
Email: pioneer@skauto.com.sg

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

--
Thanks & Regards,

Yvonne

SK Automobile Pte Ltd
48 Toh Guan Road East #01-121
Enterprise Hub Singapore608586
Tel: +65-6266 0555
Fax: +65-6266 3155
Email: pioneer@skauto.com.sg

This email has been scanned by the Symantec Email Security.cloud service.

For more information please visit <http://www.symanteccloud.com>

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3339I
Vehicle Details	
Vehicle No.:	SDZ2438Z
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Mar 2019
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X CVT
Primary Colour:	Red
Manufacturing Year:	2015
Engine No.:	L15B4020994
Chassis No.:	RU11100991
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$18,313.00
Original Registration Date:	02 Oct 2015
First Registration Date:	02 Oct 2015
Transfer Count:	0
Actual ARF Paid:	\$8,313.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	01 Oct 2025
PARF Rebate Amount:	\$6,234.00
Intended COE Rebate Details	
COE Expiry Date:	01 Oct 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$58,700.00
COE Rebate Amount:	\$38,464.00
Total Rebate Amount:	\$44,698.00

The information contained herein is correct as at 12 Mar 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/03/2019 14:28
Date Of Accident	06/03/2019 11:15
Exact Location Of Accident	INTERNATIONAL ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SDZ2438Z
Insured/Policyholder	
Name Of Registered Owner	KOH KOK WAH
NRIC No	S6823339I
Email Address	KOHKW@SANKOSIN.COM.SG
Mobile Phone No	(LOCAL) +65-97462345
Alternative Phone No	OFFICE-97462345

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL-1.5 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	AVIVA LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	10694462
Cover Note Number	

Driver

Name of Driver	KOH KOK WAH
NRIC No	S6823339I
Date Of Birth	29/07/1968
Occupation	INDOOR
Date Of Driving Pass	30/09/1994
Driving Experience	24 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97462345
Fax Number	
Contact Number	OFFICE-97462345
Email Address	KOHKW@SANKOSIN.COM.SG

Address	425 SERANGOON AVE 1 #11-229
Postcode	550425
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (Including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	STILL UPLOADING
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SBT3606D
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	


SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

International Rd

Pioneer
North

(A) SDZ 2438Z
(B) SBT 3606 D

B A

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

At the above date and time. I was travelling along International Road. I stopped my vehicle due to Red light at the traffic junction.

Vehicle B then came from behind and hit onto the rear of my vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SK Automobile Pte. Ltd.
(Co Reg. No. 201500047H)
23 Kaki Bukit Ave 4, #03-01
Vicom Inspection Centre (S415933)
Tel: 6789 5155 Fax : 6783 5155

TO : CHINA TAIPING DATE : 7-Mar-19
ATTENTION : MOTOR CLAIMS DEPARTMENT JOB TYPE : T/P CLAIMS
ESTIMATE REPORT :

OWNER PARTICULAR

NAME :

ADDRESS :

TEL. NO. :

OWNER INSURANCE :

POLICY NO. :

PERSON INCHARGE :

VEHICLE DETAILS

VEHICLE NO. : SDZ2438Z

MODEL / MAKE : HONDA VEZEL

CHASSIS NO. : RU11100991

ACCIDENT DETAIL

DATE : 06/03/2019

TIME : 11:15

QUOTATION SUMMARY PAGE 01

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR TAILGATE BA/	1	\$ 953.30	\$ 953.30
2	REAR TAILGATE WINDSCREEN MOULDING SET ne/	1	\$ 123.80	\$ 123.80
3	REAR TAILGATE "LOGO" EMBLEM ne/	1	\$ 32.90	\$ 32.90
4	REAR TAILGATE "VEZEL" EMBLEM ne/	1	\$ 38.60	\$ 38.60
5	REAR TAILGATE OUTER GARNISH SCRA/	1	\$ 165.80	\$ 165.80
6	REAR TAILGATE REFLECTOR LAMP LH/RH ? ✓ CRA/	2	\$ 413.90	\$ 827.80
7	REAR TAILGATE OUTER LOCK HANDLE SWITCH X an	1	\$ 131.70	\$ 131.70
8	REAR TAILGATE WIPER MOTOR # ? X no damage	1	\$ 258.60	\$ 258.60
9	REAR TAILGATE NUMBER PLATE LAMP LH/RH ? ✓ CRA/	2	\$ 49.90	\$ 99.80
10	REAR TAILGATE HINGE LH/RH X SVC	2	\$ 50.90	\$ 101.80
11	REAR TAILGATE DAMPER LH/RH X SVC	2	\$ 192.50	\$ 385.00
12	REAR TAILGATE INNER TRIM BOARD ? ✓ CRA/	1	\$ 270.30	\$ 270.30
13	REAR TAILGATE MECHANISM LOCK BA/	1	\$ 216.20	\$ 216.20
14	REAR TAILGATE WEATHER STRIP ne/	1	\$ 198.90	\$ 198.90
15	REAR TAILLAMP LH/RH SCRA/	2	\$ 552.30	\$ 1,104.60
16	REAR TAILLAMP INNER PANEL LH/RH X SVC	2	\$ 138.20	\$ 276.40
17	REAR BUMPER CENTER DE/	1	\$ 762.70	\$ 762.70
18	REAR BUMPER SIDE LH/RH # ? ✓ CRA/	2	\$ 195.80	\$ 391.60
19	REAR BUMPER SIDE RETAINER LH/RH X SVC	2	\$ 16.40	\$ 32.80
20	REAR BUMPER REFLECTOR LH/RH ? ✓ CRA/	2	\$ 151.40	\$ 302.80
21	REAR END PANEL BA/ (photo)	1	\$ 480.30	\$ 480.30
22	REAR END PANEL INNER TOP GARNISH ? ✓ DE/	1	\$ 102.50	\$ 102.50
23	REAR END PANEL TAILGATE ANTENNA SENSOR ? ✓ CRA/	1	\$ 121.50	\$ 121.50
24	REAR END PANEL TAILGATE ANTENNA BUZZER ? ✓ CRA/	1	\$ 98.70	\$ 98.70
25	REAR WELL PANEL repair	1	\$ 1,130.90	\$ 1,130.90
26	REAR WELL PANEL INNER TOP UPHOLSTERY BOARD X SVC	1	\$ 324.80	\$ 324.80
27	REAR WELL PANEL INNER TOOL SPONGE X SVC	1	\$ 215.90	\$ 215.90

58 05 20

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
28	REAR WELL PANEL LOWER UNDER COVER ? ✓ CR	1	\$ 213.20	\$ 213.20
29	REAR WELL SIDE PANEL LH/RH repair	2	\$ 115.80	\$ 231.60
30	REAR SUB CHASSIS FRAME RH repair	1	\$ 720.90	\$ 720.90
31	REAR SUB CHASSIS FRAME TOP PANEL LH/RH X SC	2	\$ 168.90	\$ 337.80
32	REAR FENDER RH X M	1	\$ 940.90	\$ 940.90
33	REAR FENDER ARCH GARNISH LH/RH CR	2	\$ @172 192.80	\$ 385.60
34	REAR FENDER INNER UPHOLSTERY TRIM BOARD LH/RH X M	2	\$ @295 589.70	\$ 1,179.40
35	REAR FENDER INNER SHIELD LH/RH X SC	2	\$ 198.10	\$ 396.20
36	REAR EXHAUST SILENCER BOX ? ✓ BT	1	\$ 1,080.30	\$ 1,080.30
37	REAR EXHAUST ALUMINIUM HEAT SHIELD ? ✓ BT	1	\$ 135.20	\$ 135.20
38	EXHAUST MID PIPE X SC BT	1	\$ 3,112.30	\$ 3,112.30
TOTAL PRICE				\$ 17,883.40
LESS -20%				\$ (3,576.68)
SUB TOTAL PRICE				\$ 14,306.72

8937.60

20%

7150.08

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR TAILGATE OUTER GARNISH CLIPS SET ne	1	\$ 40.00	\$ 40.00
2	REAR TAILGATE REFLECTOR LAMP CLIPS SET LH/RH ne	2	\$ 30.00	\$ 40 60.00
3	REAR TAILGATE REFLECTOR LAMP CHROME GARNISH LH/RH ne	2	\$ 20.00	\$ 40.00
4	REAR TAILGATE NUMBER PLATE WITH CASING SC	1	\$ 60.00	\$ 60.00
5	REAR TAILGATE WINDSCREEN SEALANT WITH PRIMER ne	1	\$ 100.00	\$ 60 100.00
6	REAR TAILGATE INNER TRIM BOARD CLIPS SET ne	1	\$ 60.00	\$ 40 60.00
7	REAR TAILGATE REVERSE CAMERA X SC	1	\$ 580.00	\$ 580.00
8	REAR TAILGATE CHROME MOULDING ne	1	\$ 650.00	\$ 280 650.00
9	REAR TAILLAMP CLIPS SET LH/RH X ne	2	\$ 30.00	\$ 60.00
10	REAR TAILLAMP INNER PANEL SEALANT LH/RH X ne	2	\$ 40.00	\$ 80.00
11	REAR TAILLAMP CHROME GARNISH LH/RH ne	2	\$ 20.00	\$ 40.00
12	REAR BUMPER CLIPS SET ne	1	\$ 60.00	\$ 60.00
13	REAR BUMPER CHROME GARNISH LH/RH ne	2	\$ 20.00	\$ 40.00
14	REAR BUMPER REVERSE SENSOR SET ne	1	\$ 280.00	\$ 220 280.00
15	REAR END PANEL INNER TOP GARNISH CLIPS SET ne	1	\$ 40.00	\$ 40.00
16	REAR END PANEL SEALANT ne	1	\$ 50.00	\$ 50.00
17	REAR WELL PANEL SEALANT X ne	1	\$ 100.00	\$ 100.00
18	REAR WELL PANEL LOWER UNDER COVER CLIPS SET ne	1	\$ 50.00	\$ 30 50.00
19	REAR WELL PANEL INSULATOR SOUND MAT ne	1	\$ 250.00	\$ 150 250.00
20	REAR WELL SIDE PANEL LH/RH X ne	2	\$ 20.00	\$ 40.00
21	REAR FENDER SEALANT RH X ne	1	\$ 100.00	\$ 100.00
22	REAR FENDER ARCH GARNISH CLIPS SET LH/RH ne	2	\$ 30.00	\$ 60.00
23	REAR FENDER INNER TRIM BOARD CLIPS SET LH/RH ne	2	\$ 50.00	\$ 100.00
24	REAR FENDER INNER SHIELD CLIPS SET LH/RH X ne	2	\$ 40.00	\$ 80.00
25	REAR EXHAUST GASKET ? ✓ ne	1	\$ 25.00	\$ 25.00
26	REAR EXHAUST END CHROME PIPE SC	1	\$ 350.00	\$ 250 350.00
27	EXHAUST MID PIPE GASKET ne	1	\$ 25.00	\$ 25.00

TOTAL

\$ 3,420.00

CLAIMS DETAIL : LABOUR CHARGES AND SPRAY PAINTING

TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	\$ 2,200.00	800	
TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	\$ 1,800.00	600	
TO APPLY ANTI-RUST & TUFF KOTE	\$ 200.00	100	
TO PERFORM LIGHTING & WIRING CHECK	\$ 80.00	30	
TO DISMANTLE & REPLACED REAR UNDER CARRIAGE COMPONENT LH/RH TO PERFORM FACILITATE REPAIRS	\$ 280.00	X nn	
TO SEND VEHICLE FOR 3D COMPUTERISED TO PERFORM CHECK & ADJUSTED ALL WHEEL ALIGNMENT	\$ 100.00	X nn	
TO CALIBRATE CHASSIS & CAR BODY BACK TO MANUFACTURING SPECIFICATION	\$ 380.00	? plus 100 X nn	
TO DISMANTLE & REINSTALL REAR PETROL TANK FOR FACILITATE REPAIR	\$ 250.00	X nn	
TO DISMANTLE & REINSTALL REAR WINDSCREEN PERFORM WITH WATER LEAK TEST	\$ 150.00	120	
TO PERFORM TRANSFER REAR BOOT LID MECHANISM & REALIGN BACK TO MANUFACTURING SPECIFICATION	\$ 180.00	80	
TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR WITH DISTANCE SETTING	\$ 80.00	60	
TO DISMANTLE & REPLACED REAR EXHAUST SILENCER BOX WITH REALIGN EXHAUST MID PIPE & RUBBER MOUNTING	\$ 260.00	100 80	
TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR	\$ 280.00	60	
TO PERFORM CONDUCT WATER LEAKAGE TEST OF ACCIDENT PORTION	\$ 80.00	30	

TOTAL

\$ 6,320.00

1960

ESTIMATE REPORT

TOTAL PARTS COST	:	\$	17,726.72
TOTAL LABOUR COST	:	\$	6,320.00
TOTAL REPAIR COST	:	\$	<u>24,046.72</u>

APPROVED DETAILS

EXCESS :
 NO. OF REPAIR DAYS :
 RE-SURVEY :
 P / P OR L / S :

DATE / TIME OF SURVEY :
 SURVEYED BY / FROM :
 CONTACT NUMBER :
 FAX NUMBER :
 EMAIL ADDRESS :

: 08/03/19 @ 1510
 : RABUL (LKK)
 : 900 10068
 :
 : 8 days
 : 4/5

Repair after repair

[Signature]
 12/3/19

7150.08
 1680.00
 1960.00
10,790.08
 20%
 8632.06
 4/5 - 8,600
8 days

LCC Auto Consultants hence notify the Repairer of the following:

- To survey before and spray painting
- To display damaged parts during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Full depth modification is required
- All necessary records must be kept and is subject to inspection at the time of completion

Accepted by Repairer
 Signature:
 Date:

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 3 May 2019 4:05 PM
To: Pioneer Workshop; SUR
Subject: RE: Finalized SDZ2438Z

Dear Sir/Madam,

Noted with thanks.

Kindly send Final invoice and all supporting documents directly to CHINA TAIPING

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Pioneer Workshop <pioneer@skauto.com.sg>
Sent: Thursday, 2 May 2019 7:00 PM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Subject: Re: Finalized SDZ2438Z

Dear Veron,
Confirm COR \$8,600.00 and 8 days for repair.

On Fri, Apr 26, 2019 at 1:43 PM Veron Chen (LKKAuto) <veronchen@lkkauto.com> wrote:

Dear Sir/Madam,

WITHOUT PREJUDICE

Offer Lump Sum \$8600 @ 8 working days.

Please check and confirm.

* Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Pioneer Workshop <pioneer@skauto.com.sg>
Sent: Monday, 8 April 2019 1:01 PM
To: Steve Chen (LKK Auto) <SteveChen@lkkauto.com>
Subject: Finalized SDZ2438Z

Dear Mr Steve

Kindly help to finalized below vehicle. The after photo attached.

TP CN	SDZ2438Z	Lumpsum	\$11,150.46
-------	----------	---------	-------------

Repair days: 10 Days

--

Thanks & Regards,

Yvette Zhao

SK Automobile Pte Ltd

48 Toh Guan Road East # 01-121
Enterprise Hub, Singapore 608586
D: +65 6266 0555 | F: +65 6266 3155 | pioneer@skauto.com.sg

Thanks & Regards,

Yvette Zhao

SK Automobile Pte Ltd

48 Toh Guan Road East # 01-121

Enterprise Hub, Singapore 608586

D: +65 6266 0555 | F: +65 6266 3155 | pioneer@skauto.com.sg

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Mar 2019		08 Mar 2019 18:11 Edit Adj Rpt	S\$8,600.00 Edit Estimates	S\$8,600.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	Co. Reg. No.: -								
Main Claimant:	KOH KOK WAH								
Vehicle Reg. No.:	SDZ2438Z	Date of Loss:	06/03/2019 00:00 - :59 [41 Months and 4 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D200430C02	Policy/Cover Note No.:	DMPCSN30492218022						
Vehicle Reg. No. (Insured):	SBT3606D	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	SK Automobile Pte Ltd (Toh Guan) 48 Toh Guan Road East #01-121, Enterprise Hub, 608586 Jurong East - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 19/03/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SDZ2438Z (SNM19D200430C02)
[SBT3606D]
TP
KOH KOK WAH
Mar 6 2019 12:00AM
[-]
SK Automobile Pte Ltd

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	03/05/19 15:59	General View	Load PDF	
2	03/05/19 16:00	Reinspection Photo	Load PDF	

Documentation

1 per page

No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	08/03/19 18:11	PRI CONTACT	Load PDF	
2	08/03/19 18:11	REPAIR ESTIMATE	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT19004373/R1VD3E2

Date: 28/05/2019

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSN30492218022

Claimant Vehicle No: SDZ2438Z Insured Vehicle No: SBT3606D

Date of Loss: 06/03/2019 Nature of Claim: TP Claim No: SNM19D200430C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SDZ2438Z

Make & Model: HONDA VEZEL, 1.5 (A) Engine No: L15B4020994

Reg. Date: 02/10/2015 (Man. Year: 2015) Chassis No: RU11100991

Colour: Brown Odometer: 73996 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16

Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,726.72	8,830.08	8,896.64	50.19
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,320.00	1,960.00	4,360.00	68.99
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	24,046.72	10,790.08	13,256.64	55.13
Approved Total (Overridden) (S\$)		8,600.00		
(S\$)	24,046.72	8,600.00	15,446.72	64.24
+ GST 7.00/7.00% (S\$)	1,683.27	602.00	1,081.27	64.24
Nett Amount (S\$)	25,729.99	9,202.00	16,527.99	64.24

INSPECTION

Date of Assignment: 08/03/2019

Date Inspected: 08/03/2019 Inspected At: SK Automobile Pte Ltd (Toh Guan)
48 Toh Guan Road East #01-121,
Enterprise Hub
Singapore 608586

Estimated Period of Repair: 8.0 days

Adjuster: MOHD RASUL**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 May 2019)
Parts:	M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDZ2438Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Bent	953.30 FL	*953.30 FL
2	1		*SET REAR TAILGATE WINDSCREEN MOULDING	Necessary	123.80 FL	*123.80 FL
3	1		*REAR TAILGATE LOGO EMBLEM	Necessary	32.90 FL	*32.90 FL
4	1		*REAR TAILGATE VEZEL EMBLEM	Necessary	38.60 FL	*38.60 FL
5	1		*REAR TAILGATE OUTER GARNISH	Cracked	165.80 FL	*165.80 FL
6	2		*REAR TAILGATE REFLECTOR LAMP LH / RH	Cracked	827.80 FL	*827.80 FL
7	1		*REAR TAILGATE OUTER LOCK HANDLE SWITCH	Not Necessary	131.70 FL	*- FL
8	1		*REAR TAILGATE WIPER MOTOR	No Damage	258.60 FL	*- FL
9	2		*REAR TAILGATE NUMBER PLATE LAMP LH / RH	Cracked	99.80 FL	*99.80 FL
10	2		*REAR TAILGATE HINGE LH / RH	Serviceable	101.80 FL	*- FL
11	2		*REAR TAILGATE DAMPER LH / RH	Serviceable	385.00 FL	*- FL
12	1		*REAR TAILGATE INNER TRIM BOARD	Cracked	270.30 FL	*225.00 FL
13	1		*REAR TAILGATE MECHANISM LOCK	Bent	216.20 FL	*216.20 FL
14	1		*REAR TAILGATE WEATHER STRIP	Necessary	198.90 FL	*198.90 FL
15	2		*REAR TAILLAMP LH / RH	Cracked	1,104.60 FL	*856.00 FL
16	2		*REAR TAILLAMP INNER PANEL LH / RH	Serviceable	276.40 FL	*- FL
17	1		*REAR BUMPER CENTER	Deformed	762.70 FL	*762.70 FL
18	2		*REAR BUMPER SIDE LH / RH	Cracked	391.60 FL	*391.60 FL
19	2		*REAR BUMPER SIDE RETAINER LH / RH	Serviceable	32.80 FL	*- FL
20	2		*REAR BUMPER REFLECTOR LH / RH	Cracked	302.80 FL	*150.00 FL
21	1		*REAR END PANEL	Bent	480.30 FL	*480.30 FL
22	1		*REAR END PANEL INNER TOP GARNISH	Deformed	102.50 FL	*102.50 FL
23	1		*REAR END PANEL TAILGATE ANTENNA SENSOR	Not Working	121.50 FL	*100.00 FL
24	1		*REAR END PANEL TAILGATE ANTENNA BUZZER	Cracked	98.70 FL	*80.00 FL
25	1		*REAR WELL PANEL	Repair	1,130.90 FL	*- FL
26	1		*REAR WELL PANEL INNER TOP UPHOLSTERY BOARD	Serviceable	324.80 FL	*- FL
27	1		*REAR WELL PANEL INNER TOOL SPONGE	Serviceable	215.90 FL	*- FL
28	1		*REAR WELL PANEL LOWER UNDER COVER	Cracked	213.20 FL	*213.20 FL
29	2		*REAR WELL SIDE PANEL LH / RH	Repair	231.60 FL	*- FL
30	1		*REAR SUB CHASSIS FRAME RH	Repair	720.90 FL	*- FL
31	2		*REAR SUB CHASSIS FRAME TOP PANEL LH / RH	Serviceable	337.80 FL	*- FL
32	1		*REAR FENDER RH	Not Necessary	940.90 FL	*- FL
33	2		*REAR FENDER ARCH GARNISH LH / RH	Cracked	385.60 FL	*344.00 FL
34	2		*REAR FENDER INNER UPHOLSTERY TRIM BOARD LH / RH	Cracked	1,179.40 FL	*590.00 FL
35	2		*REAR FENDER INNER SHIELD LH / RH	Serviceable	396.20 FL	*- FL
36	1		*REAR EXHAUST SILENCER BOX	Bent	1,080.30 FL	*900.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
37	1		*REAR EXHAUST ALUMINIUM HEAT SHIELD	Bent	135.20 FL	*135.20 FL
38	1		*EXHAUST MID PIPE	Bent	3,112.30 FL	*950.00 FL
39	1		*SET REAR TAILGATE OUTER GARNISH CLIPS	Necessary	40.00 FS	*40.00 FS
40	2		*SET REAR TAILGATE REFLECTOR LAMP CLIPS LH / RH	Necessary	60.00 FS	*40.00 FS
41	2		*REAR TAILGATE REFLECTOR LAMP CHROME GARNISH LH / RH	Necessary	40.00 FS	*40.00 FS
42	1		*REAR TAILGATE NUMBER PLATE WITH CASING	Scratched	60.00 FS	*60.00 FS
43	1		*REAR TAILGATE WINDSCREEN SEALANT WITH PRIMER	Necessary	100.00 FS	*60.00 FS
44	1		*SET REAR TAILGATE INNER TRIM BOARD CLIPS	Necessary	60.00 FS	*40.00 FS
45	1		*REAR TAILGATE REVERSE CAMERA	Serviceable	580.00 FS	*- FS
46	1		*REAR TAILGATE CHROME MOULDING	Distorted	650.00 FS	*280.00 FS
47	2		*SET REAR TAILLAMP CLIPS LH / RH	Not Necessary	60.00 FS	*- FS
48	2		*REAR TAILLAMP INNER PANEL SEALANT LH / RH	Not Necessary	80.00 FS	*- FS
49	2		*REAR TAILLAMP CHROME GARNISH LH / RH	Necessary	40.00 FS	*40.00 FS
50	1		*SET REAR BUMPER CLIPS	Necessary	60.00 FS	*60.00 FS
51	2		*REAR BUMPER CHROME GARNISH LH / RH	Necessary	40.00 FS	*40.00 FS
52	1		*SET REAR BUMPER REVERSE SENSOR	Necessary	280.00 FS	*220.00 FS
53	1		*SET REAR END PANEL INNER TOP GARNISH CLIPS	Necessary	40.00 FS	*40.00 FS
54	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
55	1		*REAR WELL PANEL SEALANT	Not Necessary	100.00 FS	*- FS
56	1		*SET REAR WELL PANEL LOWER UNDER COVER CLIPS	Necessary	50.00 FS	*30.00 FS
57	1		*REAR WELL PANEL INSULATOR SOUND MAT	Necessary	250.00 FS	*180.00 FS
58	2		*REAR WELL SIDE PANEL LH / RH	Not Necessary	40.00 FS	*- FS
59	1		*REAR FENDER SEALANT RH	Not Necessary	100.00 FS	*- FS
60	2		*SET REAR FENDER ARCH GARNISH CLIPS LH / RH	Necessary	60.00 FS	*60.00 FS
61	2		*SET REAR FENDER INNER TRIM BOARD CLIPS LH / RH	Necessary	100.00 FS	*100.00 FS
62	2		*SET REAR FENDER INNER SHIELD CLIPS LH / RH	Not Necessary	80.00 FS	*- FS
63	1		*REAR EXHAUST GASKET	Necessary	25.00 FS	*25.00 FS
64	1		*REAR EXHAUST END CHROME PIPE	Scratched	350.00 FS	*250.00 FS
65	1		*EXHAUST MID PIPE GASKET	Necessary	25.00 FS	*25.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) **21,303.40** **10,617.60**
 - List Item Discount on L Items 20.00/20.00% (S\$) **3,576.68** **1,787.52**

Total Parts (S\$) 17,726.72 8,830.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	New	2,200.00	800.00
2	TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	New	1,800.00	600.00
3	TO APPLY ANTI-RUST & TUFF KOTE	New	200.00	100.00
4	TO PERFORM LIGHTING & WIRING CHECK	New	80.00	30.00
5	TO DISMANTLE & REPLACED REAR UNDER CARRIAGE COMPONENT LH / RH TO PERFORM FACILITATE REPAIRS	New	280.00	0.00
6	TO SEND VEHICLE FOR 3D COMPUTERISED TO PERFORM CHECK & ADJUSTED ALL WHEEL ALIGNMENT	New	100.00	0.00
7	TO CALIBRATE CHASSIS & CAR BODY BACK TO MANUFACTURING SPECIFICATION	New	380.00	0.00
8	TO DISMANTLE & REINSTALL REAR PETROL TANK FOR FACILITATE REPAIR	New	250.00	0.00
9	TO DISMANTLE & REINSTALL REAR WINDSCREEN PERFORM WITH WATER LEAK TEST	New	150.00	120.00
10	TO PERFORM TRANSFER REAR BOOT LID MECHANISM & REALIGN BACK TO MANUFACTURING SPECIFICATION	New	180.00	80.00
11	TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR WITH DISTANCE SETTING	New	80.00	60.00
12	TO DISMANTLE & REPLACED REAR EXHAUST SILENCER BOX WITH REALIGN EXHAUST MID PIPE & RUBBER MOUNTING	New	260.00	80.00
13	TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR	New	280.00	60.00
14	TO PERFORM CONDUCT WATER LEAKAGE TEST OF ACCIDENT PORTION	New	80.00	30.00
Gross Labour Cost (S\$)			6,320.00	1,960.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >