

ASS. REC. BY:

REC:

CS/CTI19004374 / Urd3

12

Special Instruction:

Surveyor
Munimen

Marcus

ASSIGNMENT (Office)

From (Person):

Elaine Cheong

of

CTI

Date/Time:

8/3/17 @ 5:45pm

Estimated Cost:

Bill to:

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

8JX 2559Y

Insured:

SBF 118P

at Workshop m/s:

Rico 60

Tel:

9187 8064

of

8 Kaki Bkt Ave 4 # 02-24

Policy No:

DMPC SN 3022 0418022

Claim No:

8NML9D200627002

Sum Insured:

Excess:

Make of Veh:

D.O.A.

5/3/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

11/11/17 @ 11/3/17

Person Contacted:

shanelle

Vehicle:

IN OUT

Date/Time

Action/Instruction

✓) Estimate

8JX 2559Y -x

SBF 118p- CCG/CTI 16010298 / M/pq3n2

20A:31/5/16

(08/11/13) wef

ASS. REC. BY: *marcus*

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: *SJX 2578*at Workshop m/s *Rico 60*

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: *19500*

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: *2* Consistent? : Yes or NoEst. Repairs: *12* days Res.: Yes or NoLum Sum: *20* % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: *SJX 2578*Yr Regn: *5, 10*Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or *SA*Make: *KIA cerato forte*c.c. *1591*Colour: *grey*

A/C: Insured / Std / NI / NA

Sp. Reading: *158629*

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: *KN4FW41MA5200652*Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: *215/45R17*

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or *continued*

Front

Rear

R/Bal. *6* mmR/Bal. *6* mmL/Bal. *6* mmL/Bal. *6* mmD.O.A. *5/3/19*D.O.I. *11/3/19*

Survey held at _____

Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or*Rear & R.*

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

*14/3/19 LTA 11052 signed by 4848**12/3/19 L/S \$8000 confirmed with John. (Red 34,667.50, 819)*

RECEIVED 14 MAR 2019

Date/Time, File Pass to?

☐

: Preli. Report

Days Of Repair: *12*

1)

☐

: Final Report

Resurvey No. of Trip: *-*

Date/Time, File Return to?

2) *14/3 - typist*

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)

Survey Fee:

Transportation:

) S + RS SI

) Photos

) Others

Report Format: *merimen*Lump Sum / I.B.I.: (\$ *8000*)

220

TOTAL

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Mar 2019		08 Mar 2019 17:45 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	
Main Claimant:	NG SENG KAH, ID: S1491078F
Vehicle Reg. No.:	SJX2559Y
Date of Loss:	05/03/2019 22:00 - :59
Claim Type:	TP / SNM19D200627C02
Policy/Cover Note No.:	DMPCSN30220418022
Vehicle Reg. No. (Insured):	SBF118P
Policy No. (Claimant):	5105447117 CLASSIC
Excess:	S\$750.00
Repairer:	VAC (Kaki Bukit) 23 Kaki Bukit Ave 4, 768732 Kaki Bukit - Tel:
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 19/03/2019]

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



RICO 60 AUTO SERVICES PTE. LTD.

Co. & GST Reg. No.: 201807623M

Kaki Bukit Avenue 4, Premier @ Kaki Bukit, #02-24

Singapore 415875 | Email: enquiry@rico60.com

Tel: +65 6286 6060 | Fax: +65 6286 7060

PRI ARRANGEMENT

Date: 6/3/2019

To: China Taiping

ATTN: Motor Claims Department


RE: Accident involving motor vehicle nos. SJX 2559Y, SBF118P & SJQ 384A
along SLE (BKE) Before Mandai Exit on 5/3/2019 @ 22:20 hrs.

We refer to the above matter.

We are instructed by Ng Sang Kah S1491078F
to notify you of a road traffic accident on 5/3/2019 at about 22:20 hrs
along SLE (BKE) Before Mandai Exit
involving our client's vehicle no. SJX 2559Y and vehicle no. SBF118P
driven by you at the stated time.

Due to the above-mentioned accident, our client's vehicle has been damaged. Before our client/we proceed with the repair(s) of the damaged vehicle, please kindly let us know within 2 working days of your receipt of this notice, whether you or your insurer would like to conduct pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client/we shall proceed to the repair work(s) of the vehicle without further reference to you.

Thank you.


Signature

Name: Shanelle Lim

Mobile No.: 9187 8064



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New 10 Years COE Renewal Toyota Estima 2.4A



2.58% P/A Low Interest Rate
Finance 2 Years Warranty
\$4500 Down Monthly \$388
GV Credit Pte Ltd SunA2



« Back (1 2) Next »

Sort by Date Posted

20 results

34 vehicles

kia cerato

Basic Search



Price Any price **Depre** Any depre **Reg Date** 2010 to 2010 **Eng Cap** Any **Veh Type** All types
Fuel Any fuel **Mileage** Any **OMV** Any **Gear** Any Gear **Past Owners** Any
Category All categories **Scheme** All schemes **Dealer** Any Dealer **Location** Any **Status** Available

Make & Model Price Depreciation Reg Date Eng Cap Mileage Veh Type St



Kia Cerato Forte Koup 1.6A SX

\$16,999

\$8,280 /yr

15-Apr-2010

1,591 cc

159,000 km

Sports

A

3k Deposit.SUNROOF UNIT! Well Maintained! Interior And Exterior In Great Condition. Call For More Details.

Posted: 05-Mar-2019 Tags: 2010 Kia Cerato, 2010 kia cerato, Kia Cerato, kia cerato, Kia, Cerato, cerato, Used Kia



Kia Cerato Forte 1.6A SX

\$15,800

\$9,850 /yr

20-Jan-2010

1,591 cc

117,000 km

Sedan

A

Low Mileage. Well Kept Condition. Look No Further. Call Now For An Appointment.

Posted: 05-Mar-2019 Tags: 2010 Kia Cerato, 2010 kia cerato, Kia Cerato, kia cerato, Kia, Cerato, cerato, Used Kia



Kia Cerato Forte 1.6A SX (New 5-yr COE)

\$31,800

\$6,350 /yr

26-Feb-2010

1,591 cc

106,000 km

Sedan

A

100% Loan Available, Keyless Entry, Very Well Maintained, With All Wear And Tear Parts Recently Replaced. Fuel Economy Car Suitable For Daily Usage, Act Now Before It's Gone.

1axis

Posted: 05-Mar-2019 Tags: 2010 Kia Cerato, 2010 kia cerato, Kia Cerato, kia cerato, Kia, Cerato, cerato, Used Kia



Kia Cerato Forte Koup 2.0A SX

\$19,800

\$11,490 /yr

03-Mar-2010

1,998 cc

93,680 km

Sports

A

1 Owner With Low Mileage. Original Condition Inside And Out. Superb Handling And Fuel Efficient. No Repairs Needed. Call Our Friendly Sales Team Before It's Gone.

Posted: 05-Mar-2019 Tags: 2010 Kia Cerato, 2010 kia cerato, Kia Cerato, kia cerato, Kia, Cerato, cerato, Used Kia



Best Replacement Quality for Your Cushion

We provide the BEST quality materials for you to change or repair your worn out leather/cushion seats!

More info about this product



Kia Cerato Forte 1.6A SX (OPC)

\$13,800

\$8,410 /yr

25-Feb-2010

1,591 cc

-

Sedan

A

Option To Convert To Normal Plate At \$2500. Cheap Short Term Drive. No Repairs Needed. Clean And Smoke Free Interior Cabin. Leather Seats. Call Us For More Information.

Auto Zoom Enterprise Pte Ltd

Posted: 05-Mar-2019 Tags: 2010 Kia

3 Cerato, kia cerato, Kia, Cerato, cerato, Used Kia

Compare



Kia Cerato

Price Range

Depreciation

2010

Vehicle Type



Submit

Advanced Search

Home » Used Cars » 007 » Kia Cerato Forte 1.6A SX

Kia Cerato Forte 1.6A SX

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

Price \$18,998**Depreciation** \$9,060 /yr
View models with similar depre**Reg Date** 29-Jun-2010
(1yr 3mths 17days COE left)**Mileage** N.A.**Manufactured** 2010**Road Tax** \$738 /yr**Transmission** Auto**Dereg Value****OMV** \$14,414

\$12,028 as of today (change)

ARF \$14,414**COE** \$31,510**Power** 92.7 kW (124 bhp)**Engine Cap** 1,591 cc**No. of Owners** 2**Curb Weight** 1,251 kg**Type of Vehicle** Mid-Sized Sedan**Features**

4 Cylinder Inline 16 Valves DOHC Engine Producing 124bhp Mated To 5 Speed Steptronic. ABS, Knockdown Rear Seats, Keyless Entry/Start/Stop. View specs of the Kia Cerato Forte (2009-2013)

Accessories

Leather Seats, Built In Audio With AUX/USB/Steering Controls, Retractable Side Mirrors, Reverse Sensors, Solar Film, Fog Lights.

Description

Be Our Next Happy Client To Owned This Quality Pre-Owned Vehicle At Most Reasonable And Affordable Price! Selling Cheap! Very Well Maintained Exterior! Clean Upholstery! Flexible Bank/In House Loan Available. Why Wait? Call Our Professional And Friendly Staffs For A No Obligations Discussion. Reasonable Offer Will Be Considered. No Low Ballers.

Category

PARF Car

Status

Available

Resources

Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more



Car Valuation - Free


Find out the market value of your existing car for free. Get started



Location Map

Price Chart

Summary



Click on the point to view the vehicle

Shortlist

Compare

Add note

Report Error

More Actions

Seller Information

Company

007

• dealer's pricelist

• 25 vehs sold | 26 vehs available

Address

421 Tagore Industrial Avenue #02-09

Search cars nearby this location

Location

Tagore 8

Office No

65700770

Posted on: 23-Feb-2019 | Last Updated on: 25-Feb-2019

Upfront Payment

» more Financial info

Transfer Fee \$25**Down Payment** \$5,699 (change)

Maximum 70% Loan

1st Instalment \$920

Based on 2.98% interest rate

500+ dealers
competed to
buy my car!



- Sell ur Car for More Cash
- Highest Price or Get \$100 Free
- Get Paid Now, Handover Later

[SELL YOUR CAR](#)


Kia Cerato

Price Range

Depreciation

2010

Vehicle Type



Submit

Advanced Search

[Home](#) » [Used Cars](#) » [Senbel Automobile](#) » [Kia Cerato Forte 1.6A SX](#)

Kia Cerato Forte 1.6A SX

[Overview](#)
[Financial](#)
[Insurance](#)
[Accessories](#)
[Similar](#)
[Research](#)
[Photos](#)
[Map](#)

Price \$19,800

Depreciation \$10,050 /yr
View models with similar depre

Reg Date 09-Jun-2010
(1yr 2mths 28days COE left)

Mileage 95,000 km (10.8k /yr)

Manufactured 2010

Road Tax \$738 /yr

Transmission Auto

Dereg Value

\$10,559 as of today (change)

OMV \$14,548

COE \$20,514

ARF \$14,548

Engine Cap 1,591 cc

Power 92.7 kW (124 bhp)

Curb Weight 1,251 kg

No. of Owners 2

Type of Vehicle Mid-Sized Sedan

Features

1.6L 4 Cylinders 16 Valves Engine, 124 BHP, 4 Speed Automatic, ABS, Airbags, Keyless Entry/Start/Stop, Front/Rear Disc Brakes, Knockdown Rear Seats. S View specs of the Kia Cerato Forte (2009-2013)

Accessories

Original Factory 6 Discs Player, Reverse Sensors, Sports Rims, Auto Dim Rear Mirrors, Fog Lamps.

Description

Full Agent Service Since Day 1, Superb Low Mileage At 95k Only(Proved Of Pictures), Ideas For Short Terms Or Grab Used, Clean And Beautiful Interior, No Gimmicks No Hidden Cost, Buy With Peace Of Mind, Bank Or 100% In House Loan Available, Don't Miss The Opportunity And Call Our Sales Teams For More Details Before It's Gone!

Category

PARF Car

Status

Available

Resources



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more



Car Valuation - Free


Find out the market value of your existing car for free. Get started



Location Map

Price Chart

Summary



Click on the point to view the vehicle

[Shortlist](#)
[Compare](#)
[Add note](#)
[Report Error](#)
[More Actions](#)

Posted on: 08-Mar-2019 | Last Updated on: 10-Mar-2019

Upfront Payment

» more Financial Info

Transfer Fee \$25

Down Payment \$5,940 (change)

Maximum 70% Loan

1st Instalment \$1,024

Based on 2.98% interest rate

Insurance \$1,297 onwards

Compare

Not at fault? No upfront payment required! (Get a quote)

Seller Information

Company

Senbel Automobile

* dealer's pricelist

* 17 vehs sold | 9 vehs available

Address

210 Turf Club Road Lot B29

Search cars nearby this location

Japan Airlines Official

Direct Flight to Japan from SGD675. Book Now & Start Your Amazing Journey Ahead With JAL

Kia Cerato

Price Range

Depreciation

2010

Vehicle Type



Submit

Advanced Search

Home » Used Cars » Ding Feng Pte Ltd » Kia Cerato Forte 1.6A EX

Kia Cerato Forte 1.6A EX

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map



DING FENG ADVANTAGE

Price	\$19,800		
Depreciation	\$9,050 /yr View models with similar depre	Reg Date	14-Oct-2010 (1yr 7mths 2days COE left)
Mileage	152,000 km (18.1k /yr)	Manufactured	2010
Road Tax	\$738 /yr	Transmission	Auto
Dereg Value	\$11,184 as of today (change)	OMV	\$10,730
COE	\$33,132	ARF	\$10,730
Engine Cap	1,591 cc	Power	92.7 kW (124 bhp)
Curb Weight	1,251 kg	No. of Owners	2
Type of Vehicle	Mid-Sized Sedan		

Features

View specs of the Kia Cerato Forte (2009-2013)

Description

Sporty White Cerato! Original Condition, Trade In Welcome, Call Us Now For Viewing!

Category

PARF Car

Status

Available

Resources



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more



Car Valuation - Free


Find out the market value of your existing car for free. Get started



Location Map

Price Chart

Summary



Click on the point to view the vehicle

Shortlist

Compare

Add note

Report Error

More Actions

Seller Information

Company

Ding Feng Pte Ltd

» dealer's pricelist

» 18 vehs sold | 41 vehs available

Address

55 Serangoon North Avenue 4 #04-11

Posted on: 02-Mar-2019 | Last Updated on: 02-Mar-2019

Upfront Payment

» more Financial info

Transfer Fee	\$25	
Down Payment	\$5,940 (change)	Maximum 70% Loan
1st Instalment	\$764	Based on 2.98% interest rate

Compare

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1078F
Vehicle Details	
Vehicle No.:	SJX2559Y
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Mar 2019
Vehicle Make:	KIA
Vehicle Model:	CERATO FORTE 1.6SX AT ABS D/AB 2WD 4DR
Primary Colour:	Brown
Manufacturing Year:	2010
Engine No.:	G4FCAH363584
Chassis No.:	KNAFW411MA5200652
Maximum Power Output:	92.7 kW (124 bhp)
Open Market Value:	\$14,139.00
Original Registration Date:	27 May 2010
First Registration Date:	27 May 2010
Transfer Count:	2
Actual ARF Paid:	\$14,139.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 May 2020
PARF Rebate Amount:	\$7,776.00
Intended COE Rebate Details	
COE Expiry Date:	26 May 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$27,389.00
COE Rebate Amount:	\$3,276.00
Total Rebate Amount:	\$11,052.00

The information contained herein is correct as at 12 Mar 2019

OK



Rico 60 Auto Services Pte Ltd . Blk 8 , Kaki Bukit Avenue 4 , #02-24
Premier @ Kaki Bukit Singapore 415875 , Email: claims@rico60.com
Tel: 6286 6060 , FAX: 6286 7060

VEHICLE NUM:
MAKE & MODEL:
MILEAGE:
TYRE:
CHASSIS NUM:

SJX 2559 Y
KIA CERATO FORTE

Not Affected
N/A
1/2 to 80000
The price change
11/3/19
12dy.

ATTN:						
NO.	DESCRIPTION - PARTS	QTY	PRICE			
1	REAR WINDSCREEN MOULDING	1	\$ 142.00	X		
2	REAR BOOTLID	1	\$ 747.00	X		
3	REAR BOOTLID HINGE L+R	2	\$ 296.00	X		
4	BOOT LID LAMP	2	\$ 270.00	X		
5	BOOT LID MOULDING	1	\$ 193.00	X		
6	BOOT LID LOGO 'KIA'	1	\$ 55.00	X		
7	BOOT LID STOPPER	2	\$ 38.00	X		
8	BOOT LID HINGE	2	\$ 296.00	X		
9	BOOT LID INSULATOR	1	\$ 231.00	X		
10	BOOT LID WEATHER STRIP	1	\$ 148.00	X		
11	BOOT LID WIRE HARNESS	1	\$ 4,468.00	X		
12	BOOT LID LOCK	1	\$ 174.00	X		
13	BOOT LID LOCK CABLE	1	\$ 241.00	X		
14	BOOT LID KEY LOCK	1	\$ 196.00	X		
15	TAIL LAMP L+R	2	\$ 358.00	X		
16	TAIL LAMP PANEL L+R	2	\$ 520.00	X		
17	REAR BUMPER	1	\$ 601.00	X		
18	REAR BUMPER LOWER LIP	1	\$ 247.00	X		
19	REAR BUMPER BRACKET	5	\$ 110.00	X		
20	REAR BUMPER SIDE RETAINER	2	\$ 32.00	X		
21	REAR BUMPER REINFORCEMENT BRACKET	2	\$ 32.00	X		
22	REAR BUMPER REINFORCEMENT	1	\$ 394.00	X		
23	REAR BUMPER SPONGE	1	\$ 189.00	X		
24	REAR FENDER L+R	2	\$ 1,814.00	X		
25	REAR FENDER INNER PANEL L+R	2	\$ 878.00	X		
26	REAR WHEEL HOUSE PANEL L+R	2	\$ 2,192.00	X		
27	REAR WHEEL HOUSE SUPPORT PANEL L+R	2	\$ 494.00	X		
28	REAR FENDER INNER COWLING L+R	2	\$ 98.00	X		
29	REAR FENDER INNER TRIM L+R	2	\$ 546.00	X		
30	REAR FENDER AIR VENT	2	\$ 108.00	X		
35	REAR END PANEL	1	\$ 382.00	X		
36	REAR END PANEL TOP GARNISH	1	\$ 143.00	X		
37	REAR FLOOR PANEL	1	\$ 794.00	X		
38	REAR FLOOR PANEL TOP BOARD	1	\$ 189.00	X		
39	REAR EXHAUST	1	\$ 763.00	X		
40	REAR EXHAUST MOUNING	2	\$ 65.60	X		
41	REAR EXHAUST HEAT SHIELD	1	\$ 123.80	X		
39	BONNET	1	\$ 680.00	X		
40	BONNET HINGE	2	\$ 90.00	X		
41	BONNET LOCK	1	\$ 153.00	X		

42	FRONT GRILLE	295	CM	1	S	580.00	/
43	FRONT GRILLE LOGO		1/2	1	S	65.00	/
42	FRONT BUMPER		7-5	1	S	568.00	/
43	FRONT BUMPER BRACKET L+R		3-1/2	2	S	76.00	/
44	FRONT BUMPER REINFORCEMENT		3-1/2	1	S	365.00	/
45	FRONT BUMPER SPONGE		7-1/2	1	S	160.00	/
46	FRONT BUMPER FOG LAMP GRILLE L+R		1-1/2	2	S	145.00	X
47	FRONT BUMPER FOG LAMP L+R		1-1/2	2	S	920.00	X
48	FRONT BUMPER SIDE RETIANER		3-1/2	2	S	42.00	/
49	HEADLAMP L+R	560	5594 o/s one	2	S	1,188.00	12 C
50	HEADLAMP LOWER BRACKET L+R		1-1/2	2	S	48.00	X
51	FRONT SUPPORT PANEL		one/box	1	S	742.00	/
52	FRONT WIPER TANK		1-1/2	1	S	149.00	/
53	AIR CON CONDENSER SIDE GARNISH L+R	535	o/s 7-1/2	2	S	70.00	12 C
54	AIR CON CONDENSER		Best	1	S	685.00	2
55	RADIATOR		one	1	S	865.00	X
							9389
							9025
					SUBTOTAL	\$ 26,159.40	
					LESS 20%	\$ 5,231.88	
					PARTS TOTAL	\$ 20,927.52	
SPECIAL NETT				QTY	PRICE		
1	FRONT WINDSCREEN SEALANT		1-1/2	1	S	120.00	X
2	FRONT NUMBER PLATE		3-1/2	1	S	120.00	40
3	RADIATOR COOLANT		one	1	S	120.00	30
4	FRONT BUMPER LOWER LIPS		one	1	S	2,500.00	680
5	FRONT BUMPER CLIPS		one	10	S	100.00	50
6	FRONT BONNET ISOLATOR CLIPS		1-1/2	10	S	100.00	X
7	FRONT FENDER COWLING CLIPS		1-1/2	10	S	100.00	X
8	REAR BOOTLID SPOILER		one	1	S	1,500.00	X
9	REAR BUMPER LOWER LIP		one	1	S	2,500.00	680
10	REAR BUMPER CLIPS		one	10	S	100.00	50
11	REAR BUMPER REFLECTOR		3-1/2	2	S	80.00	50
11	REAR FENDER COWLING CLIPS		1-1/2	10	S	100.00	X
12	REAR FENDER INNER TRIM CLIPS		1-1/2	10	S	100.00	X
13	BOOTLID INNER TRIM CLIPS		1-1/2	10	S	100.00	X
14	REAR END PANEL TOP GARNISH CLIPS		1-1/2	10	S	100.00	X
15	REAR NUMBER PLATE		1-1/2	1	S	120.00	X
16	REVERSE SENSOR		skid	4	S	600.00	250
17	REAR END PANEL SEALANT		one	1	S	120.00	50
18	SPARE WHEEL PANEL SEALANT		1-1/2	1	S	120.00	X
							1830
					SPECIAL NETT TOTAL	\$ 8,580.00	1880
LABOUR				QTY	PRICE		
1	TO RNR ACCIDENT DAMAGE PARTS,CUT/WELD ,KNOCK&REALIGN			1	S	5,000.00	1800
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA			1	S	5,000.00	1800
3	TO RUST PROOF ACCIDENT AFFECTED AREA			1	S	120.00	120
4	TO RNR REAR WINDSCREEN		1-1/2	1	S	400.00	X
5	TO RNR REAR BOOT MECHANISM			1	S	120.00	60

6	TO RNR REAR LUGGAGE COMPARTMENT	1	\$	400.00	80
7	TO RNR REVERSE SENSOR & CHECK FUNCTION.	1	\$	120.00	50
8	TO RNR A/C CONDENSOR ASSY AND REFILL GAS	1	\$	250.00	100
9	TO CHECK WIRING LAYOUT AND HEADLAMP FOCUS	1	\$	120.00	30
10	TO CHECK WIRING LAYOUT AND TAILLAMP FUNCTION	1	\$	120.00	60
11	TO CHECK WIRING LAYOUT AND BOOTLID LAMP FUNCTION	1	\$	120.00	X
12	TO RNR TYRE AND WHEEL BALANCING	1	\$	120.00	X
13	TO DO DIAGNOSIS AND RESET , REPROGRAM OR CODING FAULT CODE.	1	\$	400.00	X
14	TO DO WATER LEAK TEST .	1	\$	120.00	X
15	TO RNR RADIATOR ASSY AND HOSES TO ASSIST WORK LOAD	1	\$	250.00	X
16	TO RNR REAR EXHAUST ASSY	1	\$	250.00	60
17	TO RNR FUEL TANK TO ASSIST WORK LOAD	1	\$	250.00	X
				LABOUR TOTAL	\$ 13,160.00
				GRAND TOTAL COST	\$ 42,667.52
					42787.52
					4160

PAGE 2 OF 2

14490

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To declare damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No other modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19004374/UVD3N2

Date: 15/03/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN30220418022	
Claimant Vehicle No :	SJX2559Y	Insured Vehicle No :	SBF118P	
Date of Loss:	05/03/2019	Nature of Claim:	TP	Claim No: SNM19D200627C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJX2559Y	Engine No:	G4FCAH363584
Make & Model:	KIA CERATO FORTE, 1.6 SX (A)	Chassis No:	KNAFW411MA5200652
Reg. Date:	27/05/2010 (Man. Year: 2010)	Odometer:	158629 km
Colour:	Grey		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/45R17	Rear Tyre Size:	215/45R17
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	29,627.52	9,391.20	20,236.32	68.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,160.00	4,160.00	9,000.00	68.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	42,787.52	13,551.20	29,236.32	68.33
Approved Total (Overridden) (\$\$)		8,000.00		
(\$\$)	42,787.52	8,000.00	34,787.52	81.30
+ GST 7.00/7.00% (\$\$)	2,995.13	560.00	2,435.13	81.30
Nett Amount (\$\$)	45,782.65	8,560.00	37,222.65	81.30

INSPECTION

Date of Assignment:	08/03/2019	
Date Inspected:	11/03/2019	Inspected At: RICO 60 AUTO SERVICES PTE LTD (HQ) 8, KAKI BUKIT AVENUE 4, #02-24, PREMIER @ KAKI BUKIT Singapore 415875

Estimated Period of Repair: 12.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Mar 2019)
Parts:	143	KIA CERATO FORTE 1.6 SX (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJX2559Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR WINDSCREEN MOULDING	Not Necessary	142.00 FL	*- FL
2	1	*REAR BOOTLID	Badly Dented	747.00 FL	*747.00 FL
3	2	*REAR BOOTLID HINGE L+R	Repair	296.00 FL	*- FL
4	2	*BOOT LID LAMP	Scratched/Cracked	270.00 FL	*270.00 FL
5	1	*BOOT LID MOULDING	Not Necessary	193.00 FL	*- FL
6	1	*BOOT LID LOGO KIA	Necessary	55.00 FL	*55.00 FL
7	2	*BOOT LID STOPPER	Not Necessary	38.00 FL	*- FL
8	2	*BOOT LID HINGE	Repeated	296.00 FL	*- FL
9	1	*BOOT LID INSULATOR	Not Necessary	231.00 FL	*- FL
10	1	*BOOT LID WEATHER STRIP	Twisted	148.00 FL	*148.00 FL
11	1	*BOOT LID WIRE HARNESS	Not Necessary	4,468.00 FL	*- FL
12	1	*BOOT LID LOCK	Twisted	174.00 FL	*174.00 FL
13	1	*BOOT LID LOCK CABLE	Not Necessary	241.00 FL	*- FL
14	1	*BOOT LID KEY LOCK	Not Necessary	196.00 FL	*- FL
15	2	*TAIL LAMP L+R	Cracked	358.00 FL	*358.00 FL
16	2	*TAIL LAMP PANEL L+R	Repair	520.00 FL	*- FL
17	1	*REAR BUMPER	Distorted	601.00 FL	*601.00 FL
18	1	*REAR BUMPER LOWER LIP	Distorted	247.00 FL	*247.00 FL
19	5	*REAR BUMPER BRACKET	Bent	110.00 FL	*110.00 FL
20	2	*REAR BUMPER SIDE RETAINER	Bent	32.00 FL	*32.00 FL
21	2	*REAR BUMPER REINFORCEMENT BRACKET	Bent	32.00 FL	*32.00 FL
22	1	*REAR BUMPER REINFORCEMENT	Cracked	394.00 FL	*394.00 FL
23	1	*REAR BUMPER SPONGE	Torn	189.00 FL	*189.00 FL
24	2	*REAR FENDER L+R	Repair	1,814.00 FL	*- FL
25	2	*REAR FENDER INNER PANEL L+R	Not Necessary	878.00 FL	*- FL
26	2	*REAR WHEEL HOUSE PANEL L+R	Repair	2,192.00 FL	*- FL
27	2	*REAR WHEEL HOUSE SUPPORT PANEL L+R	Not Necessary	494.00 FL	*- FL
28	2	*REAR FENDER INNER COWLING L+R	Torn	98.00 FL	*98.00 FL
29	2	*REAR FENDER INNER TRIM L+R	Not Necessary	546.00 FL	*- FL
30	2	*REAR FENDER AIR VENT	Not Necessary	108.00 FL	*- FL
31	1	*REAR END PANEL	Badly Dented	382.00 FL	*382.00 FL
32	1	*REAR END PANEL TOP GARNISH	Twisted	143.00 FL	*143.00 FL
33	1	*REAR FLOOR PANEL	Crumpled/Buckled	794.00 FL	*794.00 FL
34	1	*REAR FLOOR PANEL TOP BOARD	Warped	189.00 FL	*189.00 FL
35	1	*REAR EXHAUST	Repair	763.00 FL	*- FL
36	2	*REAR EXHAUST MOUNING	Not Necessary	65.60 FL	*- FL
37	1	*REAR EXHAUST HEAT SHIELD	Not Necessary	123.80 FL	*- FL
38	1	*BONNET	Buckled	680.00 FL	*680.00 FL
39	2	*BONNET HINGE	Not Necessary	90.00 FL	*- FL
40	1	*BONNET LOCK	Twisted	153.00 FL	*153.00 FL
41	1	*FRONT GRILLE	Cracked	580.00 FL	*295.00 FL
42	1	*FRONT GRILLE LOGO	Necessary	65.00 FL	*65.00 FL
43	1	*FRONT BUMPER	Distorted	568.00 FL	*568.00 FL
44	2	*FRONT BUMPER BRACKET L+R	Bent	76.00 FL	*76.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
45	1	*FRONT BUMPER REINFORCEMENT	Bent	365.00 FL	*365.00 FL
46	1	*FRONT BUMPER SPONGE	Torn	160.00 FL	*160.00 FL
47	2	*FRONT BUMPER FOG LAMP GRILLE L+R	Not Necessary	145.00 FL	*- FL
48	2	*FRONT BUMPER FOG LAMP L+R	Not Necessary	920.00 FL	*- FL
49	2	*FRONT BUMPER SIDE RETAINER	Bent	42.00 FL	*42.00 FL
50	1	*HEADLAMP L+R	O/s Cracked	1,188.00 FL	*560.00 FL
51	2	*HEADLAMP LOWER BRACKET L+R	Not Necessary	48.00 FL	*- FL
52	1	*FRONT SUPPORT PANEL	Cracked/Bent	742.00 FL	*742.00 FL
53	1	*FRONT WIPER TANK	Not Necessary	149.00 FL	*- FL
54	1	*AIR CON CONDENSER SIDE GARNISH L+R	O/s Torn	70.00 FL	*35.00 FL
55	1	*AIR CON CONDENSER	Bent	685.00 FL	*685.00 FL
56	1	*RADIATOR	Serviceable	865.00 FL	*- FL
57	1	*FRONT WINDSCREEN SEALANT	Not Necessary	120.00 FS	*- FS
58	1	*FRONT NUMBER PLATE	Bent	120.00 FS	*40.00 FS
59	1	*RADIATOR COOLANT	Necessary	120.00 FS	*30.00 FS
60	1	*FRONT BUMPER LOWER LIPS	Cracked	2,500.00 FS	*680.00 FS
61	10	*FRONT BUMPER CLIPS	Necessary	100.00 FS	*50.00 FS
62	10	*FRONT BONNET ISOLATOR CLIPS	Not Necessary	100.00 FS	*- FS
63	10	*FRONT FENDER COWLING CLIPS	Not Necessary	100.00 FS	*- FS
64	1	*REAR BOOTLID SPOILER	Not Necessary	1,500.00 FS	*- FS
65	1	*REAR BUMPER LOWER LIP	Cracked	2,500.00 FS	*680.00 FS
66	10	*REAR BUMPER CLIPS	Necessary	100.00 FS	*50.00 FS
67	2	*REAR BUMPER REFLECTOR	Broken	80.00 FS	*50.00 FS
68	10	*REAR FENDER COWLING CLIPS	Not Necessary	100.00 FS	*- FS
69	10	*REAR FENDER INNER TRIM CLIPS	Not Necessary	100.00 FS	*- FS
70	10	*BOOTLID INNER TRIM CLIPS	Not Necessary	100.00 FS	*- FS
71	10	*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	100.00 FS	*- FS
72	1	*REAR NUMBER PLATE	Not Necessary	120.00 FS	*- FS
73	4	*REVERSE SENSOR	Shorted	600.00 FS	*250.00 FS
74	1	*REAR END PANEL SEALANT	Necessary	120.00 FS	*50.00 FS
75	1	*SPARE WHEEL PANEL SEALANT	Not Necessary	120.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) **34,859.40** **11,269.00**
 - List Item Discount on L Items 20.00/20.00% (S\$) 5,231.88 1,877.80

Total Parts (S\$) 29,627.52 9,391.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RNR ACCIDENT DAMAGE PARTS,CUT/WELD,KNOCK & REALIGN	New	5,000.00	1,800.00
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	New	5,000.00	1,800.00
3	TO RUST PROOF ACCIDENT AFFECTED AREA	New	120.00	120.00
4	TO RNR REAR WINDSCREEN	New	400.00	0.00
5	TO RNR REAR BOOT MECHANISM	New	120.00	60.00
6	TO RNR REAR LUGGAGE COMPARTMENT	New	400.00	80.00
7	TO RNR REVERSE SENSOR & CHECK FUNCTION	New	120.00	50.00
8	TO RNR A/C CONDENSOR ASSY AND REFILL GAS	New	250.00	100.00
9	TO CHECK WIRING LAYOUT AND HEADLAMP FOCUS }	New	120.00	30.00
10	TO CHECK WIRING LAYOUT AND TAILLAMP FUNCTION }	New	120.00	0.00
11	TO CHECK WIRING LAYOUT AND BOOTLID LAMP FUNCTION	New	120.00	60.00
12	TO RNR TYRE AND WHEEL BALANCING	New	120.00	0.00
13	TO DO DIAGNOSIS AND RESET,REPROGRAM OR CODING FAULT CODE	New	400.00	0.00
14	TO DO WATER LEAK TEST	New	120.00	0.00
15	TO RNR RADIATOR ASSY AND HOSES TO ASSIST WORK LOAD	New	250.00	0.00
16	TO RNR REAR EXHAUST ASSY	New	250.00	60.00
17	TO RNR FUEL TANK TO ASSIST WORK LOAD	New	250.00	0.00
Gross Labour Cost (\$\$)			13,160.00	4,160.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >