



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

AIG ASIA PACIFIC INSURANCE PTE LTD
CHARTIS BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120
MOTOR CLAIMS DEPT

NO. : 33785

DATE : 07/03/2019
CLAIM NO. : 11290
POLICY NO. : AVFMSB0000651800
FROM : RAYMOND

VEHICLE NO. : FBN5571M
MAKE/MODEL : YAM / NMAX155 ABS

*not a part
of the
engine. After
11/3/19
3 day.*

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	BEARING P/N: 56460	REPLACE	2.00	\$12.00	24.00 X
2	BELLY PAN P/N: 58094	REPLACE	1.00	\$35.00	35.00
3	BOARD FOOTREST LH P/N: 59588	REPLACE	1.00	\$55.00	55.00
4	BOX FILTER AIR OUTER P/N: 58141	REPLACE	1.00	\$18.00	18.00
5	BOX FILTER AIR OUTER FRONT P/N: 58164	REPLACE	1.00	\$12.00	12.00
6	COVER CLUTCH OUTER P/N: 58147	REPLACE	1.00	\$66.00	66.00
7	COVER SIDE CENTRE LH (WHITE) P/N: 58097	REPLACE	1.00	\$30.00	30.00
8	COVER SIDE LH (GREY) P/N: 60877	REPLACE	1.00	\$38.00	38.00
9	FENDER INNER P/N: 59583	REPLACE	1.00	\$30.00	30.00
10	LABOUR P/N: 06766 - FOR DISMANTLING AND ASSEMBLING OF PARTS QUOTED.	Supply/Install	3.00	\$35.00	105.00
11	MUDGUARD FRONT (WHITE) P/N: 58087	REPLACE	1.00	\$55.00	55.00 X
12	RIM SPORT FRONT P/N: 58148	REPLACE	1.00	\$245.00	245.00 X
13	SEAL OIL P/N: 61482	REPLACE	2.00	\$1.50	3.00 X



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO.: 2002-1-0383
ISO 9001 : 2015

S/N	Description	Action	Qty	Unit Price	Amount
14	SIDE STAND P/N: 58211	REPLACE	1.00	\$25.00	25.00 X
15	SPRAY PAINT FRONT MUDGUARD (LACQUER)	Spray	1.00	\$45.00	45.00 X
16	STAND MAIN P/N: 58138	REPLACE	1.00	\$65.00	65.00 X
17	STICKER (CISCO) MUDGUARD FRONT P/N: 58618	REPLACE	1.00	\$38.00	38.00 ✓
18	TRANSPORT CHARGES P/N: 07169 - FOR COLLECTION OF ACCIDENT BIKE AND DELIVER BIKE BACK ONCE REPAIR DONE.		1.00	\$35.00	35.00 ✓
19	VALVE RIM P/N: 57073	REPLACE	1.00	\$7.00	7.00 X
SUB TOTAL					\$931.00
GST @ 7 %					\$65.17
GRAND TOTAL					<u>\$996.17</u>

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD



RAYMOND

Acknowledge & Accepted By

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

Link to Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

