

ASS. REC. BY:

REF

es/ASM 19004384/Kcd3br

Special Instruction

SALES/REP

Kenneth

ASSIGNMENT (Office)

From/Person

Kitty Teo

of

ASM (A2A)

Date/Time

11/3/2019

Estimated Cost

Till to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKU 3097K

Insured:

at Workshop no:

K. Kim Hin

Tel:

64527018

of

160 Sing Ming Drive #02-20

9717 6881
Meng Huat

Policy No:

Claim No:

S9M01G 6R

Name Insured

Excess:

\$ 900.00

Make of Veh:

D.O.A

5/3/2019

(Client's Record)

12/3/19

H.O.D. Endorsement

CA / REV / REP. / REV 24 HRS

Date/Time:

3:37pm @ 11/3/19

Person Contacted:

Shumen

Vehicle:

IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SKU 3097K-X
13/3/19	Send preli revised via SMART claim
18/4/19	@3:57pm Meng Huat will email us finalise
30/4/19	Final fig \$ 17,801.80 (Red 3865.50, 1870) confirmed by email

REF: ASM(AXA)

ASSIGNMENT

From: _____ Date: **12/3/19**

Estimated Cost: _____

☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: **SKU 3097K**

at Workshop m/s **K Kim Hin**

of **160 Sin Ming Drive # 02-20**

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: **\$900.00**

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: **\$72k**

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: **09** days Res.: Yes or No

Lum Sum: **1-B.1** % 3 Val: Yes or No

☒ CA / REV / REP. / 24 HRS

Date: **1/29** Person Contacted: _____

Vehicle: IN / OUT

Veh No: **SKU 3097K** Yr Regn: **01, 09**

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or

Make: **Mazda mx5 Roadster 1998**

Colour: **Red** A/C: Insured / Std / NI / NA

Sp. Reading: **101844** T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: **NCEC 250437**

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / ☒ STD A/Rim or

Tyre Size: F: _____ R: **205/50ZR16**

BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front R/Bal: **8** mm Rear R/Bal: **8** mm

L/Bal: **8** mm L/Bal: **8** mm

D.O.A: **5/3/19** D.O.I: **12/3/19**

Survey held at ☒

Des. of Damages: ☒ Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 30 APR 2019

RECEIVED 15 MAY 2019

30/4/2019

Date/Time, File Pass to?

☐ : Preli. ReportDays Of Repair: **9**

1)

☐ : Final ReportResurvey No. of Trip: **1**

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

Date/Time, File Return to?

2) **30/4 - typist**Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)Report Format: **SMART claim**Lump Sum / I.B.I. (\$) **17,801.80**

300

300

New Message

Type *

☒ Message

Subject *

IA SUBMITTED FOR SKU 3097K

Message *

Dear Kitty,
Please be informed that IA submitted. We have Authorize repair.Thanks Veron Chen

Cancel

Send



Auto
Consultants
Pte Ltd

21 URAVE L 001-25 PSA UBI INDUSTRIAL PARK, SINGAPORE 400033 TEL : (65) 62563061 FAX : (65) 62564312

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 13/3/2019

Survey details

Date of loss	5/3/2019
Date of appointment	11/3/2019
Date of survey	12/3/2019
Location of survey	K KIM HIN AUTO PTE LTD

Vehicle Details:

Claim Type:	Own Damage
Vehicle number	SKU 3097K
Make and Model	MAZDA ROADTER RHT 2.0A
Date of registration	15/1/2009
Excess	\$900
Market Value	\$72,000.00
Parf Rebate	\$30,821.00
Nett Loss	\$41,179.00

Repair details

Initial Estimate	\$21,667.30
------------------	-------------

Proposed/Revised repair cost:

Parts	\$14,629.30
"Check items (Estimated)	\$3,852.00
Labour	\$1,305.00
Total	\$19,786.30
Lump Sum (Estimated)	

Number of days of repair	9 days (est)
--------------------------	--------------

Remarks:

The vehicle sustained damages at the front portion

Damages Consistent
Repair Cost Economical



Service Request Details

Claim

S9M01G6R

Reference

None 

Loss Date

March 5, 2019

Report Date

Mar 6, 2019 12:00:00 AM

Request Date

March 11, 2019

Due Date

March 18, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Accelerated survey and authorize

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SKU3097K



INQUIRY

MX5 ROADSTER 2.0

Service Address

160 Sin Ming Drive, #, , , 575722

Primary Contact/Insured

LIM JIN YU, MICHELLE

547 JURONG WEST STREET 42, #02-139, 640547, Singapore

93800403

Claim Handler

TEO Kitty

6568804602

kitty.teo@axa.com.sg

Additional Instructions

XS \$900

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)

Document Type

Document SubType

[+ Upload Documents](#)

NAME

 SLG2552G TP GIA.PDF

TYPE

Reports & Statement

SUB-TYPE

GIA Report

AUTHOR

TEO Kitty

DATE UPLOADED

March 11, 2019

NAME

 AUDATEX_190110_SKU3097K.pdf

TYPE

Forms / Claim Documents



AUTHOR	K KIM HIN AUTO PTE LTD (VP)
--------	-----------------------------

DATE UPLOADED	March 9, 2019
---------------	---------------

NAME	 SJG6101Y GIA REPORT.PDF
------	---

TYPE	Reports & Statement
------	---------------------

SUB-TYPE	GIA Report
----------	------------

AUTHOR	DHIWAR Namrata
--------	----------------

DATE UPLOADED	March 7, 2019
---------------	---------------

NAME	 SKU3097K INSD GIA.PDF
------	---

TYPE	Reports & Statement
------	---------------------

SUB-TYPE	GIA Report
----------	------------

AUTHOR	DHIWAR Namrata
--------	----------------

DATE UPLOADED	March 7, 2019
---------------	---------------

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7453J
Vehicle Details	
Vehicle No.:	SKU3097K
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Mar 2019
Vehicle Make:	MAZDA
Vehicle Model:	ROADSTER RHT 2.0 A
Primary Colour:	Red
Manufacturing Year:	2007
Engine No.:	LF10366954
Chassis No.:	NCEC250437
Maximum Power Output:	122.0 kW (163 bhp)
Open Market Value:	\$26,846.00
Original Registration Date:	15 Jan 2009
First Registration Date:	15 Jan 2009
Transfer Count:	3
Actual ARF Paid:	\$26,846.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	14 Jan 2029
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$31,335.00
COE Rebate Amount:	\$30,821.00
Total Rebate Amount:	\$30,821.00

The information contained herein is correct as at 13 Mar 2019

OK

[-> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7453J
Vehicle Details	
Vehicle No.:	SKU3097K
Vehicle to be Exported:	Yes
Intended Deregistration Date:	06 Mar 2019
Vehicle Make:	MAZDA
Vehicle Model:	ROADSTER RHT 2.0 A
Primary Colour:	Red
Manufacturing Year:	2007
Engine No.:	LF10366954
Chassis No.:	NCEC250437
Maximum Power Output:	122.0 kW (163 bhp)
Open Market Value:	\$26,846.00
Original Registration Date:	15 Jan 2009
First Registration Date:	15 Jan 2009
Transfer Count:	3
Actual ARF Paid:	\$26,846.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	14 Jan 2029
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$31,335.00
COE Rebate Amount:	\$30,880.00
Total Rebate Amount:	\$30,880.00

The information contained herein is correct as at 06 Mar 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/03/2019 18:07
Date Of Accident	05/03/2019 17:55
Exact Location Of Accident	SERANGOON AVE 3 TOWARDS CTE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKU3097K
Insured/Policyholder	
Name Of Registered Owner	LIM JIN YU MICHELLE
NRIC No	S8717453J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-93800403
Alternative Phone No	OFFICE-93800403

Vehicle Particulars

Manufacturer	MAZDA
Model	ROADSTER-2.0 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA422356
Cover Note Number	

Driver

Name of Driver	LIM JIN YU MICHELLE
NRIC No	S8717453J
Date Of Birth	12/06/1987
Occupation	INDOOR
Date Of Driving Pass	20/09/2012
Driving Experience	6 YEARS AND 5 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-93800403
Fax Number	
Contact Number	OFFICE-93800403
Email Address	NOEMAIL

Address	4 LIM TUA TOW ROAD
Postcode	547714
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	1
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLG2552G
Vehicle Make/Model/Colour	AUDI
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LEE GEK PINK
NRIC/Passport Number	S7536948D
Contact Number	91891124
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SJG6101Y
-----------------------------	----------

Vehicle Make/Model/Colour	VIOS
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TIAH LEE LEE
NRIC/Passport Number	S0166397F
Contact Number	90681068
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time: 06/05/19

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name: Sandra
NRIC/FIN No. 6/3

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I SAW THE TRAFFIC LIGHT TURN GREEN AND FRONT VEHICLES ALSO MOVED. THEN I HEARD A BANG AND I SAW VEHICLE B INFRONT STOPPED. I BRAKED AS WELL BUT COULD NOT STOP IN TIME AND HIT VEHICLE B.

WHEN I ALIGHTED I REALISED IT'S A 3-CAR COLLISION.

MY SEAT BELT ON BOTH FRONT SEATS ALSO "ACTIVATED" VERY TIGHT AFTER ACCIDENT. MY PASSENGER CONSOLE IS SCRATCHED BY THE AIRBAG.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 6/03/19

Company Chop (if applicable)

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.



K. Kim Hin Auto Pte Ltd
160 Sin Ming Drive, #02-20, Sin
Ming AutoCity
575722

Claim Reference:
Assessment number: 190110
Version: 1810
Date calculated: 03/08/2019 05:23 PM

Full Report
Registration: SKU3097K
Printed: 08/03/2019 5:23 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	AXA Insurance Pte Ltd
Printed by:	SANDRA KHONG	Currency:	SGD
Claim Reference:		Date of Incident:	
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	MAZDA
Model:	MX-5 (NC)
Sub Model:	ROADSTER COUPE
Model Sheet Number:	36 42 35
Registration:	SKU3097K
VIN number:	
Odometer:	

Model Specs

FROM 02/2007	HARDTOP	HARDTOP	AUTO AIR CON
KEYLESS GO SYSTEM	ELECT BONNET	XENON HEADLAMPS	FOG LAMPS
DARKENED HEADLAMPS	THIRD BRAKE LIGHT	R/FOG LAMP	RAD GRILLE MESH TYPE
TRIM PARTS POLISHED	FRONT SPOILER	WINDSCREEN TRIM	2.0 LTR 118/125KW
AUTO GEARBOX 6 SPEED	CRUISE CONTROL	TYRES 205/45 WR 17	ST-STEEL RAD GRILLE
MUDFLAP	SIDE SKIRT	TWO COAT METALLIC	PREPARE OFF VEHICLE

FR
187

Authorised

Repair by point

9 days

Cx 8900h

L&K Auto Consultants hereby certify
the Repairs of the Insured:
• To comply with the relevant insurance policy
• To comply with the relevant insurance policy
• Parts provided are subject to inspection
• Third party survey is on a "Without Prejudice" basis
• No legal modification is allowed
• Supplementary services must be confirmed and
is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

K.Kim Hin Auto Pte Ltd
160 Sin Ming Drive, #02-20, Sin
Ming AutoCity
575722

Claim Reference:
Assessment number: 190110
Version: 1810
Date calculated: 03/08/2019 05:23 PM

Full Report
Registration: SKU3097K
Printed: 08/03/2019 5:23 PM


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
Date of Inspection: 2019-02-20

Damage Areas

All ☐
Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 45.00 SGD/h	
			WU	Price SGD
E0201H-R-X)	R + R RADIATOR INCLUDES: R + R FAN, FAN SHROUD AND LOWER COVER		12.0	54.00
S0201F-R-ZAX	RENEW FRONT BUMPER INCLUDES: R + R BUMPER AND NECESSARY ATTACHED PARTS		16.0	72.00
S0201B-R-X)	R + R FRONT BUMPER REINFORCEMENT (BUMPER REMOVED)		5.0	22.50
NO NUMBER	RENEW FRONT LOCK CARRIER		18.0	81.00
S0601A-R-X)	RENEW BOTH FRONT WINGS (FRONT BUMPER REMOVED) INCLUDES: BOTH FRONT WINGS, BOTH HEADLAMP, FRT SIDE INDICATORS, REQUIRED ATTACHED PARTS R + R AND ADJUST HEADLAMPS		9.0	40.50
S0503X-R-X	RENEW BONNET		5.0	22.50

K.Kim Hin Auto Pte Ltd
160 Sin Ming Drive, #02-20, Sin
Ming AutoCity
575722

Claim Reference:

Assessment number: 190110

Version: 1810

Date calculated: 03/08/2019 05:23 PM

Full Report

Registration: SKU3097K

Printed: 08/03/2019 5:23 PM

Code	Description	WU	Price SGD
	INCLUDES: R + R BONNET AND REQUIRED ATTACHED PARTS ASSEMBLE		
NO NUMBER	R + R BONNET STAY	1.0	4.50
S0509A-R-X	R + R BONNET CABLE	4.0	18.00
S0508X-R-X	R + R BONNET LOCK	3.0	13.50
S0504F-R-X)	RENEW BONNET HINGES	2.0	9.00
S1401A-R-X	R + R FRONT SCREEN	36.0	162.00
	INCLUDES: R + R WIPER ARMS, COWL GRILLE AND INTERIOR MIRROR		
NO NUMBER	R + R INSTRUMENT PANEL	18.0	81.00
NO NUMBER	R + R INSTRUMENT PANEL TRIM	2.0	9.00
S0802X-R-X	R + R CENTRE CONSOLE	3.0	13.50
S2206X-R-X)	R + R AIRBAG CONTROL UNIT	3.0	13.50
S2202F-R-X)	R + R FRONT IMPACT SENSOR	2.0	9.00
S0919X-R-X)	R + R L/SEAT BELT	3.0	13.50
S0919X-R-X)	R + R R/SEAT BELT	3.0	13.50
S1706X-R-X	R + R L/R SIDE PANEL TRIM	2.0	9.00
S1706X-R-X	R + R R/R SIDE PANEL TRIM	2.0	9.00
NO NUMBER	R + R REAR PANEL TRIM	2.0	9.00
T0108X-R-X	R + R CENTRAL ELECTRIC	5.0	22.50
G0501X-R-X	R + R BATTERY	2.0	9.00
NO NUMBER	R + R ENGINE PROTECTION PANEL	2.0	9.00
E0210X-R-X	R + R OVERFLOW TANK	4.0	18.00
F0105X-R-X	R + R AIR CLEANER	3.0	13.50
U0004X-R-X	DRAIN + REFILL AIR CONDITIONING	7.0	31.50
U0707X-R-X)	R + R CONDENSER	5.0	22.50
N0102X-R-X	R + R STEERING WHEEL	4.0	18.00
NO NUMBER	VENT STEERING SYSTEM	2.0	9.00
Labour Cost		Hrs	WU
Panel / Mechanical Labour		18.50	185.0
Total of Labour			832.50

Paint

Paint Work

Time Basis 10WU/h

Code	Description - TWO COAT METALLIC	WU	Price SGD
1180	FRONT BUMPER NEW PART PAINT K1	12.0	54.00
LE 0340	FRT BUMPER SUPPORT INNER- PAINT STG II	4.0	18.00
1640	BONNET NEW PART PAINT ST 1	22.0	99.00
1410	L/F WING NEW PART PAINT ST 1	10.0	45.00

K. Kim Hin Auto Pte Ltd
160 Sin Ming Drive, #02-20, Sin
Ming AutoCity
575722

Claim Reference:

Assessment number: 190110

Version: 1810

Date calculated: 03/08/2019 05:23 PM

Full Report

Registration: SKU3097K

Printed: 08/03/2019 5:23 PM

Paint Work

Time Basis 10WU/h

Code	Description - TWO COAT METALLIC	WU	Price SGD
1410	R/F WING NEW PART PAINT ST 1	10.0	45.00
L 1009	FRONT PANEL CPL INNER- PAINT STG II	7.0	31.50
2010	LEFT DOOR SURFACE PAINT ST 2	7.0	31.50
2010	RIGHT DOOR SURFACE PAINT ST 2	7.0	31.50
NO NUMBER	PREPARE FOR PAINTING	21.0	94.50
NO NUMBER	ADDITIONAL TIME PAINTING PLASTIC PARTS	5.0	22.50

Total Paint

Hrs 10.50 WU 105.0 Price SGD 472.50

Spare Parts

prices as at 2015-06-01/01
Price SGD

Code	Description	Part Number	Supplier		Price SGD	
0283	FRONT BUMPER	NEY95003XA8N		✓	By 650.00	✓
0336	FR CTR IMPACT ABSORB	NE7550111C		✓	CM 90.00	✓
0340	FRT BUMPER SUPPORT	NE7550070C		✓	By 280.00	✓
0346	FRONT BUMPER GRILLE	NE85V4240A		✓	his 1,400.00	✓
0351	FRT BUMPER CLAMP KIT	USE SINGLE PARTS		✓	me 90.00	✓
0393	L/F BUMPER SPOILER	NE51519H2E		me ✓	by 50.00	X
0394	R/F BUMPER SPOILER	NE51519H1E		me ✓	by 50.00	X
0399	FRT BUMPER CTR COVER	NE51501C0B		me ✓	by 50.00	X
0471	BONNET	NPY15231X		✓	By 1,300.00	✓
0475	L/BONNET HINGE	NE5152420A			30.00	X
0476	R/BONNET HINGE	NE5152410A			30.00	X
0481	BONNET INSULATION	NE5156681A			75.00	X
0485	INSULATION MNTG KIT	TD1156694		✓	me 25.00	✓
0493	BONNET LOCK	N12156620B		✓	By 80.00	✓
0494	BONNET PILOT PIN	F15152372B		X	by 35.00	X
0495	BONNET STAY	NE5156650			60.00	X
0500	BONNET CABLE	N12156720A		X	by 40.00	X
0508	BADGE MAZDA	F15151731A		me	0.00	X
0524	FRONT BONNET SEAL	NE5156750		X	by 30.00	X
0561	L/F HEADLAMP CPL	NH4551041F		myort ✓	430.00	✓
0562	R/F HEADLAMP CPL	NH4551031F		✓	By 430.00	✓
0637	L/F FOG LAMP CPL	GDK551690A			150.00	X
0638	R/F FOG LAMP CPL	GDK551680A		by X	150.00	X
0639	L/FOG LAMP BRACKET	N15650C21B		by X	30.00	X

K.Kim Hin Auto Pte Ltd
160 Sin Ming Drive, #02-20, Sin
Ming AutoCity
575722

Claim Reference:

Assessment number: 190110

Version: 1810

Date calculated: 03/08/2019 05:23 PM

Full Report

Registration: SKU3097K

Printed: 08/03/2019 5:23 PM

Code	Description	Part Number	Supplier	Price SGD	
0640	R/FOG LAMP BRACKET	N15650C11B		30.00	?
0741	L/F WING	N12152210C		370.00	X
0742	R/F WING	N12152110C		370.00	X
0789	L/F WING CLAMP KIT	907200612		22.50	X
0790	R/F WING CLAMP KIT	907200612		22.50	X
0843	L/F WHEELHOUSE COVER	NE5156142C		150.00	?
0844	R/F WHEELHOUSE COVER	NE5156132C		150.00	?
1019	LOCK CARRIER PANEL	NE5153150D		230.00	✓
1183	L/F WING SUPPORT	NE515224YA		60.00	X
1184	R/F WING SUPPORT	NE515214YA		60.00	X
1401	WINDSCREEN	N12163900A9D		1,300.00	✓
1411	WINDSCREEN BOND KIT	KNGKWI2		0.00	
1413	FRT SCREEN MNTG KIT	C23563938		0.00	
4325	PASSENGER AIRBAG	N12157K50A		1,700.00	✓
4332	UPP INSTRUMENT PANEL	N12160400F02	850	700.00	✓
4445	L/INSTR PANEL TRIM	N12155321C00		340.00	X
4465	CONDENSER	NE5161480C		380.00	✓
4661	LEFT SEAT BELT	N12157L90E		900.00	✓
4662	RIGHT SEAT BELT	N12157L30F		900.00	✓
7403	AIRBAG CONTACT RING	N12166CS0B		110.00	✓
7435	CENTRE IMPACT SENSOR	NE5157K1XA		240.00	✓
7440	AIRBAG CONTROL UNIT	N12357K30D		650.00	✓
7445	DRIVER AIRBAG	N12357K00G		1,350.00	✓
7491	COOLING TUBE	NE5132470C		120.00	X
7761	RADIATOR	LFG115200E		330.00	✓
7764	RADIATOR SHROUD CPL	LFG115025F		350.00	X
7787	EXPANSION TANK	LFG115350C		170.00	X
8388	AIR INLET HOSE	LFH913200B		100.00	✓
8391	AIR FILTER ASSY	LFG113320A	480	380.00	✓
8399	LWR AIR FILTER BRKT	LFG1133C1		120.00	X
9632	BATTERY COVER	LFG118593B		65.00	X
9637	BATTERY HOLDER	NE5156041B		60.00	X
9638	BATTERY BOX	LFG118591D		55.00	X
9645	HIGH TONE HORN	N12166780B		70.00	X
9646	LOW TONE HORN	NE5166790B		70.00	X
9662	MODULE BOX HOUSING	NE5166767B		420.00	X
1001	FRT BUMPER LOGO	LOGO		28.00	✓
1002	BONNET STAY HOLDER	HOLDER		20.00	✓
1003	BONNET STAY BUSH	BUSH		15.00	X
1008	BATTERY TRAY DUCT	AIR DUCT		30.00	X

K.Kim Hin Auto Pte Ltd
160 Sin Ming Drive, #02-20, Sin
Ming AutoCity
575722

Claim Reference:

Assessment number: 190110

Version: 1810

Date calculated: 03/08/2019 05:23 PM

Full Report

Registration: SKU3097K

Printed: 08/03/2019 5:23 PM

Code	Description	Part Number	Supplier	Price SGD
1009	F AIRBAG SENSOR CVR COVER		<i>Sen X</i>	60.00 <i>X</i>

f: OEM Parts

n: Non-OEM Parts

u: Used parts

Savings

Subtotal

Addition(+10.00%)

Total

0.00

18,053.00

1,805.30

19,858.30

Extras

Code	Description	Price SGD
1000	FRT NUMBER PLATE	<i>CM</i> 40.00* <i>25in</i>
1004	FRT WS SEALANT	<i>✓</i> <i>neu</i> 40.00* <i>✓</i>
1005	FRT WS DAMPING SEAL	<i>✓</i> <i>neu</i> 20.00* <i>✓</i>
1006	ERP BRACKET	<i>✓</i> <i>neu</i> 26.00* <i>✓</i>
1007	BATTERY	<i>Sen X</i> 200.00* <i>X</i>
1010	RADIATOR COOLANT	<i>✓</i> <i>neu</i> 48.00* <i>25in</i>
1011	AIR CON GAS	<i>✓</i> <i>neu</i> 100.00* <i>✓</i>
1012	PS OIL P/STREEING OIL	<i>✓</i> <i>neu</i> 30.00* <i>✓</i>
Total Extras		504.00

K.Kim Hin Auto Pte Ltd
160 Sin Ming Drive, #02-20, Sin
Ming AutoCity
575722

Claim Reference:
Assessment number: 190110
Version: 1810
Date calculated: 03/08/2019 05:23 PM

Full Report
Registration: SKU3097K
Printed: 08/03/2019 5:23 PM

Final Calculation

	SGD	SGD
Parts	18,053.00	
Addition(+10.00%)	1,805.30	
Total Parts		19,858.30
Labour Time Base 10 WU/h		
Total 185.0 WU X 45.00 SGD/h	832.50	1053
Total of Labour		832.50
Total Of Extras		504.00
Paint Work Time Base 10 WU/h		
Labour Cost 105.0 WU X 45.00 SGD/h	472.50	562.50
Total Paint Including Material		472.50
Repair Cost Excludes GST		21,667.30
GST (+7.0%)		1,516.71
Repair Cost Included GST		23,184.01

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

K.Kim Hin Auto Pte Ltd
160 Sin Ming Drive, #02-20, Sin
Ming AutoCity
575722

Claim Reference:
Assessment number: 190110
Version: 1810
Date calculated: 29/04/2019 12:08 PM

Full Report
Registration: SKU3097K
Printed: 29/04/2019 12:09 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	AXA Insurance Pte Ltd
Printed by:	SANDRA KHONG	Currency:	SGD
Claim Reference:		Date of Incident:	
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	MAZDA
Model:	MX-5 (NC)
Sub Model:	ROADSTER COUPE
Model Sheet Number:	36 42 35
Registration:	SKU3097K
VIN number:	
Odometer:	

Model Specs

FROM 02/2007	HARDTOP	HARDTOP	AUTO AIR CON
KEYLESS GO SYSTEM	ELECT BONNET	XENON HEADLAMPS	FOG LAMPS
DARKENED HEADLAMPS	THIRD BRAKE LIGHT	R/FOG LAMP	RAD GRILLE MESH TYPE
TRIM PARTS POLISHED	FRONT SPOILER	WINDSCREEN TRIM	2.0 LTR 118/125KW
AUTO GEARBOX 6 SPEED	CRUISE CONTROL	TYRES 205/45 WR 17	ST-STEEL RAD GRILLE
MUDFLAP	SIDE SKIRT	TWO COAT METALLIC	PREPARE OFF VEHICLE

K.Kim Hin Auto Pte Ltd
160 Sin Ming Drive, #02-20, Sin
Ming AutoCity
575722

Claim Reference:
 Assessment number: 190110
 Version: 1810
 Date calculated: 29/04/2019 12:08 PM

Full Report
 Registration: SKU3097K
 Printed: 29/04/2019 12:09 PM


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
 Date of Inspection: 20/02/19

Damage Areas

All ☐
 Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 45.00 SGD/h	
			WU	Price SGD
E0201H-R-X)	R + R RADIATOR INCLUDES: R + R FAN, FAN SHROUD AND LOWER COVER		12.0	54.00
S0201F-R-ZAX	RENEW FRONT BUMPER INCLUDES: R + R BUMPER AND NECESSARY ATTACHED PARTS		16.0	72.00
S0201B-R-X)	R + R FRONT BUMPER REINFORCEMENT (BUMPER REMOVED)		5.0	22.50
NO NUMBER	RENEW FRONT LOCK CARRIER		18.0	81.00
T0301A-R-X)	R + R LEFT HEADLAMP		1.0	4.50
T0301A-R-X)	R + R RIGHT HEADLAMP		1.0	4.50
NO NUMBER	ADJUST HEADLAMPS		2.0	9.00
S0503X-R-X	RENEW BONNET INCLUDES: R + R BONNET AND REQUIRED ATTACHED PARTS ASSEMBLE		5.0	22.50
NO NUMBER	R + R BONNET STAY		1.0	4.50

K.Kim Hin Auto Pte Ltd
160 Sin Ming Drive, #02-20, Sin
Ming AutoCity
575722

Claim Reference:

Assessment number: 190110

Version: 1810

Date calculated: 29/04/2019 12:08 PM

Full Report

Registration: SKU3097K

Printed: 29/04/2019 12:09 PM

Code	Description	WU	Price SGD
S0509A-R-X	R + R BONNET CABLE	4.0	18.00
S0508X-R-X	R + R BONNET LOCK	3.0	13.50
S1401A-R-X	R + R FRONT SCREEN INCLUDES: R + R WIPER ARMS, COWL GRILLE AND INTERIOR MIRROR	36.0	162.00
NO NUMBER	R + R INSTRUMENT PANEL	18.0	81.00
S0802X-R-X	R + R CENTRE CONSOLE	3.0	13.50
S2206X-R-X)	R + R AIRBAG CONTROL UNIT	3.0	13.50
S2202F-R-X)	R + R FRONT IMPACT SENSOR	2.0	9.00
S0919X-R-X)	R + R L/SEAT BELT	3.0	13.50
S0919X-R-X)	R + R R/SEAT BELT	3.0	13.50
S1706X-R-X	R + R L/R SIDE PANEL TRIM	2.0	9.00
S1706X-R-X	R + R R/R SIDE PANEL TRIM	2.0	9.00
NO NUMBER	R + R REAR PANEL TRIM	2.0	9.00
T0108X-R-X	R + R CENTRAL ELECTRIC	5.0	22.50
G0501X-R-X	R + R BATTERY	2.0	9.00
NO NUMBER	R + R ENGINE PROTECTION PANEL	2.0	9.00
E0210X-R-X	R + R OVERFLOW TANK	4.0	18.00
F0105X-R-X	R + R AIR CLEANER	3.0	13.50
U0004X-R-X	DRAIN + REFILL AIR CONDITIONING	7.0	31.50
U0707X-R-X)	R + R CONDENSER	5.0	22.50
N0102X-R-X	R + R STEERING WHEEL	4.0	18.00
0475	L/BONNET HINGE REPAIR	5.0*	22.50
0476	R/BONNET HINGE REPAIR	5.0*	22.50
0741	L/F WING REPAIR	20.0*	90.00
0742	R/F WING REPAIR	20.0*	90.00
1183	L/F WING SUPPORT REPAIR	5.0*	22.50
1184	R/F WING SUPPORT REPAIR	5.0*	22.50
Labour Cost		Hrs	WU
Panel / Mechanical Labour		23.40	234.0
Total of Labour			1,053.00

Paint

Paint Work		Time Basis 10WU/h	
Code	Description - TWO COAT METALLIC	WU	Price SGD
1180	FRONT BUMPER NEW PART PAINT K1	12.0	54.00
LE 0340	FRT BUMPER SUPPORT INNER- PAINT STG II	4.0	18.00
1640	BONNET NEW PART PAINT ST 1	22.0	99.00
1410	L/F WING REPAIR PAINT ST IV	16.0	72.00

K.Kim Hin Auto Pte Ltd
160 Sin Ming Drive, #02-20, Sin
Ming AutoCity
575722

Claim Reference:

Assessment number: 190110

Version: 1810

Date calculated: 29/04/2019 12:08 PM

Full Report

Registration: SKU3097K

Printed: 29/04/2019 12:09 PM

Paint Work

Time Basis 10WU/h

Code	Description - TWO COAT METALLIC	WU	Price SGD
1410	R/F WING REPAIR PAINT ST IV	16.0	72.00
L 1009	FRONT PANEL CPL INNER- PAINT STG II	7.0	31.50
L 1183	L/F WING SUPPORT INNER- PAINT STG II	4.0	18.00
L 1184	R/F WING SUPPORT INNER- PAINT STG II	4.0	18.00
2010	LEFT DOOR SURFACE PAINT ST 2	7.0	31.50
2010	RIGHT DOOR SURFACE PAINT ST 2	7.0	31.50
NO NUMBER	PREPARE FOR PAINTING	21.0	94.50
NO NUMBER	ADDITIONAL TIME PAINTING PLASTIC PARTS	5.0	22.50

Total Paint

Hrs 12.50 WU 125.0 Price SGD 562.50

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-06-01/01	Price SGD
0283	FRONT BUMPER	NEY95003XA8N			650.00
0336	FR CTR IMPACT ABSORB	NE7550111C			90.00
0340	FRT BUMPER SUPPORT	NE7550070C			280.00
0346	FRONT BUMPER GRILLE	NE85V4240A			1,400.00
0351	FRT BUMPER CLAMP KIT	USE SINGLE PARTS			90.00
0393	L/F BUMPER SPOILER	NE51519H2E			50.00
0394	R/F BUMPER SPOILER	NE51519H1E			50.00
0399	FRT BUMPER CTR COVER	NE51501C0B			50.00
0471	BONNET	NPY15231X			1,300.00
0485	INSULATION MNTG KIT	TD1156694			25.00
0493	BONNET LOCK	N12156620B			80.00
0508	BADGE MAZDA	F15151731A			0.00
0561	L/F HEADLAMP CPL	NH4551041F			430.00
0562	R/F HEADLAMP CPL	NH4551031F			430.00
1019	LOCK CARRIER PANEL	NE5153150D			230.00
1401	WINDSCREEN	N12163900A9D			1,300.00
1411	WINDSCREEN BOND KIT	KNGKW12			0.00
1413	FRT SCREEN MNTG KIT	C23563938			0.00
4325	PASSENGER AIRBAG	N12157K50A			1,700.00
4332	UPP INSTRUMENT PANEL	N12160400F02			850.00
4465	CONDENSER	NE5161480C			380.00
4661	LEFT SEAT BELT	N12157L90E			900.00

K.Kim Hin Auto Pte Ltd
160 Sin Ming Drive, #02-20, Sin
Ming AutoCity
575722

Claim Reference:

Assessment number: 190110

Version: 1810

Date calculated: 29/04/2019 12:08 PM

Full Report

Registration: SKU3097K

Printed: 29/04/2019 12:09 PM

Code	Description	Part Number	Supplier	Price SGD
4662	RIGHT SEAT BELT	N12157L30F		900.00
7403	AIRBAG CONTACT RING	N12166CS0B		110.00
7435	CENTRE IMPACT	NE5157K1XA		240.00
	SENSOR			
7440	AIRBAG CONTROL UNIT	N12357K30D		650.00
7445	DRIVER AIRBAG	N12357K00G		1,350.00
7761	RADIATOR	LFG115200E		330.00
8388	AIR INLET HOSE	LFH913200B		100.00
8391	AIR FILTER ASSY	LFG113320A		480.00
1001	FRT BUMPER LOGO	LOGO		28.00

f: OEM Parts

n: Non-OEM Parts

u: Used parts

Savings

Subtotal

Addition(+10.00%)

Total

0.00

14,473.00

1,447.30

15,920.30

Extras

Code	Description	Price SGD
1000	FRT NUMBER PLATE	25.00*
1004	FRT WS SEALANT	40.00*
1005	FRT WS DAMPING SEAL	20.00*
1006	ERP BRACKET	26.00*
1010	RADIATOR COOLANT	25.00*
1011	AIR CON GAS	100.00*
1012	PS OIL P/STREEING OIL	30.00*
	Total Extras	266.00

K.Kim Hin Auto Pte Ltd
160 Sin Ming Drive, #02-20, Sin
Ming AutoCity
575722

Claim Reference:
Assessment number: 190110
Version: 1810
Date calculated: 29/04/2019 12:08 PM

Full Report
Registration: SKU3097K
Printed: 29/04/2019 12:09 PM

Final Calculation

	SGD	SGD
Parts	14,473.00	
Addition(+10.00%)	1,447.30	
Total Parts		15,920.30
Labour Time Base 10 WU/h		
Total 234.0 WU X 45.00 SGD/h	1,053.00	
Total of Labour		1,053.00
Total Of Extras		266.00
Paint Work Time Base 10 WU/h		
Labour Cost 125.0 WU X 45.00 SGD/h	562.50	
Total Paint Including Material		562.50
Repair Cost Excludes GST		17,801.80
GST (+7.0%)		1,246.13
Repair Cost Included GST		19,047.93

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaenuto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M



Dept Direct: 9417 9794

Dept Direct: 9417 9795

Dept Direct: 9417 9796

Dept Direct: 9417 9797

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

K KIM HIN AUTO PTE LTD
160 SIN MING DRIVE #02-18/19/20/21
SIN MING AUTOCITY

SINGAPORE 575722
TEL : 64527018 MENG FAX : 64583895
ATTN : MENG HUAK

TAX INVOICE : AR201903-06613
DATE : 13/03/2019
CUSTOMER ID : KKI001
VEH REG. NO. : SKU3097K
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR : SGD

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1	N1Y3-50-03XABB MX5 NC 05-08	F.BUMPER W/CAP	PA PL4-H1-05	1	650.00	650.00
2	TK21-50-355 MZ3 BM/ CX3	RIVET,RAD.GRILLE 4	PA PL3-K1-03SX	20	4.50	90.00
3	NE51-50-1C0B MX5 05--	RETAINER,F BUMP (CTR)	PA PL3-J1-10F	1	50.00	50.00
4	TD11-56-694 DE BL GL TC	CLIP.BONNET INSULATOR (9/11 PCS)	PA PL3-K1-03SY	10	2.50	25.00
5	NE51-53-100F MX5 05--	F SUPPORT	PA PL3-B1-08B	1	230.00	230.00

SUB-TOTAL : 1,045.00
ADD GST 7.00 % 73.15

E. & O.E

TOTAL AMOUNT SGD : 1,118.15

[P] 13/03/2019 4:42:50PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[E] 13/03/2019 4:35:22PM

JAE Auto Pte. Ltd.

Sales Executive: KOW

This is computer generated document.
No signature is required.



ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WARRANTY CLAIMS
Call: 0417 0701 / 0749 9839



Dept. Direct: 0417 0701

Dept. Direct: 0417 0702

Dept. Direct: 0417 0703

Dept. Direct: 0417 0704

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

K KIM HIN AUTO PTE LTD
160 SIN MING DRIVE #02-18/19/20/21
SIN MING AUTOCITY

SINGAPORE 575722
TEL : 64527018 MENG FAX : 64583895
ATTN : MENG HUAK

TAX INVOICE : AR201903-06618
DATE : 13/03/2019
CUSTOMER ID : KKI001
VEH REG. NO. : SKU3097K
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 3
CURR. : SGD

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1	NE51-50-1A1B MX5 05--	RETAINER.F BUMP RH	U1 MZ-A26-E	1	50.00	50.00
2	NE51-50-1B1B MX5 05--	RETAINER.F BUMP LH	U1 MZ-A26-E	1	50.00	50.00
3	F151-51-731A RX8/MX5 05--	MASCOT.F BUMPER	U1 U1L2-SD4-T3	1	28.00	28.00
4	N156-50-1T0C MX5 07--	GRILLE.F BUMPER(W/CHROME)	U1	1	1400.00	1,400.00
		SUPPLIER				
5	NEY1-52-31XA/NPY1 MX5 NC 05--	F.BONNET	U1 SUPPLIER	1	1300.00	1,300.00
6	N121-56-620A MX5 05--	LOCK.BONNET	U1 SUPPLIER	1	80.00	80.00
7	NF28-51-0K0C MX5 07-PI	F.H LAMP RH (BEZEL)	U1 U1L1-C1-03A	1	430.00	430.00

CONTINUE NEXT PAGE

[P] 14/03/2019 11:15:05AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

ORIGINAL

[E] 13/03/2019 4:43:06PM



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450618 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

HONDA
Dept Direct: 6413 9291 / 6748 9299



Dept Direct: 6395 9610

Dept Direct: 6305 9611

Dept Direct: 6417 9792



Dept Direct: 6417 9791

Dept Direct: 6417 9795

Dept Direct: 6417 9798

Dept Direct: 6417 9799

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

K KIM HIN AUTO PTE LTD
160 SIN MING DRIVE #02-18/19/20/21
SIN MING AUTOCITY

SINGAPORE 575722
TEL : 64527018 MENG FAX : 64583895
ATTN : MENG HUAK

TAX INVOICE : AR201903-06618
DATE : 13/03/2019
CUSTOMER ID : KKI001
VEH REG. NO. : SKU3097K
TERMS : 30 days
PO NO. :
PAGE NO. : Page 2 of 3
CURR. : SGD

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
8	LF9L-13-220 MX5 05-	✓ AIR HOSE	U1 UIL2-B1-01C-A	1	100.00	100.00
9	N121-60-400F02 MX5 05-09	✓ DASHBOARD (BLACK)	U1 SUPPLIER	1	850.00	850.00
10	N121-57-K50A MX5 05-10	✓ AIR/BAG.F PASSENGER	U1 SUPPLIER	1	1700.00	1,700.00
11	N123-57-K00G MX5 05-08	✓ AIR/BAG.STEERING (URETHANE)	U1 SUPPLIER	1	1350.00	1,350.00
12	N121-66-CS0A MX5,CX7 06--/RX8 08--	✓ CLOCK SPRING.STG A/BAG	U1 UIL2-B1-01B-D	1	110.00	110.00
13	N121-57-L30E MX5 05-09	✓ BELT.F SEAT RH	U1 SUPPLIER	1	900.00	900.00
14	N121-57-L90D MX5 05-09	✓ BELT.F SEAT LH	U1 SUPPLIER	1	900.00	900.00

CONTINUE NEXT PAGE

[P] 14/03/2019 11:15:05AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

ORIGINAL

[E] 13/03/2019 4:43:06PM



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M



Wiper blade: NWB (Nippon Wiper blade), Silper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

K KIM HIN AUTO PTE LTD
160 SIN MING DRIVE #02-18/19/20/21
SIN MING AUTOCITY

SINGAPORE 575722
TEL : 64527018 MENG FAX : 64583895
ATTN : MENG HUAK

TAX INVOICE : AR201903-06618
DATE : 13/03/2019
CUSTOMER ID : KKI001
VEH REG. NO. : SKU3097K
TERMS : 30 days
PO NO. :
PAGE NO. : Page 3 of 3
CURR. : SGD

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
15 NE51-61-480C GSP MX5 05-	✓ CONDENSER (CD060422)	U1 MZ-A99	1	380.00	380.00
16 LFG1-15-200E MX5 05--AT	✓ RADIATOR	U1 MZ-A114	1	330.00	330.00

SUB-TOTAL : 9,958.00
ADD GST 7.00 % 697.06

E. & O.E TOTAL AMOUNT SGD : 10,655.06

[P] 14/03/2019 11:15:05AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[E] 13/03/2019 4:43:06PM

JAE Auto Pte. Ltd.

Sales Executive : KOW



This is computer generated document.
No signature is required.

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司 JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSHIELD GLASS
Dept Direct: 6417 9791 / 6746 9929



Dept Direct: 6302 9610

Dept Direct: 6302 9611

Dept Direct: 6417 9792

TOYOTA

LEXUS

GAZDAI



Dept Direct: 6417 9791

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9798

Wiper blade: NWB (Nippon Wiper blade), Silper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

K KIM HIN AUTO PTE LTD
160 SIN MING DRIVE #02-18/19/20/21
SIN MING AUTOCITY

SINGAPORE 575722
TEL: 64527018 MENG FAX: 64583895
ATTN: MENG HUAK

TAX INVOICE : AR201903-06952
DATE : 14/03/2019
CUSTOMER ID : KKI001
VEH REG. NO. : SKU3097K
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR. : SGD

18

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1. NF28-31-0LOC MX507-PI	F.H LAMP LH (BRIGHT)	U1 SUPPLIER	1	430.00	430.00

SUB-TOTAL : 430.00
ADD GST 7.00 % 30.10

E. & O.E

TOTAL AMOUNT SGD : 460.10

[P] 14/03/2019 11:54:28AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[E] 14/03/2019 11:53:29AM

JAE Auto Pte. Ltd.

Sales Executive : KOW



* AR201903-06952 *

This is computer generated document.
No signature is required.

Goods Received in Good Order

Signature / Co Stamp / Date

ORIGINAL



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDMILLER OIL
Dept Direct: 6417 9791 / 6745 9930



Dept Direct: 6365 9610

Dept Direct: 6365 9611

Dept Direct: 6417 9790



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9793

Wiper blade: NWB (Nippon Wiper blade), Silliper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

K KIM HIN AUTO PTE LTD
160 SIN MING DRIVE #02-18/19/20/21
SIN MING AUTOCITY

SINGAPORE 575722
TEL : 64527018 MENG FAX : 64583895
ATTN : MENG HUAK

TAX INVOICE : AR201903-11565
DATE : 16/03/2019
CUSTOMER ID : KKI001
VEH REG. NO. : SKU3097K
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR. : SGD

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1.	NE55-50-111B MX5 05--07	FOAM.F BUMPER	WH UIL1-D3-03A	1	90.00	90.00
2.	NE51-50-070C MX5 NC 05--10	F REINFORCEMENT	WH UIL1-FRT-C	1	280.00	280.00
3.	N121-63-900A MX5 05-- IMPT	F W/SCREEN	WH SUPPLIER	1	1300.00	1,300.00
4.	N123-57-K30C MX5 05--10	SAS UNIT.W/O SIDE A/BAG	WH SUPPLIER	1	650.00	650.00
5.	NE51-57-K1X MX5 05--10	SENSOR.AIR/BAG	WH UIL2-SD4-M13	1	240.00	240.00

SUB-TOTAL : 2,560.00
ADD GST 7.00 % 179.20

E. & O.E

TOTAL AMOUNT SGD : 2,739.20

[P] 16/03/2019 10:22:07AM

[E] 16/03/2019 10:15:25AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : KOW

This is computer generated document.
No signature is required.



AR201903-11565

Goods Received in Good Order

Signature / Co Stamp / Date

ORIGINAL



日美汽車私人有限公司 JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9781 / 6743 9638



Dept Direct: 6417 9781

Dept Direct: 6417 9781

Dept Direct: 6417 9781

Dept Direct: 6417 9781

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

K KIM HIN AUTO PTE LTD
160 SIN MING DRIVE #02-18/19/20/21
SIN MING AUTOCITY

SINGAPORE 575722
TEL : 64527018 MENG FAX : 64583895
ATTN : MENG HUAK

TAX INVOICE : AR201904-02477
DATE : 04/04/2019
CUSTOMER ID : KKI001
VEH REG. NO. : SKU3097K
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR. : SGD

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1. LFG1-13-220A MX5/5----	AIRCLEANER	U1 SUPPLIER	1	480.00	480.00

CM
OR

SUB-TOTAL : 480.00
ADD GST 7.00 % 33.60

E & O E TOTAL AMOUNT SGD : 513.60

[P] 04/04/2019 12:02:49PM
Goods Sold are not refundable for Cash.
Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[E] 04/04/2019 12:02:21PM

JAE Auto Pte. Ltd.

Sales Executive : KOW

This is computer generated document.
No signature is required.



* AR201904-02477 *

Goods Received in Good Order

Signature / Co Stamp / Date

ORIGINAL

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Finalised

Claim Reference:
Assessment number: 190110
Version: 1810
Date calculated: 30/04/2019 2:47 PM

Full Report
Registration: SKU3097K
Printed: 30/04/2019 2:47 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	AXA Insurance Pte Ltd
Printed by:	KK LAU	Currency:	SGD
Claim Reference:		Date of Incident:	
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	MAZDA
Model:	MX-5 (NC)
Sub Model:	ROADSTER COUPE
Model Sheet Number:	36 42 35
Registration:	SKU3097K

VIN number:

Odometer:

Model Specs

FROM 02/2007	HARDTOP	HARDTOP	AUTO AIR CON
KEYLESS GO SYSTEM	ELECT BONNET	XENON HEADLAMPS	FOG LAMPS
DARKENED HEADLAMPS	THIRD BRAKE LIGHT	R/FOG LAMP	RAD GRILLE MESH TYPE
TRIM PARTS POLISHED	FRONT SPOILER	WINDSCREEN TRIM	2.0 LTR 118/125KW
AUTO GEARBOX 6 SPEED	CRUISE CONTROL	TYRES 205/45 WR 17	ST-STEEL RAD GRILLE
MUDFLAP	SIDE SKIRT	TWO COAT METALLIC	PREPARE OFF VEHICLE

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference:
Assessment number: 190110
Version: 1810
Date calculated: 30/04/2019 2:47 PM

Full Report
Registration: SKU3097K
Printed: 30/04/2019 2:47 PM


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
Date of Inspection: 20/02/19

Damage Areas

All ☐
Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 45.00 SGD/h	
			WU	Price SGD
E0201H-R-X)	R + R RADIATOR INCLUDES: R + R FAN, FAN SHROUD AND LOWER COVER		12.0	54.00
S0201F-R-ZAX	RENEW FRONT BUMPER INCLUDES: R + R BUMPER AND NECESSARY ATTACHED PARTS		16.0	72.00
S0201B-R-X)	R + R FRONT BUMPER REINFORCEMENT (BUMPER REMOVED)		5.0	22.50
NO NUMBER	RENEW FRONT LOCK CARRIER		18.0	81.00
T0301A-R-X)	R + R LEFT HEADLAMP		1.0	4.50
T0301A-R-X)	R + R RIGHT HEADLAMP		1.0	4.50
NO NUMBER	ADJUST HEADLAMPS		2.0	9.00
S0503X-R-X	RENEW BONNET INCLUDES: R + R BONNET AND REQUIRED ATTACHED PARTS ASSEMBLE		5.0	22.50
NO NUMBER	R + R BONNET STAY		1.0	4.50

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference:
Assessment number: 190110
Version: 1810
Date calculated: 30/04/2019 2:47 PM

Full Report
Registration: SKU3097K
Printed: 30/04/2019 2:47 PM

Code	Description	WU	Price SGD
S0509A-R-X	R + R BONNET CABLE	4.0	18.00
S0508X-R-X	R + R BONNET LOCK	3.0	13.50
S1401A-R-X	R + R FRONT SCREEN INCLUDES: R + R WIPER ARMS, COWL GRILLE AND INTERIOR MIRROR	36.0	162.00
NO NUMBER	R + R INSTRUMENT PANEL	18.0	81.00
S0802X-R-X	R + R CENTRE CONSOLE	3.0	13.50
S2206X-R-X)	R + R AIRBAG CONTROL UNIT	3.0	13.50
S2202F-R-X)	R + R FRONT IMPACT SENSOR	2.0	9.00
S0919X-R-X)	R + R L/SEAT BELT	3.0	13.50
S0919X-R-X)	R + R R/SEAT BELT	3.0	13.50
S1706X-R-X	R + R L/R SIDE PANEL TRIM	2.0	9.00
S1706X-R-X	R + R R/R SIDE PANEL TRIM	2.0	9.00
NO NUMBER	R + R REAR PANEL TRIM	2.0	9.00
T0108X-R-X	R + R CENTRAL ELECTRIC	5.0	22.50
G0501X-R-X	R + R BATTERY	2.0	9.00
NO NUMBER	R + R ENGINE PROTECTION PANEL	2.0	9.00
E0210X-R-X	R + R OVERFLOW TANK	4.0	18.00
F0105X-R-X	R + R AIR CLEANER	3.0	13.50
U0004X-R-X	DRAIN + REFILL AIR CONDITIONING	7.0	31.50
U0707X-R-X)	R + R CONDENSER	5.0	22.50
N0102X-R-X	R + R STEERING WHEEL	4.0	18.00
0475	L/BONNET HINGE REPAIR	5.0*	22.50
0476	R/BONNET HINGE REPAIR	5.0*	22.50
0741	L/F WING REPAIR	20.0*	90.00
0742	R/F WING REPAIR	20.0*	90.00
1183	L/F WING SUPPORT REPAIR	5.0*	22.50
1184	R/F WING SUPPORT REPAIR	5.0*	22.50
Labour Cost		Hrs	WU
Panel / Mechanical Labour		23.40	234.0
Total of Labour			1,053.00

Paint

Paint Work		Time Basis 10WU/h	
Code	Description - TWO COAT METALLIC	WU	Price SGD
1180	FRONT BUMPER NEW PART PAINT K1	12.0	54.00
LE 0340	FRT BUMPER SUPPORT INNER- PAINT STG II	4.0	18.00
1640	BONNET NEW PART PAINT ST 1	22.0	99.00
1410	L/F WING REPAIR PAINT ST IV	16.0	72.00

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference:
 Assessment number: 190110
 Version: 1810
 Date calculated: 30/04/2019 2:47 PM

Full Report
 Registration: SKU3097K
 Printed: 30/04/2019 2:47 PM

Paint Work

Time Basis 10WU/h

Code	Description - TWO COAT METALLIC	WU	Price SGD
1410	R/F WING REPAIR PAINT ST IV	16.0	72.00
L 1009	FRONT PANEL CPL INNER- PAINT STG II	7.0	31.50
L 1183	L/F WING SUPPORT INNER- PAINT STG II	4.0	18.00
L 1184	R/F WING SUPPORT INNER- PAINT STG II	4.0	18.00
2010	LEFT DOOR SURFACE PAINT ST 2	7.0	31.50
2010	RIGHT DOOR SURFACE PAINT ST 2	7.0	31.50
NO NUMBER	PREPARE FOR PAINTING	21.0	94.50
NO NUMBER	ADDITIONAL TIME PAINTING PLASTIC PARTS	5.0	22.50

	Total Paint	Hrs	WU	Price SGD
		12.50	125.0	562.50

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-06-01/01	Price SGD
0283	FRONT BUMPER	NEY95003XA8N			650.00
0336	FR CTR IMPACT ABSORB	NE7550111C			90.00
0340	FRT BUMPER SUPPORT	NE7550070C			280.00
0346	FRONT BUMPER GRILLE	NE85V4240A			1,400.00
0351	FRT BUMPER CLAMP KIT	USE SINGLE PARTS			90.00
0393	L/F BUMPER SPOILER	NE51519H2E			50.00
0394	R/F BUMPER SPOILER	NE51519H1E			50.00
0399	FRT BUMPER CTR COVER	NE51501C0B			50.00
0471	BONNET	NPY15231X			1,300.00
0485	INSULATION MNTG KIT	TD1156694			25.00
0493	BONNET LOCK	N12156620B			80.00
0508	BADGE MAZDA	F15151731A			0.00
0561	L/F HEADLAMP CPL	NH4551041F			430.00
0562	R/F HEADLAMP CPL	NH4551031F			430.00
1019	LOCK CARRIER PANEL	NE5153150D			230.00
1401	WINDSCREEN	N12163900A9D			1,300.00
1411	WINDSCREEN BOND KIT	KNGKWI2			0.00
1413	FRT SCREEN MNTG KIT	C23563938			0.00
4325	PASSENGER AIRBAG	N12157K50A			1,700.00
4332	UPP INSTRUMENT PANEL	N12160400F02			850.00
4465	CONDENSER	NE5161480C			380.00
4661	LEFT SEAT BELT	N12157L90E			900.00

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference:
 Assessment number: 190110
 Version: 1810
 Date calculated: 30/04/2019 2:47 PM

Full Report
 Registration: SKU3097K
 Printed: 30/04/2019 2:47 PM

Code	Description	Part Number	Supplier	Price SGD
4662	RIGHT SEAT BELT	N12157L30F		900.00
7403	AIRBAG CONTACT RING	N12166CS0B		110.00
7435	CENTRE IMPACT SENSOR	NE5157K1XA		240.00
7440	AIRBAG CONTROL UNIT	N12357K30D		650.00
7445	DRIVER AIRBAG	N12357K00G		1,350.00
7761	RADIATOR	LFG115200E		330.00
8388	AIR INLET HOSE	LFH913200B		100.00
8391	AIR FILTER ASSY	LFG113320A		480.00
1001	FRT BUMPER LOGO	LOGO		28.00

f: OEM Parts	Savings	0.00
n: Non-OEM Parts	Subtotal	14,473.00
u: Used parts	Addition(+10.00%)	1,447.30
	Total	15,920.30

Extras

Code	Description	Price SGD
1000	FRT NUMBER PLATE	25.00*
1004	FRT WS SEALANT	40.00*
1005	FRT WS DAMPING SEAL	20.00*
1006	ERP BRACKET	26.00*
1010	RADIATOR COOLANT	25.00*
1011	AIR CON GAS	100.00*
1012	PS OIL P/STREEING OIL	30.00*
	Total Extras	266.00

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference:
Assessment number: 190110
Version: 1810
Date calculated: 30/04/2019 2:47 PM

Full Report
Registration: SKU3097K
Printed: 30/04/2019 2:47 PM

Final Calculation

	SGD	SGD
Parts	14,473.00	
Addition(+10.00%)	1,447.30	
Total Parts		15,920.30
Labour Time Base 10 WU/h		
Total 234.0 WU X 45.00 SGD/h	1,053.00	
Total of Labour		1,053.00
Total Of Extras		266.00
Paint Work Time Base 10 WU/h		
Labour Cost 125.0 WU X 45.00 SGD/h	562.50	
Total Paint Including Material		562.50
Repair Cost Excludes GST		17,801.80
GST (+7.0%)		1,246.13
Repair Cost Included GST		19,047.93

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Tuesday, 30 April 2019 3:52 PM
To: survey@kkimhin.com.sg
Cc: Kenneth Kong (LKKAuto); SUR
Subject: RE: SKU3097K OD-AXA QUESTION MARK ITEM

Dear Meng Huat,

Confirmed amount \$17,801.80 before excess \$900 @ 9 working days.

Best Regards,
Veron Chen | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: survey@kkimhin.com.sg <survey@kkimhin.com.sg>
Sent: Monday, 29 April 2019 1:54 PM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Cc: Kenneth Kong (LKKAuto) <KennethKong@lkkauto.com>
Subject: SKU3097K OD-AXA QUESTION MARK ITEM

Hi All,

Enclosed your attention.

Thank you.

Regard
Meng Huat
K.Kim Hin Auto