

ASS. REC. BY:

REF

REF: 08/FCI/9004388/16d302

Special Instruction:

Survey

(WS)

Kenneth

ASSIGNMENT (Office)

From (Person):

Meinarchia

of

FCI

Date/Time:

5.39pm 8/3/19

Estimated Cost:

Bill to:

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

S/L 4804P

Insured:

SHC 0835Y

at Workshop m/s

Massive Trading

Tel:

9108 2728

of

Blk 5038 # 01-405 Amk Ind. Part 2

Policy No:

Claim No:

D19001696MF8H

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

8/3/2019

CA / REV / REP. / REV 24 HRS

1 up

H.O.D. Endorsement

Date/Time: 1:49pm 11/3/19

Person Contacted:

Anthony

Vehicle IN OUT

Date/Time

Action/Instruction	✓	Estimate
--------------------	---	----------

811 1804p-NA/LIP 19004284 / r3

Doat: 8/3/19

Site 0838y - NA / 441700 42871r3

DVA: 8/3/14

ASS. REC. BY:

REF: F021

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Rear

R/Bal.

L/Bal.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

File pass to

GIA & Error rectify

14/3 C/L 844001 email confirm
(Red: 4851.34 150%)

MV: 26000/-

LTA 13,920/-

NV: 12080/-

RECEIVED 15 MAR 2019

Date/Time, File Pass to?

1) 15/3 Typst.

Date/Time, File Return to?

2)



Prell. Report



Final Report

Days Of Repair: 5

Resurvey No. of Trlp:

Add Fee:



Site Insp (\$



Interview (\$



Tech Invs (\$



Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Fixturs

Others

TOTAL

Report Format:

Lump Sum / I.B.I. (\$

TP

4400/-

170
50
50 + 50
28
348

MOTOR SURVEY ASSIGNMENT

Date	08-03-2019	Our Ref No. D19001696MFSH
Accident Date	08-03-2019	Claim Type. Third Party
Insured Vehicle	SHC0835Y	Third Party Vehicle. SJL4804P
Survey Location	Blk 5038 #01-405 Ang mo kio industrial Pk 2	
Contact Person.	ANTHONY	
Contact No.	91082728/ 91082728	Fax No. 0
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	MASSIVE TRADING & AUTO	Attention. NIL
Cc : TP Solicitor	TEO KENG SIANG LLC	TP Solicitor Fax No. 63335676
Officer Incharge	MERINA CHIA SAN SAN	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5011Z
Vehicle Details	
Vehicle No.:	SJL4804P
Vehicle to be Exported:	No
Intended Deregistration Date:	18 Mar 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA AXIO 1.5X A
Primary Colour:	Grey
Manufacturing Year:	2008
Engine No.:	1NZD198772
Chassis No.:	NZE1416097757
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$13,420.00
Original Registration Date:	28 Nov 2008
First Registration Date:	28 Nov 2008
Transfer Count:	3
Actual ARF Paid:	\$8,608.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	27 Nov 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$14,835.00
COE Rebate Amount:	\$13,920.00
Total Rebate Amount:	\$13,920.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 18 Mar 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	08/03/2019 14:27
Date Of Accident	08/03/2019 11:35
Exact Location Of Accident	RAFFLES LINK TWDS RAFFLES BLVD
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SJL4804P
Insured/Policyholder	
Name Of Registered Owner	LOW WENG YEW(LIU YONGYAO)
NRIC No	S7345011Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97972727
Alternative Phone No	OTHERS-97972727
Vehicle Particulars	
Manufacturer	TOYOTA
Model	AXIO
Exact Purpose for which vehicle was being used at time of accident	WORKING
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	SD19V00925/VPL/R00
Cover Note Number	
Driver	
Name of Driver	LOW WENG YEW(LIU YONGYAO)
NRIC No	S7345011Z
Date Of Birth	18/12/1973
Occupation	OUTDOOR
Date Of Driving Pass	30/05/2008
Driving Experience	10 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97972727
Fax Number	
Contact Number	OTHERS-97972727
EEmail Address	NOEMAIL

Address	BLK 19 EUNOS CRESCENT #04-2923
Postcode	400019
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER TO THE ATTACHED STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHC835Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	YIP HAY SANG
NRIC/Passport Number	S1694009G
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. The form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

6. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) 'My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurers who have insured vehicle(s) involved in this accident (all insurers) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"; the insurers' lawyers/law firms; the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be situated outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name
ID No./Pin No.

Individual Statement

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 08/03/2019 @ around 11.55hrs I was travelling along Raffles Link towards Raffles Blvd. I stopped at the slip rd waiting for the main rd traffic to clear. While waiting, I felt an impact from the rear of my vehicle. I got out of my vehicle and realised that a taxi (SHC8354) had collided into my vehicle rear portion.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Officer's Signature
Name:
NRIC/ID No.:

Blk 5038 #01-405 Ang Mo Kio Industrial Pk 2 Singapore 569541
H/p 91082728

Low Weng Yew
Blk 19 Eunos Crescent
#04-2923
Singapore 400019

Vehicle No : SJL 4804 P
Make : Toyota Axio
Year : 2009

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

5 day,

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

QTY	DESCRIPTION	UNIT PRICE	TOTAL PRICE	REMARKS
1 pc	X Rear n/s fender		\$985.60	X
1/2 pcs	Rear fender inner trim		\$770.40	X
1 pc	Rear boot lid		\$775.60	—
1 pc	Rear boot lid emblem "Logo"		\$42.10	—
1 pc	Rear boot lid emblem "Axio"		\$48.30	—
1 pc	Rear boot lid emblem "X"		\$40.70	—
2 pcs	Rear boot lid hinges	\$105.20	\$210.40	X
1 pc	Rear boot lid inner lock		\$265.70	—
1 pc	X Rear boot lid insulator		\$435.75	X
1 pc	Rear boot rubber		\$165.10	32.55JA
1 pc	Rear end panel		\$485.35	—
1 pc	Rear end panel inner garnish		\$205.15	—
2 pcs	Rear tail-lamp assy	\$405.10	\$810.20	—
2 pcs	Rear tail-lamp lower bracket	\$65.10	\$130.20	—
2 pcs	Rear tail-lamp panel	\$205.10	\$410.20	—
1 pc	Rear bumper		\$955.10	—
2 pcs	Rear bumper bracket	\$85.10	\$170.20	X
2 pcs	Rear bumper side retainer	\$65.70	\$131.40	—
1 pc	Rear spare tyre cover board		\$475.15	—
1 pc	Rear exhaust silencer		\$655.85	X
			\$8,168.45	
	Less 25 %		\$2,042.11	
			\$6,126.34	

S. Nett Item

1 set	✓	Rear reverse sensor	family
1 pc	✓	Rear no plate	
20 pcs	✓	Clip	

	Shan	\$200.00	✓
	Sn	\$40.00	✓
\$2.50	na	\$50.00	✓
		<u>\$250.00</u>	

balance c/f	\$6,416.34
-------------	------------

SJL 4804 P

balance b/f \$1.00

Labour Charges

Remove/renew the above parts including knocking, welding & cutting.

\$1,200.00 7001

To putty & spray paint on rear accident affected portion.

\$1,200.00 8001

Check/reconnect wiring.

\$35.00 201

To spray anti rust on accident affected portion.

\$150.00 601

Remove/renew rear exhaust silencer.

\$150.00 601

Remove/refit rear boot upholstery to facilitate repair

\$100.00 801

Total \$9,251.34




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19004388/Ktd3e2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 18-03-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 835Y	Veh. Inspected	SJL 4804P	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19001696MFSH	Excess (\$)	0.00	
Assign From	MERINA CHIA	Assign Date	08/03/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA AXIO (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	NZE1416097757	Colour	METALLIC GREY	
Odometer	138993	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/70 R14	HABILEAD	9 mm	
L/H Front Tyre	185/70 R14	HABILEAD	9 mm	
R/H Rear Tyre	185/70 R14	HABILEAD	9 mm	
L/H Rear Tyre	185/70 R14	HABILEAD	9 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/03/2019	Inspection Date	11/03/2019	
Survey held at	BLK 5038 #01-405 AMK IND PARK 2			
Repairer	MASSIVE TRADING & AUTO			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJL 4804P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR N/S FENDER	TO REPAIR SEE LABOUR	985.60	-
2	REAR FENDER INNER TRIM @\$385.20	N/S DEFORMED	770.40	385.20
1	REAR BOOT LID	BENT	775.60	775.60
1	REAR BOOT LID EMBLEM "LOGO"	NECESSARY	42.10	42.10
1	REAR BOOT LID EMBLEM "AXIO"	NECESSARY	48.30	48.30
1	REAR BOOT LID EMBLEM "X"	NECESSARY	40.70	40.70
2	REAR BOOT LID HINGES @\$105.20	TO REPAIR SEE LABOUR	210.40	-
1	REAR BOOT LID INNER LOCK	DENTED	265.70	265.70
1	REAR BOOT LID INSULATOR	SERVICEABLE	435.75	-
1	REAR END PANEL	BENT	485.35	485.35
1	REAR END PANEL INNER GARNISH	MTG DISTORTED	205.15	205.15
2	REAR TAIL-LAMP ASSY @\$405.10	CRACKED	810.20	810.20
2	REAR TAIL-LAMP LOWER BRACKET @\$65.10	N/S CRACKED	130.20	65.10
2	REAR TAIL-LAMP PANEL @\$205.10	N/S BENT	410.20	205.10
1	REAR BUMPER	BENT	955.10	823.60
2	REAR BUMPER BRACKET @\$85.10	TO REPAIR SEE LABOUR	170.20	-
2	REAR BUMPER SIDE RETAINER @\$65.70	N/S DISTORTED	131.40	65.70
1	REAR SPARE TYRE COVER BOARD	CRACKED	475.15	475.15
1	REAR EXHAUST SILENCER	TO REPAIR SEE LABOUR	655.85	-
	LESS 25% DISCOUNT		-2,000.84	-1,173.24
			6,002.51	3,519.71
<u>SPECIAL NETT ITEMS</u>				
1	REAR BOOT RUBBER (SN)	CUT	123.82	32.55
1	REAR REVERSE SENSOR (SN)	SHORTED	200.00	200.00
1	REAR NO PLATE (SN)	SERVICEABLE	40.00	-
20	CLIP @\$2.50 (SN)	NECESSARY	50.00	50.00
			413.82	282.55

Report Ref No. CS/FCI19004388/Ktd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	REMOVE / RENEW THE ABOVE PARTS INCLUDING KNOCKING, WELDING & CUTTING. INCLUSIVE OF THE REPAIR OF REAR N/S FENDER, REAR BOOT LID HINGES, REAR BUMPER BRACKET AND REAR EXHAUST SILENCER.		1,200.00	700.00
	TO PUTTY & SPRAY PAINT ON REAR ACCIDENT AFFECTED PORTION.		1,200.00	800.00
	CHECK / RECONNECT WIRING.		35.00	20.00
	TO SPRAY ANTI RUST ON ACCIDENT AFFECTED PORTION.		150.00	60.00
	REMOVE / RENEW REAR EXHAUST SILENCER.		150.00	60.00
	REMOVE / REFIT REAR BOOT UPHOLSTERY TO FACILITATE REPAIR.		100.00	80.00
			2,835.00	1,720.00
	GRAND TOTAL		9,251.33	5,522.26
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,400.00

Report Ref No. CS/FCI19004388/Ktd3e2

MARKET VALUE: \$26,000.00(EST)-LTA REIMBURSEMENT VALUE: \$13,920.00=NETT VALUE: \$12,080.00

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.