

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL: 6441 5655 FAX: 6441 5355/6243 8121
R.O.C No: 200104141D GST Reg. No. 20-0104141-D

TO : SXXX8330H

LIM AH HUAT

BLK 479 PASIR RIS DR. 4

03-447

SINGAPORE 510479

TEL: FAX:

PH: 93380558

ATTN:

ESTIMATE BILL

Number : EB00005102

Date : 11/03/2019

Case No : AD00010277

Vehicle No : SKV7862L

Chassis: MNTBBAB17Z0024698

Year of Mfr 2015

Policy No

Model : NISSAN SYLPHY

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	POWER STEERING PIPE	1.0			
2	FRONT CHASSIS BRACKET RH	1.0			
List Price - Parts Sub Total					0.00
3	HEADLAMP PANEL RH ✓ Bent	1.0	196.00	10	176.40
4	HEADLAMP PANEL LH ✓ R	1.0	196.00	10	176.40
5	ENGINE DUST COVER ✓ de/warped	1.0	75.80	10	68.22
6	FRONT BUMPER CENTER LOWER GRILLE ✓	1.0	255.30	10	229.77
7	FRONT BRACE PANEL ✓ Twi	1.0	49.60	10	44.64
8	FRONT TEMPERATURE SWITCH ✓ 11	1.0	59.30	10	53.37
9	FRONT DOOR RH X R	1.0	876.40	10	788.76
10	FRONT FENDER RH ✓ Bent/Buc	1.0	672.10	10	604.89
11	FRONT FENDER INNER SHIELD RH X 11	1.0	101.10	10	90.99
12	FRONT FENDER LH X R	1.0	672.10	10	604.89
13	BONNET ✓ Buc	1.0	847.70	10	762.93
14	BONNET HINGE RH X 11	1.0	41.00	10	36.90
15	BONNET HINGE LH X 11	1.0	41.00	10	36.90
16	BONNET LOCK ✓ Twi	1.0	56.60	10	50.94
17	BONNET RUBBER ✓ R	1.0	49.90	10	44.91
18	BONNET INSULATOR X 11	1.0	150.40	10	135.36
19	BONNET INSULATOR CLIP X 11	10.0	4.40	10	39.60
20	SUPPORT PANEL ASSEMBLY ✓ Bent/Twi 279.30	1.0	1,239.80	10	1,115.82
21	SUPPORT PANEL TOP GARNISH ✓ D.S	1.0	370.40	10	333.36
22	SUPPORT PANEL TOP GARNISH CLIP ✓ R	10.0	4.40	10	39.60
23	FRONT GRILLE WITH CHROME ✓ 548.00	1.0	700.70	10	630.63
24	FRONT GRILLE EMBLEM ✓ R	1.0	57.70	10	51.93
25	HEADLAMP LH? holder one	1.0	473.40	10	426.06
26	HEADLAMP RH ✓ one	1.0	473.40	10	426.06
27	SUPPORT PANEL INNER SIDE GARNISH RH ✓ D.S	1.0	175.50	10	157.95
28	SUPPORT PANEL INNER SIDE GARNISH LH X 11	1.0	175.50	10	157.95
29	FRONT BUMPER ✓ D.S	1.0	476.50	10	428.85
30	FRONT BUMPER RETAINER RH ✓ Bent	1.0	21.10	10	18.99
31	FRONT BUMPER RETAINER LH ✓ Bent	1.0	21.10	10	18.99
32	FRONT BUMPER REINFORCEMENT ✓ Buc	1.0	512.40	10	461.16

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : SXXX8330H

LIM AH HUAT

BLK 479 PASIR RIS DR. 4

03-447

SINGAPORE 510479

TEL : FAX :

PH : 93380558

ATTN :

ESTIMATE BILL

Number : EB00005102

Date : 11/03/2019

Case No : AD00010277

Vehicle No : SKV7862L

Chassis : MNTBBAB17Z0024698

Year of Mfr 2015

Policy No

Model : NISSAN SYLPHY

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
33	FRONT BUMPER SPONGE ✓ <i>70-1</i>	1.0	206.30	10	185.67
34	FRONT BUMPER LOWER GARNISH ✗ <i>11</i>	1.0	255.30	10	229.77 X
35	FRONT BUMPER NUMBER GARNISH ✓ <i>70-1</i>	1.0	255.30	10	229.77
36	FRONT AIR RESOLATOR LH ✗ <i>11</i>	1.0	246.00	10	221.40 X
Nett Price - Parts Sub Total					6454.17
37	AIR CON SUCTION HOSE ✗ <i>11</i>	1.0	314.20	0	314.20 X
38	AIR CON DISCHARGE PIPE ✗ <i>11</i>	1.0	280.40	0	280.40 X
39	AIR CON LIQUID PIPE ✗ <i>11</i>	1.0	108.30	0	108.30 X
40	RADIATOR TOP HOSE ✗ <i>11</i>	1.0	41.30	0	41.30 X
41	RADIATOR TOP HOSE JOINT ✗ <i>11</i>	1.0	21.10	0	21.10 X
42	RADIATOR BOTTOM HOSE ✗ <i>11</i>	1.0	80.00	0	80.00 X
43	ALTERNATOR ✗ <i>11</i>	1.0	1,484.80	0	1,484.80 X
44	FRONT OIL STICK ✗ <i>11</i>	1.0	25.30	0	25.30 X
45	BONNET CABLE ✓ <i>11</i>	1.0	53.60	0	53.60
46	FRONT MANIFOLD INTAKE ✗ <i>11</i>	1.0	856.30	0	856.30 X
47	FRONT HORN RH ✓ <i>11</i>	1.0	89.60	0	89.60
48	FRONT HORN LH ✓ <i>11</i>	1.0	89.60	0	89.60
49	FRONT OIL COOLER ✗ <i>11</i>	1.0	471.70	0	471.70 X
50	FRONT WIPER TANK WITH MOTOR ✗ <i>11</i>	1.0	204.90	0	204.90 X
51	FRONT SPARE TANK ✓ <i>11</i>	1.0	88.00	0	88.00
52	AIR CON CONDENSER ✓ <i>11</i>	1.0	777.20	0	777.20
53	RADIATOR ✓ <i>11</i>	1.0	902.10	0	902.10
54	RADIATOR COWLING, MOTOR & FAN ✓ <i>11</i>	1.0	516.40	0	516.40
55	RADIATOR COOLANT ✓ <i>11</i>	1.0	150.00	0	150.00
56	FRONT NUMBER PLATE ✓ <i>11</i>	1.0	30.00	0	30.00
57	FRONT NUMBER PLATE HOLDER ✓ <i>11</i>	1.0	30.00	0	30.00
58	FRONT CHASSIS RH - REPAIR ✗ <i>11</i>	1.0			
59	FRONT CHASSIS LH - REPAIR ✗ <i>11</i>	1.0			
Special Nett Price - Parts Sub Total					2706.50
Parts Total					6,614.80
60	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	1,200.00	0	1,200.00
61	SPRAY PAINT ON THE AFFECTED AREAS	1.0	1,200.00	0	1,200.00
62	ANTI-RUST COATING	1.0	300.00	0	300.00

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

* N = Item not subjected to GST

Page 2 of 3

Issued by : Anyasia

102/239

207
816991

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : SXXX8330H
LIM AH HUAT
BLK 479 PASIR RIS DR. 4
03-447
SINGAPORE 510479
TEL : FAX :
PH : 93380558
ATTN :

ESTIMATE BILL

Number : EB00005102
Date : 11/03/2019
Case No : AD00010277
Vehicle No : SKV7862L
Chassis : MNTBBAB17Z0024698
Year of Mfr : 2015
Policy No :
Model : NISSAN SYLPHY

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
63	WIRING	1.0	80.00	0	30 80.00
64	TO SERVICE & TOP-UP AIR-CON GAS	1.0	180.00	0	100 180.00
	Labour 1 Sub Total				2,960.00
					2330
					11490.67
					- 20%
					9192.54
SINGAPORE DOLLARS : NINETEEN THOUSAND NINE HUNDRED SIXTY AND CENTS FORTY-FIVE ONLY			Less Excess		0.00
			SUBTOTAL		18,654.63
			GST 7.00%		1,305.82
			TOTAL		19,960.45

Date of accident : 10/03/2019 07:15 PM. Place : HARBOURFRONT WALK IN VIVOCITY CARPARK

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

* N = Item not subjected to GST