

URGENT

URGENT

URGENT

22/03/2003

ASS. REC. BY:

Surveyor

REF:

CS3/LPC19000207/GH037

social instruction:

ASSIGNMENT (Office)

From (Person):

Ong Li Li

of

JPC

Date/Time:

11/03/2019

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBN 6580 E

Insured:

SMA 185R

at Workshop m/s

SI Motoring

Tel:

6749 9535

of

Blk 3006 ubi Rd 1 # 01-366

Policy No:

Claim No:

18/18/19/VP05/021266

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

27/12/2018

CA / REV / REP. / REV 24 HRS

(wp)

Date/Time:

9.54am 4/1/18

Person Contacted:

Ah seng

H.O.D. Endorsement:

Vehicle IN / OUT

Date/Time

Action/Instruction (X) Estimate

FBN 6580 E - X

SMA 185R - X

Submit PRS Report.

\$ 2400, 5 Days.
(Red: 7050; 74%)

26/4/2019

Nivitha (LKK Auto)

From: ONG LI LI <llong@lonpac.com>
Sent: Monday, 11 March 2019 12:25 PM
To: Admin-D (LKKAuto); assignments
Cc: MT_Claim_SG; SUR
Subject: RE: Our Ref: 18/18/19/VP05/021266 PRE-INSPECTION OF FBN 6580E [External General]
Attachments: 21266 TP SURVEY REPORT.pdf

Lonpac External - General

Dear Catherine

Please see attached for TP survey report with photographs and let us have your surveyor's review and report.

Thank you.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



Lonpac External - General data is for internal / external use.

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Friday, 4 January, 2019 9:58 AM
To: ONG LI LI; assignments
Cc: MT_Claim_SG; SUR
Subject: RE: Our Ref: 18/18/19/VP05/021266 RE: PRE-INSPECTION OF FBN 6580E

Dear Sir/Mdm,


Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



This email has been checked for viruses by AVG antivirus software.
www.avg.com

MENU

HIGHLIGHTS

DESCRIPTION
Get the appSPECS
Login Sign up FREE

SELLER INFO

Yamaha Aerox 155

Price S\$10500.00



unknown



1000km



FE-****-B



Class 2B



CHAT


(MESSAGES/U/48655)



Description

Mileage less than 1000km. Brembo front brake. Hel
brake line front. Rear YSS suspension. On-board front
and rear cam. Stainless steel rear rack.

Specifications

[MENU](#)**Bike Model**

Other Yamaha Models

Bike Class

Class 2B

Bike Type

Scooters

Transmission

Automatic

**Engine
Capacity**

155 cc

**Under Hire
Purchase**

No

Additional

First Owner

Yes

**Effective Date
Ownership**

22-08-2018

**Original Reg.
Date**

N/A

Bike Color

Additional


MENU

HIGHLIGHTS

DESCRIPTION
Get the app

SPECS
Login Sign up FREE

SELLER INFO



Road Tax
Expiry Date 23-08-2019

Mileage 1000km

Instalment
Details N/A



Accessories

(<https://www.singaporebikes.com/bikemart/sg/>)

Seller Information



slowrider
Join date:11 Jul,2003

PRUDENT ADJUSTORS SERVICES

BLOCK 607 ELIAS ROAD #05-192

SINGAPORE 510607

BUSINESS REGN. No. 53193457L

HP 96699986

VEHICLE DAMAGE INSPECTION REPORT

Miss NUR SHAFEENA BINTE SAMARUDDEEN Our Ref : PA/FBN6580/0119/tpw
Apt Blk 155 Simei Road #10-200 Date : 12 February 2019
Singapore 520155

REFERENCES

Claim Type	: Third Party	Date of Accident	: 27 October 2018
Vehicle No.	: FBN 6580 E	Date of Assignment	: 04 January 2019
Make	: Yamaha	Date of Inspection	: 04 January 2019
Model	: Aerox GDA155CVT	Date of Re-inspn	: NIL
Reg. Date	: 20 November 2018	Chassis No	: Blocked
Color	: Red	Engine No	: G3J1E0270370
Odometer	: Meter Damage		

TYRE CONDITION

	<u>Make</u>	<u>Size</u>	<u>Thread Balance</u>
Front	IRC	110/80 -14	8mm
Rear	IRC	140/70 -14	8mm

GENERAL DESCRIPTION OF DAMAGE (PHOTOGRAPHS ATTACHED)

The vehicle sustained damage at front and both portion.

Please refer to photographs and assessment of repairs for details

Enclosed (43) photographs depicting damage and after repair

INSPECTION AND ADJUSTMENT

Original Quotation : \$ 11,371.88 Revised Assessment : \$ 9,450.00 **Lump sum**

Survey conducted at S 1 Motoring

In accordance to your instruction, we have not authorized repairs.

In normal circumstances, repairs to the vehicle would take approximately
Ten (10) days to complete.

This survey was conducted on a "WITHOUT PREJUDICE" basis.

Note:

The workshop has agreed to undertake the repair on a lump sum basis, and or the use of ex-stock
Reconditioned parts whichever is possible

PRUDENT ADJUSTORS SERVICESVehicle No: **FBN 6580 E**

Our Ref: PA/FBN6580/0119/tpw

ADJUSTMENT ON REPAIR COST AND REPLACEMENT OF PARTS

S/N	Description Material	Qty	Condition	Original Quotation	Revised Quotation	
1	Visor	1 pc	Scratch	280.00	56 280.00	/
2	Upper meter cover	1 pc	Cracked	205.00	105 205.00	/
3	Meter assy	1 pc	Damage	580.00	X 580.00	X NN
4	Cover handle upper	1 pc	Cracked	308.00	X 308.00	X NN
5	Handle bar complete	1 pc	Bent	228.00	125 228.00	/
6	Handle bar balancer (end grips)	1 set	Missing	80.00	60 80.00	/
7	Handle bar grips	1 set	Torn	60.00	15 60.00	/
8	Wind mirror	1 set	Grazed	160.00	70 160.00	/
9	Brake lever	1 pc	Grazed	98.00	18 98.00	/
10	Brake master pump complete	1 pc	Grazed	328.00	285 328.00	/
11	Headlamp assy (LED)	1 pc	Cracked	695.00	289 695.00	/
12	Headlamp Cowling	1 pc	Cracked	388.00	85 388.00	/
13	Wire harness assy	1 set	Cut	720.00	X 720.00	X NN
14	Front fork @ \$510/-	2 pcs	Bent	1,020.00	654 1,020.00	/
15	Fork under bracket complete	1 pc	Distorted	315.00	X 315.00	X NN
16	Front mudguard	1 pc	Cracked	220.50	49 220.50	/
17	Side panel (Mat black) @ \$231.60/-	2 pcs	Hdr cracked	463.20	84 463.20	/
18	Side cover @ \$180/-	2 pcs	Cut	360.00	53 360.00	/
19	Front signal @ \$104/-	2 pcs	Cracked	208.00	68 208.00	/
20	Leg shield panel	1 pc	Deformed	285.00	19 285.00	/
21	Main switch assy	1 pc	Jam	268.50	X 268.50	X NN
22	Body cover panel	1 pc	Deformed	338.00	38 338.00	/
23	Board footrest @ \$315/-	2 pcs	Cut RH	630.00	24 315.00	/
24	Board footrest mat @ \$120/-	2 pcs	Cut RH	240.00	48 120.00	/
25	Body side cover @ \$ 225/-	2 pcs	Cracked	450.00	105 450.00	/
26	Rear signal RH (LED)	1 pc	Grazed	125.00	95 125.00	/
27	Muffler protector	1 pc	Cut	110.00	38 110.00	/
28	Muffler assy	1 pc	Dented	850.00	Repair 850.00	X
				10,013.20	9,578.20	2383
List price less 10%				1,001.32	957.82	
				9,011.88	8,620.38	2144.7

PRUDENT ADJUSTORS SERVICES

Vehicle No: **FBN 6580 E**


Our Ref: PA/FBN6580/0119/tpw

ADJUSTMENT ON REPAIR COST AND REPLACEMENT OF PARTS

<u>Add special nett item</u>					
29	Front number plate	1 pc	Necessary	20.00	15.00 /
30	IU unit	1 pc	Grazed	160.00	160.00 X
31	IU unit cover	1 pc	Torn	80.00	60.00 X
32	IU unit bracket	1 pc	Bent	60.00	50.00 X
33	Steering cone bearing	1 set	Necessary-50%	210.00	50 105.00 /
34	Side cover emblem	1 pc	Necessary	160.00	160.00 20
35	Body sticker	1 set	Necessary	220.00	220.00 120.
				910.00	770.00 205
<u>Labour</u>					
	Towing (2 trips)			150.00	120.00 50
	Check electrical			250.00	150.00 30
	Chassis frame align			550.00	450.00 250
	Workmanship			500.00	400.00 300
				1,450.00	1,120.00 630
Total parts & labour concluded				<u>11,371.88</u>	<u>10,510.38</u>
Lump sum repair adjustment				2979.7	<u>9,450.00</u>

20% : 2400

The information contained in this document is privileged and confidential and is intended for the exclusive use of the addressee designation. If you are not the addressee; any enclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this document not meant for you, please contact us immediately to arrange for it to return.


Prudent Adjustors Services
Bok Jee Tan

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 9432B

Vehicle Details

Vehicle No.: FBN6580E

Vehicle to be Exported: Yes

Intended Deregistration Date: 05 Jan 2019

Vehicle Make: YAMAHA

Vehicle Model: AEROX GDR155 CVT

Primary Colour: Red

Manufacturing Year: 2018

Engine No.: G3J1E0270370

Chassis No.: MH3SG4610JJ158438

Maximum Power Output: -

Open Market Value: \$2,207.00

Original Registration Date: 20 Nov 2018

First Registration Date: 20 Nov 2018

Transfer Count: 1

Actual ARF Paid: \$332.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 19 Nov 2028

COE Category: D - Motorcycle

COE Period(Years): 10

QP Paid: \$2,509.00

COE Rebate Amount: \$2,007.00

Total Rebate Amount: \$2,007.00

The information contained herein is correct as at 05 Jan 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 03/01/2019 11:19
Date Of Accident 27/10/2018 17:50
Exact Location Of Accident NICOLL HIGHWAY
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number FBN6580E
Insured/Policyholder
Name Of Registered Owner NUR SHAFEENA BINTE SAMARUDDEEN
NRIC No S9319432B
Email Address FEENA_0293@HOTMAIL.COM
Mobile Phone No (LOCAL) +65-94527751
Alternative Phone No OTHERS-94527751

Vehicle Particulars

Manufacturer YAMAHA
Model GDR155A (AEROX)-155CC

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category MOTORCYCLE

Insurance Company

Name of Insurance Company SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage THIRD PARTY FIRE AND/OR THEFT
Fleet Policy NO
Policy Number D18MTMC1007507

Cover Note Number

Driver

Name of Driver NUR SHAFEENA BINTE SAMARUDDEEN
NRIC No S9319432B
Date Of Birth 02/06/1993
Occupation INDOOR
Date Of Driving Pass 21/07/2014
Driving Experience 4 YEARS AND 3 MONTHS
Gender FEMALE
Mobile Number (LOCAL) +65-94527751

Fax Number
Contact Number OTHERS-94527751

Address	BLK 155 SIMEI ROAD #10-200
Postcode	520155
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	1
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	10 UBI AVENUE 3
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

Details of Witness 1

Name	SATWANT
Phone Number	97777024
Email Address	

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMA185R
Vehicle Make/Model/Colour	TOYOTA
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	CHIDAMVARAM THANGARAJU
NRIC/Passport Number	S2641395H
Contact Number	92336859

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

NUR SHAFEENA BINTE SAMARUDDEEN

Approximate Age

25

Injuries Sustain

Injured person in which vehicle?

FBN6580E

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

YES

Address

BLK 155 SIMEI ROAD#10-200

Postcode

520155




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref : CS3/LPC19000207/Gtd3e2-1	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Date : 29-04-2019	
			Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMA 185R	Veh. Inspected	FBN 6580E	
Policy No.		Coverage (\$)	0.00	
Claim No.	18/18/19/VP05/021266	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	11/03/2019	
2. Vehicle Particulars & Condition				
Make & Model	YAMAHA AEROX	c.c	155	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	MH3SG4610JJ158438	Colour	RED	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	110/80-14	IRC	5 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	140/70-14	IRC	5 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S, N/S BODY AND FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/12/2018	Inspection Date	04/01/2019	
Survey held at	S1 MOTORING BLK 3006 UBI ROAD 1 #01-366 SINGAPORE 408700			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBN 6580E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	VISOR	SCRATCHED	280.00	56.00
1	UPPER METER COVER	CRACKED	205.00	105.00
1	METER ASSY	NOT NECESSARY	580.00	-
1	COVER HANDLE UPPER	NOT NECESSARY	308.00	-
1	HANDLE BAR COMPLETE	BENT	228.00	125.00
1	SET HANDLE BAR BALANCER (END GRIPS)	MISSING	80.00	60.00
1	SET HANDLE BAR GRIPS	TORN	60.00	15.00
1	SET WIND MIRROR	GRAZED	160.00	70.00
1	BRAKE LEVER	GRAZED	98.00	18.00
1	BRAKE MASTER PUMP COMPLETE	GRAZED	328.00	285.00
1	HEADLAMP ASSY (LED)	CRACKED	695.00	289.00
1	HEADLAMP COWLING	CRACKED	388.00	85.00
1	SET WIRE HARNESS ASSY	NOT NECESSARY	720.00	-
2	FRONT FORK @\$510.00	BENT	1,020.00	654.00
1	FORK UNDER BRACKET COMPLETE	NOT NECESSARY	315.00	-
1	FRONT MUDGUARD	CRACKED	220.50	49.00
2	SIDE PANEL (MAT BLACK) @\$231.60	HDR CRACKED	463.20	84.00
2	SIDE COVER @\$180.00	CUT	360.00	53.00
2	FRONT SIGNAL @\$104.00	CRACKED	208.00	68.00
1	LED SHIELD PANEL	DEFORMED	285.00	19.00
1	MAIN SWITCH ASSY	NOT NECESSARY	268.50	-
1	BODY COVER PANEL	DEFORMED	338.00	38.00
2	BOARD FOOTREST @\$315.00	O/S CUT	630.00	24.00
2	BOARD FOOTREST MAT @\$120.00	O/S CUT	240.00	48.00
2	BODY SIDE COVER @\$225.00	CRACKED	450.00	105.00
1	REAR SIGNAL RH (LED)	GRAZED	125.00	95.00
1	MUFFLER PROTECTOR	CUT	110.00	38.00
1	MUFFLER ASSY	TO REPAIR SEE LABOUR	850.00	-
	LESS 10% DISCOUNT		-1,001.32	-238.30
			9,011.88	2,144.70

Report Ref No. CS3/LPC19000207/Gtd3e2-1

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT NUMBER PLATE (SN)	NECESSARY	20.00	15.00
1	IU UNIT (SN)	NOT NECESSARY	160.00	-
1	IU UNIT COVER (SN)	NOT NECESSARY	80.00	-
1	IU UNIT BRACKET (SN)	NOT NECESSARY	60.00	-
1	SET STEERING CONE BEARING (SN)	NECESSARY	210.00	50.00
1	SIDE COVER EMBLEM (SN)	NECESSARY	160.00	20.00
1	SET BODY STICKER (SN)	NECESSARY	220.00	120.00
			910.00	205.00
	<u>LABOUR</u>			
	TOWING (2 TRIPS).		150.00	50.00
	CHECK ELECTRICAL.		250.00	30.00
	CHASSIS FRAME ALIGN. INCLUSIVE OF THE REPAIR OF MUFFLER ASSY.		550.00	250.00
	WORKMANSHIP.		500.00	300.00
			1,450.00	630.00
	GRAND TOTAL		11,371.88	2,979.70
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,400.00

Report Ref No. CS3/LPC19000207/Gtd3e2-1

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.