

 INSR: WSP: <i>flys high</i> Tel: Liability: RMKS:	 INSR: WSP: Tel: Liability: RMKS:		INSR: WSP: Tel: Liability: RMKS:	 INSR: WSP: Tel: Liability: RMKS:
--	--	---	--	--

PRELIMINARY ADVICE	Date/Time:	Sent By:	Payment Breakdown Form:		
			Post-Repair Photos:	<input type="checkbox"/>	<input type="checkbox"/>
			Others:	<input type="checkbox"/>	<input type="checkbox"/>

FINAL SETTLEMENT	Date/Time: 26.01.19	Confirm with 29%	Email <input checked="" type="checkbox"/>	Call <input type="checkbox"/>
------------------	---------------------	------------------	---	-------------------------------

Total:	\$5 11,600.00	Global Sum \$5:			
FINAL PAYMENT	Date/Time: 26-07-09	Confirm with: Proc.	Email:	Call:	

Payee 1:	SS ILWD	Name 1:	FLYING ANGEL SPIN PRINTING
Payee 2: (Strike if N.A.)	SS	Name 2:	
Payee 3: (Strike if N.A.)	SS	Name 3:	

ASS. REC. BY:

REF: CS/PWD 19004829/Aqd3

Special Instruction:

SALVAGE

menmen

Adrian

ASSIGNMENT (Office)

From (Person):

Lionel Tan

of

FWD

Date/Time:

11/3/19 @ 6:12pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SDW 6882M

Insured:

SLU 1246Z

at Workshop in/s

Flying High

Tel:

67492997

of

11cnci Bkt Ave 6 # 61-29

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 10/3/2019

CA / REV / REP. / REV 24 HRS

'DS'

H.O.D. Endorsement:

Date/Time:

9:56am 12/3/19

Person Contacted:

Dean

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (—) Estimate
	SDW 6882M - C(3/MSG 130) 3141 / Agt 11
	SLU 1246Z - X
	D.O.A - 12/12/2013

REF: FWD

ASSIGNMENT

From: Date: 12/3/19

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SDW 6882M

at Workshop n/s:

of Blk 11 Caki Bkt Ave 6 #01-29

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 12 days Res: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS ^{1up}

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SDW6882M. Yr Regn: 2007 / Nov

Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Camry cc 1998

Colour: Gold. A/C: Insured / Std / NI / NA

Sp. Reading: 223388. T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MROS3BK4107016312

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size F: 235/40R18

R: 235/40R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Haliblead.

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. D.O.I. 12/03/19.

Survey held at Flying High.

Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP FWD.

COE Expiry: 2022 Nov

MV: 28.5K

PV: 18.3K.

Nett: 10.2K.

43: 10.000 (USD 14,911.50 67%)

5995H

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$))

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Subject: SDW6882M.

Date:

Toyota Camry.
MR053BK4107A6312

Front Number Plate Bent	30(SN) ✓
Front Number Plate Holder Deland	30(SN) ✓
Front Number Plate Gasket:	=
Front Bumper Deland	456.80 ✓
Front Bumper Clips New	30 ✓
Front Bumper Side Holder x02 New	66.1x2=132.20 ✓
Front Bumper Tow Cover. New	43.70 x
Front Bumper Lower Spoiler Repair	1290(SN) x
Front Bumper Sponge caulked	191.40 ✓
Front Bumper Reinforcement. Bent	286.80 ✓
Front Bumper Chrome Moulding x02 New	67.3x2=134.60 ✓
Front Bumper Fog Lamp x02 New	289.9x2=579.80 x
Front Bumper Fog Lamp Cover x02 New	123.5x2=247 x
Front Grille caulked	382.30 ✓
Front Grille Logo. New	61.10 ✓
Headlamp x02 caulked	682.3x2=1364.60 ✓
Front Bumper Panel Bent	182.20 ✓

Subject: SDW 6882M.

Date:

Rear Exhaust Manifold Not new
Rear Exhaust Heat Insulator. Crumpled

63.90 - X

171.20 ✓

10250

S/N: 1220

7687.50

Panel Beating	2800	2000.	
Spray Painting	2400	1600.	
Wiring	150	60	
To undersend	150	100	
To remove upholstery.	150	80	
To remove reverse sensor	100	50.	
To remove rear seat	250	150	
To remove rear windscreen.	180	120	
To remove fuel tank	150	80	4500
To transfer bootlid fittings.	150	60.	
To perform chassis alignment	300	200	

total: 13407.50

L/S: 10K. (Nett Value)

12 Days.






LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

6303 6363

With In-Store Inchcape Certified Environment 12 Months & 100,000 km

Free Tyre & Service Credits up to \$3,000

Interest Rate 2.28%

Extended Warranty 1yr

► **SEARCH** Camry Price Range Depreciation > 10 year(s) Vehicle Type

► Used Car Comparison

— Comparing 4 Vehicles —

Toyota Camry 2.0A (COE till 03/2022)



Clear All

Add all to Shortlist

Back to search result

Add to Shortlist

Toyota Camry 2.0A (COE till 04/2022)



Add to Shortlist

Toyota Camry 2.0A (COE till 04/2023)



Add to Shortlist

Toyota Camry 2.0A (COE till 05/2023)



Add to Shortlist

CAR DETAILS

Price	\$24,000	\$28,000	\$31,800	\$33,800
Instalment	N.A.	N.A.	N.A.	N.A.
Registration Date	12-Apr-2007	18-May-2007	30-Apr-2008	27-Jun-2008
Manufactured	2006	2007	2007	2008
Mileage	-	180,000 km	116,000 km	158,000 km
Transmission	Auto	Auto	Auto	Auto
Engine Cap	1,998 cc	1,998 cc	1,998 cc	1,998 cc
Road Tax	\$1,452 /yr	\$1,452 /yr	\$1,331 /yr	\$1,331 /yr
Power	108.0 kW (144 bhp)	108.0 kW (144 bhp)	108.0 kW (144 bhp)	108.0 kW (144 bhp)
Curb Weight	1,530 kg	1,530 kg	1,530 kg	1,530 kg
Features	Smooth And Responsive 2.0L DOHC VVT-I Engine, ABS, SRS Airbags, Multi-Function Steering Wheel, Auto Head Lights, Dual Electric Seats.	Smooth And Responsive 2.0L DOHC VVT-I Engine, ABS, SRS Airbags, Multi-Function Steering Wheel, Auto Head Lights, Dual Electric Seats.	2.0L DOHC 16 Valves VVTI Engine, ABS, Airbags, Auto Head Light, Multi-Function Steering, Cruise Control, Auto Side Mirrors With Indicator, Rear Aircon	Powerful 2.0L 16 V VVT-I, 4 Airbags, A Steering Wheel, D Control Aircon.
Accessories	Factory Fitted Audio And CD System, Leather Seats, Reverse Sensors, Retractable Side Mirrors With Indicator Lights, Rear Aircon, Solar Film.	Factory Fitted Audio/CD System, Leather Seats, Sports Rims, Reverse Sensors, Retractable Side Mirrors With Indicator Lights, Rear Aircon, Solar Film.	New Leather Seats, Dual Electric Seats, Sports Rims, Kenwood DVD/Reverse Camera/Sensors, Multi Steering Control, Fog Lamps, Digital Climatic Aircon.	Beige Interior, Lear Audio/CD Player, A Lamps, Rear Aircon Remote Alarm.
Description	Many Wear And Tear Repaired With Receipts To Prove. Owner Believe In Preventive Maintenance. 100% Accident-Free. Low Commitment But At Attractive Price.	COE Till 30/04/2022, 1st Owner. Agent Maintained. New Tyres And GPS System. Excellent And Original Condition, Well Maintained Interior And Exterior, Call Now For Viewing.	"One Year In-Home Warranty", High Loan Available, Price Stated Above Is Actual Selling Price, STA Or VICOM Evaluation Are Welcome, Purchase Comes With Official Warranty Certificate For A Peace Of Mind, Fully Refurbished, New Paintwork Done, Accident-Free, Wear And Tear Replaced, Bank Or In-House Loan Available, Free 2 x Fully Synthetic Oil Servicing, Free Grooming.	Consignment Unit, Obligation Viewing
COE	\$25,174	\$26,004	\$20,441	\$19,356
OMV	\$27,853	\$27,655	\$26,761	\$26,497
ARF	\$30,639	\$30,421	\$26,761	\$26,497
Depreciation	\$7,860 /yr	\$8,930 /yr	\$7,690 /yr	\$8,010 /yr
No. of Owners	3	1	2	1
Type of Vehicle	Luxury	Luxury	Luxury	Luxury
Category	COE Car, Direct Owner Sale	COE Car, Direct Owner Sale	COE Car	COE Car, Consignm
Availability	Available	Available	Available (Pending) A buyer have paid a deposit for this car.	Available
Remarks				

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Details	
Owner ID Type:	Singapore NRIC
Owner ID:	5995H
Vehicle Details	
Vehicle No.:	SDW6882M
Vehicle to be Exported:	Yes
Intended Deregistration Date:	12 Mar 2019
Vehicle Make:	TOYOTA
Vehicle Model:	CAMRY 2.0 AUTO ABS AIRBAG
Primary Colour:	Beige
Manufacturing Year:	2007
Engine No.:	1AZE057319
Chassis No.:	MR053BK4107016312
Maximum Power Output:	108.0 kW (144 bhp)
Open Market Value:	\$26,761.00
Original Registration Date:	09 Nov 2007
First Registration Date:	09 Nov 2007
Transfer Count:	0
Actual ARF Paid:	\$29,438.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Details	
COE Expiry Date:	08 Nov 2022
COE Category:	B - Car (1601cc & above)
COE Period(Years):	5
PQP Paid:	\$25,084.00
COE Rebate Amount:	\$18,344.00
Total Rebate Amount:	\$18,344.00
Remarks	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 12 Mar 2019

OK

Nivitha (LKK Auto)

From: lionel.tan@fwd.com
Sent: Monday, 11 March 2019 6:12 PM
To: assignments@lkkauto.com; sur@lkkauto.com
Cc: motorclaims.sg@fwd.com
Subject: FW: PRE-REPAIR INSPECTION NOTIFICATION - FWD REF: SLU 1246Z // NTUC REF: GBH 5381B // OUR REF: L19.0320.LT(JT)
Attachments: PR 1.jpg; PR 2.jpg; PR 3.jpg; PR 4.jpg

Policy Number: PNPV2018-00014035

Hi LKK Team,

Please arrange survey (SJE) with repairer.

Regards,
Lionel

From: Kuru & Co [mailto:kurulegal@yahoo.com.sg]
Sent: Monday, March 11, 2019 5:39 PM
To: Lionel Tan Tian Pei - SGUser
Cc: Motor Claims SG - SG Common
Subject: Re: PRE-REPAIR INSPECTION NOTIFICATION - FWD REF: SLU 1246Z // NTUC REF: GBH 5381B // OUR REF: L19.0320.LT(JT)

Dear Sirs,

Our client is agreeable to the following surveyor(s): **LKK Auto Consultants Pte Ltd**

Please arrange for your surveyor to survey our client's vehicle at the following address:

Flying High Spray Painting

Blk 1 Kaki Bukit Ave 6

#01-29 AutoBay @ Kaki Bukit

Singapore 417883

Tel: 67492997 - Dean

Please instruct your surveyor to conduct the pre-repair survey immediately and complete the pre-repair survey within 2 working days of his appointment.

Kindly let us have the pre-repair and/or post repair survey report upon completion of the survey(s).

As solicitors on record, our client shall look to you for payment of our legal costs plus disbursements should you reach a direct settlement with our client's repairer.

Thanks / Rgds,
Lena
Kuru & Co
150 South Bridge Road
#04-06 Fook Hai Building
Singapore 058727
Tel: 6532 2009
Fax: 6532 2007

On Monday, 11 March 2019, 5:27:11 pm SGT, lionel.tan@fwd.com <lionel.tan@fwd.com> wrote:

Without Prejudice

Dear Sir/Madam,

Please select one of our surveyors as follows: -

1. LKK AUTO CONSULTANTS PTE LTD
2. INFINITI APPRAISAL SERVICE
3. AJAX INSPECTION SERVICES PTE LTD
4. APPRAISALS ASSOCIATES PTE LTD
5. VICOM LTD

If you are not agreeable to any of the above, we would proceed to appoint a surveyor to conduct a pre repair survey & post repair inspection within the timeline stipulated under the NIMA protocol.

We look forward to your reply.

Thank you.

Lionel

From: Kuru & Co [mailto:kurulegal@yahoo.com.sg]

Sent: Monday, 11 March, 2019 4:38 PM

To: Motor Claims SG - SG Common; NTUC Income Motor Dept; Annie Koh; NTUC PRI; MTSurvey

Subject: PRE-REPAIR INSPECTION NOTIFICATION - FWD REF: SLU 1246Z // NTUC REF: GBH 5381B // OUR REF: L.19.0320.LT(JT)

Dear Sirs,

**ACCIDENT INVOLVING SDW 6882M, SLU 1246Z, GBH 5381B, SDG 8883G, FBH 2523D & SLG 9400R ON 10.03.19
AT/ALONG CTE
ACCIDENT AND PRE-REPAIR SURVEY** **NOTIFICATION OF**

We act for **Lim Kang Hock**, whose vehicle registration number **SDW 6882M** was damaged in the above accident.

A copy of the Police report filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle.

If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Thanks / Rgds,

Lena

Kuru & Co
150 South Bridge Road
#04-06 Fook Hai Building
Singapore 058727
Tel: 6532 2009
Fax: 6532 2007

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments. Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

Asher Sng (LKKAUTO)

From: Asher Sng (LKKAUTO)
Sent: Monday, 29 April 2019 11:38 AM
To: pheronlim@gmail.com
Subject: Accident Involving SDW 6882M & SLU 1246Z on 10/03/2019

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Your Ref: SDW 6882M
Our Ref: CC4/FWD19004429/Aea3

Dear Sir/Madam,

Accident Involving SDW 6882M & SLU 1246Z on 10/03/2019

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will base on the number of days of repair as recommended by our surveyor.

Kindly take note that the case handler in-charge is Asher and she can be contacted at her DID 6841 6051

In order to expedite the claim process, please forward all relevant documents to us (LKK) to proceed on negotiate settlement.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	12 Mar 2019 17:02	Clim Dtl Modified	Claimant's Name: -> -.	[A] Nivitha Govindasamy
2	12 Mar 2019 17:02	Clim Veh Model Changed	(201714) TOYOTA CAMRY 2.0 (A).	[A] Nivitha Govindasamy
3	12 Mar 2019 17:02	Clim Created	Reg No: - Acct Date: 2019/03/10. Claim Type: TP. Insurer: FWD Singapore Pte. Ltd. (HQ). Workshop: Flying High Spray Painting (HQ)	[A] Nivitha Govindasamy
4	12 Mar 2019 17:02	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ); RR Region: FWD - Ext Auto Adj Assignment. Suggested Adj. : AJAX Inspection Services Pte Ltd.	[A] Nivitha Govindasamy
5	12 Mar 2019 17:02	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/03/21	[A] Nivitha Govindasamy
6	12 Mar 2019 17:02	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] Nivitha Govindasamy
7	12 Mar 2019 17:02	Adj Adjuster Assigned	[None] -> ADRIAN LING	[A] Nivitha Govindasamy
8	12 Mar 2019 17:03	Clim Registration Modified	Reg No:->SDW6882M.	[A] Nivitha Govindasamy
9	16 Mar 2019 14:30	Clim Dtl Modified	Claimant's Name: - -> LIM KANG HOCK. Claimant's ID: -> S1505995H.	[A] HOW MEI KWAN
10	24 Jun 2019 10:30	Label Added	(20005):Direct Settlement .	[A] Asher Sng Rong Yi
11	27 Jun 2019 16:45	Adj Rpt Initiated		[A] JOANNE LEE KHANG MIN
12	27 Jun 2019 16:45	Clim Dtl Modified	JPJ Reg. Date: -> 2007/11/09.	[A] JOANNE LEE KHANG MIN
13	27 Jun 2019 16:45	Clim Details Notified		[A] JOANNE LEE KHANG MIN
14	01 Jul 2019 15:43	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2019/03/21	[A] Asher Sng Rong Yi
15	01 Jul 2019 15:44	Adj Mandate Request	Cur.Req:11600.00:LIABILITY: 100% B:28 6VEH CC OI 5TH QUANTUM: (a) COR : \$10,000 + (b) LOR : \$1,600.00 (10days x \$160) Total: a+b = \$11,600.00 PLEASE REVERT WITH YOUR APPROVAL / MANDATE / INSTRUCTIONS, IF ANY.	[A] Asher Sng Rong Yi

Date From



Date To



Audit Type: None

Go

ACTIVITY

[24/06/2019 10:31] Asher Sng Rong Yi:
 MARKET VALUE: \$28,500
 LTA REBATE: \$18,344
 NETT VALUE: \$10,156

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2192685	27/06/2019 16:45	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SDW6882M	SLU1246Z	11.77

7/22/2019

Merimen e-Claims

Print Received Message

This mail is associated with :

***SDW6882M (1201900006414)**
[SLU1246Z]

TP

LIM KANG HOCK

Mar 10 2019 12:00AM

[Yew Hong Ean]

Flying High Spray Painting

From FWD Singapore Pte. Ltd. (HQ) (FWD_SG), sent on 15/07/2019 17:28 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$11600.00) - SDW6882M - Claim Handler: Lionel Tan

Approved:11600.00.

FWD SINGAPORE PTE. LTD.
6 TEMASEK BOULEVARD,
#18-01 SUNTEC TOWER FOUR,
SINGAPORE 038986
Attn: Motor Claims Dept

Dear Sir/ Madam

ACCIDENT INVOLVING VEHICLE NO SDW 6882M & SLU 1246Z ON 10/03/2019

We are authorized by the owner of SDW 6882M their above claims.

I/We therefore propose to claim from your as follows:

1.	Cost of Repairs (w/GST)	S\$ 10,000.00
2.	Loss of Use/Rental-(S\$200 x 10 days)	S\$ 2,000.00
3.	LTA Search Fee/GIA Reports	S\$ -
TOTAL		<u>S\$ 12,000.00</u>

Please let us have your reply soonest possible.

Thank you.

Yours faithfully

FLYING HIGH SPRAY PAINTING
BLK 1 KAKI BUKIT AVE 8
#01-29 SINGAPORE 417883
(AUTO BAY @ KAKI BUKIT)
TEL: 6749 2997 FAX: 6744 2942

AUTHORISATION TO ACT

I, LIM KANG HOCK ("the third party claimant") of 36 JALAN TARI
PIRING 5799189 (address), owner of SDW 6882 M (vehicle no.) hereby
Authorize FLYING HIGH SPRAY PAINTING ("the workshop") to act for
me with respect to my claim for repair cost and/or rental and/or loss of use ("claim") for my vehicle
no. SDW 6882 M that was damaged pursuant to the accident which occurred on 10/03/19
(date) along CTE BESIDE BRADDELL RD EXIT TO BA PIE ^{EXIT} (location) involving vehicle
No/s SDG 8883 G, SLG 9400 R, SLV 1246 Z, (the accident).
GBH 5381 B, FBH 2523 D

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit
and the workshop is further authorized to receive payment further to settlement of my claim with
payment cheque/s being made in a favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without
prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other
vehicle is concerned.

Dated this 12 (day) of 03 (month) 2019 (year)

林江福

Signed by "the third party Claimant"
(with company stamp if applicable)

FLYING HIGH SPRAY PAINTING
BLK 1 KAKI BUKIT AVE 6
#01-29 SINGAPORE 417883
(AUTO BAY @ KAKI BUKIT)
TEL: 6749 2997 FAX: 6744 2942

23
Signed by "the workshop"
(with company stamp)

RELEASE

Claim Reference:	1201900006414
Surveyor's Reference:	CC4/FWD19004429/Aea3
TP Reference:	SDW 6882M

We, **FLYING HIGH SPRAY PAINTING** ("Workshop") hereby agree and confirm that we are authorized by the owner ("Claimant") of motor vehicle **SDW 6882M** ("Vehicle") to accept the sum of **\$11,600.00**, being the amount claimed for **\$10,000.00** (repair costs), **\$1,600** (loss of rental/-use), **\$ -** (loss of income), **\$ -** (disbursement) as compensation for the loss of or damage to the Vehicle, as a result of an accident ("Accident") which occurred on **10/03/2019** (date of accident) at / along **CTE BESIDE BRADDELL RD EXIT 10 B4 PIE EXIT** (location) involving vehicle no/s. **SDW 6882M** and **SLU 1246Z**.

This is pursuant to the inspection conducted on **12/03/2019** (date) at the Workshop.

We confirm that this acceptance is in full and final settlement of all claims arising from the damage to the Vehicle (whether now or hereafter to become manifest), to the intent that FWD Singapore Pte. Ltd. and all other persons, in particular the driver of **SLU 1246Z** be absolutely and finally exonerated and discharged from all claims of every nature and kind whatsoever which have been made or which may be made in respect of this Accident.

We also declare that we are authorized by the Claimant to receive the above compensation and we have full authority to make the claim as set out above and to settle the matter on behalf of the Claimant in any manner we deem fit.

This settlement is reached on a without prejudice and without admission of liability basis. As such, this Release is not to be construed as an admission of liability on the part of FWD Singapore Pte Ltd, their policyholder and / or authorised driver and shall not be used as evidence in any claims and / or action which may be lodged by any of them.

Dated this 5th day of August 2019

CLAIMANT

FLYING HIGH SPRAY PAINTING

BLK 1 KAKI BUKIT AVE 6
#01-29 SINGAPORE 417883
(AUTO BAY @ KAKI BUKIT)
TEL: 6749 2997 FAX: 6744 2942


[Signed by the "Workshop" with Co. Stamp]

For and on behalf of the "Claimant"





LWP

[FWD's appointed surveyor with Co. Stamp]

For and on behalf of FWD Singapore Pte. Ltd.

高 飛 汽 車 噴 漆 廠

FLYING HIGH SPRAY PAINTING

Blk 1, Kaki Bukit Ave 6, #01-29 Singapore 417883 (AutoBay@Kaki Bukit)
Tel: 6749 2997 Fax: 6744 2942 Email: info@ohmycar.sg
Business Reg. No. 42523200

INVOICE

Vehicle no: SDW 6882 M
Model: TOYOTA CAMRY
Name: LIM KANG HOCK
Date of accident: 10/03/2019
Address: C/O No 1 kaki bukit ave 6
 #01-29 AutoBay@kaki bukit
 S (417883)

FINAL REPAIR BILL FOR VEHICLE NO SDW 6882 M

QTY	ITEM	AMOUNT
1	LUMP SUM REPAIR COST	\$10,000.00
	Total	\$10,000.00
Dollars	TEN THOUSAND ONLY	



DAWN ENTERPRISES

21 Seletar West Farmway 1
Singapore 798125
Tel: 63832661 Fax: 64842836
Reg No.430058/00D

Nº 36526

F/Hush

RENTAL AGREEMENT

DATE 10/3/19

HIRER'S PARTICULARS

Name Lim Kong Hock
Address 36 Jalan Taxi Piring
S 6799189

I/C or Passport No. 1505995H Country _____

Occupation _____

Date of Birth _____ Age _____

Driving Licence No. _____ Date Passed _____

Tel: (HP) 93892997 (Residence) _____

DRIVER'S PARTICULARS

Name _____

Address _____

I/C or Passport No. _____ Country _____

Occupation _____

Date of Birth _____ Age _____

Driving Licence No. _____ Date Passed _____

Tel: (Office) _____ (Residence) _____

IMPORTANT NOTES:

1. No Insurance Coverage if the driver is below 24yrs old or less than 2 years driving licence
2. This vehicle is licensed to carry 24 passengers only
3. Hirer is liable to pay first \$ 2000 as excess all claims any accident plus loss of earning while damaged vehicle is under repair
4. For usage to Malaysia subject to higher excess all claims of \$50,000.00 and different rental rate
5. Please notify our office should there be any accident involving this hired vehicle within 24 hrs
6. No refund will be given for vehicle returns early
7. No refund will be given for petrol left in vehicle
8. Hirer is liable to pay all parking fee and traffic summonses
9. Vehicles to be return during office hour only
10. No Service on Public Holiday and Sunday

CHARGES

10 Day at \$200.00 per days \$2000.00

Day at \$ _____ per week

Day at \$ _____ per month

TOTAL AMOUNT

\$2000.00

AMOUNT PAID

\$2000.00

BALANCE DUE

Days Extension From _____ To _____

Amount Deposit (refundable) \$

SCHEDULE

MODEL

SFH3989P

T Camry

Date

Time

Mileage

10/3/19

20/3/19

FROM

10/3/19

TO

20/3/19

I/we have read and understood the terms and conditions above and hereby agreed to abide

Hirer's Signature

Driver/Guarantor's Signature

DAWN ENTERPRISES

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Mar 2019 Edit Reg		11 Mar 2019 00:00 Edit Adj Rpt	\$410,000.00 Edit Estimates	\$410,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	Yew Hong Ean, ID: S8476051Z								
Main Claimant:	LIM KANG HOCK, ID: S1505995H								
Vehicle Reg. No.:	SDW6882M	Date of Loss:	10/03/2019 00:00 - :59 [136 Months and 1 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 1201900006414	Policy/Cover Note No.:	PNPV2018-00014035						
Vehicle Reg. No. (Insured):	SLU1246Z	Policy No. (Claimant):	2018-V8000280-VDP-R008						
		Excess:							
Repairer:	Flying High Spray Painting (HQ) BLK 1 Kaki Bukit Ave 5, #01-29 Auto Bay, 417883 Kaki Bukit - Tel: 67492997								
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Lionel Tan]								
Claimant's Insurer:	Great American Insurance Company (HQ) - Tel: 6804 6047								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 21/03/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> FWD_SG (15/07/2019): Alert - Adj Mandate Approved (\$411600.00) - SDW6882M - Claim Handler: Lionel Tan 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SDW6882M (1201900006414)
[SLU1246Z]
TP
LIM KANG HOCK
Mar 10 2019 12:00AM
[Yew Hong Ean]
Flying High Spray Painting












































[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)



















































View View in Browser



















































Letters/Correspondences				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	(Draft)	Third Party Express Settlement - Payment Breakdown	1 Edit		

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	01/07/19 15:43	Adjuster Immediate Advice	1 Load HTML		

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	14/05/19 18:38	General View	1 Load JPG	<input checked="" type="checkbox"/>	
2	14/05/19 18:38	General View	1 Load JPG	<input checked="" type="checkbox"/>	
3	14/05/19 18:38	General View	1 Load JPG	<input checked="" type="checkbox"/>	
4	14/05/19 18:38	General View	1 Load JPG	<input checked="" type="checkbox"/>	
5	14/05/19 18:38	General View	1 Load JPG	<input checked="" type="checkbox"/>	
6	14/05/19 18:38	General View	1 Load JPG	<input checked="" type="checkbox"/>	
7	14/05/19 18:38	General View	1 Load JPG	<input checked="" type="checkbox"/>	
8	14/05/19 18:38	General View	1 Load JPG	<input checked="" type="checkbox"/>	
9	14/05/19 18:38	General View	1 Load JPG	<input checked="" type="checkbox"/>	
10	14/05/19 18:38	General View	1 Load JPG	<input checked="" type="checkbox"/>	
11	14/05/19 18:38	General View	1 Load JPG	<input checked="" type="checkbox"/>	
12	14/05/19 18:38	General View	1 Load JPG	<input checked="" type="checkbox"/>	
13	14/05/19 18:38	General View	1 Load JPG	<input checked="" type="checkbox"/>	
14	14/05/19 18:38	General View	1 Load JPG	<input checked="" type="checkbox"/>	
15	14/05/19 18:38	General View	1 Load JPG	<input checked="" type="checkbox"/>	
16	14/05/19 18:38	General View	1 Load JPG	<input checked="" type="checkbox"/>	
17	14/05/19 18:38	General View	1 Load JPG	<input checked="" type="checkbox"/>	
18	14/05/19 18:38	General View	1 Load JPG	<input checked="" type="checkbox"/>	
19	14/05/19 18:38	General View	1 Load JPG	<input checked="" type="checkbox"/>	
20	14/05/19 18:38	General View	1 Load JPG	<input checked="" type="checkbox"/>	
21	14/05/19 18:38	General View	1 Load JPG	<input checked="" type="checkbox"/>	
22	14/05/19 18:38	General View	1 Load JPG	<input checked="" type="checkbox"/>	
23	14/05/19 18:38	General View	1 Load JPG	<input checked="" type="checkbox"/>	
24	14/05/19 18:38	General View	1 Load JPG	<input checked="" type="checkbox"/>	
25	14/05/19 18:38	General View	1 Load JPG	<input checked="" type="checkbox"/>	
26	14/05/19 18:38	General View	1 Load JPG	<input checked="" type="checkbox"/>	
27	14/05/19 18:38	General View	1 Load JPG	<input checked="" type="checkbox"/>	
28	14/05/19 18:38	General View	1 Load JPG	<input checked="" type="checkbox"/>	
29	14/05/19 18:38	General View	1 Load JPG	<input checked="" type="checkbox"/>	
30	14/05/19 18:38	General View	1 Load JPG	<input checked="" type="checkbox"/>	

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
31	14/05/19 18:38	General View	 Load JPG	<input checked="" type="checkbox"/>
32	14/05/19 18:38	General View	 Load JPG	<input checked="" type="checkbox"/>
33	14/05/19 18:38	General View	 Load JPG	<input checked="" type="checkbox"/>
34	14/05/19 18:38	General View	 Load JPG	<input checked="" type="checkbox"/>
35	14/05/19 18:38	General View	 Load JPG	<input checked="" type="checkbox"/>
36	14/05/19 18:38	General View	 Load JPG	<input checked="" type="checkbox"/>
37	14/05/19 18:38	General View	 Load JPG	<input checked="" type="checkbox"/>
38	14/05/19 18:38	General View	 Load JPG	<input checked="" type="checkbox"/>
39	14/05/19 18:38	General View	 Load JPG	<input checked="" type="checkbox"/>
40	14/05/19 18:38	General View	 Load JPG	<input checked="" type="checkbox"/>
41	14/05/19 18:38	General View	 Load JPG	<input checked="" type="checkbox"/>
42	14/05/19 18:38	General View	 Load JPG	<input checked="" type="checkbox"/>
43	14/05/19 18:38	General View	 Load JPG	<input checked="" type="checkbox"/>
44	14/05/19 18:38	General View	 Load JPG	<input checked="" type="checkbox"/>
45	14/05/19 18:38	General View	 Load JPG	<input checked="" type="checkbox"/>
46	14/05/19 18:38	General View	 Load JPG	<input checked="" type="checkbox"/>
47	14/05/19 18:38	General View	 Load JPG	<input checked="" type="checkbox"/>
48	14/05/19 18:38	General View	 Load JPG	<input checked="" type="checkbox"/>
49	14/05/19 18:38	General View	 Load JPG	<input checked="" type="checkbox"/>
50	14/05/19 18:38	General View	 Load JPG	<input checked="" type="checkbox"/>
51	14/05/19 18:38	General View	 Load JPG	<input checked="" type="checkbox"/>
52	14/05/19 18:38	General View	 Load JPG	<input checked="" type="checkbox"/>
53	14/05/19 18:38	General View	 Load JPG	<input checked="" type="checkbox"/>
54	14/05/19 18:38	General View	 Load JPG	<input checked="" type="checkbox"/>
55	14/05/19 18:38	General View	 Load JPG	<input checked="" type="checkbox"/>
56	14/05/19 18:38	General View	 Load JPG	<input checked="" type="checkbox"/>
57	14/05/19 18:38	General View	 Load JPG	<input checked="" type="checkbox"/>
58	14/05/19 18:38	General View	 Load JPG	<input checked="" type="checkbox"/>
59	14/05/19 18:38	General View	 Load JPG	<input checked="" type="checkbox"/>
60	14/05/19 18:38	General View	 Load JPG	<input checked="" type="checkbox"/>
61	14/05/19 18:38	General View	 Load JPG	<input checked="" type="checkbox"/>
62	14/05/19 18:38	General View	 Load JPG	<input checked="" type="checkbox"/>
63	14/05/19 18:38	General View	 Load JPG	<input checked="" type="checkbox"/>
64	14/05/19 18:38	General View	 Load JPG	<input checked="" type="checkbox"/>
65	14/05/19 18:38	General View	 Load JPG	<input checked="" type="checkbox"/>
66	14/05/19 18:38	General View	 Load JPG	<input checked="" type="checkbox"/>
67	14/05/19 18:38	General View	 Load JPG	<input checked="" type="checkbox"/>
68	14/05/19 18:38	General View	 Load JPG	<input checked="" type="checkbox"/>
69	14/05/19 18:38	General View	 Load JPG	<input checked="" type="checkbox"/>
70	14/05/19 18:38	General View	 Load JPG	<input checked="" type="checkbox"/>
71	14/05/19 18:38	General View	 Load JPG	<input checked="" type="checkbox"/>
72	14/05/19 18:38	General View	 Load JPG	<input checked="" type="checkbox"/>
73	14/05/19 18:38	General View	 Load JPG	<input checked="" type="checkbox"/>
74	14/05/19 18:38	General View	 Load JPG	<input checked="" type="checkbox"/>
75	14/05/19 18:38	General View	 Load JPG	<input checked="" type="checkbox"/>
76	14/05/19 18:38	General View	 Load JPG	<input checked="" type="checkbox"/>
77	14/05/19 18:38	General View	 Load JPG	<input checked="" type="checkbox"/>
78	14/05/19 18:38	General View	 Load JPG	<input checked="" type="checkbox"/>
79	14/05/19 18:38	General View	 Load JPG	<input checked="" type="checkbox"/>
80	14/05/19 18:38	General View	 Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
81	14/05/19 18:38	General View		<input checked="" type="checkbox"/>
82	14/05/19 18:38	General View		<input checked="" type="checkbox"/>
83	14/05/19 18:38	General View		<input checked="" type="checkbox"/>
84	14/05/19 18:38	General View		<input checked="" type="checkbox"/>
85	14/05/19 18:38	General View		<input checked="" type="checkbox"/>
86	14/05/19 18:38	General View		<input checked="" type="checkbox"/>
87	14/05/19 18:38	General View		<input checked="" type="checkbox"/>
88	14/05/19 18:38	General View		<input checked="" type="checkbox"/>
89	14/05/19 18:38	General View		<input checked="" type="checkbox"/>
90	14/05/19 18:38	General View		<input checked="" type="checkbox"/>
91	14/05/19 18:38	General View		<input checked="" type="checkbox"/>
92	14/05/19 18:38	General View		<input checked="" type="checkbox"/>
93	14/05/19 18:38	General View		<input checked="" type="checkbox"/>
94	14/05/19 18:38	General View		<input checked="" type="checkbox"/>
95	14/05/19 18:38	General View		<input checked="" type="checkbox"/>
96	14/05/19 18:38	General View		<input checked="" type="checkbox"/>
97	14/05/19 18:38	General View		<input checked="" type="checkbox"/>
98	14/05/19 18:38	General View		<input checked="" type="checkbox"/>
99	14/05/19 18:38	Replacement Part Photo		<input checked="" type="checkbox"/>
100	14/05/19 18:38	Replacement Part Photo		<input checked="" type="checkbox"/>
101	14/05/19 18:38	Replacement Part Photo		<input checked="" type="checkbox"/>
102	14/05/19 18:38	Replacement Part Photo		<input checked="" type="checkbox"/>
103	14/05/19 18:38	Replacement Part Photo		<input checked="" type="checkbox"/>
104	14/05/19 18:38	Replacement Part Photo		<input checked="" type="checkbox"/>
105	14/05/19 18:38	Replacement Part Photo		<input checked="" type="checkbox"/>
106	14/05/19 18:38	Replacement Part Photo		<input checked="" type="checkbox"/>
107	14/05/19 18:38	Replacement Part Photo		<input checked="" type="checkbox"/>
108	14/05/19 18:38	Replacement Part Photo		<input checked="" type="checkbox"/>
109	14/05/19 18:38	Replacement Part Photo		<input checked="" type="checkbox"/>
110	14/05/19 18:38	Replacement Part Photo		<input checked="" type="checkbox"/>
111	14/05/19 18:38	Replacement Part Photo		<input checked="" type="checkbox"/>
112	14/05/19 18:38	Replacement Part Photo		<input checked="" type="checkbox"/>
113	14/05/19 18:38	Replacement Part Photo		<input checked="" type="checkbox"/>
114	14/05/19 18:38	Replacement Part Photo		<input checked="" type="checkbox"/>
115	14/05/19 18:38	Replacement Part Photo		<input checked="" type="checkbox"/>
116	14/05/19 18:38	Replacement Part Photo		<input checked="" type="checkbox"/>
117	14/05/19 18:38	Replacement Part Photo		<input checked="" type="checkbox"/>
118	14/05/19 18:38	Replacement Part Photo		<input checked="" type="checkbox"/>
119	14/05/19 18:38	Replacement Part Photo		<input checked="" type="checkbox"/>
120	14/05/19 18:38	Replacement Part Photo		<input checked="" type="checkbox"/>
121	14/05/19 18:38	Replacement Part Photo		<input checked="" type="checkbox"/>
122	14/05/19 18:38	Replacement Part Photo		<input checked="" type="checkbox"/>
123	14/05/19 18:38	Replacement Part Photo		<input checked="" type="checkbox"/>
124	14/05/19 18:38	Replacement Part Photo		<input checked="" type="checkbox"/>
125	14/05/19 18:38	Replacement Part Photo		<input checked="" type="checkbox"/>
126	14/05/19 18:38	Replacement Part Photo		<input checked="" type="checkbox"/>
127	14/05/19 18:38	Replacement Part Photo		<input checked="" type="checkbox"/>
128	14/05/19 18:38	Replacement Part Photo		<input checked="" type="checkbox"/>
129	14/05/19 18:38	Replacement Part Photo		<input checked="" type="checkbox"/>
130	14/05/19 18:38	Replacement Part Photo		<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
131	14/05/19 18:38	Replacement Part Photo		<input checked="" type="checkbox"/>
132	14/05/19 18:38	Replacement Part Photo		<input checked="" type="checkbox"/>
133	14/05/19 18:38	Replacement Part Photo		<input checked="" type="checkbox"/>
134	14/05/19 18:38	Replacement Part Photo		<input checked="" type="checkbox"/>
135	14/05/19 18:38	Replacement Part Photo		<input checked="" type="checkbox"/>
136	14/05/19 18:38	Replacement Part Photo		<input checked="" type="checkbox"/>
137	14/05/19 18:38	Replacement Part Photo		<input checked="" type="checkbox"/>
138	14/05/19 18:38	Replacement Part Photo		<input checked="" type="checkbox"/>
139	14/05/19 18:38	Replacement Part Photo		<input checked="" type="checkbox"/>
140	14/05/19 18:38	Replacement Part Photo		<input checked="" type="checkbox"/>
141	14/05/19 18:38	Replacement Part Photo		<input checked="" type="checkbox"/>
142	14/05/19 18:38	Replacement Part Photo		<input checked="" type="checkbox"/>
143	14/05/19 18:38	Replacement Part Photo		<input checked="" type="checkbox"/>
144	14/05/19 18:38	Replacement Part Photo		<input checked="" type="checkbox"/>
145	14/05/19 18:38	Replacement Part Photo		<input checked="" type="checkbox"/>
146	14/05/19 18:38	Replacement Part Photo		<input checked="" type="checkbox"/>
147	14/05/19 18:38	Replacement Part Photo		<input checked="" type="checkbox"/>
148	14/05/19 18:38	Replacement Part Photo		<input checked="" type="checkbox"/>
149	14/05/19 18:38	Replacement Part Photo		<input checked="" type="checkbox"/>
150	14/05/19 18:38	Replacement Part Photo		<input checked="" type="checkbox"/>
151	14/05/19 18:38	Replacement Part Photo		<input checked="" type="checkbox"/>
152	14/05/19 18:38	Replacement Part Photo		<input checked="" type="checkbox"/>
153	14/05/19 18:38	Replacement Part Photo		<input checked="" type="checkbox"/>
154	14/05/19 18:38	Replacement Part Photo		<input checked="" type="checkbox"/>
155	14/05/19 18:38	Replacement Part Photo		<input checked="" type="checkbox"/>
156	14/05/19 18:38	Replacement Part Photo		<input checked="" type="checkbox"/>
157	14/05/19 18:38	Replacement Part Photo		<input checked="" type="checkbox"/>
158	14/05/19 18:38	Replacement Part Photo		<input checked="" type="checkbox"/>
159	14/05/19 18:38	Replacement Part Photo		<input checked="" type="checkbox"/>
160	14/05/19 18:38	Replacement Part Photo		<input checked="" type="checkbox"/>
161	14/05/19 18:38	Replacement Part Photo		<input checked="" type="checkbox"/>
162	14/05/19 18:38	Replacement Part Photo		<input checked="" type="checkbox"/>
163	14/05/19 18:38	Replacement Part Photo		<input checked="" type="checkbox"/>
164	14/05/19 18:38	Replacement Part Photo		<input checked="" type="checkbox"/>
165	14/05/19 18:38	Replacement Part Photo		<input checked="" type="checkbox"/>
166	14/05/19 18:38	Replacement Part Photo		<input checked="" type="checkbox"/>
167	14/05/19 18:38	Replacement Part Photo		<input checked="" type="checkbox"/>
168	14/05/19 18:38	Replacement Part Photo		<input checked="" type="checkbox"/>
169	14/05/19 18:38	Replacement Part Photo		<input checked="" type="checkbox"/>
170	14/05/19 18:38	Replacement Part Photo		<input checked="" type="checkbox"/>
171	14/05/19 18:38	Replacement Part Photo		<input checked="" type="checkbox"/>
172	14/05/19 18:38	Replacement Part Photo		<input checked="" type="checkbox"/>
173	14/05/19 18:38	Replacement Part Photo		<input checked="" type="checkbox"/>
174	14/05/19 18:38	Replacement Part Photo		<input checked="" type="checkbox"/>
175	14/05/19 18:38	Replacement Part Photo		<input checked="" type="checkbox"/>
176	14/05/19 18:38	Replacement Part Photo		<input checked="" type="checkbox"/>
177	14/05/19 18:38	Replacement Part Photo		<input checked="" type="checkbox"/>
178	14/05/19 18:38	Replacement Part Photo		<input checked="" type="checkbox"/>
179	14/05/19 18:38	Replacement Part Photo		<input checked="" type="checkbox"/>
180	14/05/19 18:38	Replacement Part Photo		<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
181	14/05/19 18:38	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
182	14/05/19 18:38	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	16/03/19 14:31	TP POLICE REPORT	 Load PDF	
2	16/03/19 14:31	ACKNOWLEDGEMENT EMAIL TO FWD DD 12.03.2019	 Load PDF	
3	18/03/19 13:15	TP GIA REPORT	 Load PDF	
4	28/06/19 09:34	WORKSHOP INVOICE	 Load PDF	
5	28/06/19 09:34	RENTAL RECEIPT	 Load PDF	
6	13/08/19 10:09	AUTHORISATION TO ACT FORM	 Load PDF	
7	13/08/19 10:09	Release Voucher	 Load PDF	
8	13/08/19 10:09	LOD	 Load PDF	
No	Finalized On	FWD Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	19/03/19 09:48	E-filed GIA Report	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLU1246Z (Insd veh)	Model:	TOYOTA CAMRY 2.0 (A)
	SDW6882M (TP veh)		
Date of Accident:	10/03/2019		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	: \$	24,917.50	
Final Repair Cost	: \$	10,000.00	
Loss of Use	: \$	days at \$0.00 per day	
Rental (if any)	: \$	1,600.00	10 days
LTA / GIA Search Fee	: \$	0.00	
Others:	: \$	0.00	
	: \$		
Final Settlement Sum	: \$	11,600.00	

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability 100 (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): 0 (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Flying High Spray Painting	: \$	11,600.00
2)		: \$	

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

13 Aug
2019

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD19004429/AEA3Q2
Date: 13/08/2019

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2018-00014035
Claimant Vehicle No: SDW6882M Insured Vehicle No: SLU1246Z
Date of Loss: 10/03/2019 Nature of Claim: TP Claim No: 1201900006414

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SDW6882M
Make & Model: TOYOTA CAMRY, 2.0 (A) Engine No: 1AZE057319
Reg. Date: 09/11/2007 (Man. Year: 2007) Chassis No: MR053BK4107016312
Colour: Gold Odometer: 223388 km
Engine Capacity: 1998 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/40 R18 Rear Tyre Size: 235/40 R18
Front Left Side: Habilead 6 mm Rear Left Side: Habilead 6 mm
Front Right Side: Habilead 6 mm Rear Right Side: Habilead 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,137.50	9,253.62	8,883.88	48.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,780.00	4,500.00	2,280.00	33.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	24,917.50	13,753.62	11,163.88	44.80
Approved Total (Overridden) (S\$)		10,000.00		
Nett Amount (S\$)	24,917.50	10,000.00	14,917.50	59.87
+ Car Rental (10.0 x S\$160.00/day) (S\$)		1,600.00		
Nett Liability (S\$)		11,600.00		

INSPECTION

Date of Assignment: 11/03/2019
Date Inspected: 12/03/2019 Inspected At: Flying High Spray Painting (HQ)
BLK 1 Kaki Bukit Ave 6, #01-29 Auto Bay
Singapore 417883
Estimated Period of Repair: 12.0 days

Adjuster: ADRIAN LING

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 28 Jun 2019)	
Parts: 143	TOYOTA CAMRY 2.0 (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SDW6882M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT NUMBER PLATE	Bent	30.00 FS	*30.00 FS
2	1		*FRONT NUMBER PLATE HOLDER	Deformed	30.00 FS	*30.00 FS
3	1		*FRONT BUMPER	Deformed	456.80 F	*456.80 FL
4	1		*FRONT BUMPER CLIPS	Necessary	30.00 F	*30.00 FL
5	2		*FRONT BUMPER SIDE HOLDER	Necessary	132.20 F	*132.20 FL
6	1		*FRONT BUMPER TOW COVER	Not Necessary	43.70 F	*- FL
7	1		*FRONT BUMPER LOWER SPOILER	Repair	1,200.00 FS	*- FS
8	1		*FRONT BUMPER SPONGE	Cracked	191.40 F	*191.40 FL
9	1		*FRONT BUMPER REINFORCEMENT	Bent	286.80 F	*286.80 FL
10	2		*FRONT BUMPER CHROME MOULDING	Necessary	134.60 F	*134.60 FL
11	2		*FRONT BUMPER FOG LAMP	Not Necessary	579.80 F	*- FL
12	2		*FRONT BUMPER FOG LAMP COVER	Not Necessary	247.00 F	*- FL
13	1		*FRONT GRILLE	Cracked	382.30 F	*382.30 FL
14	1		*FRONT GRILLE LOGO	Necessary	61.10 F	*61.10 FL
15	2		*HEADLAMP	Cracked	1,364.60 F	*1,364.60 FL
16	1		*FRONT BRACE PANEL	Bent	182.20 F	*182.20 FL
17	1		*REAR NUMBER PLATE	Not Necessary	30.00 FS	*- FS
18	1		*REAR NUMBER PLATE HOLDER	Not Necessary	30.00 FS	*- FS
19	1		*REAR BUMPER	Distorted	499.50 F	*499.50 FL
20	1		*REAR BUMPER CLIPS	Necessary	30.00 F	*30.00 FL
21	2		*REAR BUMPER SIDE HOLDER	Necessary	131.20 F	*131.20 FL
22	1		*REAR BUMPER LOWER SPOILER	Deformed	1,200.00 FS	*700.00 FS
23	1		*REAR BUMPER REFLECTOR	O/S Cracked	166.40 F	*83.20 FL
24	1		*REAR BUMPER REINFORCEMENT	Bent	381.40 F	*381.40 FL
25	1		*REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
26	1		*REAR END PANEL	Distorted	581.40 F	*581.40 FL
27	1		*REAR END PANEL TOP GARNISH	Deformed	382.20 F	*382.20 FL
28	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
29	2		*TAILLAMP	Cracked	816.20 F	*816.20 FL
30	2		*TAILLAMP PANEL	Repair	385.00 F	*- FL
31	1		*BOOTLID	Buckled	957.00 F	*957.00 FL
32	1		*BOOTLID LOCK	Damaged	381.50 F	*381.50 FL
33	1		*BOOTLID WEATHERSTRIPE	Cut	123.50 F	*123.50 FL
34	2		*BOOTLID HINGE	Not Necessary	165.60 F	*- FL
35	2		*BOOTLID LAMP	Cracked	561.60 F	*561.60 FL
36	1		*TOYOTA LOGO	Necessary	61.70 F	*61.70 FL
37	1		*REAR RH FENDER	Buckled	980.20 F	*980.20 FL
38	2		*REAR FENDER INNER TRIM	Not Necessary	693.60 F	*- FL
39	1		*REAR FENDER INNER TRIM CLIPS	Not Necessary	60.00 F	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*SPARE TYRE PANEL	Distorted	708.00 F	*708.00 FL
41	1		*SPARE TYRE PANEL TOP COVER	Not Necessary	289.90 F	*- FL
42	1		*SPARE TYRE LOCK SCREW	Not Necessary	131.40 F	*- FL
43	1		*SPARE TYRE PANEL INSULATION PAD	Necessary	280.00 FS	*200.00 FS
44	1		*REAR RH CHASSIS MEMBER	Repair	581.50 F	*- FL
45	1		*REAR WINDSCREEN MOULDING	Necessary	178.20 F	*178.20 FL
46	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*60.00 FS
47	1		*REAR EXHAUST PIPE	Repair	981.40 F	*- FL
48	1		*BOOTLID OUTER GARNISH	Cracked	381.50 F	*381.50 FL
49	1		*REAR EXHAUST MOUNTING	Not Necessary	63.90 F	*- FL
50	1		*REAR EXHAUST HEAT INSULATOR	Crumpled	171.20 F	*171.20 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	18,137.50	11,911.50
- List Item Discount on L Items 0.00/25.00% (\$)	0.00	2,657.88
Total Parts (\$)	18,137.50	9,253.62

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	2,800.00	2,000.00
2	SPRAY PAINTING	New	2,400.00	1,600.00
3	WIRING	New	150.00	60.00
4	TO UNDERSEAL	New	150.00	100.00
5	TO REMOVE UPHOLSTERY	New	150.00	80.00
6	TO REMOVE REVERSE SENSOR	New	100.00	50.00
7	TO REMOVE REAR SEAT	New	250.00	150.00
8	TO CAMERA REAR WINDSCREEN	New	180.00	120.00
9	TO REMOVE FUEL TANK	New	150.00	80.00
10	TO TRANSFER BOOTLID FITTINGS	New	150.00	60.00
11	TO PERFORM CHASSIS ALIGNMENT	New	300.00	200.00
Gross Labour Cost (S\$)			6,780.00	4,500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >