

TP FWD
Asher

Flying High

Subject: SDW6882M

Date:

Toyota Camry

MR053BK4107016312

Front Number Plate Bent	30(SN) ✓
Front Number Plate Holder Deland	30(SN) ✓
Front Number Plate Garnish:	=
Front Bumper Deland	456.80 ✓
Front Bumper Clips New	30 ✓
Front Bumper Side Holder x02 New	66.1x2=132.20 ✓
Front Bumper Tow Cover. New	43.70 x
Front Bumper Lower Spoiler Repair	1290(SN) x
Front Bumper Sponge caulked	191.40 ✓
Front Bumper Reinforcement. Best	286.80 ✓
Front Bumper Chrome Moulding x02 New	67.3x2=134.60 ✓
Front Bumper Fog Lamp x02 New	289.9x2=579.80 x
Front Bumper Fog Lamp Cover x02 New	123.5x2=247 x
Front Grille caulked	382.30 ✓
Front Grille Logo. New	61.10 ✓
Headlamp x02 caulked	682.3x2=1364.60 ✓
Front Bumper Panel Best	182.20 ✓

Subject: SDW6882M.

Date:

	Rees Number Plate	30(SN) X
	Rees Number Plate Holder	30(SN) X
	Rees Bumper Distorted	499.50 ✓
	Rees Bumper Clips. New	30 ✓
	Rees Bumper Side Holder x02 New	656x2=1312 ✓
	Rees Bumper Lower Spoiler Del'd	1200(SN) 700(SN)
	Rees Bumper Reflector x02 RH cracked	83.2x2=166.40 83.20
	Rees Bumper Reinforcement. Best	381.40 ✓
	Reverse Sensor Damaged	280(SN) 200(SN)
	Rees End Panel Distorted	581.40. ✓
	Rees End Panel Top Garnish Del'd	382.20. ✓
	Rees End Panel Sealant new	60(SN) ✓
	Taillamp x02 cracked	408.1x2=816.20 ✓
	Taillamp Panel x02 Reps	192.5x2=385 X.
	Bootlid Buckle	957 ✓
	Bootlid Lock Dam'd	381.50. ✓
	Bootlid Weatherstripe. At	123.50 ✓
	Bootlid Chrome Moulding	==
	Bootlid Hinge x02 New	82.8x2=165.60 X
	Bootlid Lamp x02 cracked	280.8x2=561.60 ✓
	Toyota Logo. New	61.70 ✓
	Rees RH Fender Buckle	980.20 ✓
	Rees Fender Inner Trim x02 } New	346.8x2=693.60 +
	Rees Fender Inner Trim Clips. } New	60 +
	Spare Tyre Panel Distorted	708 ✓
	Spare Tyre Panel Top Cover } New	285.90 +
	Spare Tyre Lock Screw. } New	131.40 +
	Spare Tyre Panel Insulation Paid New	280(SN) 200(SN)
	Rees RH Chassis Member Reps	581.50 +
	Rees Windscreen Moulding } New	178.20 ✓
	Rees Windscreen Sealant	60(SN) ✓
	Rees Exhaust Pipe Reps	981.40 X
Bootlid Outer Garnish <		
381.50 /		
cracked		

Subject: SDW 6882M

Date:

Rees Exhst Mounting Noe new
Rees Exhst Heat Insulator, crumpled

63.90 x

171.20 ✓

10250

S-N: 1220

7687.50

Panel Beating	2800	2000.	
Spray Painting	2400	1600.	
Wiring	150	60	
To undersent	150	100	
To remove upholstery.	150	80	
To remove reverse sensor	100	50.	
To remove rees sent	250	150	
To remove rees windscreen.	180	120	
To remove fuel tank	150	80	4500
To transfer bootlid fittings.	150	60	
To perform chassis alignment	300	200	

total: 13407.50

L/S : G.K. (Nett Value)

12 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and**
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: