

Accident Photo



Accident Photo




Accident Photo




Accident Photo



Accident Photo



Accident Photo



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	22/06/2018 12:35
Date Of Accident	21/06/2018 15:00
Exact Location Of Accident	JALAN EUNOS.
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKT4511E
Insured/Policyholder	
Name Of Registered Owner	TAN PAIY PEE
NRIC No	S1749193H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97902586
Alternative Phone No	OFFICE-97902586

Vehicle Particulars

Manufacturer	TOYOTA
Model	WISH 1.8X CVT

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA204850
Cover Note Number	

Driver

Name of Driver	TAN PAIY PEE
NRIC No	S1749193H
Date Of Birth	02/03/1946
Occupation	INDOOR
Date Of Driving Pass	21/09/1970
Driving Experience	47 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97902586
Fax Number	
Contact Number	OFFICE-97902586
Email Address	NOEMAIL

Address	86 BUTTERFLY AVE
Postcode	349832
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CROSS JUNCTION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I CHECK THAT TRAFFIC IS CLEAR THUS I PROCEED TO DO A LH TURN WHEN SUDDENLY VEHICLE B CAME AT HIGH SPEED AND HIT ONTO MY VEHICLE'S FRONT LH PORTION.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKA8652E
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

Accident Sketch Plan Pg. 1


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
 5. Any false reporting may be referred to the Police for investigation.
 6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- B. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I check that traffic is clear thus I proceed to do a u-turn when suddenly vehicle B came at high speed and hit onto my vehicle's front LH position.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]

Policyholder's Signature
Date & Time:

6773 PULAU ARUMUTAM 100000

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SMC ✓

Accident Sketch Plan Pg. 1



redefining Insurance

Date: 27/06/2018

To: Owner of Vehicle Number: SKT4511E

The following has been advised to you via your workshop, SINE MOTOR PIL through their staff, _____

Please tick the applicable box if you had been advised on the content as seen below:

- ☒ You had been advised by the workshop that in the case that you wish to claim against your own policy, there is a Fourteen (14) days clause whereby the claim must be made within the stipulated timeframe from the day of occurrence.
- ☒ You had been advised by the workshop on the liability and merits of the case accordingly.
- ☒ You had been advised by the workshop on the claims procedure for the type of claim that you will be making due to this accident.
- ☒ There will be delay to your vehicle repair due to the unavailability of spare parts locally and there is no other option except to indent it from overseas.
- ☒ There will be no cancellation/withdrawal of the Own Damage claim once the order of the spare parts have been placed. If you wish to cancel/withdraw the claim, you shall bear all costs, expenses &/or related charges incurred directly &/or indirectly to the procurement of the spare parts.
- ☒ The estimated waiting time for the spare parts to arrive is 4 - 6 weeks. The estimated arrival time does not include the repair period.
- ☒ You will be driving the vehicle out despite being advised by the workshop mechanic/personnel that the vehicle may not be road worthy.
- ☒ For vehicles below Three (3) years old, your Insurance Company will use only genuine original parts to repair your vehicle.
- ☐ For vehicles above Three (3) years old, your Insurance Company will be carrying out repairs using any combination of genuine original parts and/or original equipment manufacturer (OEM) parts.
- ☒ You had been advised by the workshop of the Twelve (12) months warranty for Own Damage repairs on workmanship related to the accident.
- ☒ For vehicles that are under warranty with a local distributor, you have been advised by the workshop to check with your local distributor on any effect to your warranty prior to making this Own Damage claim.
- ☐ Others _____

Signed and acknowledge by:

Name and signature of policyholder/authorised driver

Name and signature of workshop personnel including company stamp

Identification Card

REPUBLIC OF SINGAPORE **DRIVING LICENCE**



Identification Number: **S1749193H**

TAN PUI PEH

Valid until: **02 Mar 1995**
 Valid from: **25 Mar 1993**



REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S1749193H



TAN PUI PEH

陳 飛 鵬

CHINESE

Sex: **M**
 Date of Birth: **02-25-1940**
 Issued at: **401K.H**




YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES

		AGE LIMIT
Class 1	Motor vehicles exceeding 300 cc	21 to 34 years
Class 2	Motor vehicles up to 300 cc and 400 cc	21 to 34 years
Class 3	Motorcycles and mopeds	21 to 34 years
Class 4	Motor Cycles and Motor Bikes with a maximum speed of 45 km/h or less	21 to 34 years

17493





Identification Number: **S1749193H**

TAN PUI PEH

CHINESE

Sex: **M**
 Date of Birth: **02-25-1940**
 Issued at: **401K.H**

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S1749193H

Date: **11-26-1993** No: **17493H**



1. $1000 \times 0.05 = 50$
 2. $1000 \times 0.05 = 50$
 3. $1000 \times 0.05 = 50$
 4. $1000 \times 0.05 = 50$
 5. $1000 \times 0.05 = 50$
 6. $1000 \times 0.05 = 50$
 7. $1000 \times 0.05 = 50$
 8. $1000 \times 0.05 = 50$
 9. $1000 \times 0.05 = 50$
 10. $1000 \times 0.05 = 50$

05/25/2015

www.tandf.co.uk/journals/ISSN 1360-0567

© 2000 Blackwell Science Ltd *Journal of Internal Medicine* 247: 361–367

Your SmartDrive Comprehensive Essential

poly(ethyleneterephthalate)
 0.005
 0.001

DOI: 10.1002/pola
 Received 24 October 2018; accepted 24 October 2018
 Published online 2 November 2018

Prigamber	201:0477-150
DM: 3815	31:49:23

1994, 1995, 1996, 1997, 1998, 1999, 2000, 2001, 2002, 2003, 2004, 2005, 2006, 2007, 2008, 2009, 2010, 2011, 2012, 2013, 2014, 2015, 2016, 2017, 2018, 2019, 2020, 2021, 2022, 2023, 2024, 2025, 2026, 2027, 2028, 2029, 2030, 2031, 2032, 2033, 2034, 2035, 2036, 2037, 2038, 2039, 2040, 2041, 2042, 2043, 2044, 2045, 2046, 2047, 2048, 2049, 2050, 2051, 2052, 2053, 2054, 2055, 2056, 2057, 2058, 2059, 2060, 2061, 2062, 2063, 2064, 2065, 2066, 2067, 2068, 2069, 2070, 2071, 2072, 2073, 2074, 2075, 2076, 2077, 2078, 2079, 2080, 2081, 2082, 2083, 2084, 2085, 2086, 2087, 2088, 2089, 2090, 2091, 2092, 2093, 2094, 2095, 2096, 2097, 2098, 2099, 2100, 2101, 2102, 2103, 2104, 2105, 2106, 2107, 2108, 2109, 2110, 2111, 2112, 2113, 2114, 2115, 2116, 2117, 2118, 2119, 2120, 2121, 2122, 2123, 2124, 2125, 2126, 2127, 2128, 2129, 2130, 2131, 2132, 2133, 2134, 2135, 2136, 2137, 2138, 2139, 2140, 2141, 2142, 2143, 2144, 2145, 2146, 2147, 2148, 2149, 2150, 2151, 2152, 2153, 2154, 2155, 2156, 2157, 2158, 2159, 2160, 2161, 2162, 2163, 2164, 2165, 2166, 2167, 2168, 2169, 2170, 2171, 2172, 2173, 2174, 2175, 2176, 2177, 2178, 2179, 2180, 2181, 2182, 2183, 2184, 2185, 2186, 2187, 2188, 2189, 2190, 2191, 2192, 2193, 2194, 2195, 2196, 2197, 2198, 2199, 2200, 2201, 2202, 2203, 2204, 2205, 2206, 2207, 2208, 2209, 2210, 2211, 2212, 2213, 2214, 2215, 2216, 2217, 2218, 2219, 2220, 2221, 2222, 2223, 2224, 2225, 2226, 2227, 2228, 2229, 2230, 2231, 2232, 2233, 2234, 2235, 2236, 2237, 2238, 2239, 2240, 2241, 2242, 2243, 2244, 2245, 2246, 2247, 2248, 2249, 2250, 2251, 2252, 2253, 2254, 2255, 2256, 2257, 2258, 2259, 2260, 2261, 2262, 2263, 2264, 2265, 2266, 2267, 2268, 2269, 2270, 2271, 2272, 2273, 2274, 2275, 2276, 2277, 2278, 2279, 2280, 2281, 2282, 2283, 2284, 2285, 2286, 2287, 2288, 2289, 2290, 2291, 2292, 2293, 2294, 2295, 2296, 2297, 2298, 2299, 2300, 2301, 2302, 2303, 2304, 2305, 2306, 2307, 2308, 2309, 2310, 2311, 2312, 2313, 2314, 2315, 2316, 2317, 2318, 2319, 2320, 2321, 2322, 2323, 2324, 2325, 2326, 2327, 2328, 2329, 2330, 2331, 2332, 2333, 2334, 2335, 2336, 2337, 2338, 2339, 2340, 2341, 2342, 2343, 2344, 2345, 2346, 2347, 2348, 2349, 2350, 2351, 2352, 2353, 2354, 2355, 2356, 2357, 2358, 2359, 2360, 2361, 2362, 2363, 2364, 2365, 2366, 2367, 2368, 2369, 2370, 2371, 2372, 2373, 2374, 2375, 2376, 2377, 2378, 2379, 2380, 2381, 2382, 2383, 2384, 2385, 2386, 2387, 2388, 2389, 2390, 2391, 2392, 2393, 2394, 2395, 2396, 2397, 2398, 2399, 2400, 2401, 2402, 2403, 2404, 2405, 2406, 2407, 2408, 2409, 2410, 2411, 2412, 2413, 2414, 2415, 2416, 2417, 2418, 2419, 2420, 2421, 2422, 2423, 2424, 2425, 2426, 2427, 2428, 2429, 2430, 2431, 2432, 2433, 2434, 2435, 2436, 2437, 2438, 2439, 2440, 2441, 2442, 2443, 2444, 2445, 2446, 2447, 2448, 2449, 2450, 2451, 2452, 2453, 2454, 2455, 2456, 2457, 2458, 2459, 2460, 2461, 2462, 2463, 2464, 2465, 2466, 2467, 2468, 2469, 2470, 2471, 2472, 2473, 2474, 2475, 2476, 2477, 2478, 2479, 2480, 2481, 2482, 2483, 2484, 2485, 2486, 2487, 2488, 2489, 2490, 2491, 2492, 2493, 2494, 2495, 2496, 2497, 2498, 2499, 2500, 2501, 2502, 2503, 2504, 2505, 2506, 2507, 2508, 2509, 2510, 2511, 2512, 2513, 2514, 2515, 2516, 2517, 2518, 2519, 2520, 2521, 2522, 2523, 2524, 2525, 2526, 2527, 2528, 2529, 2530, 2531, 2532, 2533, 2534, 2535, 2536, 2537, 2538, 2539, 2540, 2541, 2542, 2543, 2544, 2545, 2546, 2547, 2548, 2549, 2550, 2551, 2552, 2553, 2554, 2555, 2556, 2557, 2558, 2559, 2560, 2561, 2562, 2563, 2564, 2565, 2566, 2567, 2568, 2569, 2570, 2571, 2572, 2573, 2574, 2575, 2576, 2577, 2578, 2579, 2580, 2581, 2582, 2583, 2584, 2585, 2586, 2587, 2588, 2589, 2590, 2591, 2592, 2593, 2594, 2595, 2596, 2597, 2598, 2599, 2600, 2601, 2602, 2603, 2604, 2605, 2606, 2607, 2608, 2609, 2610, 2611, 2612, 2613, 2614, 2615, 2616, 2617, 2618, 2619, 2620, 2621, 2622, 2623, 2624, 2625, 2626, 2627, 2628, 2629, 2630, 2631, 2632, 2633, 2634, 2635, 2636, 2637, 2638, 2639, 2640, 2641, 2642, 2643, 2644, 2645, 2646, 2647, 2648, 2649, 2650, 2651, 2652, 2653, 2654, 2655, 2656, 2657, 2658, 2659, 2660, 2661, 2662, 2663, 2664, 2665, 2666, 2667, 2668, 2669, 2670, 2671, 2672, 2673, 2674, 2675, 26

400-222-2222
 1-800-855-8555
 MDH 1.572.22

© 2004 Blackwell Publishing Ltd, *Journal of Internal Medicine* 255: 105–112

SmartLink, Copyright © 2004 by The McGraw-Hill Companies

- ```

1 # Create a new variable called 'age' with the value 2000000000
2 age = 2000000000
3 # Print out variable 'age'
4 print(age)
5 # Print out variable 'age'
6 print(age)

```

China Project for 2018 Results

- a.  $\frac{1}{2} \ln \left( \frac{1 + \sqrt{1 + 4x}}{1 - \sqrt{1 + 4x}} \right) + \frac{1}{2} \ln \left( \frac{1 + \sqrt{1 + 4x}}{1 - \sqrt{1 + 4x}} \right) = \ln \left( \frac{1 + \sqrt{1 + 4x}}{1 - \sqrt{1 + 4x}} \right)$
- b.  $\ln \left( \frac{1 + \sqrt{1 + 4x}}{1 - \sqrt{1 + 4x}} \right) = \ln \left( \frac{1 + \sqrt{1 + 4x}}{1 - \sqrt{1 + 4x}} \right) + \ln \left( \frac{1 + \sqrt{1 + 4x}}{1 - \sqrt{1 + 4x}} \right)$

### Vehicle details

| Waktu dan Model Penelitian                  | Tempat dan Waktu Pengambilan Sampel         | Metode Pengambilan Sampel       | Salah |
|---------------------------------------------|---------------------------------------------|---------------------------------|-------|
| Waktu: 10 April 2019<br>Lokasi: Gedung Aula | Tempat: Gedung Aula<br>Waktu: 10 April 2019 | Metode Pengambilan Sampel: Acak | Salah |
| Waktu: 10 April 2019<br>Lokasi: Gedung Aula | Tempat: Gedung Aula<br>Waktu: 10 April 2019 | Metode Pengambilan Sampel: Acak | Salah |
| Waktu: 10 April 2019<br>Lokasi: Gedung Aula | Tempat: Gedung Aula<br>Waktu: 10 April 2019 | Metode Pengambilan Sampel: Acak | Salah |

[illegible]

**Excess applicable** . . . . . 12,500,000

[illegible]

### Drivers details

1. 在 2019 年 12 月 31 日，A 公司应计提的坏账准备为 100 万元。  
 2. 在 2020 年 12 月 31 日，A 公司应计提的坏账准备为 150 万元。  
 3. 在 2021 年 12 月 31 日，A 公司应计提的坏账准备为 200 万元。  
 4. 在 2022 年 12 月 31 日，A 公司应计提的坏账准备为 250 万元。

44:

Accident Photo





Accident Photo



Accident Photo



Accident Photo



**Enquire Vehicle & Owner Information ( Vehicle No. SKT4511E As At 21 Jun 2018 / 15:00:00 )****Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: H600-40871.18/KC

**Current Owner Details**

Owner ID Type: Singapore NRIC

Owner ID: S1749193H

Owner Name: TAN PAIY PEE

Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes

Registered Block/House No.: 86

Registered Street Name: BUTTERFLY AVENUE

Registered Unit No.: -

Registered Building Name: -

Registered Postal Code: 349832

**Current Vehicle Details**

Vehicle No.: SKT4511E

Make Description/Model: TOYOTA / WISH 1.8X CVT ABS D/AIRBAG 2WD 5DR

Insurance Company Name: AXA INSURANCE PTE LTD

# HENDON AUTOMOTIVE PTE LTD

280 Woodlands Industrial Park E5, #01-19 Harvest @ Woodlands (S) 757322

Tel : 9459 2885

Fax: 6334 5178

Email: hendon.automotive@gmail.com

Date : 01/09/18

OUR REF : TP/SKA 8652E/18

M/S : HERMAN SOFFIAN BIN KAMBARI

BLK 524A TAMPINES CENTRAL 7

#02-39

SINGAPORE 521524

Statement Of Claim On Veh No : SKA 8652E

MODEL : HONDA FIT

LUMP SUM OF REPAIR

INCLUDING SUPPLY OF PARTS & LABOUR

PANEL BEATING & SPRAY PAINTING

\$9,600.00

# Treasure Appraisal Services

9 Joo Chiat Place Singapore 427743  
HP: (65) 9833 1618 Fax: (65) 6747 1017  
Email: treasureappraisal@gmail.com  
Reg No: 53218791A



## TAX INVOICE

Bill to : Herman Soffian Bin Kambari

C/O : Hendon Automotive Pte Ltd  
280 Woodlands Industrial Park E5 #01-19  
Harvest @ Woodlands  
Singapore 757322  
Tel: 9459 2885 Fax: 6334 5178  
Contact: Lynn Sim HP:

Invoice No : TAS-1807-1150  
Date : 05-Jul-18  
Report No : T-HD-180623/8652E  
Terms : COD


| S/N   | Descriptions                                                                                                                                                                                                                                                                                                                                                                                                                                                                     | Amount (\$\$) |
|-------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|
| 1     | <p>Service Rendered In Respect of:</p> <p>Vehicle Number : SKA 8652 E<br/>Vehicle Make/Model : Honda Fit<br/>Date of Inspection : 23-Jun-18<br/>Date of Accident : 21-Jun-18</p> <p>Appraisal fees include transportation and follow-up inspection.</p> <p>Submission of appraisal report by hand.</p> <p>Photography services including storage of media and submission of color photograph copies by hand.</p> <p><b>SINGAPORE DOLLARS EIGHT HUNDRED AND NINETEEN ONLY</b></p> | \$ 819.00     |
| Total |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                  | \$ 819.00     |

E. & O.E

All cheques should be crossed and made payable to "Treasure Appraisal Services".

All cheques should indicate our "Invoice No" on the reverse side of the cheque.

for Treasure Appraisal Services





# Treasure Appraisal Services

9 Joo Chiat Place Singapore 427743  
HP: (65) 9833 1618 Fax: (65) 6747 1017  
Email: treasureappraisal@gmail.com  
Reg No: 53218791A



## VEHICLE ASSESSMENT REPORT

Report No : T-HD-180623/8652E  
Date : 05-Jul-18

### REFERENCE

Assigned By : Herman Soffian Bin Kambari  
Name of Workshop : Hendon Automotive Pte Ltd  
Place of Inspection : 280 Woodlands Industrial Park E5 #01-19 Harvest @ Woodlands Singapore 757322  
Date of Assignment : 23-Jun-18  
Date of Accident : 21-Jun-18  
Date of Inspection : 23-Jun-18

### PARTICULARS OF DAMAGED VEHICLE

|                |              |                   |               |
|----------------|--------------|-------------------|---------------|
| Vehicle Reg No | : SKA 8652 E | Chassis No        | : GE81017935  |
| Year of Reg    | : Apr-11     | Odometer/km       | : 131116      |
| Make/Model     | : Honda Fit  | Engine No         | : L15A1569628 |
| Vehicle Colour | : Blue       | Engine Capacity   | : 1496 cc     |
| Vehicle Type   | : Hatchback  | Transmission Type | : Auto        |

### PRE-ACCIDENT CONDITION OF VEHICLE (STATIC TESTS ONLY)

|                     |               |                    |               |
|---------------------|---------------|--------------------|---------------|
| General Condition   | : Good        |                    |               |
| Body Paint Work     | : Good        | Footbrake          | : Serviceable |
| Steering            | : Serviceable | Handbrake          | : Serviceable |
| Front Undercarriage | : Serviceable | Rear Undercarriage | : Serviceable |

| TIRES CONDITION | Tire Brand | Size         | Tread Balance |
|-----------------|------------|--------------|---------------|
| Front RH        | : Michelin | : 205/45 R16 | : 80%         |
| Rear RH         | : Michelin | : 205/45 R16 | : 80%         |
| Front LH        | : Michelin | : 205/45 R16 | : 80%         |
| Rear LH         | : Michelin | : 205/45 R16 | : 80%         |

Road Wheels Type : Sport Rim

Note: The above percentages represent the estimated remaining balance of the tire treads in mm.  
\* Denotes damaged components.

### SYNOPSIS OF DAMAGES

At the time of survey, we noted that the vehicle has sustained an impact damages on the front portions.

For further detail of the damages, please refer to our schedule and 174 pcs of surveyed photograph attached.

# Treasure Appraisal Services

9 Joo Chiat Place Singapore 427743  
HP: (65) 9833 1818 Fax: (65) 6747 1017  
Email: treasureappraisal@gmail.com  
Reg No: 53218791A



## RECOMMENDATIONS

We referred to your instruction to appraise the above vehicle SKA 8652 E on 23-Jun-18 and in the accordance, we have carried out a physical assessment at your appointed workshop.

A static inspection was carried out and report is enclosed for your reference. The estimated repair cost submitted by the repairer for **SGD 14,264.12** as per attached schedule has been scrutinised and revised by us against the actual damages found on the vehicle and we recommended the replacements and rectifications accordingly.

The repair cost has been revised to **SGD 11,975.16** and therefore in the consideration of the repairer giving a further 20% even discount, it was agreed that the repairs to be carried out at a contractual lump sum of **SGD 9,600.00** nett.

In such event, the repairer shall has the prerogative to either use new, OEM, re-conditioned parts and/or repair any damaged body parts that the repairer is confident and capable of repairing as long as the vehicle is put on the road in its pre-accident and road worthy condition and to the entire satisfaction of the owner.

Under normal circumstances, the estimated period of repairs is **Eight (8)** working days.

Pursuant to your instructions, we have NOT AUTHORISED to carry out the repairs on your behalf and we are submitting this report for your consideration.

This survey and/or appraisalment was carried out to the best of our knowledge, ability and on a "STRICTLY WITHOUT PREJUDICE" basis to any party concern.

We are reverting the matter to you for your discretion.

Yours Truly,  
Treasure Appraisal Services



Dixon Yee T W  
Automobile Appraiser

The revised estimate was made from a visual inspection. Any discrepancies or unseen damage/s should be notified to the company within **Fourteen (14) days** from the date thereof. Otherwise, the revised amount should deem to be valid.

This report is strictly confidential and is given for the use of client and their authorised assigned agent and any disclosure or publication of it or part or whole shall be the responsibility of such person and no liability shall be attached to TREASURE APPRAISAL SERVICES thereof.

# Treasure Appraisal Services

9 Joo Chiat Place Singapore 427743  
HP: (65) 9833 1618 Fax: (65) 6747 1017  
Email: treasureappraisal@gmail.com  
Reg No: 53218791A



## APPRAISEMENT SCHEDULE

Vehicle Registration No: SKA 8652 E

Report No: T-HD-180623/8652E

| S/N        | Descriptions                      | Condition | Qty    | Repairer's Estimate | Our Assessment     |
|------------|-----------------------------------|-----------|--------|---------------------|--------------------|
| LIST ITEMS |                                   |           |        |                     |                    |
| 1          | Bonnet panel                      | Damaged   | 1 pc   | \$ 716.90           | \$ 716.90 ✓        |
| 2          | Bonnet insulator mat              | Damaged   | 1 pc   | \$ 134.50           | \$ 134.50 ✓        |
| 3          | Bonnet insulator clip             | Necessary | 1 set  | \$ 35.00            | \$ 35.00 ✓         |
| 4          | Bonnet RH hinge                   | Damaged   | 1 pc   | \$ 38.50            | \$ 38.50 ✓         |
| 5          | Bonnet LH hinge                   | Damaged   | 1 pc   | \$ 38.50            | \$ 38.50 ✓         |
| 6          | Bonnet lock assy                  | Damaged   | 1 pc   | \$ 105.00           | \$ 105.00 ✓        |
| 7          | Bonnet lock cable                 | Reusable  | 1 pc   | \$ 48.50            | \$ -               |
| 8          | Bonnet stand                      | Repaired  | 1 pc   | \$ 82.50            | \$ -               |
| 9          | Bonnet stand clip                 | Necessary | 1 pc   | \$ 18.60            | \$ 18.60 ✓         |
| 10         | Front grille assy                 | Damaged   | 1 pc   | \$ 183.60           | \$ 183.60 ✓        |
| 11         | RH headlamp assy                  | Damaged   | 1 pc   | \$ 716.90           | \$ 716.90 657.9 ✓  |
| 12         | RH headlamp lower support bracket | Damaged   | 1 pc   | \$ 36.90            | \$ 36.90 ✓         |
| 13         | LH headlamp assy                  | Damaged   | 1 pc   | \$ 716.90           | \$ 716.90 657.9 ✓  |
| 14         | LH headlamp lower support bracket | Damaged   | 1 pc   | \$ 36.90            | \$ 36.90 ✓         |
| 15         | Headlamp clip                     | Necessary | 2 pcs  | \$ 7.00             | \$ 7.00 ✓          |
| 16         | Front RH fender panel             | Damaged   | 1 pc   | \$ 571.50           | \$ 571.50 Repair ✓ |
| 17         | Front RH fender inner panel       | Repaired  | 1 pc   | \$ 327.30           | \$ -               |
| 18         | Front RH fender mud shield        | Reusable  | 1 pc   | \$ 121.60           | \$ -               |
| 19         | Front LH fender panel             | Repaired  | 1 pc   | \$ 571.50           | \$ -               |
| 20         | Front LH fender inner panel       | Repaired  | 1 pc   | \$ 327.30           | \$ -               |
| 21         | Front LH fender mud shield        | Reusable  | 1 pc   | \$ 121.60           | \$ -               |
| 22         | Front fender mud shield clip      | Necessary | 2 sets | \$ 35.00            | \$ 35.00 ✓         |
| 23         | Front bumper cover                | Damaged   | 1 pc   | \$ 760.90           | \$ 760.90 660.9 ✓  |
| 24         | Front bumper tow hook cover       | Reusable  | 1 pc   | \$ 28.50            | \$ -               |
| 25         | Front bumper centre grille        | Damaged   | 1 pc   | \$ 118.50           | \$ 118.50 ✓        |
| 26         | Front RH bumper blanking cover    | Damaged   | 1 pc   | \$ 30.50            | \$ 30.50 ✓         |
| 27         | Front LH bumper blanking cover    | Reusable  | 1 pc   | \$ 30.50            | \$ -               |
| 28         | Front RH bumper side retainer     | Damaged   | 1 pc   | \$ 36.80            | \$ 36.80 ✓         |
| 29         | Front LH bumper side retainer     | Damaged   | 1 pc   | \$ 36.80            | \$ 36.80 ✓         |
| 30         | Front bumper reinforcement        | Damaged   | 1 pc   | \$ 310.50           | \$ 310.50 ✓        |
| 31         | Front support panel               | Damaged   | 1 pc   | \$ 589.50           | \$ 589.50 352.6 ✓  |
| 32         | Front brace panel                 | Damaged   | 1 pc   | \$ 146.90           | \$ 146.90 ✓        |
| 33         | Front lower panel                 | Damaged   | 1 pc   | \$ 183.40           | \$ 183.40 ✓        |
| 34         | Horn assy                         | Damaged   | 1 pc   | \$ 120.00           | \$ 120.00 ✓        |
| 35         | Air con condenser assy            | Damaged   | 1 pc   | \$ 855.90           | \$ 855.90 733.22 ✓ |
| 36         | Air con liquid pipe               | Damaged   | 1 pc   | \$ 186.50           | \$ 186.50 X ✓      |
| 37         | Air con suction pipe              | Damaged   | 1 pc   | \$ 296.50           | \$ 296.50 X } NN ✓ |
| 38         | Air con discharge pipe            | Damaged   | 1 pc   | \$ 385.00           | \$ 385.00 X ✓      |
| 39         | Air con electric fan assy         | Damaged   | 1 pc   | \$ 585.00           | \$ 585.00 338.3 ✓  |
| 40         | Radiator assy                     | Damaged   | 1 pc   | \$ 1,437.60         | \$ 1,437.60 1276 ✓ |
| 41         | Radiator upper support bracket    | Damaged   | 1 pc   | \$ 18.50            | \$ 9.25 ✓          |

# Treasure Appraisal Services

9 Joo Chiat Place Singapore 427743  
 HP: (65) 9833 1618 Fax: (65) 6747 1017  
 Email: treasureappraisal@gmail.com  
 Reg No: 53218791A



| S/N                        | Descriptions                    | Condition | Qty   | Repairer's Estimate | Our Assessment |
|----------------------------|---------------------------------|-----------|-------|---------------------|----------------|
| <b>LIST ITEMS</b>          |                                 |           |       |                     |                |
| 42                         | Radiator lower support mounting | Damaged   | 2 pcs | \$ 65.00            | \$ 65.00       |
| 43                         | Radiator electric fan assy      | Damaged   | 1 pc  | \$ 585.00           | \$ 585.00      |
| 44                         | Radiator spare tank assy        | Reusable  | 1 pc  | \$ 89.60            | \$ -           |
| 45                         | Radiator inlet hose             | Reusable  | 1 pc  | \$ 38.60            | \$ -           |
| 46                         | Radiator outlet hose            | Reusable  | 1 pc  | \$ 42.60            | \$ -           |
| 47                         | Air cleaner box assy            | Reusable  | 1 pc  | \$ 190.60           | \$ -           |
| 48                         | Alternator assy                 | Damaged   | 1 pc  | \$ 1,101.50         | \$ 1,101.50    |
| 49                         | Washer tank assy                | Damaged   | 1 pc  | \$ 115.10           | \$ 115.10      |
| 50                         | Washer tank neck hose           | Damaged   | 1 pc  | \$ 62.50            | \$ 62.50       |
| 51                         | Washer tank top cover           | Damaged   | 1 pc  | \$ 42.60            | \$ 42.60       |
|                            |                                 |           |       | \$ 13,482.90        | \$ 11,452.95   |
| Less Discount : 20%        |                                 |           |       | \$ 2,696.58         | \$ 2,290.59    |
| List Parts Sub-Total :     |                                 |           |       | \$ 10,786.32        | \$ 9,162.36    |
| <b>SPECIAL NETT ITEMS</b>  |                                 |           |       |                     |                |
| 1                          | Front number plate with holder  | Damaged   | 1 set | \$ 50.00            | \$ 50.00       |
| 2                          | Radiator coolant                | Necessary | 1 pc  | \$ 45.00            | \$ 30.00       |
| 3                          | Front grille "RS" emblem        | Necessary | 1 set | \$ 32.80            | \$ 32.80       |
| 4                          | Front grille logo               | Necessary | 1 set | \$ 45.00            | \$ 45.00       |
| 5                          | Front bumper clip               | Necessary | 1 set | \$ 35.00            | \$ 35.00       |
| Special Nett Parts Total : |                                 |           |       | \$ 207.80           | \$ 192.80      |
| Parts Total :              |                                 |           |       | \$ 10,994.12        | \$ 9,355.16    |

| S/N | Labour Descriptions                                                                                                                                                                                                                 | Repairer's Estimate | Our Assessment |
|-----|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------|----------------|
| 1   | To furnish towing service to workshop.                                                                                                                                                                                              | \$ 150.00           | \$ 60.00       |
| 2   | Re-focus headlamp assy set.                                                                                                                                                                                                         | \$ 60.00            | \$ 40.00       |
| 3   | Diagnose, replace and/or repair to rectify front electrical system for proper functioning.                                                                                                                                          | \$ 60.00            | \$ 40.00       |
| 4   | Dismantle, replace, repair and/or re-install aircon condenser assy including vacuum and re-charge aircon                                                                                                                            | \$ 150.00           | \$ 120.00      |
| 5   | Dismantle and replace alternator assy and belting.                                                                                                                                                                                  | \$ 150.00           | \$ 120.00      |
| 6   | To carry out accident body repairs; dismantle vehicle body part/s, dismember affected damaged body panel/s, replace and/or repair, re-construction, weld to re-join and re-align vehicle body structures to pre-accident condition. | \$ 1,200.00         | \$ 1,000.00    |
| 7   | To furnish, putty, sanding, masking, prepare paint mixture & toning, complete cleaning, spray paint, polishing and waxing on affected areas.                                                                                        | \$ 1,200.00         | \$ 1,000.00    |

# Treasure Appraisal Services

9 Joo Chiat Place Singapore 427743

HP: (65) 9833 1618 Fax: (65) 6747 1017

Email: treasureappraisal@gmail.com

Reg No: 53218791A



| S/N | Labour Descriptions                                                                 | Repairer's Estimate | Our Assessment |
|-----|-------------------------------------------------------------------------------------|---------------------|----------------|
| 8   | To furnish and apply under-sealing & rust proofing coats on accident affected area. | \$ 300.00           | \$ 240.00      |
|     | Labour Total :                                                                      | \$ 3,270.00         | \$ 2,620.00    |
|     | Parts & Labour Total :                                                              | \$ 14,264.12        | \$ 11,975.16   |

**Note:** The repairer has agreed to undertake the repairs at our adjusted amount of **SGD 9,600.00** on a **\*Contractual Lump Sum Basis** corresponding to supply of all parts, labour and spray painting charges.

**N.B:** \*Under Contractual Lump Sum Basis, the repairer shall have the prerogative to either use new, OEM, re-conditioned parts and/or repair any damaged body parts that the repairer is confident and capable of repairing as long as the vehicle is put on the road in its pre-accident and road worthy condition and to the entire satisfaction of the owner.

Under normal circumstances, the estimated period of repairs is **Eight (8)** working days. Pursuant to your instruction, we have NOT AUTHORISED the repairs on your behalf.

Treasure Appraisal Services



Dixon Yee T W  
Automobile Appraiser

9067.49

20% 17250

Service Request Details

|              |                                   |
|--------------|-----------------------------------|
| Claim        | S8M00LRC                          |
| Reference    | CS3/ASM18011477/Gqd3s2-1          |
| Loss Date    | June 21, 2018                     |
| Report Date  | Jun 22, 2018 12:00:00 AM          |
| Request Date | March 12, 2019                    |
| Due Date     | March 12, 2020                    |
| Vendor Name  | LKK AUTO CONSULTANTS PTE LTD (TP) |
| Type of Loss | Third Party Vehicle Damage        |
| Services     | Re-inspection                     |

Actions

Next Step

Finish the work

Complete Work

Move

|                                 |                                                                    |
|---------------------------------|--------------------------------------------------------------------|
| Vehicle Information             |                                                                    |
| Incident Vehicle Registration # | SKA8652E                                                           |
| Make                            | TPVD HONDA                                                         |
| Model                           | FIT 1.5RS A                                                        |
| Service Address                 | 51 Ubi Avenue 1, #01-25, ... 408933                                |
| Primary Contact/Insured         | TAN PAIY PEE<br>86 BUTTERFLY AVENUE, 349832, Singapore<br>97902586 |
| Claim Handler                   | PAY Daniel<br>zhihao.pay@axa.com.sg                                |

Additional Instructions Please attend to the re-inspection 12 MARCH 2019 @ 4:00PM

Messages Invoices History Documents Assessment Metrics Notes

Document Type

Document SubType

+ Upload Documents

| NAME | TYPE | SUB-TYPE | AUTHOR | DATE<br>UPLOADED |
|------|------|----------|--------|------------------|
|------|------|----------|--------|------------------|

SKT4511E INS GIA

Reports & Statement

GIA Report

Merimen



Service Request Details

|              |                                   |
|--------------|-----------------------------------|
| Claim        | S8MX0LRC                          |
| Reference    | CS3/ASM18011477/Gpd3s2-1          |
| Loss Date    | June 21, 2018                     |
| Report Date  | Jun 22, 2018 12:00:00 AM          |
| Request Date | March 12, 2019                    |
| Due Date     | March 12, 2020                    |
| Vendor Name  | LKK AUTO CONSULTANTS PTE LTD (TP) |
| Type of Loss | Third Party Vehicle Damage        |
| Services     | Re-Inspection                     |

Actions

Next Step

Complete Work

Finish the work

More

|                                        |             |
|----------------------------------------|-------------|
| Vehicle Information                    |             |
| Incident Vehicle Registration #        | SKA8652E    |
| Make                                   | TPVD HONDA  |
| Model                                  | FIT 1.5RS A |
| Service Address                        |             |
| 51 Ubi Avenue 1, 401-25, , 408933      |             |
| Primary Contact/Insured                |             |
| TAN PAIY PEE                           |             |
| 86 BUTTERFLY AVENUE, 349832, Singapore |             |
| 97902586                               |             |
| Claim Handler                          |             |
| PAY Daniel                             |             |
| zhihao.pay@axa.com.sg                  |             |

Additional Instructions Please attend to the re-inspection 12 MARCH 2019 @ 4:00PM

Messages Invoices History Documents Assessment Metrics Notes

Add

| CREATED USER | VERSION DATE    | ESTIMATED AMOUNT | APPROVED AMOUNT | STATUS | SHARE | CLONE |
|--------------|-----------------|------------------|-----------------|--------|-------|-------|
| User Portal  | 3/15/19 1:33 PM | 7250             | 7250            | Open   | Share | Clone |

<<   **Assessment Details**

General & Workshop Details   Vehicle & Driver Details   Taxes & Ratio   Parts & Labour   Miscellaneous   Summary

**Vehicle & Driver Details**

|                       |                                           |                         |                                                         |
|-----------------------|-------------------------------------------|-------------------------|---------------------------------------------------------|
| Vehicle Registration# | SKA8652E                                  | Purchase Date           | <input type="text" value="mm/dd/yyyy"/>                 |
| Registration State    | <input type="text" value="SINGAPORE"/>    | Registration Date *     | <input type="text" value="04/08/2011"/>                 |
| Mileage               | <input type="text" value="161013"/>       | Age of Vehicle          | <input type="text" value="7"/>                          |
| Driver Details        |                                           |                         |                                                         |
| CATEGORY              | POLICY INFORMATION                        | FNOL INFORMATION        | POST SURVEY INFORMATION                                 |
| Manufacturing Year    | <input type="text" value="2008"/>         | Driver Name             | <input type="text" value="HERMAN SOFFIAN BIN KAMBARU"/> |
| Make                  | <input type="text" value="TOYOTA"/>       | Date of Birth           | <input type="text" value="mm/dd/yyyy"/>                 |
| Model                 | <input type="text" value="WISH 1.8"/>     | Age                     | <input type="text" value="0"/>                          |
| Type                  | <input type="text" value=""/>             | Occupation              | <input type="text" value="Unknown"/>                    |
| Type of Paint         | <input type="text" value=""/>             | Education Qualification | <input type="text" value="Other"/>                      |
| Chassis No            | <input type="text" value="ZGE206022155"/> | Driving Experience      | <input type="text" value="0"/>                          |
| Engine No             | <input type="text" value="ZZR1538876"/>   | Driver License #        | <input type="text" value=""/>                           |
| Engine Capacity       | <input type="text" value="1496 cc"/>      |                         |                                                         |



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Detailed Assessment

Inspection Date \*

03/12/2019

Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/Unarmed Driver Excess

0

Other Excess

Condition of Vehicle at time of survey

General condition

Good

Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good

Tyre Condition

Age of Tyres

Front Tyre Size

205/45ZR16

Front left side

MICHELIN 6mm

Front right side

MICHELIN 6mm

Spare wheel

Rear Tyre Size

205/45ZR16

Rear left side

MICHELIN 6mm

Rear right side








































MICHELIN 6mm

Assessment Details

General & Workshop DetailsVehicle & Driver DetailsVehicle ConditionTaxes & RatioParts & LabourMiscellaneousSummary

Parts

|  | EDIT | S/N | QUAN<br>TITY | MATERIAL | SIDE | PART NAME                    | PART<br>NUMBER | REPAIR/REPLACE<br>(PARTS) | CONDITION | LIST<br>PRICE | DEPL/<br>BITTON | DISC<br>OUNT% | SALY<br>AGEN | PART<br>PRICE(NT) | ACTION<br>(PARTS) | REMOVE |
|--|------|-----|--------------|----------|------|------------------------------|----------------|---------------------------|-----------|---------------|-----------------|---------------|--------------|-------------------|-------------------|--------|
|  |      | 1   | 1            |          |      | BONNET PANEL                 |                |                           | Replaced  | 716.9         |                 | 20            |              | 573.52            | Reviewing         |        |
|  |      | 2   | 1            |          |      | BONNET<br>INSULATOR MAT      |                |                           | Replaced  | 134.5         |                 | 20            |              | 107.6             | Reviewing         |        |
|  |      | 3   | 1            |          |      | SET BONNET<br>INSULATOR CLIP |                |                           | Replaced  | 35            |                 | 20            |              | 28                | Reviewing         |        |
|  |      | 4   | 1            |          |      | BONNET RH<br>HINGE           |                |                           | Replaced  | 38.5          |                 | 20            |              | 30.8              | Reviewing         |        |
|  |      | 5   | 1            |          |      | BONNET LH<br>HINGE           |                |                           | Replaced  | 38.5          |                 | 20            |              | 30.8              | Reviewing         |        |
|  |      | 6   | 1            |          |      | BONNET LOCK<br>ASSY          |                |                           | Replaced  | 105           |                 | 20            |              | 84                | Reviewing         |        |
|  |      | 7   | 1            |          |      | BONNET LOCK<br>CABLE         |                |                           | Reused    | 0             |                 | 20            |              | 0                 | Reviewing         |        |
|  |      | 8   | 1            |          |      | BONNET STAND                 |                |                           | Repair    | 0             |                 | 20            |              | 0                 | Reviewing         |        |
|  |      | 9   | 1            |          |      | BONNET STAND<br>CLIP         |                |                           | Replaced  | 18.6          |                 | 20            |              | 14.88             | Reviewing         |        |
|  |      | 10  | 1            |          |      | FRONT GRILLE<br>ASSY         |                |                           | Replaced  | 183.6         |                 | 20            |              | 146.88            | Reviewing         |        |
|  |      | 11  | 1            |          |      | RH HEADLAMP<br>ASSY          |                |                           | Replaced  | 657.9         |                 | 20            |              | 526.32            | Reviewing         |        |

|                                                                                       | EDIT                                                                                  | SR NO | QUAN TITY | MATERIAL | SIDE | PART NAME                      | PART NUMBER | REPAIR/REPLACE (PARTS) | CONDITION   | LIST PRICE | DEPR/ BTTR% | DISC COUNT% | SALV AGE% | PART PRICE(NET) | ACTION (PARTS) | REMOVE                                                                              |
|---------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|-------|-----------|----------|------|--------------------------------|-------------|------------------------|-------------|------------|-------------|-------------|-----------|-----------------|----------------|-------------------------------------------------------------------------------------|
|    |    | 25    | 1         |          |      | FRONT BUMPER CENTRE GRILLE     |             |                        | Replaced    | 118.5      |             | 20          |           | 94.8            | Reviewing      |    |
|    |    | 26    | 1         |          |      | FRONT RH BUMPER BLANKING COVER |             |                        | Replaced    | 30.5       |             | 20          |           | 24.4            | Reviewing      |    |
|    |    | 27    | 1         |          |      | FRONT LH BUMPER BLANKING COVER |             |                        | Reused      | 0          |             | 20          |           | 0               | Reviewing      |    |
|    |    | 28    | 1         |          |      | FRONT RH BUMPER SIDE RETAINER  |             |                        | Replaced    | 36.8       |             | 20          |           | 29.44           | Reviewing      |    |
|    |    | 29    | 1         |          |      | FRONT LH BUMPER SIDE RETAINER  |             |                        | Replaced    | 36.8       |             | 20          |           | 29.44           | Reviewing      |    |
|    |    | 30    | 1         |          |      | FRONT BUMPER REINFORCEMENT     |             |                        | Replaced    | 310.5      |             | 20          |           | 248.4           | Reviewing      |    |
|    |    | 31    | 1         |          |      | FRONT SUPPORT PANEL            |             |                        | Replaced    | 352.6      |             | 20          |           | 282.08          | Reviewing      |    |
|    |    | 32    | 1         |          |      | FRONT BRACE PANEL              |             |                        | Replaced    | 146.9      |             | 20          |           | 117.52          | Reviewing      |    |
|  |  | 33    | 1         |          |      | FRONT LOWER PANEL              |             |                        | Replaced    | 183.4      |             | 20          |           | 146.72          | Reviewing      |  |
|  |  | 34    | 1         |          |      | HORN ASSY                      |             |                        | Replaced    | 120        |             | 20          |           | 96              | Reviewing      |  |
|  |  | 35    | 1         |          |      | AIR CON CONDENSER ASSY         |             |                        | Replaced    | 733.22     |             | 20          |           | 586.58          | Reviewing      |  |
|  |  | 36    | 1         |          |      | AIR CON LIQUID PIPE            |             |                        | Serviceable | 0          |             | 20          |           | 0               | Reviewing      |  |
|  |  | 37    | 1         |          |      | AIR CON SUCTION PIPE           |             |                        | Serviceable | 0          |             | 20          |           | 0               | Reviewing      |  |

## Labour

| EDIT | SR NO | REPAIR/REPLACE (LABOUR) | PART NAME                                                                                                                                                                                                                          | LABOUR R&R | LABOUR REPAIR | PAINT | ACTION (LABOUR) | COMMENT | REMOVE |
|------|-------|-------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------|---------------|-------|-----------------|---------|--------|
|      | 1     |                         | TO FURNISH TOWING SERVICE TO WORKSHOP.                                                                                                                                                                                             | 50         | 0             | 0     | Reviewing       |         |        |
|      | 2     |                         | RE-FOCUS HEADLAMP ASSY SET. }                                                                                                                                                                                                      | 30         | 0             | 0     | Reviewing       |         |        |
|      | 3     |                         | DIAGNOSE, REPLACE AND/OR REPAIR TO RECTIFY FRONT ELECTRICAL SYSTEM FOR PROPER FUNCTIONING. }                                                                                                                                       | 0          | 0             | 0     | Reviewing       |         |        |
|      | 4     |                         | DISMANTLE, REPLACE, REPAIR AND/OR RE-INSTALL AIRCON CONDENSER ASSY INCLUDING VACUUM AND RE-CHARGE AIRCON.                                                                                                                          | 60         | 0             | 0     | Reviewing       |         |        |
|      | 5     |                         | DISMANTLE AND REPLACE ALTERNATOR ASSY AND BELTING.                                                                                                                                                                                 | 60         | 0             | 0     | Reviewing       |         |        |
|      | 6     |                         | TO CARRY OUT ACCIDENT BODY REPAIRS; DISMANTLE VEHICLE BODY PART/S; DISMEMBER AFFECTED DAMAGED BODY PANEL/S; REPLACE AND/OR REPAIR, RE-CONSTRUCTION, WELD TO RE-JOIN AND RE-ALIGN VEHICLE BODY STRUCTURE TO PRE-ACCIDENT CONDITION. | 800        | 0             | 0     | Reviewing       |         |        |
|      | 7     |                         | TO FURNISH, PUTTY, SANDING, MASKING, PREPARE PAINT MIXTURE & TONING, COMPLETE CLEANING, SPRAY PAINT, POLISHING AND WAXING ON AFFECTED AREAS.                                                                                       | 800        | 0             | 0     | Reviewing       |         |        |



<< Assessment Details

| General & Workshop Details |       | Vehicle & Driver Details           |           | Vehicle Condition | Taxes & Ratio | Parts & Labour | Miscellaneous | Summary |
|----------------------------|-------|------------------------------------|-----------|-------------------|---------------|----------------|---------------|---------|
| EDIT                       | SR NO | NAME                               | ACTION    | AMOUNT            | COMMENT       | REMOVE         |               |         |
|                            | 1     | DAY OF REPAIR                      | Reviewing |                   | 7             |                |               |         |
|                            | 2     | SET FRONT NUMBER PLATE WITH HOLDER | Reviewing | 40                | REPLACED      |                |               |         |
|                            | 3     | RADIATOR COOLANT                   | Reviewing | 30                | REPLACED      |                |               |         |
|                            | 4     | SET FRONT GRILLE "RS" EMBLEM       | Reviewing | 32.8              | REPLACED      |                |               |         |
|                            | 5     | SET FRONT GRILLE LOGO              | Reviewing | 45                | REPLACED      |                |               |         |
|                            | 6     | SET FRONT BUMPER CLIP              | Reviewing | 35                | REPLACED      |                |               |         |



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

| General & Workshop Details | Vehicle & Driver Details | Vehicle Condition | Taxes & Ratio | Parts & Labour | Miscellaneous | Summary |
|----------------------------|--------------------------|-------------------|---------------|----------------|---------------|---------|
| Claim Amount               | \$9,067.50               |                   | Claim Amount  |                | \$9,067.50    |         |
| CATEGORY                   | ESTIMATE                 | REVISED AMOUNT    |               |                |               |         |
| Spare Parts                | \$7,024.70               |                   | \$7,024.70    |                |               |         |
| Labour                     | \$1,860.00               |                   | \$1,860.00    |                |               |         |
| Miscellaneous              | \$182.80                 |                   | \$182.80      |                |               |         |

Submit for Review



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

|                                                                                 |  |       |  |                |  |           |  |        |  |         |  |                        |  |
|---------------------------------------------------------------------------------|--|-------|--|----------------|--|-----------|--|--------|--|---------|--|------------------------|--|
| <div><div>Add</div><div>Approve</div><div>Deny</div><div>Submit All</div></div> |  | SR NO |  | NAME           |  | ACTION    |  | AMOUNT |  | COMMENT |  | REMOVE                 |  |
| <div><div></div><div></div><div></div></div>                                    |  | 1     |  | FINAL LUMP SUM |  | Reviewing |  | 7250   |  |         |  | <div><div></div></div> |  |