

Veron Chen (LKKAUTO)

From: CDGE Braddell Private Cars Crash Repair Operation
<braddell_operation@sparkcarcare.com>
Sent: Wednesday, 20 March 2019 10:14 AM
To: Kenneth Kong (LKKAUTO)
Subject: Fw: SMF3469B - Supp and Check Photos
Attachments: IMG_1508.JPG; IMG_1527.JPG; IMG_1518.JPG; IMG_1524.JPG; IMG_1525.JPG; IMG_1526.JPG; IMG_1546.JPG; IMG_1532.JPG; IMG_1533.JPG; IMG_1544.JPG; IMG_1545.JPG

Re-send

Best Regards
External Business | ComfortDelGro Engineering Pte Ltd
Off: 6383 7656 (Ngo - Supervisor) / Off: 6383 8115 (William) / Off: 6383 7362 (Andrew)

Fax: 6281 5767
www.SPARKcarcare.com

From: CDGE Braddell Private Cars Crash Repair Operation
Sent: Tuesday, 19 March 2019 9:53 AM
To: LKK Kenneth
Subject: SMF3469B - Supp and Check Photos

Dear Kenneth

Please note that the both front seat belt have been activated. Hence, need to replace driver and pax seat belt and air bag control unit.

RH rear tyre torn, need to replace.

Both front lower arm dent.

Andrew
Best Regards
External Business | ComfortDelGro Engineering Pte Ltd
Off: 6383 7656 (Ngo - Supervisor) / Off: 6383 8115 (William) / Off: 6383 7362 (Andrew)
Fax: 6281 5767
www.SPARKcarcare.com