

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

ISLAND RECOVERY SERVICES
59 UBI AVE 1
#07-08 BIZLINK CENTRE
S 408938

TP uol
Veron.

Vehicle No :YN 8738 H
Make/Model :ISUZU NHR85AUE4A
Accident date :07.03.2019

No	DESCRIPTION	Qty	Amount (\$\$)
Special Nett Items			
1	Rear number plate <i>Best</i>	1	\$ 60.00 <i>30(SN)</i>
2	Tailgate LH bracket <i>Cracked</i>	1	\$ 287.50 ✓
3	Reverse sensor <i>Dangd.</i>	1	\$ 322.00 <i>200(SN)</i>
4	Aluminium flat bed <i>Reps</i>	1	\$ 5,175.00 +
5	Aluminium flat bed stickers <i>new</i>	1	\$ 172.50 <i>100(SN)</i>
6	Aluminium flat bed lower adjoining beam <i>Best</i>	1	\$ 1,380.00 <i>850(SN)</i>
7	Aluminium flat bed lower adjoining beam sticker <i>Hec</i>	1	\$ 115.00 <i>80(SN)</i>
8	Rear under rider <i>Reps</i>	1	\$ 920.00 x
9	Rear under rider sticker <i>new</i>	1	\$ 115.00 <i>50(SN)</i>
10	Rear Hydraulic pump (outer) @ \$4,025.00 <i>Dangd. LH</i>	2	\$ 8,050.00 <i>2800(SN)</i>
11	Rear Hydraulic pump (inner) @ \$2,875.00 <i>Dangd</i>	2	\$ 5,750.00 <i>2400(SN)</i>
12	Rear LH Hydraulic pump (outer) bracket <i>Best</i>	1	\$ 172.50 ✓
13	Rear LH Hydraulic pump (inner) bracket <i>Best</i>	1	\$ 172.50 ✓
14	Rear LH side gate advertisement sticker <i>new</i>	1	\$ 345.00 <i>150(SN)</i>
15	LH tailgate <i>new</i>	1	\$ 290.00 +
16	Rear LH side gate <i>Reps</i>	2	\$ 2,155.10 x
17	Rear LH side gate hinge <i>new</i>	1	\$ 63.30 x
18	Rear LH side gate lower panel <i>Dented</i>	1	\$ 1,029.30 <i>700(SN)</i>
Total			\$ 26,574.70

Labour Cost

1	To check wiring	\$ 50.00 <i>30</i>
2	Remove & reinstall reverse sensor	\$ 100.00 <i>50</i>
3	Remove & reinstall flat bed assy	\$ 800.00 <i>450</i>
4	Remove & reinstall hydraulic pump system	\$ 800.00 <i>450</i>
5	Remove ,replace & repair consistent to the accident	\$ 1000.00 <i>650</i>
6	Respray painting	\$ 800.00 <i>400</i>
Total		\$ 3550.00

Grand Total \$ 30124.70

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total 10022.50
L/s: 8K
07 Days

8K