

1/10/2019

ASS. REC. BY:

REF: CS/MSG/1900 4449 LAST3

Special Instruction:

SAT/VEH/
MEMPHIS

Adrian

ASSIGNMENT (Office)

From (Person):

Katherine Wong

of

M81G

Date/Time: 11/3/19 @ 4:19pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EYA / INV / MY / CS

To Inspect Vehicle No:

SMA 9757G

Insured:

SLD 7063J

at Workshop in/

Hua Meng Spray

Tel:

67465519

of

1 kaki Bkt Ave 6 #01-81

Policy No:

28781062QMY

Claim No:

587141

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A. 7/3/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

11:12am 12/3/19

Person Contacted:

jue

Vehicle

INT/OUT

Date/Time	Action/Instruction (✓) Estimate	
	SMA 9757G - NA / CTI 19004234 / r3	D.O.A. 07/03/2019
	SLD 7063J - NA / CTI 19004234 / r3	D.O.A. 07/03/2019
14/03/19	@ 14:39 p.m. revert pending estimate from report to Katherine via memo.	

Adrian

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SMA97576 Yr Regn: 2015 DecType: M.Cab / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Nissan X-Trail c.c. 1997Colour: White A/C: Insured / Std / Nil / NASp. Reading: 83710 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: JN1JANT32Z0001245Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 225/60R18R: 225/60R18BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 12/03/19Survey held at Hua MengDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP MS/6
13/06/19 Combined HS \$4,000/- @ 6 days with Adrian
(~~\$1,000~~ \$10,072.60 Red - 72%)

mv:

PV:

Nett:

RECEIVED 13 JUN 2019

RECEIVED 17 JUN 2019

Resurvey no of Trip - 1

Date/Time, File Pass to?

Date/Time, File Return to?

1) Typist

2)

3)

4)

5)

6)

Prel. Report:

Final Report: \$4,000/- HS

Part Prices Check:

IN

OUT

Survey Fee:

Basic & Add.

S + RS, SI

Photos

Others

TOTAL

Date:

20011211

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Mar 2019		11 Mar 2019 16:19 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	CHAN JUN AN GERALD, ID: S8928501A		
Main Claimant:	HYRIL ANNUAR BIN BORHAN, ID: S7042733H		
Vehicle Reg. No.:	SMA9757G	Date of Loss:	07/03/2019 00:00 - :59 [38 Months and 25 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 587141	Policy/Cover Note No.:	28781062QMY Coverage: 27/06/2018 - 26/06/2019
Vehicle Reg. No. (Insured):	SLD7063J	Policy No. (Claimant):	
		Excess:	
Repairer:	Hua Meng Spray Painting Workshop (HQ) No 1 Kaki Bukit Avenue 6, #01-61 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 67478064, 67465519		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 12/03/2019]		
Adj Asg. Remarks:	on WP. Liability unclear.Non Reporting. TP want to use LKK as the SJE. Contact Person: June / 6747 8064 / 6746 5519.		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View Sent Message

This mail is associated with :

***SMA9757G (587141)
[SLD7063J]**

TP

HYRIL ANNUAR BIN BORHAN

Mar 7 2019 12:00AM

[CHAN JUN AN GERALD]

Hua Meng Spray Painting Workshop

[Resend](#)[View Recipients](#)[Print Message](#)[Delete Message](#)[Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 14/03/2019 14:39 PM.
To katherine_wong@sg.msg-asia.com
CC sur@lkkauto.com
Subject SMA9757G (587141) [SLD7063J] TP

Dear Katherine,

Please be informed that we have inspected the vehicle SMA 9757G on 12/03/2019.

We are pending estimate from repairer.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

DOCUMENTS SUMMARY

There are no documents.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	07/03/2019 16:34
Date Of Accident	07/03/2019 13:50
Exact Location Of Accident	PAYA LEBAR ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMA9757G
Insured/Policyholder	
Name Of Registered Owner	MR HYRIL ANNUAR BIN BORHAN
NRIC No	S7042733H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-81382266
Alternative Phone No	OTHERS-81382266

Vehicle Particulars

Manufacturer	NISSAN
Model	X-TRAIL
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN3067391800
Cover Note Number	

Driver

Name of Driver	MR HYRIL ANNUAR BIN BORHAN
NRIC No	S7042733H
Date Of Birth	09/12/1970
Occupation	OUTDOOR
Date Of Driving Pass	05/04/1995
Driving Experience	23 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81382266
Fax Number	
Contact Number	OTHERS-81382266
Email Address	NOEMAIL

Address	BLK 673A YISHUN AVE 4 #12-638
Postcode	761673
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : ARSAD SAPUTRA GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER TO THE ATTACHED STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLD7063J
Vehicle Make/Model/Colour	MAZDA 3
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	CHAN LI YUN, CHERYL
NRIC/Passport Number	S9312659I
Contact Number	97450650
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name MR HYRIL ANNUAR BIN BORHAN
Approximate Age
Injuries Sustain SLIGHT
Injured person in which vehicle? SMA9757G
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance? NO
Address
Postcode

DETAILS OF INJURED PERSON 2

Name ARSAD SAPUTRA
Approximate Age
Injuries Sustain SLIGHT
Injured person in which vehicle? SMA9757G
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance? NO
Address
Postcode

SKETCH PLAN

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

JN1JANT3220001245

HYRIL ANNUAR BIN BORHAN
BLK 673A YISHUN AVE 4
#12-638
S 761673

TP MS16
Shirley

Date :30.04.2019
Vehicle No :SMA 9757 G
Make/Model :NISSAN X-TRAIL
Accident date :07.03.2019

No	DESCRIPTION	Qty	Amount (\$\$)
Nett Items			
1	Rear windscreen rubber <i>all new</i>	1	\$ 56.2 X
2	Rear tailgate <i>Repis</i>	1	\$ 46.2 X
3	Rear tailgate hinges @ \$54.50	2	\$ 109 X
4	Rear tailgate upper lock	1	\$ 230.6 X
5	Rear tailgate lower lock	1	\$ 177.8 X
6	Rear tailgate inner board	1	\$ 497.9 X
7	Rear tailgate AWD emblem	1	\$ 80.9 ✓
8	Rear tailgate X TRONICCVT emblem	1	\$ 65.7 ✓
9	Rear tailgate SPARCO emblem	1	\$ 65.7 ✓
10	Rear tailgate centre NISSAN emblem	1	\$ 95.7 ✓
11	Rear tailgate handle	1	\$ 152.5 X
12	Rear tailgate shock absorber @ \$1161.20	2	\$ 2322.4 X
13	Rear tailgate reflector @ \$785.40	2	\$ 1570.8 X
14	Rear tailgate inner side rubber @ \$19.90	2	\$ 39.8 X
15	Rear tailgate inner side rubber clips(1set)	1	\$ 60 X
16	Rear tailgate weather strip	1	\$ 174.6 X
17	Rear end pannel <i>Dented</i>	1	\$ 492.3 ✓
18	Rear end pannel top garnish <i>all new</i>	1	\$ 93.5 X
19	Rear bumper <i>Deformed</i>	1	\$ 686.2 ✓
20	Rear bumper side holder @ \$58.40 <i>new</i>	2	\$ 116.8 ✓
21	Rear bumper lower reflector @ \$73.20 <i>cracked</i>	2	\$ 146.4 ✓
22	Rear bumper reinforcement <i>Bent</i>	1	\$ 650.2 X 587.10
23	Rear bumper sponge <i>all new</i>	1	\$ 147.2 X
24	Rear bumper bracket @ \$192.30 <i>all new</i>	2	\$ 384.6 X
			\$ 8463
Less 10% Disc			\$ 846.3
Total			\$ 7616.7

Special Nett Items

1	Rear tailgate camera <i>all new</i>	1	\$ 800 X
2	Rear tailgate WORKS sticker <i>new</i>	1	\$ 58 ✓
3	Rear bumper top Xtrail garnish <i>Deformed</i>	1	\$ 264 ✓
4	Rear bumper lower cover <i>Distorted</i>	1	\$ 371.9 ✓
5	Rear bumper reverse sensor @ \$328.00 <i>2 pieces damaged</i>	4	\$ 1312 X 360
6	Rear End Panel Top Chrome Moulding <i>all new</i> (Double Sided Adhesive)	350	\$ 2805.9
Total			\$ 2805.9

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

HYRIL ANNUAR BIN BORHAN
BLK 673A YISHUN AVE 4
#12-638
S 761673

Date :30.04.2019
Vehicle No :SMA 9757 G
Make/Model :NISSAN X-TRAIL
Accident date :07.03.2019

No	DESCRIPTION	Qty	Amount (\$\$)
----	-------------	-----	---------------

Labour Cost

- 1 Remove & Reinstall rear windscreen
- 2 Remove & Reinstall reverse sensor
- 3 Remove & Reinstall Upholstery
- 4 Remove replace & repair consistent to the accident
- 5 Respray painting
- 6 Tuff kote

	\$ 150
	\$ 200
	\$ 150
	\$ 1600
	\$ 1400
	\$ 150
Total	\$ 3650

Grand Total \$ 14072.6

14422.60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total 4587.02
L/S: AK
06 Days.



LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19004449/AGSD3N2

Date: 17/06/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	28781062QMY
Claimant Vehicle No :	SMA9757G	Insured Vehicle No :	SLD7063J
Date of Loss:	07/03/2019	Nature of Claim:	TP
		Claim No:	587141

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMA9757G	Engine No:	MR20791980B
Make & Model:	NISSAN X-TRAIL, 2.0 CVT (A)	Chassis No:	JN1JANT32Z0001245
Reg. Date:	10/12/2015 (Man. Year: 2015)	Odometer:	83710 km
Colour:	White		
Engine Capacity:	1997 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/60R18	Rear Tyre Size:	225/60R18
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	10,772.60	3,437.02	7,335.58	68.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,650.00	1,550.00	2,100.00	57.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	14,422.60	4,987.02	9,435.58	65.42
Approved Total (Overridden) (\$\$)		4,000.00		
Nett Amount (\$\$)	14,422.60	4,000.00	10,422.60	72.27

INSPECTION

Date of Assignment:	11/03/2019	
Date Inspected:	12/03/2019	Inspected At:
		Hua Meng Spray Painting Workshop (HQ)
		No 1 Kaki Bukit Avenue 6, #01-61
		Autobay@Kaki Bukit
		Singapore 417883

Estimated Period of Repair: 6.0 days

Adjuster: XING GUO QIANG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 17 Jun 2019)
Parts:	N/A NISSAN X-TRAIL 2.0 CVT (A) (Model not available in database)
Labour:	Repairer's (Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMA9757G)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN RUBBER	Not Necessary	56.20 FN	*- FN
2	1		*REAR TAILGATE	Repair	46.20 FN	*- FN
3	2		*REAR TAILGATE HINGES	Not Necessary	109.00 FN	*- FN
4	1		*REAR TAILGATE UPPER LOCK	Not Necessary	230.60 FN	*- FN
5	1		*REAR TAILGATE LOWER LOCK	Not Necessary	177.80 FN	*- FN
6	1		*REAR TAILGATE INNER BOARD	Not Necessary	497.90 FN	*- FN
7	1		*REAR TAILGATE AWD EMBLEM	Necessary	80.90 FN	*80.90 FN
8	1		*REAR TAILGATE X TRONICCVT EMBLEM	Necessary	65.70 FN	*65.70 FN
9	1		*REAR TAILGATE SPARCO EMBLEM	Necessary	65.70 FN	*65.70 FN
10	1		*REAR TAILGATE CENTRE NISSAN EMBLEM	Necessary	95.70 FN	*95.70 FN
11	1		*REAR TAILGATE HANDLE	Not Necessary	152.50 FN	*- FN
12	2		*REAR TAILGATE SHOCK ABSORBER	Not Necessary	2,322.40 FN	*- FN
13	2		*REAR TAILGATE REFLECTOR	Not Necessary	1,570.80 FN	*- FN
14	2		*REAR TAILGATE INNER SIDE RUBBER	Not Necessary	39.80 FN	*- FN
15	1		*SET REAR TAILGATE INNER SIDE RUBBER CLIPS	Not Necessary	60.00 FN	*- FN
16	1		*REAR TAILGATE WEATHER STRIP	Not Necessary	174.60 FN	*- FN
17	1		*REAR END PANEL	Dented	492.30 FN	*492.30 FN
18	1		*REAR END PANEL TOP GARNISH	Not Necessary	93.50 FN	*- FN
19	1		*REAR BUMPER	Deformed	686.20 FN	*686.20 FN
20	2		*REAR BUMPER SIDE HOLDER	Necessary	116.80 FN	*116.80 FN
21	2		*REAR BUMPER LOWER REFLECTOR	Cracked	146.40 FN	*146.40 FN
22	1		*REAR BUMPER REINFORCEMENT	Bent	650.20 FN	*587.10 FN
23	1		*REAR BUMPER SPONGE	Not Necessary	147.20 FN	*- FN
24	2		*REAR BUMPER BRACKET	Not Necessary	384.60 FN	*- FN
25	1		*REAR TAILGATE CAMERA	Not Necessary	800.00 FS	*- FS
26	1		*REAR TAILGATE WORKS STICKER	Necessary	58.00 FS	*58.00 FS
27	1		*REAR BUMPER TOP XTRAIL GARNISH	Deformed	264.00 FS	*264.00 FS
28	1		*REAR BUMPER LOWER COVER	Distorted	371.90 FS	*371.90 FS
29	1		*REAR BUMPER REVERSE SENSOR (4 Pcs)	Damaged (2 Pcs only)	1,312.00 FS	*360.00 FS
30	1		*REAR END PANEL TOP CHROME MOULDING (DOUBLE SIDED ADHESIVE)	Necessary	350.00 FS	*280.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	11,618.90	3,670.70
- Nett Item Discount on N Items 10.00/10.00% (\$\$)	846.30	233.68
Total Parts (\$\$)	10,772.60	3,437.02

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REINSTALL REAR WINDSCREEN	New	150.00	0.00
2	REMOVE & REINSTALL REVERSE SENSOR	New	200.00	60.00
3	REMOVE & REINSTALL UPHOLSTERY	New	150.00	80.00
4	REMOVE REPLACE & REPAIR CONSISTENT TO THE ACCIDENT	New	1,600.00	650.00
5	RESPRAY PAINTING	New	1,400.00	700.00
6	TUFF KOTE	New	150.00	60.00
Gross Labour Cost (S\$)			3,650.00	1,550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >