

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 6748 4422/ 6745 4422 Fax : 6747- 6720 REG NO 200501102H

LONPAC INSURANCE BHD

100 Beach Road # 19 - 00
 Shaw Tower
 Singapore 189702
 Tel : 6250 - 7388
 Fax : 6296 - 2706

Poh Kin.

Quotation

DATE : 09.03.2019
 VEH NO : SJN8919E
 MODEL : Honda Freed
 D O A : 08.03.2019
 YR REF : GBB3322S

Attn : Motor Claim Dept (Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SJN8919E (HONDA FREED)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
NO	LIST ITEMS		
1	Rear Number Plate Lamp - LH & RH <i>the new</i>	2	90.20 <i>+</i>
2	Rear Bumper <i>behind</i>	1	689.10 <i>✓</i>
3	Rear Bumper Clips <i>new</i>	1 set	30.00 <i>✓</i>
4	Rear Bumper Side Holders - LH & RH <i>new</i>	2	65.00 <i>✓</i>
5	Rear Bumper Towing Cover <i>the new</i>	1	32.40 <i>+</i>
6	Rear End Panel <i>Dented</i>	1	592.80 <i>✓</i>
7	Rear End Panel Inner <i>Dented</i>	1	381.40 <i>✓</i>
8	Rear End Panel Top Cover <i>behind</i>	1	185.40 <i>✓</i>
9	Rear End Panel Top Cover Clips <i>new</i>	1 set	10.00 <i>✓</i>
10	Tail Lamp - LH & RH <i>LH ut, RH cracked.</i>	2	745.40 <i>✓</i>
11	Tail Lamp Panel - LH & RH <i>RH Dented</i>	2	420.60 <i>210.30</i>
12	Tailgate <i>Disrupted</i>	1	1,460.30 <i>✓</i>
13	Tailgate Lock <i>changed</i>	1	265.00 <i>✓</i>
14	Tailgate Weatherstripe <i>ut</i>	1	198.60 <i>✓</i>
15	Tailgate Damper - LH & RH <i>cut</i>	2	337.80 <i>✓</i>
16	Tailgate Outer Garnish <i>behind</i>	1	287.30 <i>✓</i>
17	Tailgate Outer Garnish Clips <i>new</i>	1 set	10.00 <i>✓</i>
18	Tailgate Inner Pocket Handle <i>behind</i>	1	28.00 <i>✓</i>
19	Tailgate Wiper Arm <i>ut</i>	1	70.40 <i>✓</i>
20	Tailgate Wiper Arm Cover <i>ut</i>	1	15.40 <i>✓</i>
21	Tailgate Wiper Motor <i>changed</i>	1	285.30 <i>✓</i>
22	Tailgate Inner Trim Board <i>behind</i>	1	298.50 <i>✓</i>
23	Tailgate Inner Trim Board Clips <i>new</i>	1 set	30.00 <i>✓</i>
24	Tailgate Glass <i>Shattered</i>	1	1,380.90 <i>✓</i>
25	Tailgate Glass Moulding <i>new</i>	1	115.00 <i>✓</i>
26	Tailgate Brake Lamp <i>the new</i>	1	248.10 <i>+</i>
27	Honda Logo <i>new</i>	1	35.20 <i>✓</i>

28	Freed Emblem <i>New</i>		1	49.20	✓
29	Rear Fender Inner Trim Board - LH & RH <i>Def</i>		2	875.80	✓
30	Rear Fender Inner Trim Board Clips <i>New</i>		1 set	60.00	✓
31	Rear Fender Inner Trim Board Upper x 2 <i>New</i>		2	590.80	✓
32	Rear Fender Inner Trim Board Upper Clips		1 set	60.00	✓
33	Rear Fender - RH <i>Repair</i>		1	1,098.00	✓
34	Rear Exhaust Pipe <i>New</i>	8712 10	1	608.40	✓
35	Rear Exhaust Mounting <i>New</i>		1	33.00	✓
36	Floor Panel <i>Repair</i>	6969.68	1	1,419.30	✓

\$ 13,102.60
 (2,620.52)
\$ 10,482.08

Less 20%

S/NET ITEMS

1	Rear Number Plate <i>Call</i>		1	30.00	✓
2	Rear Number Plate Holder <i>Def</i>		1	30.00	✓
3	Reverse Sensor <i>Def</i>		1	280.00	200
4	Rear End Panel Sealant <i>New</i>	1410	1	60.00	✓
5	Rear Camera <i>Def</i>		1	550.00	380
6	Tailgate Glass Sealant <i>New</i>		1	60.00	✓
7	Tailgate Glass Solar Film <i>New</i>		1	280.00	200
8	Rear Video Recorder <i>Def</i>		1	580.00	450

\$ 1,870.00

Total parts

\$ 12,352.08

LABOUR CHARGE

1	To knocking & pull out rear portion & renew above parts	\$	1,600.00 1200
2	To putty & spray up paint works	\$	1,400.00 1200
3	To underseal	\$	150.00 60
4	To check wiring	\$	50.00 30
5	To remove upholstery	\$	150.00 80
6	To remove rear LH & RH seats	\$	280.00 160
7	To remove reverse sensor	\$	100.00 50
8	To remove rear camera	\$	100.00 50
9	To remove video recorder	\$	100.00 50
10	To remove exhaust pipe	\$	150.00 X

- 11 To transfer tailgate fittings
- 12 To replace tailgate glass
- 13 To remove fender glass

\$	150.00 <i>80</i>
\$	180.00 <i>120</i>
\$	120.00 <i>X.</i>
\$	4,530.00
\$	16,882.08

Grand Total

GST Will be reflected in the final bills

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

*total: 11459.68.
 h/s: 9150.
 09 Days.*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer:
 Signature:
 Date: