



GOLDBELL ENGINEERING

Industrial Vehicles.
20,000 Served. And Counting.

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

GOLDBELL ENGINEERING PTE LTD

10 Tuas Avenue 18 Singapore 638894

Tel: +65 6861 0007 Fax: +65 6861 3676 (Sales)

Fax: +65 6863 0425 (Service) +65 6862 1347 (Parts)

Website: www.goldbell.com.sg

Co. Reg No.: 198003963G

Page 1 / 2

Acknowledged by Repairer

ESTIMATE

Signature:

Date:

Date : 08/03/2019
To :
Attn. :
Office / Mobile :
Email Address :

From : GOLDBELL ENGINEERING PTE LTD
Attn. : ANDYOOILK
Office / Mobile : +65 67730073
Email / Fax No. : AndyOoiLK@goldbell.com.sg

Reg No : SKH5666Z
Model : FREED HYBRID 1.5G AUTO
Chassis No : GB71036933
Engine No : LEB5564487
Quotation No. : 83306
Ref. No. : GBE/SVC/SALES
D.O.A. : 07/03/2019
Policy No. : D18MTPV01011966
Claim Type : THIRD PARTY
Workshop : PANDAN

S/N	Part No	Description	Qty	U/Price	%	Net Price	Ext Price
1		FRONT BUMPER / <i>00</i>	1	1,074.00	-20	859.20	859.20
2		FRONT BUMPER REINFORCEMENT ?	1	447.00	-20	357.60	357.60
3		FRONT BUMPER BRACKET LH ?	1	33.00	-20	26.40	26.40
4		FRONT BUMPER SIDE RETAINER LH - <i>BR</i>	1	19.20	-20	15.36	15.36
5		FRONT BUMPER TRIANGLE COVER LH / <i>MIS</i>	1	81.00	-20	64.80	64.80
6		RADIATOR GRILLE -TOP / <i>BR</i>	1	1,002.00	-20	801.60	801.60
7		RADIATOR GRILLE -LOWER / <i>BR</i>	1	144.00	-20	115.20	115.20
8		HEADLAMP ASSY LH / <i>BR</i>	1	1,740.00	-20	1,392.00	1,392.00
9		FRONT FENDER LH / <i>00</i>	1	567.00	-20	453.60	453.60
10		RADIATOR SUPPORT PANEL ?	1	720.00	-20	576.00	576.00

PARTS TOTAL : 4,661.76

SPECIAL NETT ITEMS

1 FRONT NUMBER PLATE WITH GARNISH 1 *35* 45.00

PARTS TOTAL: 45.00

LABOUR CHARGES

1 TO REMOVE & REPLACE DAMAGED *250*
PARTS , CUT , WELD , STRAIGHTEN &
PANEL BEAT ACCIDENT AREAS *500* 1000.00

2 TO CHECK AND REPAIR WIRING SYSTEM *30* 50.00

3 TO REMOVE & REFIT AIR CON
CONDENSOR AND TOP UP AIR CON GAS *?* 120.00

4 SUNDRIES *20* 50.00

5 TO PUTTY , CLEAN , SPRAY PAINT AND
POLISING ON FRONT *750* 1400.00
BUMPER , BONNET , RADIATOR SUPPORT
PANEL , FRONT FENDER LH ,

LABOUR TOTAL : 2,620.00

SUB-TOTAL : 7,326.76

GST @ 0% for \$ 7,326.76 0.00

GRAND TOTAL (\$\$) : 7,326.76

*Spk (LKK) wil promote
83228813 11/3/19 3.10 pm
PIP
Reg for 1st day
4 days*

biSAFE
ST & R



Certificate No: AJA/SJWQ1243

Certificate No: AJA/SJWQ1243



GOLDBELL
ENGINEERING

Industrial Vehicles.
20,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

10 Tuas Avenue 18 Singapore 638894
Tel: +65 6861 0007 Fax: +65 6861 3676 (Sales)
Fax: +65 6863 0425 (Service) +65 6862 1347 (Parts)
Website: www.goldbell.com.sg
Co. Reg. No.: 198003963G

Page 2 / 2

ESTIMATE

Date	: 08/03/2019	Reg No	: SKH5666Z
To	:	Model	: FREED HYBRID 1.5G AUTO
Attn.	:	Chassis No	: GB71036933
Office / Mobile	:	Engine No	: LEB5564487
Email Address	:	Quotation No.	: 83306
		Ref. No.	: GBE/SVC/SALES
From	: GOLDBELL ENGINEERING PTE LTD	D.O.A.	: 07/03/2019
Attn.	: ANDYOOILK	Policy No.	: D18MTPV01011966
Office / Mobile	: +65 67730073	Claim Type	: THIRD PARTY
Email / Fax No.	: AndyOoiLK@goldbell.com.sg	Workshop	: PANDAN

PREPARED BY : ANDYOOILK

DATE / TIME : _____

SURVEYOR : _____

MOBILE NO : _____

OFFICE FAX NO : _____

EMAIL ADDRESS : _____

EXCESS AMOUNT : _____

REPAIR TYPE : PART-BY-PART / LUMP SUM

AUTHORISATION : AUTHORISED / NOT AUTHORISED

RE-SURVEY : BEFORE PAINT / AFTER PAINT

NO. OF DAYS : _____

REMARKS : _____



Certificate No: AJA/ISO/1242 Certificate No: AJA/ISO/1242